Hull plating fit-up inspection, Z23, 2025-12-23

Document number	INS-Z23-20251223-1
Revision	1
Status	APPROVED
Classification	CONFIDENTIAL
Author	Merrin Glenmore
Approved by	-
Date	2025-12-23

Inspection type	Hull plating fit-up inspection
Zone	Z23
Date	2025-12-23
Inspector	Merrin Glenmore
Number of findings	6

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Missing fastener	Deck 24, frame 305	Major	Install fastener per drawing and record torque.	2025-12-30
F-02	Corrosion spot	Deck 57, frame 87	Critical	Treat and re-coat the area.	2025-12-30
F-03	Incorrect torque	Deck 55, frame 96	Minor	Re-torque to drawing value.	2025-12-30
F-04	Missing fastener	Deck 36, frame 193	Minor	Install fastener per drawing and record torque.	2025-12-26
F-05	Weld porosity	Deck 68, frame 134	Minor	Grind out and re-weld; repeat inspection.	2026-01-22
F-06	Weld porosity	Deck 25, frame 299	Minor	Grind out and re-weld; repeat inspection.	2026-01-22

Assessment

1 critical findings; non-conformance reports raised.