Test IC 76 / repaired: independent self-fed trajectories; failed lines end early