Test IC 39 / repaired: independent self-fed trajectories; failed lines end early