Stress vs Strain of Specimen 50A3 20 Strain-Stress Curve Min. Stress Point Stress Min.: -123.17 MPa Strain at Min.: 0.0000 Compressive Stress [MPa] -120 -140 -0.1 -0.2 -0.3 -0.4 -0.5 -0.6 -0.7 0.1 Strain Mean over Region of Interest [-]