Stress vs Strain of Specimen 50A1 50 Strain-Stress Curve Min. Stress Point Stress Min.: -241.54 [MPa] Strain at Min.: -0.0522 Compressive Stress [MPa] -50 -100 150 -200 -250 -0.01 -0.02 -0.03 -0.04 -0.05 -0.06 0.01 Strain Mean over Region of Interest [-]