Stress vs Strain of Specimen 60A1 20 Strain-Stress Curve Min. Stress Point Stress Min.: -110.50 MPa 0 Strain at Min.: -0.0730 Compressive Stress [MPa] -20 -40 -60 -80 -100 -120 -0.01 -0.02 -0.04 -0.05 -0.06 -0.07 -0.08 -0.03 Strain Mean over Region of Interest [-]