Stress vs Strain of Specimen 25A1 Strain-Stress Curve Min. Stress Point -20 Stress Min.: -197.95 MPa Strain at Min.: -0.2037 -40 Compressive Stress [MPa] -160 -180 -200 -0.05 -0.1 -0.15 -0.2 -0.25 Strain Mean over Region of Interest [-]