Stress vs Strain of Specimen 25A4 20 Strain-Stress Curve Min. Stress Point Stress Min.: -105.95 MPa 0 Strain at Min.: -0.0311 Compressive Stress [MPa] -20 -40 -60 -80 -100 -120 0.005 -0.01 -0.015 -0.02 -0.03 -0.035 -0.005 -0.025 Strain Mean over Region of Interest [-]