Stress vs Strain of Specimen 45A1 20 Strain-Stress Curve Min. Stress Point Stress Min.: -132.99 MPa Strain at Min.: -0.1977 Compressive Stress [MPa] -120 -140 -0.02 -0.04 -0.06 -0.08 -0.1 -0.12 -0.14 -0.16 -0.18 Strain Mean over Region of Interest [-]