Stress vs Strain of Specimen 0A13 200 Strain-Stress Curve Min. Stress Point Stress Min.: -1049.77 MPa 0 Strain at Min.: -3.1683 Compressive Stress [MPa] -200 -400 -600 -800 -1000 -1200 -0.5 -1.5 -2 -3.5 -2.5 0.5 Strain Mean over Region of Interest [-]