Stress vs Strain of Specimen 10A3 50 Strain-Stress Curve Min. Stress Point Stress Min.: -199.78 MPa Strain at Min.: -0.0585 0 Compressive Stress [MPa] -50 -100 -150 -200 -0.06 0.01 -0.01 -0.02 -0.03 -0.04 -0.05 Strain Mean over Region of Interest [-]