Stress vs Strain of Specimen 25A3 50 Strain-Stress Curve Min. Stress Point Stress Min.: -199.56 [MPa] Strain at Min.: -0.0456 0Compressive Stress [MPa] -50 100 -150 -200 -0.015 -0.02 -0.025 -0.03 -0.035 -0.04 -0.005 -0.01 -0.045 Strain Mean over Region of Interest [-]