Stress vs Strain of Specimen 35A1 20 Strain-Stress Curve Min. Stress Point 0 Stress Min.: -165.75 [MPa] Strain at Min.: -0.1648 -20 Compressive Stress [MPa] -40 -60 -80 -100 -120 -140 -160 -180 -0.02 -0.06 -0.08 -0.1 -0.12 -0.14 -0.16 -0.18 -0.04 Strain Mean over Region of Interest [-]