Stress vs Strain of Specimen 35A3 20 Strain-Stress Curve Min. Stress Point 0 Stress Min.: -172.07 MPa Strain at Min.: -0.0902 -20 Compressive Stress [MPa] -40 -60 -80 -100 120 -140 -160 -180 -0.01 -0.03 -0.04 -0.05 -0.02 -0.06 -0.07 -0.08 -0.09 -0.1 Strain Mean over Region of Interest [-]