Stress vs Strain of Specimen 50A2 20 Strain-Stress Curve Min. Stress Point 0 Stress Min.: -120.61 [MPa] Strain at Min.: -0.0341 Compressive Stress [MPa] -120 -140 0.005 -0.01 -0.015 -0.02 -0.03 -0.035 -0.005 -0.025 Strain Mean over Region of Interest [-]