Stress vs Strain of Specimen 30A1 20 Strain-Stress Curve Min. Stress Point 0 Stress Min.: -178.62 MPa Strain at Min.: -0.1442 -20 Compressive Stress [MPa] -40 -60 -80 -100 -120 -140 -160 -180 0 -0.04 -0.06 -0.08 -0.1 -0.12 -0.14 -0.16 0.02 -0.02 Strain Mean over Region of Interest [-]