Stress vs Strain of Specimen 40A2 Strain-Stress Curve Min. Stress Point -20 Stress Min.: -198.59 MPa Strain at Min.: -0.0264 -40 Compressive Stress [MPa] -160 -180 -200 0.005 -0.01 -0.015 -0.02 -0.025 -0.03 -0.005 Strain Mean over Region of Interest [-]