Stress vs Strain of Specimen 20A3 50 Strain-Stress Curve Min. Stress Point Stress Min.: -234.53 [MPa] Strain at Min.: -0.0282 Compressive Stress [MPa] -50 -100 150 -200 -250 -0.03 0.005 -0.005 -0.01 -0.015 -0.02 -0.025 Strain Mean over Region of Interest [-]