Stress vs Strain of Specimen 30A3 Strain-Stress Curve Min. Stress Point -20 Stress Min.: -188.10 [MPa] Strain at Min.: -0.0557 -40 Compressive Stress [MPa] -160 -180 -200 -0.01 -0.02 -0.03 -0.04 -0.06 0.01 -0.05 Strain Mean over Region of Interest [-]