
Pre-Power Supply
P1
C13_Plug
L
PE
N
SW1
Standby On/Off
SW2
SW_Rotary_3x3
SW3
SW_DIP_x03
J1
ATX-24
PS_ON#
PWR_OK
+12V
+5V
+5VSB
+3.3V
GND
-12V
SW5
SW_SPST_LED
Shunt
R1
Sense
Meter_Power_5V
Meter_Power_Ground
PSU+
PSU-
U1
Buck Boost1
in+
in-
out+
out-
F1
Fuse
F2
Fuse
F3
Fuse
J2
3.3V
J3
3.3V GND
J4
5V
J5
5V Ground
J6
12V
J7
12V GND
J8
+Var
J9
-Var
R3
220Ohms
Standby
LED Blue
R2
220Ohms
Stable
LED Green