MAHARASHTRA POLLUTION CONTROL BOARD

Tel: 24010437/24020781/24014701

Fax: 24024068 / 24023516 Website: http://mpcb.gov.in E-mail: ms@mpcb.gov.in

No. MPCB/MS/PSO/B- 4149



Kalpataru Point, 2nd - 4th Floor Opp. Cine Planet Cinema, Near Sion Circle, Sion (E) Mumbai-400 022.

Date: 0 6.11.2018.

To, M/s. Praniti Stone Metal., Gut.No-337, A/p- Khandala, Tal & Dist. Ahmednagar.

<u>Sub</u>: Conditional Restart Directions under section 33A of the Water (Prevention & Control of Pollution) Act, 1974 and under section 31A of the Air (Prevention & Control Pollution) Act, 1981.

Ref: 1. Closure Direction vide No.MPCB/PSO/Nashik/CD/B-3982, dtd.10-10.2016.

2. Request letter received from the industry on dated 14/06/2018.

3. Verification carried by Board Officials by visit to industry dtd. 08/08/2018.

4. MS, MPCB approval dated 05/11/2018 in Office Note no. 180904-FTS-0032

This refers to Closure Directions issued by the Board vide above reference cited at 1 to the industry for non- compliances observed by the Board Officials during their visit to the industry

Considering the reply submitted by the industry to the Board office vide above referred letter 2, and approval given by Hon'ble Member Secretary on Office vide above reference cited at 4, Closure Directions issued by the Board is hereby withdrawn subject to the compliance of following terms and conditions:

- The industry shall not restart the production activity till to obtain valid consent to operate from Maharashtra Pollution Control Board. In no case the industry shall be operated without valid consent to operate of the Board.
- The industry shall provide proper enclosure to the all sources of dust emissions such as crushing section, conveyer belts, screening section, fine dust collection unit etc. so as not to cause any Air Pollution Problem in the nearby surrounding area.
- 3. The industry shall provide water spraying / sprinkling arrangement at all sources of dust emissions such as crushing section, conveyer belts, screening section, fine dust collection unit etc. so as not to cause any Air Pollution Problem in the nearby surrounding area.
- 4. The industry shall ensure regular and continuous cleaning and wetting facility in the premises.
- 5. The industry shall construct metallic road for movement of vehicles within the factory premises.

- 6. The industry shall carriy out thick plantation along the Periphery of the unit so as to avoid any sort Air Pollution problem in the nearby surrounding area.
- 7. The industry shall comply with all provisions of various environmental enactments and achieve the standards of air quality as per Environment (Protection) Act 1986.
- 8. Industry shall submit the fresh Bank Guarantee Rs. 50,000 /- towards for providing Air Pollution Control system and operation & maintenance of APC system valid for consented period.
- 9. In case of non-confirming to emissions and effluent discharge standards due to failure of operation of pollution control devices and above conditions 1 to 8 the industry shall voluntarily suspend / stop the related manufacturing activity forthwith and report to the Board office, immediately.

These directions are issued under the powers conferred upon me by the Board under section 33 A of Water (Prevention and control of Pollution) Act, 1974. These directions shall be followed scrupulously in case of non-compliance the Board is constrained to take stringent legal action including forfeiting of bank guarantee and closure of unit, which may please be noted.

This is issued with approval of Member Secretary of the Board.

Principal Scientific Officer

Copy submitted for information to:

Member Secretary, MPCB, Mumbai- 400022

Copy to:

- Regional Officer, M.P.C. Board, Nashik You are directed to obtain fresh Bank Guarantee Rs. 50,000 /- towards for providing Air Pollution Control system and operation & maintenance of APC system valid for consented period.
- Sub-Regional Officer, MPCB Ahmednagar He is directed to carryout strict monitoring of the said unit at specified interval after resuming manufacturing activities and shall submit non compliances if any observed to this office forthwith for necessary further action to Regional Officer, Nashik with copy to Principal Scientific Officer, MPCB, Sion Mumbai.
- The Executive Engineer, MSEDCL, Ahmednagar- He is requested to restore the power supply of the said unit, immediately.