

OFFICE OF THE MANAGING DIRECTOR – Technical wing MANIPUR STATE POWER DISTRIBUTION COMPANY LIMITED

(3rd Floor, Secured Building, Near Hotel Imphal, North AOC, Imphal East, Manipur - 795001)

No. 1/12/2015/PMU-III(R&E Project)/MSPDCL/ 44/0 - 15

Imphal, September 23, 2016

OFFICE ORDER

Ref: No. 1/12/2015/PMU-III(R&E Project)/MSPDCL/4146-52 dated September 09, 2016

As instructed before AM(Project)/AM(O&M)/Manager(P&C) who have been allocated for inspection under R&E Project should verify the report submitted by the firm and submit to the Corporate Office, PMU-III wing on a bi weekly basis (on Saturday). This should be strictly followed. The empaneled firms should be advised to submit their report on time.

- 2) Concerned AM(Project)/AM(O&M)/Manager(P&C) should visit all the work site regularly and take photographs of good and bad quality work and send it to Corporate Office, PMU-III weekly. Necessary support in term of vehicle allowance of Rs. 3000 per month will be provided from Corporate Office.
- 3) The photographs should be categories on all aspects of erection (Pole straightness, Pole depth, Pole painting, Pole muffing, Conductor stringing, X-arm height on the pole) with Good/Bad remarks.
- 4) All these is to control the quality of work executed by the firms. In recent visit by the undersigned at some work site, the quality of work was below par. This kind of sub-standard work will not be tolerated in MSPDCL. Subsequent to the inspection, the firm was removed from the empaneled list (copy enclosed).
- 5) Concerned AM(Project)/AM(O&M)/Manager(P&C) will be held responsible if sub-standard work at the work-site if not reported and have communicated with the concerned firm to rectify the work. It will be taken as a negligence on part of the concerned AM(Project)/AM(O&M)/Manager(P&C).
- 6) The execution of the work should be done in consultation with the Sub Division Officials and any issues should be solved by them. AM(Project)/AM(O&M)/Manager(P&C) are for monitoring and inspection of the execution of the work.

(R. Sudhan, IAS) Managing Director, MSPDCL

Copy to:-

- 1. The Executive Director (Technical), MSPDCL for information.
- 2. The General Manager EC-I, EC-II and EC-III, MSPDCL for information.
- 3. The Deputy General Manager, 14 Revenue Division of MSPDCL for information.
- 4. All concerned Managers of MSPDCL for information.
- 5. All concerned Assistant Managers (Project) and (O&M) of MSPDCL for information.
- 6. PMU- III State Projects, MSPDCL



MANIPUR STATE POWER DISTRIBUTION COMPANY LIMITED

(Regd. Office: Electricity Complex, Patta No. 1293 under 87(2), Khwai Bazar, Keishampat, District – Imphal West, Manipur – 795001)

No. 2/44/(NON-P)/IED-III/2015-MSPDCL-TECH 1490-04

Imphal, the ²³Sept, 2015

MEMORANDUM

Imphal, the 3Sept. 2014

Whereas, the MSPDCL is taking up the replacement of AAC wire of LT line by AB Cable in the places not covered by the project R-APDRP Part-B, DDUGJY etc.

And Whereas, under the aforesaid scope of work consists of dismantling of existing LT line, dismantling of unserviceable Pole including cross arms, erection of Single Pole including muffing of poles, Stringing of AB Cable including installation of Insulation Piercing Connector etc.

And Whereas, the MSPDCL issued work orders for execution of LT works for the distribution Transformers of Langthabal Lamabam Leirak 250 KVA under Singjamei Sub-Divn of Imphal Electrical Division No.-III on pilot project vide order No. 2/44/(NON-P)/IED-III/2015-MSPDCL-TECH/2847-53 dated 13/2/16 to M/S Thangtech Global Infra Pvt. Ltd, Uripok Yambem Leikai, Imphal.

And Whereas, as per complaint of locality, the Utility inspected the site and found the following:-

- 1) Half painted Poles
- 2) Broken Pole muffing structures
- 3) Heavily sagging AB Cable
- 4) AB cables are lying all on road and even across the road in certain places upon which Vehicles were seen plying above the AB cable.

All these show lack of seriousness of the project executing Firm, The casual attitude of the Firm, if left un-noticed, shall result to deterioration of work quality in MSPDCL.

And Whereas, as per order clause No. 18.1 "Termination of Contract" provides the rights of the MSPDCL to cancel the work

Therefore, MSPDCL hereby cancelethe Firm M/S Thangtech Global Infra Pvt. Ltd, Uripok Yambem Leikai, Imphal from the Empanelled List of Firms of MSPDCL.

(R. Sudhan, IAS)
Managing Director
MSPDCL

Copy to:-

- 1. The Commissioner (Power), Government of Manipur for kind information
- 2. The Executive Director(Tech), MSPDCL, for kind information.
- 3. M/S Thangtech Global Infra Pvt. Ltd, Uripok Yambem Leikai, Imphal.
- 4. All the Empanelled Firms of MSPDCL
- 5. PMU III