(DH)(30),(RA)(31), RVR350

CAT A,B,C,D

Note: • Missed approach climb gradient.

Changes: Missed approach procedure