All 36 full-horizon physics controls; eight configuration-only probes are separate
PASS/FAIL: predeclared validation; 0/1: each judge classification, not learner performance

	baseline	double position iterations	double velocity iterations	half physics step
panda / nominal	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1
panda / toss	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0
panda / release	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0
panda / oscillate	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0
robotiq / nominal	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1
robotiq / toss	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0
robotiq / release	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0
robotiq / oscillate	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0	PASS C50/C200/N50: 0/0/0
robotiq / development disagreement	PASS C50/C200/N50: 1/1/0	PASS C50/C200/N50: 1/1/0	PASS C50/C200/N50: 1/1/1	PASS C50/C200/N50: 1/1/1