

ClearLane Bus Reliability Audit

Route: M15
Borough: Manhattan
Period: weekday_am
Generated: 2026-06-25T00:57:08.036Z

Executive Summary

ClearLane identified 3 priority bottleneck(s). Findings require human review before operational, enforcement, or policy action.

ClearLane is a decision-support tool. Findings are based on available data and optional visual evidence. They require human review before operational, enforcement, or policy action.

Key Metrics

Segments analyzed: 50
Priority bottlenecks: 3
Lowest observed avg speed: 2.1 mph
Relevant 311 complaints nearby: 92509
Vision evidence findings: 0

Live and Street Context

MTA Bus Time: available (13 vehicle records)
Bus lane context records: 50

Top Bottlenecks

1. PIKE ST/MADISON ST to PIKE ST/SOUTH ST - 2.1 mph, critical
2. PIKE ST/SOUTH ST to PIKE ST/MADISON ST - 2.4 mph, critical
3. PIKE ST/MADISON ST to PIKE ST/SOUTH ST - 2.5 mph, critical

Recommendations

1. Field-verify PIKE ST/MADISON ST to PIKE ST/SOUTH ST during weekday AM peak.
Reason: The top segment combines low historical speed with nearby curb and traffic complaint signals.
2. Review bus-lane and camera enforcement eligibility for the priority segment.
Reason: Bus-lane context overlaps with at least one slow segment and optional evidence suggests possible blockage.
3. Evaluate nearby loading-zone or curb-management changes to reduce recurring curb conflicts.
Reason: Relevant 311 complaints and optional visual evidence are consistent with curbside activity affecting bus movement.
4. Re-run ClearLane after any intervention to compare before/after segment speeds.
Reason: A repeatable audit ledger and metrics artifact can support transparent intervention review.

Audit Appendix

Ledger: demo-output/live-enforcement/audit-log.ndjson
Final ledger hash: 9c1ab00818acffecf423eceb5f5203d37affb47597b7b59668625b1270cc0d02