

Oakter - MTD Report - 1st Jan 2026 to 20th Jan 2026

Phase	Total	Pass	Fail
SCRAP_PCB	19	0	19
PCB_REJECTION	40	37	3
VOLTAGE_PCB	3412	3412	0
PERIPHERIAL	3546	3546	0
PCB_MAPPING	3751	3751	0
AGEING	2969	2962	7
NIC_MAPPING	2576	2573	3
PACKGING	2611	2611	0
MASTER_CARTON	2955	2955	0

VOLTAGE_PCB

Total Pass	Total Fail
3412	0

No failed items recorded for this phase.

PCB_MAPPING

Total Pass	Total Fail
3751	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
2962	7

Identifier	Failure Reason
MZ2022569	,Drift: [34.18s], Allowed: [7.53s], Read Time: [1/17/2026 10:31:48 PM], Meter Time: [1/17/2026 10:32:23 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022610	,Drift: [35.25s], Allowed: [7.37s], Read Time: [1/17/2026 10:23:53 PM], Meter Time: [1/17/2026 10:24:29 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022634	,Drift: [32.16s], Allowed: [7.37s], Read Time: [1/17/2026 11:02:56 PM], Meter Time: [1/17/2026 11:03:29 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022799	,Drift: [12.40s], Allowed: [4.31s], Read Time: [1/17/2026 9:58:24 PM], Meter Time: [1/17/2026 9:58:37 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022817	,Drift: [7.01s], Allowed: [5.32s], Read Time: [1/20/2026 11:50:40 AM], Meter Time: [1/20/2026 11:50:33 AM], RCR2 Reg: [73]

Identifier	Failure Reason
MZ2022827	,Drift: [43.05s], Allowed: [9.19s], Read Time: [1/20/2026 12:11:53 PM], Meter Time: [1/20/2026 12:12:37 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022930	,Drift: [77.47s], Allowed: [6.73s], Read Time: [1/20/2026 1:25:33 PM], Meter Time: [1/20/2026 1:24:16 PM], RCR2 Reg: [73]

NIC_MAPPING

Total Pass	Total Fail
2573	3

Identifier	Failure Reason
MZ2022930	;Drift: [77.47s], Allowed: [6.73s], Read Time: [1/20/2026 1:25:33 PM], Meter Time: [1/20/2026 1:24:16 PM], RCR2 Reg: [73]

Identifier	Failure Reason
MZ2022827	;Drift: [43.05s], Allowed: [9.19s], Read Time: [1/20/2026 12:11:53 PM], Meter Time: [1/20/2026 12:12:37 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022817	;Drift: [7.01s], Allowed: [5.32s], Read Time: [1/20/2026 11:50:40 AM], Meter Time: [1/20/2026 11:50:33 AM], RCR2 Reg: [73]

PERIPHERIAL

Total Pass	Total Fail
3546	0

No failed items recorded for this phase.

PACKGING

Total Pass	Total Fail
2611	0

No failed items recorded for this phase.

MASTER_CARTON


Total Pass	Total Fail
2955	0

No failed items recorded for this phase.


SCRAP_PCB

Total Pass	Total Fail
0	19

Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/14382	Scrap Rejection [W4 SMT TRACK DAMAGE]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15587	Scrap Rejection [Track damage]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15706	Scrap Rejection [RELAY TRACK NG]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/001311	Scrap Rejection [R123 SMT TRACK DAMAGE]



Identifier	Failure Reason
357/W/AE0176/V8-21/1P4G/0825/17187	Scrap Rejection [R61 SMT TRACK DAMAGE]




Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/20755	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24139	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24432	Scrap Rejection [R1 Smt TRACK DAMAGE]



Identifier	Failure Reason
359/W/AE0245/V8-21/1P4G/1025/26923	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30163	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30385	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30450	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30773	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31097	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31111	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31291	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35835	Scrap Rejection [Scrap PCB from visual rejection]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37296	Scrap Rejection [C1 Track Damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37302	Scrap Rejection [Track damage]



PCB_REJECTION

Total Pass	Total Fail
37	3

Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/10246	High PPM Rejection [Fail]



Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/20429	High PPM Rejection [Fail]



Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/22698	High PPM Rejection [Fail]

