

Oakter - MTD Report - 1st Jan 2026 to 25th Jan 2026

Phase	Total	Pass	Fail
SCRAP_PCB	20	0	20
TRC_REJECTION	20	20	0
PCB_REJECTION	39	39	0
VOLTAGE_PCB	3508	3508	0
PERIPHERAL	3550	3550	0
PCB_MAPPING	3766	3766	0
AGEING	3483	3463	20
NIC_MAPPING	2571	2571	0
PACKGING	2611	2611	0
MASTER_CARTON	2955	2955	0

VOLTAGE_PCB

Total Pass	Total Fail
3508	0

No failed items recorded for this phase.

PCB_MAPPING

Total Pass	Total Fail
3766	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
3463	20

Identifier	Failure Reason
MZ2022744	,Drift: [71.11s], Allowed: [14.35s], Read Time: [1/24/2026 3:30:18 PM], Meter Time: [1/24/2026 3:31:30 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022799	,Drift: [12.40s], Allowed: [4.31s], Read Time: [1/17/2026 9:58:24 PM], Meter Time: [1/17/2026 9:58:37 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2022817	,Drift: [7.01s], Allowed: [5.32s], Read Time: [1/20/2026 11:50:40 AM], Meter Time: [1/20/2026 11:50:33 AM], RCR2 Reg: [73]
Identifier	Failure Reason
MZ2022827	,Drift: [43.05s], Allowed: [9.19s], Read Time: [1/20/2026 12:11:53 PM], Meter Time: [1/20/2026 12:12:37 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2022930	,Drift: [77.47s], Allowed: [6.73s], Read Time: [1/20/2026 1:25:33 PM], Meter Time: [1/20/2026 1:24:16 PM], RCR2 Reg: [73]
Identifier	Failure Reason
MZ2023042	,Drift: [45.34s], Allowed: [9.51s], Read Time: [1/21/2026 3:18:05 PM], Meter Time: [1/21/2026 3:18:51 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023043	,Drift: [41.68s], Allowed: [9.48s], Read Time: [1/21/2026 2:39:55 PM], Meter Time: [1/21/2026 2:40:37 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023047	,Drift: [21.74s], Allowed: [5.24s], Read Time: [1/21/2026 2:18:49 PM], Meter Time: [1/21/2026 2:19:11 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023105	,Drift: [43.29s], Allowed: [9.26s], Read Time: [1/21/2026 1:18:00 PM], Meter Time: [1/21/2026 1:18:44 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023152	,Drift: [58.95s], Allowed: [11.54s], Read Time: [1/23/2026 12:45:44 PM], Meter Time: [1/23/2026 12:46:43 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023186	,Drift: [53.47s], Allowed: [11.55s], Read Time: [1/23/2026 12:36:25 PM], Meter Time: [1/23/2026 12:37:19 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023188	,Drift: [49.36s], Allowed: [10.85s], Read Time: [1/23/2026 2:19:24 PM], Meter Time: [1/23/2026 2:20:14 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023246	,Drift: [51.12s], Allowed: [10.66s], Read Time: [1/23/2026 12:55:32 PM], Meter Time: [1/23/2026 12:56:24 PM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023300	,Drift: [51.91s], Allowed: [10.51s], Read Time: [1/23/2026 11:51:08 AM], Meter Time: [1/23/2026 11:52:00 AM], RCR2 Reg: [121]
Identifier	Failure Reason
MZ2023389	,Drift: [41.15s], Allowed: [8.20s], Read Time: [1/21/2026 5:14:14 PM], Meter Time: [1/21/2026 5:14:56 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2023430	,Drift: [48.44s], Allowed: [10.27s], Read Time: [1/23/2026 11:33:22 AM], Meter Time: [1/23/2026 11:34:11 AM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2023463	,Drift: [50.81s], Allowed: [10.57s], Read Time: [1/23/2026 6:51:20 PM], Meter Time: [1/23/2026 6:52:11 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2023486	,Drift: [49.05s], Allowed: [10.52s], Read Time: [1/23/2026 6:58:49 PM], Meter Time: [1/23/2026 6:59:39 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2023525	,Drift: [51.66s], Allowed: [9.86s], Read Time: [1/23/2026 7:03:50 PM], Meter Time: [1/23/2026 7:04:42 PM], RCR2 Reg: [121]

Identifier	Failure Reason
MZ2023530	,Drift: [52.46s], Allowed: [9.84s], Read Time: [1/23/2026 7:09:06 PM], Meter Time: [1/23/2026 7:09:59 PM], RCR2 Reg: [121]

NIC_MAPPING

Total Pass	Total Fail
2571	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
3550	0

No failed items recorded for this phase.

PACKGING

Total Pass	Total Fail
2611	0

No failed items recorded for this phase.

MASTER_CARTON


Total Pass	Total Fail
2955	0

No failed items recorded for this phase.


SCRAP_PCB

Total Pass	Total Fail
0	20

Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/14382	Scrap Rejection [W4 SMT TRACK DAMAGE]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15587	Scrap Rejection [Track damage]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15706	Scrap Rejection [RELAY TRACK NG]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/001311	Scrap Rejection [R123 SMT TRACK DAMAGE]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/10246	Scrap Rejection [Handling issue]




Identifier	Failure Reason
357/W/AE0176/V8-21/1P4G/0825/17187	Scrap Rejection [R61 SMT TRACK DAMAGE]




Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/20755	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24139	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24432	Scrap Rejection [R1 Smt TRACK DAMAGE]



Identifier	Failure Reason
359/W/AE0245/V8-21/1P4G/1025/26923	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30163	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30385	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30450	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30773	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31097	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31111	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31291	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35835	Scrap Rejection [Scrap PCB from visual rejection]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37296	Scrap Rejection [C1 Track Damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37302	Scrap Rejection [Track damage]



PCB_REJECTION

Total Pass	Total Fail
39	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
20	0

No failed items recorded for this phase.