

# Oakter - MTD Report - 1st Jan 2026 to 31st Jan 2026

Phase	Total	Pass	Fail
SCRAP_PCB	20	0	20
TRC_REJECTION	40	40	0
PCB_REJECTION	39	39	0
VOLTAGE_PCB	3506	3506	0
PERIPHERAL	3524	3524	0
PCB_MAPPING	3509	3509	0
AGEING	3966	3965	1
NIC_MAPPING	2673	2673	0
PACKGING	2701	2701	0
MASTER_CARTON	3045	3045	0

## VOLTAGE\_PCB

Total Pass	Total Fail
3506	0

No failed items recorded for this phase.

## PCB\_MAPPING

Total Pass	Total Fail
3765	0

No failed items recorded for this phase.

## AGEING

Total Pass	Total Fail
3965	1

Identifier	Failure Reason
MZ2022799	,Drift: [12.40s], Allowed: [4.31s], Read Time: [1/17/2026 9:58:24 PM], Meter Time: [1/17/2026 9:58:37 PM], RCR2 Reg: [121]

## NIC\_MAPPING

Total Pass	Total Fail
2673	0

No failed items recorded for this phase.

## PERIPHERIAL

Total Pass	Total Fail
3524	0

No failed items recorded for this phase.

## PACKGING

Total Pass	Total Fail
2701	0

No failed items recorded for this phase.

## MASTER\_CARTON


Total Pass	Total Fail
3045	0

No failed items recorded for this phase.


## SCRAP\_PCB

Total Pass	Total Fail
0	20

Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/14382	Scrap Rejection [W4 SMT TRACK DAMAGE]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15587	Scrap Rejection [Track damage]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15706	Scrap Rejection [RELAY TRACK NG]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/001311	Scrap Rejection [R123 SMT TRACK DAMAGE]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/10246	Scrap Rejection [Handling issue]



Identifier	Failure Reason
357/W/AE0176/V8-21/1P4G/0825/17187	Scrap Rejection [R61 SMT TRACK DAMAGE]




Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/20755	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24139	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24432	Scrap Rejection [R1 Smt TRACK DAMAGE]



Identifier	Failure Reason
359/W/AE0245/V8-21/1P4G/1025/26923	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30163	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30385	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30450	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30773	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31097	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31111	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31291	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35835	Scrap Rejection [Scrap PCB from visual rejection]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37296	Scrap Rejection [C1 Track Damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37302	Scrap Rejection [Track damage]



## PCB\_REJECTION

Total Pass	Total Fail
39	0

No failed items recorded for this phase.

## TRC\_REJECTION

Total Pass	Total Fail
40	0

No failed items recorded for this phase.