

# Oakter - MTD Report - MTD: 1st Jan 2026 to 14thJan

| Phase         | Total | Pass | Fail |
|---------------|-------|------|------|
| PCB_REJECTION | 14    | 6    | 8    |
| VOLTAGE_PCB   | 3102  | 3093 | 9    |
| PERIPHERIAL   | 3089  | 3088 | 1    |
| PCB_MAPPING   | 3231  | 3231 | 0    |
| AGEING        | 2151  | 2079 | 72   |
| NIC_MAPPING   | 2004  | 1999 | 5    |
| PACKGING      | 1976  | 1976 | 0    |
| MASTER_CARTON | 2320  | 2320 | 0    |

## VOLTAGE\_PCB

| Total Pass | Total Fail |
|------------|------------|
| 3093       | 9          |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0199/V8-21/1P4G/0925/23632 | TP10(3.0)      |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0304/V8-21/1P4G/1225/36225 | TP4(0.0)       |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0304/V8-21/1P4G/1225/35571 | TP10(3.1)      |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0304/V8-21/1P4G/1225/36143 | TP10(3.0)      |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0304/V8-21/1P4G/1225/37302 | TP10(0.0)      |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0245/V8-21/1P4G/1025/26923 | TP9(3.1)       |

| Identifier                         | Failure Reason    |
|------------------------------------|-------------------|
| 359/W/AE0304/V8-21/1P4G/1225/31111 | TP8(0.1),TP9(1.2) |

| Identifier                         | Failure Reason |
|------------------------------------|----------------|
| 359/W/AE0193/V8-21/1P4G/0825/20755 | TP10(3.1)      |

| Identifier                         | Failure Reason               |
|------------------------------------|------------------------------|
| 340/W/AE0136/V8-18/1P4G/0725/15587 | TP11(0.1),TP7(0.0),TP10(0.1) |

## PCB\_MAPPING

| Total Pass | Total Fail |
|------------|------------|
| 3231       | 0          |

No failed items recorded for this phase.

## AGEING

| Total Pass | Total Fail |
|------------|------------|
| 2079       | 72         |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021227  | Energy Range Cumm KVAh Fail Found 14915.2073364258 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022031  | Energy Range Cumm KVAh Fail Found 66407.5134277344 (-26.3050179130219%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021689  | Energy Range Cumm KVAh Fail Found 14495.2275390625 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022179  | Energy Range Cumm KVAh Fail Found 61265.2586669922 (-20.2696267980365%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022027  | Energy Range Cumm KVAh Fail Found 67250.1000976563 (-25.3699669475285%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022158  | Energy Range Cumm KVAh Fail Found 61442.9533691406 (-20.0383755925969%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022001  | Energy Range Cumm KVAh Fail Found 67331.0229492188 (-25.2801637341796%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2020893  | Energy Range Cumm KVAh Fail Found 4099.66760253906 Expected between Start Meter 6183.11007553339 and End Meter 6072.85791015625 Energy Range Cumm KVAh Fail Found 4099.66760253906 (-33.7062679459467%) Expected between Previous Meter 6184.09535187483 and Range 5565.68581668735 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2020857  | Energy Range Cumm KVAh Fail Found 15120.0219726563 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022047  | Energy Range Cumm KVAh Fail Found 62393.6186523438 (-18.8011834306911%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022180  | Energy Range Cumm KVAh Fail Found 69177.5003662109 (-23.2310564397568%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022015  | Energy Range Cumm KVAh Fail Found 71780.1459960938 (-20.3428000788002%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022008  | Energy Range Cumm KVAh Fail Found 65856.23046875 (-26.9167979013123%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022200  | Energy Range Cumm KVAh Fail Found 67919.0290222168 (-24.6276306881443%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2020008  | Energy Range Cumm KVAh Fail Found 131419.651123047 (72.6350307630721%) Expected between Previous Meter 76125.714776516 and Range 76886.9719242811 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021177  | Energy Range Cumm KVAh Fail Found 56667.5729980469 (-10.9196034749457%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022186  | Energy Range Cumm KVAh Fail Found 61308.7204589844 (-20.2130657882414%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022181  | Energy Range Cumm KVAh Fail Found 68201.6036987305 (-24.3140466575275%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |
| Identifier | Failure Reason  |
| MZ2021689  | Energy Range Cumm KVAh Fail Found 5866.80981445313 Expected between Start Meter 6183.11007553339 and End Meter 6072.85791015625                     |
| Identifier | Failure Reason  |
| MZ2022177  | Energy Range Cumm KVAh Fail Found 68844.292175293 (-23.6008304366052%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507  |
| Identifier | Failure Reason  |
| MZ2022002  | Energy Range Cumm KVAh Fail Found 66089.927734375 (-26.6574550210409%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507  |
| Identifier | Failure Reason  |
| MZ2022011  | Energy Range Cumm KVAh Fail Found 65736.6728515625 (-27.0494756060208%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |
| Identifier | Failure Reason  |
| MZ2021180  | Energy Range Cumm KVAh Fail Found 57203.3303222656 (-10.077402682541%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812  |
| Identifier | Failure Reason  |
| MZ2022197  | Energy Range Cumm KVAh Fail Found 68956.047668457 (-23.4768110502174%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507  |
| Identifier | Failure Reason  |
| MZ2022038  | Energy Range Cumm KVAh Fail Found 61957.4282226563 (-19.368839986834%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007  |
| Identifier | Failure Reason  |
| MZ2022023  | Energy Range Cumm KVAh Fail Found 61684.8676757813 (-19.7235492396031%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |
| Identifier | Failure Reason  |
| MZ2022016  | Energy Range Cumm KVAh Fail Found 72276.6845703125 (-19.7917720483294%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022032  | Energy Range Cumm KVAh Fail Found 62094.6430664063 (-19.1902691142209%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2021346  | Energy Range Cumm KVAh Fail Found 0 Expected between Start Meter 81733.2730400562 and End Meter 63227.8372802734 Energy Range Cumm KVAh Fail Found 0 (-100%) Expected between Previous Meter 65804.6541748047 and Range 59224.1887573242 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022195  | Energy Range Cumm KVAh Fail Found 68243.2263183594 (-24.2678564291989%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021913  | Energy Range Cumm KVAh Fail Found 4110.77807617188 Expected between Start Meter 6183.11007553339 and End Meter 6072.85791015625 Energy Range Cumm KVAh Fail Found 4110.77807617188 (-33.5266058773558%) Expected between Previous Meter 6184.09535187483 and Range 5565.68581668735 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021015  | Energy Range Cumm KVAh Fail Found 56052.4502563477 (-11.8865652635516%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022154  | Energy Range Cumm KVAh Fail Found 69106.0625 (-23.3103337985827%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022020  | Energy Range Cumm KVAh Fail Found 62150.06640625 (-19.1181413918218%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2022021  | Energy Range Cumm KVAh Fail Found 66666.4475097656 (-26.017668763023%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022157  | Energy Range Cumm KVAh Fail Found 68407.4340820313 (-24.0856287326972%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021018  | Energy Range Cumm KVAh Fail Found 56221.7708129883 (-11.6203964208184%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021227  | Energy Range Cumm KVAh Fail Found 4075.98303222656 Expected between Start Meter 6183.11007553339 and End Meter 6072.85791015625 Energy Range Cumm KVAh Fail Found 4075.98303222656 (-34.0892596199887%) Expected between Previous Meter 6184.09535187483 and Range 5565.68581668735 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021174  | Energy Range Cumm KVAh Fail Found 56867.7950439453 (-10.6048580518039%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022152  | Energy Range Cumm KVAh Fail Found 68499.0531005859 (-23.9839555697867%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2020893  | Energy Range Cumm KVAh Fail Found 14606.3813476563 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022022  | Energy Range Cumm KVAh Fail Found 64701.7368164063 (-28.1979840900044%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022165  | Energy Range Cumm KVAh Fail Found 61068.1098632813 (-20.5261954968097%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021033  | Energy Range Cumm KVAh Fail Found 56377.2355957031 (-11.3760086032848%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022025  | Energy Range Cumm KVAh Fail Found 72570.5014648438 (-19.4657120942416%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021329  | Energy Range Cumm KVAh Fail Found 15059.4365844727 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021013  | Energy Range Cumm KVAh Fail Found 55888.8377075195 (-12.1437612215748%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022168  | Energy Range Cumm KVAh Fail Found 67719.9931640625 (-24.8485084660378%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022018  | Energy Range Cumm KVAh Fail Found 71240.2934570313 (-20.9418952886986%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2021622  | Energy Range Cumm KVAh Fail Found 121650.72265625 (-10.5087550101347%) Expected between Previous Meter 135935.892578125 and Range 122342.303320312 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022187  | Energy Range Cumm KVAh Fail Found 67729.6681518555 (-24.8377717584682%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022013  | Energy Range Cumm KVAh Fail Found 64983.0275878906 (-27.8858248583788%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2022036  | Energy Range Cumm KVAh Fail Found 67589.626953125 (-24.9931808846225%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2021172  | Energy Range Cumm KVAh Fail Found 56489.9647827148 (-11.198800366763%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021157  | Energy Range Cumm KVAh Fail Found 14818.2225341797 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021035  | Energy Range Cumm KVAh Fail Found 14699.6229248047 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022172  | Energy Range Cumm KVAh Fail Found 69679.7436523438 (-22.6736976701781%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022034  | Energy Range Cumm KVAh Fail Found 65426.6157226563 (-27.3935579753382%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2022033  | Energy Range Cumm KVAh Fail Found 71545.177734375<br>(-20.6035534325184%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022040  | Energy Range Cumm KVAh Fail Found 61814.7807617188<br>(-19.5544808466675%) Expected between Previous Meter<br>76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022193  | Energy Range Cumm KVAh Fail Found 69157.2037353516<br>(-23.2535803948095%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022037  | Energy Range Cumm KVAh Fail Found 72047.9760742188<br>(-20.0455786984024%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022035  | Energy Range Cumm KVAh Fail Found 61559.8955078125<br>(-19.8861875408003%) Expected between Previous Meter<br>76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022167  | Energy Range Cumm KVAh Fail Found 69568.1108398438<br>(-22.7975809130955%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2022194  | Energy Range Cumm KVAh Fail Found 59508.961227417<br>(-22.5552655655494%) Expected between Previous Meter<br>76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason   |
|------------|--|
| MZ2022030  | Energy Range Cumm KVAh Fail Found 66761.326171875<br>(-25.9123782477834%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022024  | Energy Range Cumm KVAh Fail Found 67031.2531738281<br>(-25.6128298300374%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022028  | Energy Range Cumm KVAh Fail Found 65188.6638183594<br>(-27.6576223924437%) Expected between Previous Meter<br>90111.3095452785 and Range 81100.1785907507 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022166  | Energy Range Cumm KVAh Fail Found 61440.2326660156 (-20.0419163052332%) Expected between Previous Meter 76840.5517327785 and Range 69156.4965595007 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021178  | Energy Range Cumm KVAh Fail Found 57021.1323852539 (-10.3638145335587%) Expected between Previous Meter 63613.9658203125 and Range 57252.5692382812 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2021913  | Energy Range Cumm KVAh Fail Found 14392.6765136719 Expected between Start Meter 18190.8703470826 and End Meter 15165.8713378906 |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022041  | Energy Range Cumm KVAh Fail Found 72713.6889648438 (-19.3068113960689%) Expected between Previous Meter 90111.3095452785 and Range 81100.1785907507 |

## NIC\_MAPPING

| Total Pass | Total Fail |
|------------|------------|
| 1999       | 5          |

| Identifier | Failure Reason  |
|------------|---|
| MZ2022358  | ;Drift: [33.85s], Allowed: [7.18s], Read Time: [1/15/2026 8:10:34 PM], Meter Time: [1/15/2026 8:11:08 PM] |

| Identifier | Failure Reason   |
|------------|--|
| MZ2017137  | ;Drift: [5.29s], Allowed: [4.77s], Read Time: [9/25/2025 7:54:44 PM], Meter Time: [9/25/2025 7:54:50 PM];Drift: [178.09s], Allowed: [63.27s], Read Time: [11/13/2025 7:31:59 PM], Meter Time: [11/13/2025 7:34:58 PM];Drift: [24.03s], Allowed: [9.60s], Read Time: [12/19/2025 5:13:58 PM], Meter Time: [12/19/2025 5:14:23 PM];Drift: [37.18s], Allowed: [14.33s], Read Time: [12/23/2025 3:52:21 PM], Meter Time: [12/23/2025 3:52:59 PM];Drift: [6.13s], Allowed: [4.45s], Read Time: [1/7/2026 7:21:04 PM], Meter Time: [1/7/2026 7:21:11 PM];Drift: [8.46s], Allowed: [5.44s], Read Time: [1/12/2026 1:01:48 PM], Meter Time: [1/12/2026 1:01:57 PM] |

| Identifier | Failure Reason   |
|------------|--|
| MZ2021035  | ;Drift: [28.81s], Allowed: [6.54s], Read Time: [1/10/2026 12:28:36 AM], Meter Time: [1/10/2026 12:28:08 AM];Drift: [11.79s], Allowed: [4.21s], Read Time: [1/14/2026 10:52:05 AM], Meter Time: [1/14/2026 10:51:54 AM] |

| Identifier | Failure Reason   |
|------------|--|
| MZ2021617  | ;Drift: [49.88s], Allowed: [10.50s], Read Time: [1/15/2026 1:35:38 PM], Meter Time: [1/15/2026 1:36:28 PM] |

| Identifier | Failure Reason   |
|------------|--|
| VT0002107  | ;Drift: [390.48s], Allowed: [22.39s], Read Time: [12/27/2025 10:47:45 AM], Meter Time: [12/27/2025 10:41:15 AM];Drift: [3.72s], Allowed: [2.22s], Read Time: [12/31/2025 6:36:01 PM], Meter Time: [12/31/2025 6:35:58 PM];Drift: [39.34s], Allowed: [4.51s], Read Time: [1/2/2026 4:21:41 PM], Meter Time: [1/2/2026 4:21:02 PM] |

## PERIPHERAL

| Total Pass | Total Fail |
|------------|------------|
| 3088       | 1          |

| Identifier                         | Failure Reason                |
|------------------------------------|-------------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/31291 | GPIO: Relay Pin Check Failed. |

## PACKGING

| Total Pass | Total Fail |
|------------|------------|
| 1976       | 0          |

No failed items recorded for this phase.

## MASTER\_CARTON

| Total Pass | Total Fail |
|------------|------------|
| 2320       | 0          |

No failed items recorded for this phase.

## PCB\_REJECTION

| Total Pass | Total Fail |
|------------|------------|
| 6          | 8          |


| Identifier                         | Failure Reason           |
|------------------------------------|--------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/32966 | Visual Rejection [Fail ] |




| Identifier                         | Failure Reason                        |
|------------------------------------|---------------------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/34287 | Visual Rejection [componentd Damage ] |




| Identifier   | Failure Reason                               |
|--|--|
| 359/W/AE0304/V8-21/1P4G/1225/343453<br>59/W/AE0304/V8-21/1P4G/1225/34345 | Visual Rejection [componentd missing issue ] |



| Identifier                         | Failure Reason      |
|------------------------------------|---------------------|
| 359/W/AE0304/V8-21/1P4G/1225/35835 | Visual Rejection [] |



| Identifier                         | Failure Reason                      |
|------------------------------------|-------------------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/37296 | Visual Rejection [soldering issue ] |



| Identifier                         | Failure Reason          |
|------------------------------------|-------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/32966 | High PPM Rejection Fail |



| Identifier                         | Failure Reason          |
|------------------------------------|-------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/34304 | High PPM Rejection Fail |



| Identifier                         | Failure Reason          |
|------------------------------------|-------------------------|
| 359/W/AE0304/V8-21/1P4G/1225/36298 | High PPM Rejection Fail |

