

Oakter - Daily Report - 16th Jan 2026

Phase	Total	Pass	Fail
SCRAP_PCB	14	0	14
PCB_REJECTION	21	6	15
VOLTAGE_PCB	183	183	0
PERIPHERIAL	255	255	0
PCB_MAPPING	276	276	0
AGEING	208	208	0
NIC_MAPPING	272	272	0
PACKGING	249	249	0
MASTER_CARTON	250	250	0

VOLTAGE_PCB

Total Pass	Total Fail
183	0

No failed items recorded for this phase.

PCB_MAPPING

Total Pass	Total Fail
276	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
208	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
272	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
255	0

No failed items recorded for this phase.

PACKGING

Total Pass	Total Fail
249	0

No failed items recorded for this phase.

MASTER_CARTON


Total Pass	Total Fail
250	0

No failed items recorded for this phase.


SCRAP_PCB

Total Pass	Total Fail
0	14

Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/15587	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/20755	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0199/V8-21/1P4G/0925/24139	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0245/V8-21/1P4G/1025/26923	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30163	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30385	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30450	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/30773	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31097	Scrap Rejection [Track damage]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31111	Scrap Rejection [track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31291	Scrap Rejection [Track damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35835	Scrap Rejection [Scrap PCB from visual rejection]



Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37296	Scrap Rejection [C1 Track Damage]




Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37302	Scrap Rejection [Track damage]



PCB_REJECTION

Total Pass	Total Fail
6	15


Identifier	Failure Reason
340/W/AE0126/V8-18/1P4G/0725/12682	Visual Rejection [shoting]




Identifier	Failure Reason
340/W/AE0136/V8-18/1P4G/0725/14382	Visual Rejection [track damage]



Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/001311	Visual Rejection [shoting]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/02917	Visual Rejection [power Button Not work issue]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/03117	Visual Rejection [Betttery issue]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/03674	Visual Rejection [shoting issue]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/06925	Visual Rejection [Button issue]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/07434	Visual Rejection [components shift issue]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/09814	Visual Rejection [shift issue]




Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/10969	Visual Rejection [damage issue]




Identifier	Failure Reason
357/W/AE0176/V8-21/1P4G/0825/17187	Visual Rejection [track damage]




Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/21311	Visual Rejection [components missing]



Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/21630	Visual Rejection [components Damage]



Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/21825	Visual Rejection [components missing]



Identifier	Failure Reason
359/W/AE0245/V8.21/1P4G/1025/27518	Visual Rejection [Led Damage]

