

Oakter - Daily Report - 2nd Jun 2026

Phase	Total	Pass	Fail
SCRAP_PCB	0	0	0
TRC_REJECTION	4	4	0
PCB_REJECTION	0	0	0
VOLTAGE_PCB	20	18	2
PERIPHERIAL	61	59	2
PCB_MAPPING	82	82	0
AGEING	0	0	0
NIC_MAPPING	0	0	0
PACKGING	0	0	0
MASTER_CARTON	0	0	0

VOLTAGE_PCB

Total Pass	Total Fail
18	2

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35224	TP4(0.3),TP11(0.0),TP8(0.5),TP9(0.5)

Identifier	Failure Reason
359/W/AE0245/V8-21/1P4G/1025/25770	TP10(3.1)

PCB_MAPPING

Total Pass	Total Fail
82	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
59	2

Identifier	Failure Reason
340/W/AE84/V8-18/1P4G/0625/03527	NIC Uart: At Script Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/34689	GPIO: Impluse LED, LCD Segment, Backlight, Push Button Check Failed.

PACKGING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

MASTER_CARTON

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

SCRAP_PCB

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PCB_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
4	0

No failed items recorded for this phase.