

Oakter - Daily Report - 26th May 2026

Phase	Total	Pass	Fail
SCRAP_PCB	0	0	0
TRC_REJECTION	2	2	0
PCB_REJECTION	0	0	0
VOLTAGE_PCB	150	148	2
PERIPHERIAL	6	5	1
PCB_MAPPING	13	13	0
AGEING	0	0	0
NIC_MAPPING	0	0	0
PACKGING	0	0	0
MASTER_CARTON	0	0	0

VOLTAGE_PCB

Total Pass	Total Fail
148	2

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/34770	TP4(16.8)

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/34852	TP4(0.0),TP11(0.0),TP8(0.0),TP9(0.0)

PCB_MAPPING

Total Pass	Total Fail
13	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
5	1

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/36834	GPIO: Impluse LED, LCD Segment, Backlight, Push Button Check Failed.

PACKGING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

MASTER_CARTON

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

SCRAP_PCB

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PCB_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
2	0

No failed items recorded for this phase.