

Oakter - Daily Report - 30th May 2026

VOLTAGE_PCB

Total Pass	Total Fail
157	6

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35224	TP4(0.0),TP11(0.0),TP8(0.0),TP9(0.0)

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/34932	TP8(0.2),TP9(1.2)

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35340	TP4(0.0),TP11(0.0),TP8(0.0),TP9(0.0)

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35253	TP8(0.1),TP9(1.2)

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35397	TP4(1.8),TP11(0.0),TP8(1.6),TP9(1.4)

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35344	TP10(3.1)

PCB_MAPPING

Total Pass	Total Fail
30	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PACKGING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

MASTER_CARTON

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

SCRAP_PCB

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PCB_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
6	0

No failed items recorded for this phase.