

Oakter - Daily Report - 4th Jun 2026

Phase	Total	Pass	Fail
SCRAP_PCB	0	0	0
TRC_REJECTION	4	4	0
PCB_REJECTION	0	0	0
VOLTAGE_PCB	2	2	0
PERIPHERIAL	45	43	2
PCB_MAPPING	41	41	0
AGEING	0	0	0
NIC_MAPPING	0	0	0
PACKGING	0	0	0
MASTER_CARTON	0	0	0

VOLTAGE_PCB

Total Pass	Total Fail
2	0

No failed items recorded for this phase.

PCB_MAPPING

Total Pass	Total Fail
41	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
43	2

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35628	GPIO: Meter Cover Button Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35639	RTC: RTC Action, Date Time Check Failed.

PACKGING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

MASTER_CARTON

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

SCRAP_PCB

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PCB_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
4	0

No failed items recorded for this phase.