

Oakter - Daily Report - 25th May 2026

Phase	Total	Pass	Fail
SCRAP_PCB	0	0	0
TRC_REJECTION	0	0	0
PCB_REJECTION	0	0	0
VOLTAGE_PCB	7	6	1
PERIPHERIAL	23	20	3
PCB_MAPPING	12	12	0
AGEING	0	0	0
NIC_MAPPING	0	0	0
PACKGING	0	0	0
MASTER_CARTON	0	0	0

VOLTAGE_PCB

Total Pass	Total Fail
6	1

Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/22798	TP10(3.1)

PCB_MAPPING

Total Pass	Total Fail
12	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
20	3

Identifier	Failure Reason
359/W/AE0234/V8-21/1P4G/0925/24907	NIC Uart: At Script Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/31883	NIC Uart: At Script Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/36834	GPIO: Impluse LED, LCD Segment, Backlight, Push Button Check Failed.

PACKGING

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

MASTER_CARTON

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

SCRAP_PCB

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PCB_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.