

Oakter - Daily Report - 5th Jun 2026

Phase	Total	Pass	Fail
SCRAP_PCB	0	0	0
TRC_REJECTION	1	1	0
PCB_REJECTION	0	0	0
VOLTAGE_PCB	5	5	0
PERIPHERIAL	117	108	9
PCB_MAPPING	108	108	0
AGEING	1	1	0
NIC_MAPPING	4	4	0
PACKGING	8	8	0
MASTER_CARTON	15	15	0

VOLTAGE_PCB

Total Pass	Total Fail
5	0

No failed items recorded for this phase.

PCB_MAPPING

Total Pass	Total Fail
108	0

No failed items recorded for this phase.

AGEING

Total Pass	Total Fail
1	0

No failed items recorded for this phase.

NIC_MAPPING

Total Pass	Total Fail
4	0

No failed items recorded for this phase.

PERIPHERIAL

Total Pass	Total Fail
108	9

Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/20853	GPIO: Relay Pin Check Failed.

Identifier	Failure Reason
359/W/AE0193/V8-21/1P4G/0825/21268	GPIO: Relay Pin Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35201	RTC: RTC Action, Date Time Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35207	GPIO: Backlight, Relay Pin Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/35636	NIC Uart: At Script Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/36966	GPIO: NIC Ready Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37198	RTC: RTC Action, Date Time Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37206	GPIO: Relay Pin Check Failed.

Identifier	Failure Reason
359/W/AE0304/V8-21/1P4G/1225/37209	RTC: RTC Action, Date Time Check Failed.

PACKGING

Total Pass	Total Fail
8	0

No failed items recorded for this phase.

MASTER_CARTON

Total Pass	Total Fail
15	0

No failed items recorded for this phase.

SCRAP_PCB

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

PCB_REJECTION

Total Pass	Total Fail
0	0

No failed items recorded for this phase.

TRC_REJECTION

Total Pass	Total Fail
1	0

No failed items recorded for this phase.