


Model	Year	MG	SG	Illustration	Restrictions	UPD	14:20	25.02.2010	PORSCHE	PET	PORSCHE
9442	1988	8	02	802-15		248					



Pos	Part Number	Description	Remark	Qty	Model
		front apron and bumper			TURBO
1	951 505 071 00	lining upper part		1	
2	951 505 075 02	front apron lower part		1	
2	951 505 075 02	front apron lower part	88	1	M758
3	944 505 523 00	pipng		1	
4	N 013 967 9	tapping screw B 4,2		9	
5	951 505 157 00	spacer		7	
6	999 591 742 02	speed nut		9	
7	900 151 028 02	washer B 4,3		2	
8	951 505 347 00	stopper		2	
9	900 910 010 09	lock nut M 6		2	
10	N 011 666 7	washer B 6,4		2	
11	951 505 513 00	attachment strip	/L	1	
(11)	951 505 514 00	attachment strip	/R	1	
12	N 011 666 7	washer B 6,4		6	
13	N 010 215 13	hexagon-head bolt M 6 X 15		6	
14	951 575 361 00	air duct	/L	1	
(14)	951 575 362 00	air duct	/R	1	
15	951 575 371 00	fastening angle		2	
16	N 013 884 4	tapping screw BZ 4,8 X 13		4	
17	N 011 665 3	washer B 5,3		4	
18	N 015 458 1	speed nut 4,8 X 19		4	

Model	Year	MG	SG	Illustration	Restrictions	UPD	14:20	25.02.2010	PORSCHE PET PORSCHE		
9442	1988	8	02	802-15		248					

Pos	Part Number			Description	Remark	Qty	Model	Pos	Part Number			Description	Remark	Qty	Model
19	N	010	215 13	hexagon-head bolt M 6 X 15		4	M036/058	39	N	011	665 3	washer B 5,3		2	
20	N	011	666 7	washer B 6,4		4		40	951	575	131 00	air duct		1	
21	N	011	524 7	washer A 6,4		4		41	900	143	007 02	tapping screw B 4,2 X 13		2	
22	900	910	010 09	lock nut M 6		4		42	900	025	002 02	washer A 4,3		2	
23	951	505	373 00	spring		4		43	N	015	447 1	speed nut 4,2 X 10,3		2	
24	951	505	353 00	cap		1		44	999	049	001 40	plastic nut		2	
25	900	143	072 02	oval-head sheetmetal screw B 3,9 X 19		1		45	951	505	381 00	fastening angle		3	
26	N	011	663 1	washer B 3,7		1		46	999	190	151 30	tubular rivet 4 X 11,05		3	
27	951	505	010 01	bumper		1		47	951	505	355 00	bracket		3	
28	951	505	349 00	cap		1		48	N	015	470 2	speed nut		6	
29	951	505	017 00	impact pipe		2	M573	49	N	013	968 7	tapping screw		6	87-
(29)	951	505	015 00	impact absorber		2		50	N	011	665 3	washer		6	
30	N	100	897 01	pan-head screw M 8 X 70		2		51	951	628	301 00	cover		2	
31	900	031	001 02	washer 8,4		2									
32	N	010	242 12	hexagon-head bolt M 8 X 25		2									
33	N	011	525 13	washer A 8		2									
34	951	575	133 00	air duct		1									
(34)	951	575	133 01	air duct		1									
35	999	217	013 00	hexagon-head bolt M 6		4									
36	937	503	255 01	spacer		4									
37	N	015	458 1	speed nut 4,8 X 19		2									
38	N	013	884 4	tapping screw 4,8 X 13		2									