


Model	Year	MG	SG	Illustration	Restrictions	UPD	14:19	25.02.2010	PORSCHE PET PORSCHE		
9442	1988	8	01	801-05		248					



Pos	Part Number	Description	Remark	Qty	Model
1	944 501 119 01	side member heat shield		1	
(1)	944 501 120 01	side member centre	/L	1	
2	999 703 119 40	stopper	/R	2	
(2)	803 803 583	drain bush		2	
(2)	803 803 583 A	cap		10	
3	944 501 203 00	floor section centre	-86	1	
3	944 501 501 00	floor section centre	87-	1	
4	477 803 283	side member		2	
5	951 501 105 00	side member use also: 477.803.145	/L	1	
(5A)	951 501 116 00	side member use also: 477.803.145	/R	1	
6	477 803 125 A	end piece	/L	1	
(6)	944 502 066 02	end piece	/R	1	
7	477 803 129	retaining bow		2	
8	477 803 145	bush		2	
9	951 501 265 00	jacking point centre		2	
10	951 501 083 00	jacking point	/L/H	1	
(10)	951 501 084 00	jacking point	/R/H	1	
11	411 803 595	lid 136 MM \$		2	
12	477 803 871 A	jacking point	/L/H	1	
(12)	477 803 872 A	jacking point	/R/H	1	
13	477 809 214 A	cover plate		1	
14	999 072 005 09	hexagon-head bolt M 6 X 12		X	

Model	Year	MG	SG	Illustration	Restrictions	UPD	14:19	25.02.2010	PORSCHE PET PORSCHE		
9442	1988	8	01	801-05		248					

Pos	Part Number			Description	Remark	Qty	Model	Pos	Part Number			Description	Remark	Qty	Model
15	N	012	006 4	lock ring B 6		3		34	999	072	005 09	hexagon-head bolt M 6 X 12		4	
16	N	011	524 7	washer A 6,4		X		35	900	151	029 02	washer 6,4		4	
17		900	076 010 02	hexagon nut M 6		2		37	951	501	181 00	gusset plate	/L	1	
18	477	803	387 B	heat shield		1		(37)	951	501	182 00	gusset plate	/R	1	
19	N	015	458 1	speed nut B 4,8 X 20		4		38	N	010	375 4	hexagon-head bolt M 8 X 75		2	
20		900	151 027 02	washer B 5,3		4		39	900	910	003 02	lock nut M 8		2	
21	N	013	968 7	tapping screw B 4,8 X 13		4						VM 8			
22	477	803	253	transverse strut		1									
23	N	011	008 8	hexagon nut M 8		4									
24	N	011	525 13	washer A 8,4		4									
25		900	027 015 02	lock ring B 8		4									
26	A	951	504 869 00	heat shield upper		1									
26		951	504 869 00	heat shield		1									
27	N	090	239 1	combination screw B 4,8 X 13		2									
29		999	591 485 02	speed nut B 4,8 X 13		2									
30	477	803	291	transverse strut		2									
31	N	010	237 6	hexagon-head bolt M 8 X 12		8									
32	N	012	229 3	spring washer A 8		8									
33		951	503 139 00	heat shield	-86	1									
(33)		951	503 139 00	heat shield	87-	1	M249								
(33)		944	503 137 00	heat shield	87-	1									