


Model	Year	MG	SG	Illustration	Restrictions	UPD	22:52	23.01.2010	PORSCHE	PET	PORSCHE
9442	1991	8	02	802-15		248					



Pos	Part Number	Description	Remark	Qty	Model
		front apron and bumper			944S2, TURBO
1	951 505 071 00	lining upper part		1	
2	951 505 075 02	lining lower part		1	
3	944 505 523 00	pipng		1	
4	N 013 967 9	tapping screw B 4,2		9	
5	951 505 157 00	spacer		7	
6	999 591 742 02	speed nut		9	
7	900 151 028 02	washer B 4,3		2	
8	951 505 347 00	stopper		2	
9	900 910 010 09	lock nut M 6		2	
10	N 011 666 7	washer B 6,4		2	
11	951 505 513 00	attachment strip	/L	1	
(11)	951 505 514 00	attachment strip	/R	1	
12	N 011 666 7	washer B 6,4		6	
13	N 010 215 13	hexagon-head bolt M 6 X 15		6	
14	951 575 361 00	air duct	/L	1	TURBO
(14)	951 575 362 00	air duct	/R	1	TURBO
15	951 575 371 00	fastening angle		2	TURBO
16	N 013 884 4	tapping screw BZ 4,8 X 13		4	TURBO
17	N 011 665 3	washer B 5,3		4	TURBO
18	N 015 458 1	speed nut 4,8 X 19		4	TURBO
19	N 010 215 13	hexagon-head bolt M 6 X 15		4	TURBO

Model	Year	MG	SG	Illustration	Restrictions	UPD	22:52	23.01.2010	PORSCHÉ PET PORSCHÉ		
9442	1991	8	02	802-15		248					

Pos	Part Number		Description	Remark	Qty	Model	Pos	Part Number		Description	Remark	Qty	Model
20	N	011 666 7	washer B 6,4		4	TURBO	40	951 575 131 00	air duct			1	TURBO
21	N	011 524 7	washer A 6,4		4	TURBO	(40)	944 575 133 00	air duct			1	944S2
22		900 910 010 09	lock nut M 6		4	TURBO	41	900 143 007 02	tapping screw B 4,2 X 13			2	
23		951 505 373 00	spring		4		42	900 025 002 02	washer A 4,3			2	
24		951 505 353 00	cap		1		43	N 015 447 1	speed nut 4,2 X 10,3			2	
25		900 143 072 02	oval-head sheetmetal screw B 3,9 X 19		1		44	999 049 001 40	plastic nut			2	
26	N	011 663 1	washer B 3,7		1		45	951 505 359 00	fastening angle			2	
27		951 505 010 01	bumper		1		46	N 015 458 1	speed nut			2	
28		951 505 349 00	cap		1		47	951 505 355 00	bracket			3	
29		951 505 017 00	impact pipe		2		48	N 015 470 2	speed nut			6	
(29)		951 505 015 00	impact absorber		2	M036/058	49	N 013 968 7	tapping screw			6	
30	N	100 897 01	pan-head screw M 8 X 70		2		50	N 011 665 3	washer			6	
31		900 025 007 02	washer 8,4		2		51	951 628 301 00	cover			2	
32		900 075 029 09	hexagon-head bolt M 8 X 25		2		52	944 503 255 00	spacer			6	
33		900 025 007 02	washer A 8		2		53	N 013 975 4	tapping screw			3	
34		951 575 133 00	air duct		1		54	951 701 133 00	spacer			2	
(34)		951 575 133 01	air duct		1	M573	55	999 591 498 40	special nut			X	
35		999 217 013 00	hexagon-head bolt M 6		4		56	911 701 121 03	support			1	
36		937 503 255 01	spacer		4		57	928 701 050 03	support			1	
37	N	015 458 1	speed nut 4,8 X 19		2		58	N 011 522 8	washer 4,3			X	
38	N	013 884 4	tapping screw 4,8 X 13		2		59	900 143 134 00	tapping screw BZ 4,2 X 9,5			X	
39	N	011 665 3	washer B 5,3		2		60	900 144 020 02	tapping screw B 4,8 X 32			2	