




- 1. Table of Contents (This Page) Created on Wed Feb 26 22:41:24 2014
- 2. bottom
- 3. top-gnd
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab






























| There are 3 different drill sizes used in this layout, 449 holes total |              |       |                |  |
|--|--------------|-------|----------------|--|
| Symbol   | Diam. (Inch) | Count | <u>Plated?</u> |  |
| Y  | 0.012        | 435   | YES            | Title: (unknown) - Fabrication Drawing |
| +  | 0.038        | 10    | YES            | Author: Andreas Rosvall                |
| ×  | 0.126        | 4     | YES            | Date: Wed Feb 26 21:41:25 2014 UTC     |



Board outline is the centerline of this path