

# SSR-40DA COMPRESSOR WIRING DIAGRAM

Relay CH2 (GPIO 5) → SSR-40DA → 120VAC → Compressor

