


**(a) Your 7
real sensors**



**(b) Redraw 1,500 times
(repeats allowed)**



*some sensors appear twice,
others not at all*

(c) The spread = the error bar

