


(a) Your 7
real sensors



(b) Redraw 1,500 times
(repeats allowed)



some sensors appear twice,
others not at all

(c) The spread = the error bar

