

Electronic Components Tracking System

- 1. Excel file Stock Detail and Product BOM upload using a software Tool to server.
- 2. Login Screen



3. Main Screen to select Product Part Number Which will show List of BOM of the Product Parent Part Number. On click of "Select" button navigate to Material pick screen.



4. Shows Rack view in the screen with Part Number, Location, Qty to pick and Blue Button "PICK" to be clicked after material is picked from that location after clicking the color will be changed to green and text to "PICKED". After Rack-1 is finished move on to Rack-2, follow this steps until all Rack is picked.

| | | Material Pick | | |
|--------------|--------|---------------|--------------|--------|
| | | | | |
| Rack -1 | | | | |
| | | | | |
| R1T1L1 QTY-2 | R1T1L2 | R1T1L3 | R1T1L4 | R1T1L5 |
| PICKED | | | | |
| R1T2L1 | R1T2L2 | R1T2L3 | R1T2L4 QTY-5 | R1T2L5 |
| | | | PICK | |
| R1T3L1 | R1T3L2 | R1T3L3 QTY-6 | R1T3L4 | R1T3L5 |
| | | PICK | | |
| | | | | |
| | | | | Rack-2 |
| | | | | |
| | | | | |

5. After all Rack materials picked, click Button "**Transact**", which will minus the store stock qty with picked qty, and all report excel and PDF can be downloaded.