

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

✓

2

Clinical systems

2 to fix

3

Network and ports

✓

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Step 1 of 6

Site and hardware

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

Load profile

Save as template

Export config (YAML)

Hospital

Who this box is for. Shows up in the console, alerts, and support logs.

Hospital name *

Cedar County Memorial Hospital

Site ID *

cedar-county-mo

Lowercase, used in hostnames and URLs

State

Missouri

Licensed beds

25

Facility type

Critical access hospital

Time zone

America/Chicago (Central)

IT contact (daytime) *

[Name, phone]

After-hours contact *

[Name, phone]

Service tier

Pilot

Box

Pick the hardware, then plug it in (or its SSD) so the Configurator can check it.

Protectli
VP2420e

Pilot standard

4× 2.5G Ethernet · TPM 2.0
module · 8 GB · 120 GB SSD

Dell Wyse
5070

Desk testing only

1 Ethernet + USB NIC · fTPM 2.0 ·
not for hospitals

Other x86-64 box

Checked against the minimum
spec when you plug it in

Hostname

br-cedar-county-01

Serial number

PT24E-00417

Asset tag

[Hospital asset tag]

Auto-filled from the site ID

Read from the box when plugged in

Hardware check (read from the plugged-in box)

x86-64 CPU	Intel J6412	Pass
UEFI boot	Enabled	Pass
TPM 2.0	Present, owned: no	Pass
Ethernet ports	4 found (need 2+)	Pass
Memory	8 GB (need 4+)	Pass
Target disk	120 GB SSD (need 16+)	Pass
Secure Boot	Off in firmware. Turn on after first flash.	Action
LTE modem	Not detected	Optional

Readiness

You cannot build until every step is green.

- ✓

Site and hardware

Done
- ⚠

Clinical systems

2 to fix
- ✓

Network and ports

Done
- ⚠

Security and enrollment

1 to fix
- Build image

Not started
- Flash and verify

Not started

What this step writes

Part of site-config.yaml, baked into the image

```
site:
  id: cedar-county-mo
  name: Cedar County Memorial Hospital
  state: MO
  beds: 25
  type: critical_access
  tz: America/Chicago
  tier: pilot
device:
  hostname: br-cedar-county-01
  model: protectli-vp2420e
  serial: PT24E-00417
```

Next: Clinical systems

Clinical systems: what to check and listen for

EHR

Loads the vendor profile: which hosts, ports and pages to check.

MEDITECH Expense, 6.x, MAGIC	TruBridge Thrive / CPSI	Epic Community Connect Hosted by a partner	Oracle Health CommunityWorks
athenahealth athenaOne	Vista / RPMS VA, IHS	Other EHR Manual checks	No EHR checks Network only
Version	EHR host or URL *	How deep to check	Read-only service account
Expense 2.2	ehr.cedarcounty.local	L3: log in and read (read-only)	

L1 ping · L2 login page · L3 read

Required for L3. Ask the hospital for a read-only account.

Interfaces: what to listen for

Two ways to watch HL7 traffic. You can use both.

Read the interface engine (Mirth Connect)

Asks Mirth for channel status. Never reads message content.

Mirth admin API *

https://10.20.1.15:8443

Read-only Mirth user

beacon_ro

Watch	Channel	Message types	Alert if silent for	Alert on errors
☒	ADT_IN	ADT^A01-A08	5 min	3 in 15 min
☒	LAB_RESULTS_OUT	ORU^R01	15 min	3 in 15 min
☒	PHARM_ORDERS	RDE^O11	30 min	5 in 15 min
☐	RAD_ORDERS	ORM^O01	60 min	5 in 15 min

Pull channel list from Mirth

Passive listen on a mirror port (SPAN)

The box only listens. It never sends on this port and has no IP address there.

Listen on port

eth1 (tap, no IP) ▾

MLLP ports to watch

2575, 6661, 7001

Only these source hosts (optional)

10.20.1.15, 10.20.1.40

What is kept

Counts and timing only ▾

ⓘ

Patient data stays off the box. Message type, time, size and a keyed hash of the control ID are kept. Names, MRNs and results never leave the parser. This cannot be turned off here.

☒ Alert if no ADT messages seen during business hours

Silence window: 10 min, 07:00-19:00

Critical services to check (20)

14 of 20 on. Turned-off services show as "Not watched" in the console, never as green.

Clinical Systems					Network and Site				
☒	EHR	L3 read	ehr.cedarcounty.local	Every 60 s	☒	Internet	HTTPS	3 public probes	Every 60 s
☒	ADT	Mirth + SPAN	ADT_IN	Every 60 s	☒	WAN circuit	Ping gateway	10.20.0.1	Every 60 s
☒	Lab	Mirth	LAB_RESULTS_OUT	Every 60 s	☒	Firewall	SNMP v3	10.20.0.1	Every 60 s
☒	Pharmacy	Mirth	PHARM_ORDERS	Every 60 s	☒	DNS	Lookup	ehr.cedarcounty.local	Every 60 s
☒	Imaging (PACS)	TCP 104	10.20.1.60	Every 60 s	☒	DHCP	Lease test	eth0	Every 60 s
☒	e- Prescribing	HTTPS	Surescripts endpoint	Every 60 s	☒	Wireless APs	Ping list	14 hosts	Every 60 s
					☐	VPN tunnel	Ping far end	10.40.0.1	Off
					☒	Phones	SIP OPTIONS	10.20.5.10	Every 60 s
					☒	Printing	TCP 9100	6 printers	Every 60 s
Security and Identity									
☒	Certificates	TLS expiry	5 hosts	Every 60 s					
☐	Microsoft 365	Graph API	—	Off					
☐	Backups	Job status	—	Off					
☐	Antivirus / EDR	Console API	—	Off					
☐	Custom check	Pick a method	—	Off					
Edit check method and target					Set business hours per service				
					Copy from another site				

[Back](#)

2 to fix: EHR service account, Mirth user password

Next: Network and ports

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

2

Clinical systems

2 to fix

3

Network and ports

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Step 3 of 6

Network and ports

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

Load profile

Save as template

Export config (YAML)

Ports

Give each port one job. The Configurator blinks a port's light when you click it, so you can find it on the box.

eth0

Link up · 1 Gb/s

Role

Management (uplink)

64:62:66:21:0a:10

eth1

Link up · mirror traffic seen

Role

Passive tap (SPAN, no IP)

64:62:66:21:0a:11

eth2

No link

Role

Unused (disabled)

64:62:66:21:0a:12

eth3

No link

Role

Unused (disabled)

64:62:66:21:0a:13

wwan0

No modem found

Role

Backup path (LTE)

—

wlan0

Radio disabled

Role

Off (recommended)

—

Blink port lights

Re-detect ports

Management network (eth0)

How the box reaches the hospital network and the Beacon Relay cloud.

DHCP

Get an address automatically

Static IP

Recommended for hospitals

DHCP reservation

Hospital pins the address

IP address / prefix *

10.20.0.50/24

Gateway *

10.20.0.1

DNS servers

10.20.0.10, 10.20.0.11

Search domain

cedarcounty.local

VLAN ID

120

MTU

1500

NTP servers

10.20.0.10, time.cloudflare.com

802.1X port login

Off

Outbound web proxy (if required)

Proxy does TLS inspection

No

Blank if untagged

Blank = direct. Format http://host:port

Hospital firewall asks

Send this to the hospital's IT. The box opens no inbound ports to the internet.

Destination	Port	Why
relay.beaconrelay.net	443/tcp	Control plane (mTLS)
updates.beaconrelay.net	443/tcp	Signed OS updates
NTP servers above	123/udp	Clock (certificates need it)
Hospital DNS	53/udp	Name lookups

Downtime page on the hospital LAN

https://10.20.0.50 · read-only downtime info

Allow ping to the box from the LAN

Copy as email

Download PDF for hospital IT

Backup path (LTE)

Keeps alerts flowing if the hospital's internet is down.

Use LTE when the main link fails

No modem found in this box. Add one, then re-detect.

Carrier

Verizon

APN

vzwinternet

SIM PIN

Monthly data alert (MB)

500

Back

Next: Security and enrollment

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

✓

2

Clinical systems

2 to fix

3

Network and ports

✓

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Step 4 of 6

Security and enrollment

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

Load profile

Save as template

Export config (YAML)

Control plane connection

Where the box reports. The box will refuse any server that does not match this fingerprint.

Control plane URL *

https://relay.beaconrelay.net

Root CA fingerprint (SHA-256)

Missing. Paste from the CA, or click Fetch and compare it by phone with the CA owner.

Device certificate life

24 hours (renews automatically)



Pin the CA (required)

Box refuses any other certificate



Report every 60 s

Fetch fingerprint from server

Test connection from this computer

Enrollment

How the box proves it belongs to this site on first boot.

Token

Create a one-time token

Token expires

In 24 hours

Bound to

Serial PT24E-00417

tok_.....7Q2F

Single use

On first boot the box shows up in the console as Quarantined. A second person confirms it before it goes live.

Disk encryption and boot

Locks the box's data if it is stolen.



Encrypt /data (LUKS2)

All logs and settings on the box



Unlock with the box's TPM chip

Sealed to firmware and Secure Boot state



Require Secure Boot

Turn on after first flash. Step 1 flagged it.



Lock firmware setup with a password

Recovery key

Print once and store in the hospital safe

Firmware password

.....

Stored in the team vault, not on this computer

Local access

Who can log in at the box itself.

SSH

Off

Console login (keyboard + screen)

Break-glass account only



Block USB storage devices



Require a second person to confirm break-glass use

Updates

Signed A/B updates. A bad update rolls back by itself.

Update channel

Pilot

Maintenance window

Sun 02:00–04:00 CT

Roll back after

3 failed boots

Health check before keeping an update

All on-checks green for 10 min

Downtime bundle

What the box serves on the hospital LAN when the EHR is down.

Bundle

Cedar County v4 (2026-09-10)



Include downtime forms (PDF)



Include contact tree

Back

1 to fix: CA fingerprint

Next: Review and build

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

✓

2

Clinical systems

2 to fix

3

Network and ports

✓

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Step 5 of 6

Review and build the image

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

Load profile

Save as template

Export config (YAML)

Pipeline

Runs the repo's pipeline/ scripts in Docker on this computer.

	Stage	What it does	Status	Time
✓	00-debootstrap	Base Debian system	Reused from cache	0:04
✓	10-configure	Packages, users, hardening	Done	1:12
✓	20-partition	ESP, boot, rootfs A/B, /data	Done	0:21
	30-agent	Device agent + HL7 sidecar	Running	0:48
	35-site-config	Bake in this site's settings	Waiting	—
	40-rauc	Sign update bundle	Waiting	—
	50-verify	Boot test + checksums	Waiting	—

```
[21:54:02] 30-agent  npm ci --omit=dev (device-agent)
[21:54:19] 30-agent  added 142 packages in 17s
[21:54:20] 30-agent  install hl7-sidecar (python 3.11, venv)
[21:54:31] 30-agent  systemd: beacon-agent.service enabled
[21:54:32] 30-agent  systemd: beacon-hl7.service enabled
[21:54:33] 30-agent  writing /etc/beacon/agent.json (no secrets)
[21:54:34] 30-agent  ...
```

Cancel build

Open full log

Start build

Output

Filled in when the build finishes.

Image file	br-cedar-county-01_v0.9.3.img.zst
Size	—
SHA-256	—
Signed by	—
Manifest	build-manifest.json

Review

Everything the image will contain. Click a line to jump back and change it.

Site	Cedar County Memorial Hospital · MO · 25 beds · pilot	Edit
Box	Protectli VP2420e · PT24E-00417 · br-cedar-county-01	Edit
EHR	MEDITECH Expanse 2.2 · L3 read	Edit
Listening	Mirth (3 channels) + SPAN on eth1, ports 2575/6661/7001	Edit
Checks	14 of 20 services	Edit
Network	eth0 static 10.20.0.50/24 · VLAN 120 · no proxy	Edit
Security	CA pinned · LUKS2 + TPM · SSH off · USB storage blocked	Edit
Updates	Pilot channel · Sun 02:00–04:00 CT	Edit

Build options

Fast: reuse release v0.9.3 and add this site's settings

About 4 minutes. Use for every normal box.

Full rebuild from source

About 25 minutes. Only after a code change.

Release

v0.9.3 (stable, signed)

Signing key

USB token · key 0xB7C1

☒

Keep build logs with the profile

Back

Build running · 2:25 so far

Next: Flash and verify

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

2

Clinical systems

2 to fix

3

Network and ports

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Step 6 of 6

Flash and verify

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

Load profile

Save as template

Export config (YAML)

How to get the image onto the box

Write the box's SSD directly

SSD out of the box, in a USB adapter. Fastest.

Make a USB installer stick

Boot the box from the stick. It installs itself and wipes the old OS.

Save image file only

For flashing on another computer later.

Target drive

Only removable and non-system drives can be picked.



/dev/sda · Samsung 870 EVO · 500 GB · SATA

This computer's system disk. Cannot be selected.

Protected



/dev/sdb · Kingston A400 (in USB-SATA adapter) · 120 GB · USB 3

Old Windows install: 4 partitions



/dev/sdc · SanDisk Ultra Fit · 32 GB · USB 3

FAT32 · "INSTALL"

Rescan drives

Open drive tools

After flashing

Printed on the box label and shown here.

- Put the SSD back. Turn on Secure Boot in firmware.
- Plug eth0 into the hospital switch, eth1 into the mirror port.
- Power on. Wait for the box to appear as Quarantined in the console.
- A second person confirms it. It goes live.

Print box label

Print recovery key sheet

Confirm

Everything on /dev/sdb (Kingston A400, 120 GB) will be erased, including the old Windows install.

Type the drive path to confirm

/dev/sdb

Must match exactly



Wipe old partitions first (blkdiscard)

Recommended for SSDs that had Windows



Read the whole drive back and check SHA-256 after writing

Erase /dev/sdb and write image

Progress

Wipe

done

Write

6.1 of 9.3 GB · 212 MB/s

Verify SHA-256

waiting

Back

Finish and log this box

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

2

Clinical systems

2 to fix

3

Network and ports

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Tools

Drive tools: erase, format, check

Drives on this computer

The system disk is locked and never offered for any action.

	Device	Model / serial	Size	Connection	Health	Contents
	 /dev/sda	Samsung 870 EVO S6PNNX0T4 ...	500 GB	SATA	Good	This computer
	 /dev/sdb	Kingston A400 50026B77 ...	120 GB	USB 3 (ASMedia bridge)	Good	Windows (4 partitions)
	 /dev/sdc	SanDisk Ultra Fit 4C530001 ...	32 GB	USB 3	n/a	FAT32
	 /dev/nvme0n1	WD SN570 (M.2 in USB-NVMe adapter) 21504Q ...	250 GB	USB 3.2	Wear 62%	Beacon Relay v0.9.1

/dev/sdb · Kingston A400 · 120 GB

Plugged in 21:47 through a USB-SATA adapter.

EFI

MSR

C: NTFS "Windows"

Recovery

sdb1	EFI	100 MB	Power-on hours	3,112
sdb2	MSR	16 MB	Reallocated sectors	0
sdb3	C: NTFS "Windows"	118.9 GB	Life used	9%
			Temperature	31 °C
sdb4	Recovery	612 MB	Self-test	Short: passed

Format tab (preview)

For reusing a drive, e.g. making a hand-off stick.

Partition table

File system

Label

Layout

GPT

exFAT

BLANK

One partition, whole drive

Also offered: ext4, FAT32, NTFS · MBR for old machines · Partitions tab: add, delete, resize, set flags.

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

Rescan drives

Erasure certificates

Actions on /dev/sdb

Erase

Format

Partitions

Health test

Back up to image file



Quick wipe

Removes partition tables and signatures. Data is still recoverable. Seconds.

Supported



SSD discard (TRIM whole drive)

Tells the SSD every block is free. Fast. Most data becomes unreadable.

Supported



Overwrite with zeros, 1 pass

Writes every block. NIST 800-88 "Clear". About 9 min for 120 GB.

Supported



Overwrite with random data, 1 pass

Same as above with random data.

Supported



ATA Secure Erase

The drive erases itself, including spare blocks. NIST "Purge".

Blocked by USB adapter



NVMe Sanitize (crypto or block erase)

For NVMe drives. NIST "Purge".

Not an NVMe drive

⚠ USB adapters usually block Secure Erase. For a true Purge, connect the drive directly to a SATA or M.2 port on a Linux machine, or run this from the Configurator boot stick on the box itself.

After erasing

Verify

Create one GPT partition, exFAT, label "BLANK"

Read back 10% at random



Save an erasure certificate (PDF) for hospital records

Drive model, serial, method, NIST level, time, operator, verify result

This cannot be undone

Everything on **/dev/sdb** (Kingston A400, serial ending ...B77) will be destroyed, including the Windows install.

Type the drive path

Type the last 4 of the serial

/dev/sdb

Erase /dev/sdb (enter both to unlock)

Beacon Relay

Configurator · build bench

BUILD A BOX

1

Site and hardware

✓

2

Clinical systems

2 to fix

3

Network and ports

✓

4

Security and enrollment

1 to fix

5

Review and build image

6

Flash and verify

TOOLS

Drive tools (erase, format)

Profiles and history

This computer

Ubuntu 24.04 · running as admin

Docker engine ready

Signing key: USB token present

UI bound to 127.0.0.1:7443

Tools

Profiles and history

Profile: Cedar County Memorial · relay 01 · draft saved 21:52

New site profile

Import YAML

Site profiles

One profile per box. Saved as YAML so it can live in the repo (secrets stay in the vault).

Site	EHR	Box serial	Status	
Cedar County Memorial cedar-county-mo	MEDITECH Expanse	PT24E-00417	Building	Open · Duplicate
Harlan Valley Hospital harlan-valley-ks	TruBridge	PT24E-00391	Live	Open · Duplicate
Ozark Ridge Medical ozark-ridge-mo	athenahealth	PT24E-00402	Live	Open · Duplicate
Prairie View Clinic prairie-view-ks	Epic Community Connect	—	Draft	Open · Duplicate
Bench test unit dev-bench	No EHR checks	WY5070-0021	Desk test	Open · Duplicate

Start from a template

Critical access hospital · MEDITECH

Mirth + SPAN, 16 checks, static IP

Critical access hospital · TruBridge

SPAN only, 14 checks

Rural clinic · athena

Cloud EHR, network checks only

Audit log

Every build, flash and erase on this computer. Operator: [Your name]. Kept 7 years; export for the hospital on request.

When	Action	Site	Device	Detail	Proof	Result
21:52	Build started	cedar-county-mo	PT24E-00417	v0.9.3 fast	—	Running
21:49	Drive erased	—	Kingston ...B77	Zeros, 1 pass, 10% verify	Cert #E-0031	OK
Sep 22 16:10	Box flashed	harlan-valley-ks	PT24E-00391	v0.9.3	sha256 9f2c...a41e matched	OK
Sep 22 15:58	Flash refused	—	/dev/sda	System disk	Blocked by guard	Blocked
Sep 20 11:02	Profile edited	ozark-ridge-mo	—	Mirth channels +1	—	OK

Export CSV

Export PDF

Beacon Relay

Service desk

Master board

Alerts2

Fleet8 sites

Sites

Alert routing

Support sessions

Audit log

[Your name]

Operations manager

MFA verified

Alerts

Open · 3

Acknowledged · 1

Resolved today · 6

Search

Site, service, device

Sample data

P1 Demo County Memorial

9 min

Lab results interface degraded

Lab results aren't reaching MEDITECH.

Unacknowledged · escalated to Tier 2

P1 Osage Creek Medical Center

4 min

Printing down (2nd floor)

Wristband and label printers can't print.

Unacknowledged · escalates in 1:12

P2 Prairie Ridge Hospital

2 h

TLS certificate expires in 6 days

Patient portal certificate expires Sep 29.

Acknowledged by [tech name]

P3 Flint Hills Community Hospital

1 d

New Beacon Link awaiting confirmation

Device br-flh-01 is in quarantine until confirmed.

Waiting on operations

P1

Demo County Memorial · Lab results interface · Mirth channel ch-lab

Unacknowledged

Escalated to Tier 2 at 21:36

Lab results aren't reaching MEDITECH

Clinicians may see delayed or missing lab results in the chart. Orders are still flowing out; results coming back are failing.

Acknowledge

Open site

Start support session

Copy ticket text

What we see

Last good message 21:31:02 (9 min ago)
Errors, last 15 min 3 NACKs
Check depth L2, TLS handshake OK

Also affected

Printing is down at this site (may be unrelated)

Similar past incidents

Aug 14 · Prairie Ridge Hospital

Root cause: Lab LIS service hung. Fix: restarted LIS interface service. Resolved in 22 min · match 0.81

Jul 2 · Demo County Memorial

Root cause: expired cert on LIS endpoint. Fix: renewed certificate. Resolved in 1 h 10 min · match 0.64

Confirmed before paging

- Retried the check twice
- Checked a second dependency (Lab LIS host reachable)
- Confirmed WAN is up (primary fiber)

Open runbook: Lab interface stalled

Who's been paged

Tier 1 · Onsite tech (SMS + call) 21:31 · no ack

Tier 2 · Beacon Relay service desk 21:36 · ringing

Tier 3 · On-call engineer at 21:46 if no ack

Facts only: recorded check results and timestamps. Beacon Relay never shows patient data here.

Beacon Relay

Service desk

Master board

Alerts2

Fleet8 sites

Sites

Alert routing

Support sessions

Audit log

[Your name]

Operations manager

MFA verified

Fleet

Sample data

Sites monitored4

All systems working1

Need attention2

Devices awaiting confirmation1

Kansas and Missouri

KANSAS

MISSOURI

Prairie Ridge Hospital

Flint Hills Community Hospital

Demo County Memorial

Osage Creek Medical Center

Schematic. Real state basemap in build.

Working

Degraded

Down

Not reporting

Site	Service tier	Status	Open alerts	Last heartbeat
Demo County Memorial MO · 25 beds · br-dcm-01	Tier 2 managed	1 down, 2 degraded	2	12 s ago
Osage Creek Medical Center MO · 22 beds · br-ocm-01	Tier 1 watch	1 down	1	1 m ago
Prairie Ridge Hospital KS · 18 beds · br-prh-01	Tier 2 managed	All working	1 (ack)	9 s ago
Flint Hills Community Hospital KS · 25 beds · br-flh-01	Tier 1 watch	Awaiting confirmation	0	never

Beacon Relay

Service desk

Master board

Alerts

2

Fleet

8 sites

Sites

Alert routing

Support sessions

Audit log

[Your name]

Operations manager

MFA verified

Fleet /

Demo County Memorial

Critical access hospital · 25 beds · Jefferson City area, MO · Tier 2 managed service

17 working

2 degraded

1 down

Topology

Sample data

Overview

Support

2 open

Topology

Clinical systems

EHR	MEDITECH Expanse · L3 read OK	Working
ADT		Working
Lab	Results delayed	Degraded
Pharmacy		Working
Imaging		Working
e-Prescribing	Surescripts reachable	Working

Interfaces

ADT feed	Mirth · last msg 8 s ago	Working
Lab results	Mirth · 3 errors in 15 min	Degraded
Pharmacy orders	Mirth · last msg 21 s ago	Working
Custom check	Not configured	Unknown

Beacon Link

Device	br-dcm-01
Status	Online · 12 s ago
Connection	Fiber, LTE backup ready
Software	1.4.2 (current)
Certificate	Auto-renews in 18 h

Who gets paged

Edit

Tier 1 · Onsite tech · SMS + call · 5 min

Tier 2 · Service desk · call + Teams · 10 min

Tier 3 · On-call engineer · call

Network and site

Internet		Working
WAN circuit	Primary fiber	Working
Firewall		Working
DNS		Working
DHCP		Working
Wireless APs	14 of 14 up	Working
VPN tunnel	To clinic	Working
Phones		Working
Printing	2nd floor label printers	Down

Security and identity

Certificates	Next expiry in 41 days	Working
Microsoft 365	No risky sign-ins	Working
Backups	Last success 02:10	Working
Antivirus / EDR	42 of 42 checked in	Working

Recent incidents

Sep 23 · Lab results interface **open**

Sep 23 · Printing down **open**

Sep 11 · WAN failover to LTE · 14 min

Jul 2 · LIS certificate expired · 1 h 10 min

Topology

Downtime page

Beacon Relay

Service desk

Master board

Alerts

2

Fleet

8 sites

Sites

Alert routing

Support sessions

Audit log

[Your name]

Operations manager

MFA verified

Fleet /

Demo County Memorial

Critical access hospital · 25 beds · Tier 2 managed service

Log a reported issue

Sample data

OverviewSupportTopology

Issues, last 30 days

12

Caught before anyone called

9

Reported by hospital staff

3

Median time to resolve

24 min

Open now

2

Support log

All

Open

Detected by us

Reported by hospital

When	Issue	How we found out	Status	Owner	Time
Sep 23 21:36	Printing down (2nd floor) Label printers refuse connections. Nurse station called 12 min after we alerted.	Detected, then reported Call from 2 West nurse station	Open	Service desk	4 min
Sep 23 21:31	Lab results interface degraded Results from Lab LIS failing into MEDITECH. Orders still flowing.	Detected by Beacon Relay No one has reported it yet	Open	[Tech name]	9 min
Sep 19 14:05	Slow EHR logins, east wing Reported slowness. All checks normal; wireless AP 7 reboot resolved it.	Reported by hospital Email from IT lead	Resolved	[Tech name]	38 min
Sep 16 03:12	Backup job failed Nightly backup missed. Re-ran at 06:00, verified.	Detected by Beacon Relay Caught overnight	Resolved	Service desk	3 h 1 min
Sep 11 10:42	WAN failover to LTE Fiber cut by road crew. LTE carried traffic; ISP repaired.	Detected by Beacon Relay Before staff noticed	Resolved	Service desk	14 min
Sep 8 09:15	Fax to pharmacy not arriving Outside what Beacon Relay monitors. Logged for the record; vendor fixed.	Reported by hospital Call from pharmacy	Resolved	[Tech name]	1 h 20 min
Sep 2 16:50	Certificate expiring on patient portal Flagged 14 days out. Hospital IT renewed it.	Detected by Beacon Relay 14 days before expiry	Resolved	Hospital IT	6 days
Aug 29 07:20	Intermittent ADT delays Watching queue depth after a MEDITECH patch.	Detected by Beacon Relay Pattern over 3 days	Monitoring	Service desk	ongoing

When logging a call, record the system and symptom only. Never enter patient names, MRNs or other patient details.

⌵

Beacon Relay

Service desk

Master board

Alerts2

Fleet8 sites

Sites

Alert routing

Support sessions


Audit log

[Your name]

Operations manager

MFA verified

Topology



CLINICAL SYSTEM

Lab LIS

Degraded

Host

Reachable (L2 TLS OK)

Interface

Lab results channel degraded

Also at this site

Printing down

Open this issue

Click any box in the diagram to see its facts here.
Facts are recorded check results; related problems are shown side by side, never guessed as causes.

Beacon Relay

Service desk

Master board

Alerts2

Fleet8 sites

Sites

Alert routing

Support sessions

Audit log

[Your name]

Operations manager

MFA verified

Alert routing

Who gets paged, how, and how long before it moves up.

Site

Demo County Memorial (Tier 2 managed) ▾

Send test page

Save changes

P1

Critical: patient care affected

Any time, day or night

TIER 1

Onsite tech (hospital)

SMS + phone call

Acknowledge within 5 min

TIER 2

Beacon Relay service desk

Phone call + Teams

Acknowledge within 10 min

TIER 3

On-call engineer

Phone call

Final escalation

P2

Degraded: workaround exists

Business hours only

TIER 1

Onsite tech (hospital)

Email + SMS

Acknowledge within 30 min

TIER 2

Beacon Relay service desk

Email + Teams

Acknowledge within 2 h

TIER 3

None

Ticket only

Next business day

Alert messages carry site, service, severity, time and a link. They never include patient information.

Severity by service

EHR, ADT, Lab, Pharmacy

P1

Internet, WAN, Firewall, DNS

P1

Interfaces (any channel)

P1

Printing, Phones, Wireless

P2

Certificates under 14 days

P2

Backups, AV/EDR, M365

P3

Hours and on-call

Business hours: Mon to Fri, 7:00 to 17:00 CT

After hours: P1 only, straight to service desk

On-call engineer this week: [name]

Maintenance windows

Sun 02:00 to 04:00 · MEDITECH patching · EHR alerts paused

Alerts during a window are logged, not paged.

[Add a window](#)