## MECH 463 - Homework 9

This homework gives some practice at using Lagrange's Equations. All the questions here are reproduced from Homework 3. For each system, draw the displaced shape, and mark the displacements and rotations at key points in terms of the specified coordinate system (which is chosen for practice, not necessarily for convenience.) In terms of these coordinates, write the kinetic and potential energies of the system. Take the partial derivatives and substitute into Lagrange's equations to get the equations of motion. You need not solve the equations of motion for the natural frequencies and mode shapes unless you want the practice.

1. A wire with three springs  $k_1$ ,  $k_2$  and  $k_3$  passes over two pulleys of radius  $r_1$  and  $r_2$  and polar moment of inertia  $J_1$  and  $J_2$ . A torque T(t) is applied to the first pulley.

Knietic energy:
$$T = \frac{1}{2}J_{1}\dot{\theta}_{1}^{2} + \frac{1}{2}J_{2}\dot{\theta}_{2}^{2}$$
Potential energy:
$$V = \frac{1}{2}k_{1}(r_{1}\theta_{1})^{2} + \frac{1}{2}k_{2}(r_{1}\theta_{1}+r_{2}\theta_{2})^{2} + \frac{1}{2}k_{3}(r_{2}\theta_{2})^{2}$$
Generalized forces,  $Q_{1} = T$ ,  $Q_{2} = 0$ . Also  $R = 0$ 

$$Recall \ Lagrange's \ Equations$$

$$\frac{d}{dt}\left(\frac{\partial T}{\partial \dot{q}_{1}}\right) - \frac{\partial T}{\partial q_{1}} + \frac{\partial V}{\partial q_{1}} + \frac{\partial R}{\partial \dot{q}_{1}} = Q_{1}$$

$$For \ i = 1, \ q_{1} = \theta_{1}, \ \dot{q}_{1} = \dot{\theta}_{2}, \ \dot{Q}_{1} = T$$

$$\frac{d}{dt}\left(J_{1}\dot{\theta}_{1}\right) - 0 + k_{1}r_{1}^{2}\theta_{1} + k_{2}r_{1}(r_{1}\theta_{1}+r_{2}\theta_{2}) + 0 = T$$

$$For \ i = 2, \ q_{1} = \theta_{2}, \ \dot{q}_{1} = \dot{\theta}_{2}, \ \dot{Q}_{1} = 0$$

$$\frac{d}{dt}\left(J_{2}\dot{\theta}_{2}\right) - 0 + k_{2}r_{2}\left(r_{1}\theta_{1}+r_{2}\theta_{2}\right) + k_{3}r_{2}^{2}\theta_{2} + 0 = 0$$

$$\ln \ mabrix \ notation:$$

$$\begin{bmatrix} J_{1} & 0 \\ 0 & J_{2} \end{bmatrix} \begin{bmatrix} \ddot{\theta}_{1} \\ \dot{\theta}_{2} \end{bmatrix} + \begin{bmatrix} (k_{1}+k_{2})r_{1}^{2} & k_{2}r_{1}r_{2} \\ k_{2}r_{1}r_{2} & (k_{2}+k_{3})r_{2}^{2} & \theta_{2} \end{bmatrix} = \begin{bmatrix} T \\ 0 \end{bmatrix}$$

2. A wire with springs  $k_1$  and  $k_2$  passes over a pulley, radius r, mass  $m_2$  and moment of inertia  $J = \frac{1}{2}m_2 r^2$ , and supports a second mass  $m_1$ . A torque T(t) acts on the pulley.

Rotation of pulley = 
$$0 = \frac{\infty}{r}$$

$$T = \frac{1}{2} J \Theta^{2} + \frac{1}{2} m_{1} \dot{x}_{2}^{2}$$


$$= \frac{1}{4} m_{2} \dot{x}_{1}^{2} + \frac{1}{2} m_{1} \dot{x}_{2}^{2}$$

$$V = \frac{1}{2}k_2 x_1^2 + \frac{1}{2}k_1 (x_2 - x_1)^2$$

Note: no need to include gravity because displacements are measured from the equilibrium position.

$$Q_1 = \frac{\partial \theta}{\partial x_1} \cdot T = \frac{T}{F}$$

$$Q_2 = \frac{\partial \theta}{\partial x_2} \cdot T = 0$$



$$\frac{d}{dt}\left(\frac{\partial T}{\partial \dot{q}i}\right) - \frac{\partial T}{\partial \dot{q}i} + \frac{\partial V}{\partial \dot{q}i} + \frac{\partial R}{\partial \dot{q}i} = Q_i$$

For 
$$i=1$$
  $q_i=x_i$   $q_i=x_i$ 

$$\frac{d}{dt} \left( \frac{1}{2} m_2 \dot{x}_1 \right) - 0 + k_2 \dot{x}_1 + k_1 (\dot{x}_2 - \dot{x}_1) (-1) + 0 = \frac{1}{r}$$

$$\frac{d}{dt} \left( m_1 \dot{si}_2 \right) - 0 + k_1 \left( x_2 - x_1 \right) + 0 = 0$$

In matrix form:


$$\begin{bmatrix} \frac{1}{2}m_2 & 0 \\ 0 & m_1 \end{bmatrix} \begin{bmatrix} 3i_1 \\ 3i_2 \end{bmatrix} + \begin{bmatrix} k_1 + k_2 & -k_1 \\ -k_1 & k_1 \end{bmatrix} \begin{bmatrix} 3i_1 \\ 3i_2 \end{bmatrix} = \begin{bmatrix} 7/r \\ 0 \end{bmatrix}$$

Two uniform rods are pinned at their upper ends and connected together by a spring stiffness k, a distance  $\ell$  down. The long rod has mass 2m and length  $2\ell$ . The s hort rod has mass m and length  $\ell$ . A force f(t) is applied at the midpoint of the long rod.

(A) and (B) are the centres of mass of the two rods.

At A displacement = 
$$\frac{5l_1}{2} = y$$
  
rotation =  $\frac{5l_1}{2l}$ 

At (B) displacement = 
$$\frac{x_2}{z}$$
  
rotation =  $\frac{x_2}{\ell}$ 



Kinetic energy, 
$$T = \frac{1}{2} (2m) (\frac{\dot{x}_1}{2})^2 + \frac{1}{2} (\frac{1}{12} \cdot 2m \cdot (2l)^2) (\frac{\dot{x}_1}{2l})^2 + \frac{1}{2} m (\frac{\dot{x}_2}{2})^2 + \frac{1}{2} (\frac{1}{12} m l^2) (\frac{\dot{x}_2}{2})^2 = \frac{1}{3} m \dot{x}_1^2 + \frac{1}{6} m \dot{x}_2^2$$

Potential energy, 
$$V = \frac{1}{2} k \left( x_2 - \frac{3U_1}{2} \right)^2 + 2mg \left( l - \sqrt{l^2 - \left( \frac{3L_1}{2} \right)^2} \right)$$
  
 $+ mg \left( \frac{1}{2} - \sqrt{\left( \frac{1}{2} \right)^2 - \left( \frac{3L_1}{2} \right)^2} \right)$   
 $= \frac{1}{2} k \left( x_2 - \frac{x_1}{2} \right)^2 + 2mg l \left( 1 - \left( 1 - \left( \frac{x_1}{2l} \right)^2 \right)^{\frac{1}{2}} \right)$   
 $+ \frac{mg l}{2} \left( 1 - \left( 1 - \left( \frac{x_2}{2l} \right)^2 \right)^{\frac{1}{2}} \right)$   
 $\approx \frac{1}{2} k \left( x_2 - \frac{x_1}{2} \right)^2 + \frac{mg x_1^2}{4l} + \frac{mg x_2^2}{4l}$ 

Generalized force 
$$Q_1 = \frac{\partial y}{\partial x_1} f(t)$$
 where y is the displacement associated with  $f(t) = \frac{3u_1}{2}$ 

$$Q_2 = \frac{\partial y}{\partial x_1} f(t) = 0$$

$$\frac{d}{dt}\left(\frac{\partial T}{\partial \dot{q}_i}\right) - \frac{\partial T}{\partial \dot{q}_i} + \frac{\partial V}{\partial \dot{q}_i} + \frac{\partial R}{\partial \dot{q}_i} = Q_i$$

For 
$$i=1$$
  $q_i=x$ ,  $\dot{q}_i=\dot{x}$ ,

$$\frac{d}{dt} \left( \frac{2}{3} m \dot{x}_{i} \right) - 0 + k \left( x_{2} - \frac{x_{i}}{2} \right) \cdot \left( -\frac{1}{2} \right) + \frac{mg x_{i}}{2l} + 0 = \frac{1}{2} f(t)$$

For 
$$i=2$$
  $q_i=x_2$   $q_i=x_2$ 

$$\frac{d}{dt} \left( \frac{1}{3} m \dot{x}_2 \right) - 0 + k \left( x_2 - \frac{x_1}{2} \right) + \frac{mg x_2}{21} + 0 = 0$$

In matrix notation:

$$\begin{bmatrix} \frac{2}{3}m & 0 \\ 0 & \frac{1}{3}m \end{bmatrix} \begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \end{bmatrix} + \begin{bmatrix} \frac{k}{4} + \frac{mg}{2l} & -\frac{k}{2} \\ -\frac{k}{2} & k + \frac{mg}{2l} \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} = \begin{bmatrix} f(t) \\ 0 \end{bmatrix}$$

Alternatively, use free body diagram.

Take moments about tops of pendulums

$$2m\frac{x_1}{2} \cdot l + J_1 \frac{x_1}{2l} + 2mg \cdot \frac{x_1}{2}$$
  
-  $kl(x_2 - \frac{x_1}{2}) - f(t) l = 0$ 

$$m\frac{\ddot{x}_{2}}{2}, \frac{1}{2} + J_{2}\frac{\ddot{x}_{2}}{l} + mg \cdot \frac{x_{1}}{2} + kl \left(x_{2} - \frac{x_{1}}{2}\right) = 0$$

$$2m\frac{x_1}{2}$$

$$\frac{1}{2}$$


Divide first equation by 21 and second by 1 to get

4. A movie projector reel drive consists of a tightly wound helical spring, stretched around two grooved pulleys. The pulleys have radii  $r_1$  and  $r_2$  and centroidal moments of inertia  $J_1$  and  $J_2$ . The stiffness of each exposed length of spring is k.

$$T = \frac{1}{2}J_1\dot{\theta}_1^2 + \frac{1}{2}J_2\dot{\theta}_2^2$$

$$V = \frac{1}{2}k\left(r_2\theta_2 - r_1\theta_1\right)^2 + \frac{1}{2}k\left(r_1\theta_1 - r_2\theta_2\right)^2$$

$$Q_1 = Q_2 = 0$$



Recall Lagrange's equations

$$\frac{d}{dt}\left(\frac{\partial T}{\partial \dot{q}_i}\right) - \frac{\partial T}{\partial q_i} + \frac{\partial V}{\partial q_i} + \frac{\partial R}{\partial \dot{q}_i} = Q_i$$

For 
$$i=1$$
  $q_i=x_i$   $q_i=x_i$ 

$$\frac{d}{dt}\left(J_{i}\dot{\theta}_{i}\right)-O+k\left(r_{2}\theta_{2}-r_{i}\theta_{i}\right)\left(-r_{i}\right)+k\left(r_{i}\theta_{i}-r_{2}\theta_{2}\right)\left(r_{i}\right)+O=0$$

For 
$$i=2$$
  $q_i=sl_2$   $q_i=sl_2$ 

$$\frac{d}{dt}\left(J_{z}\dot{\theta_{z}}\right)-O+k\left(\Gamma_{z}\theta_{z}-\Gamma_{i}\theta_{i}\right)\left(\Gamma_{z}\right)+k\left(\Gamma_{i}\theta_{i}-\Gamma_{z}\theta_{z}\right)\left(-\Gamma_{z}\right)+O=O$$

In matrix form:


$$\begin{bmatrix} J_1 & 0 \\ 0 & J_2 \end{bmatrix} \begin{bmatrix} \ddot{\theta}_1 \\ \ddot{\theta}_2 \end{bmatrix} + \begin{bmatrix} 2kr_1^2 & -2kr_1r_2 \\ -2kr_1r_2 & 2kr_2^2 \end{bmatrix} \begin{bmatrix} \theta_1 \\ \theta_2 \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \end{bmatrix}$$

## 5, A uniform slender rod of length $\ell$ is suspended at one end as a pendulum by a light string of length $\frac{1}{2}\ell$ . A force f(t) acts at the lower end of the rod.

Assume small displacements.

$$\Rightarrow x = \frac{1}{2}0_1 + \frac{1}{2}0_2$$

$$y = \frac{1}{2}0_1 + \frac{1}{2}0_2$$



$$T = \frac{1}{2} m \sin^{2} + \frac{1}{2} J \dot{\theta}_{z}^{2}$$

$$= \frac{1}{2} m (\frac{1}{2} \dot{\theta}_{1} + \frac{1}{2} \dot{\theta}_{2})^{2} + \frac{1}{2} (\frac{1}{12} m l^{2}) \dot{\theta}_{z}^{2}$$

$$= \frac{1}{8} m l^{2} (\dot{\theta}_{1} + \dot{\theta}_{2})^{2} + \frac{1}{24} m l^{2} \dot{\theta}_{z}^{2}$$

$$V = mg \left( \frac{1}{2} \left( 1 - \cos \theta_1 \right) + \frac{1}{2} \left( 1 - \cos \theta_2 \right) \right)$$

$$\simeq mgl \left( \theta_1^2 + \theta_2^2 \right) \qquad using \quad \cos \theta \simeq 1 - \frac{\theta^2}{2}$$

$$Q_1 = \frac{\partial y}{\partial \theta_1} f(t) = \frac{1}{2} f(t)$$

$$Q_2 = \frac{\partial y}{\partial \theta_2} f(t) = \lambda f(t)$$

Recall Lagranges equations
$$\frac{d}{dt} \left( \frac{\partial T}{\partial \dot{q}_i} \right) - \frac{\partial T}{\partial q_i} + \frac{\partial V}{\partial q_i} + \frac{\partial R}{\partial \dot{q}_i} = Q_i$$

For 
$$i=1$$
  $q_i = 0$ ,  $q_i = 0$ ,  $\frac{d}{dt} \left( \frac{1}{4}ml^2 \left( \frac{1}{2} + 0 \frac{1}{2} \right) \right) - 0 + \frac{mql}{2} 0$ ,  $+0 = \frac{1}{2}f(t)$ 

For 
$$i=2$$
  $9i=9z$   $9i=0z$   $\frac{1}{2}$   $9i=0z$   $\frac{1}{2}$   $\frac{1}{2}$ 

Divide by 
$$l$$
 and  $\Rightarrow \begin{bmatrix} m_1/4 & m_1/4 \\ m_1/4 & m_1/3 \end{bmatrix} \begin{bmatrix} \ddot{\theta}_1 \\ \ddot{\theta}_2 \end{bmatrix} + \begin{bmatrix} mg \\ \ddot{2} \\ 0 \end{bmatrix} \begin{bmatrix} \theta_1 \\ \theta_2 \end{bmatrix} = \begin{bmatrix} \dot{z}f(t) \\ f(t) \end{bmatrix}$ 
put in matrix form