



Drawing No.



P-P



1、可在1、4、5、8平衡块钻去重孔。每个平衡块钻孔数不超过3个，铰链区5°范围内，不允许钻穿，孔深20max

● 2、不平衡量≤20g·cm

3、其余平衡块不允许钻孔

Mark	Quant.	CR. No.	Before	After	Signature	Date
			Part Name CE18 Crankshaft		Drawing No.	
					Drawing Mark	Quant. Weight Scale
			Material			1:1
Design		Standard.			Page	Total
Check		Approval			OP270	
Audit						
Process		Date				