


# RICHARDS-GEBAUR AFB MISSOURI

# ADMINISTRATIVE RECORD COVER SHEET

AR File Number



BASEWIDE ENVIRONMENTAL BASELINE SURVEY RICHARDS-GEBAUR AIR FORCE BASE, MISSOURI December 1993



# BASEWIDE ENVIRONMENTAL BASELINE SURVEY RICHARDS-GEBAUR AIR FORCE BASE, MISSOURI

DECEMBER 1993

# **Environmental Baseline Survey Errata Sheet**

Page	Section	Paragraph	Line	Error corrections	
S-4	*	5	4-5	Lead has been found in the sediments of a drainage swale	
				located in the central region of the Cantonment Area.	
S-4	*	7	1-2	The area northwest of the POL Storage Yard contains	
-	<u> </u>			construction debris on the surface. It has not been determined	
				if the area qualifies as a landfill.	
S-5,	*	5	15-16	The central drainage swale/wetland in Area D-3 is	
S-6,				contaminated with lead ten times greater than the USEPA	
and		!		recommended action range. This should be Category 7	
S-7				property. Excavation of a fuel line in Area D-1 proved	
				contaminated soil is present. A portion of Area D-1 should be	
		:		Category 6 property. FT002 has an area contaminated with	
1				lead greater than the USEPA recommended action range. A	
		1		portion of Area B-1 should be Category 6 property. These	
	_			corrections apply throughout the EBS.	
S-5	*	6	All	Some of the property identified as "Category 7" is not, and	
		`		some areas should have been classified "Category 7" instead of	
				"Category 1" (Uncontaminated).	
S-7	*	*	*	The Small Arms Range is classified as "Category 3"; samples	
	i			confirm this fact. The POL Storage Yard is larger than shown.	
				Immediately north of the POL Storage Area is a "Category 3"	
	_			area. The NDI Laboratory is "Category 7" property.	
2-5	*	7	*	Refer to errata for page S-4.	
3-2	*	*	*	Remove all property improvements in the section of land	
				containing the Belton Training Complex property. No roads or	
	_			structures existed in 1955 within the section.	
3-4	*	*	*	Change the Belton Training Complex coding to "Industrial	
				Use."	
3-5	*	*	*	Change the NDI Laboratory coding to "Aviation Support."	
3-6	3.2	2	_5	Replace the term "sites" with "parcels."	
3-7	3.2	4	3-4	Replace "The effluent is heldand passed through" with "A	
				portion of the flight line area is served by a detention reservoir	
				(Facility 943) which processes effluent through"	
3-8	*	*	*	Add a surface impoundment 3/8" southwest of the POL Storage	
	_			Yard on this figure.	
3-12	3.3.1.2	bullet 2	9	Replace the term "rounds" with "shell casings."	
3-13	3.3.2	2	2	Replace "1983" with "September 1982."	
3-13	3.3.2	5	9-10	Replace the sentence "An interim removalSite SS006" with	
] ]				"Interim removal/remedial actions have been completed at sites	
				SS 003, SS 004, SS 006, ST 007 and SS 009."	



	<del></del>	<u>.</u>	T	m	
3-14	*	*	*	The size of site ST005 is larger than depicted. ST005 extends	
J		ļ	ļ	toward the southwest another 1/8". The size of site SS004 is	
				much smaller than depicted.	
3-15	3.3.2	2	2	Replace "six" with "seven."	
3-15	3.3.2	2	3	Replace "four" with "five."	
3-15	3.3.2	2	4	Add "SS009" to the list of sites.	
3-15	3.3.2	2	6	Replace "These five" with "Appropriate portions of these six	
				sites"	
3-15	3.3.2	2	9	Replace "and they are" with "therefore appropriate	
				portions of these sites are"	
3-15	3.3.3.1	2	8-9	Restructure the sentence by removing "but not confirmedat	
				IRP site ST007."	
3-15	3.3.3.1	2	9-10	Replace "both of these ASTs are" with "this AST is"	
3-16	3.3.3.2	1	2	Replace "remaining 29" with "less than half of the	
				remaining"	
3-16	3.3.3.3	3	13	Replace "are currently being" with "were"	
3-16	3.3.3.3	3	14	Restructure the sentence by removing "and may require further	
				investigation." Add the sentences "A large leak was discovered	
]				near building 942. The immediate area of the leak is	
1				considered Category 6, surrounded by a Category 7 buffer zone	
	_			which is scheduled for investigation."	
3-16	3.3.3.3	4	2-4	Remove the last sentence in this paragraph.	
3-16	3.3.4	1	1	Replace "oil, fuel, and grease" with "lighter-than-water	
				non-aqueous phase liquids"	
3-17	3.3.4	1 '	1	Replace "33 OWSs" with "nine (9) OWS systems"	
3-17	3.3.4	1	6	Replace "Ten" with "Five" and "OWSs" with "OWS	
				systems."	
3-17	3.3.4	1	9-11	Remove the last sentence in this paragraph. Replace with "One	
	-			OWS system is still operational and has not been closed in	
1				accordance with MDNR regulations. This OWS system is	
				considered Category 7."	
3-17	3.3.5	2	2-3	Remove the sentence beginning "However, no records", and	
				replace it with "In 1983, CH2M Hill reported (IRP Records	
]				Search) that based on a 1976 report, Chlordane was used at the	
J				rate of 220 gallons per year. Usage rates of other chlorinated	
			!	pesticides were also noted in this report. During the EBS	
				records search, the 1976 report was not available for review."	
3-17	3.3.5	3	2	Add "All buildings are therefore considered Category 2 with	
				respect to pesticide use based on normal pesticide usage."	
3-19	3.3.8	1	1-2	Remove the words/phrases "no significant", "either" and "water	
				or," Add "These areas are considered Category 6."	
3-19	3,3.8	3	2	Delete "and sediments."	
3-19	3.3.10	1	1-2	See errata for page S-4.	



3-19	3.4	1	2-4	Change the last sentence to read "Issues regarding these resources are discussed within Section 3.3 where appropriate."	
3-20	3.4.4	1	5-6	5-6 Replace "buildings" with "structures."	
4-6	*	Table 4-4	* Add a footnote to "Unable to locate*": " * A cluster of 7 tanks, now removed, existed northeast of 15403 Andrews Road (across Kensington Avenue) at an old demolished service station.		
4-8	*	Table 4-5	*	Remove all references to the Paint Stripper Hanger. The Paint Stripper Hanger is not a Formerly Used Defense Site. This area was not Air Force property when the contractor inspected it. The area noted in the study was already under investigation by the owner.	
6-3	*	*	*	Add to the List of Preparers: P. Mark Esch, BRAC Environmental Coordinator, U.S. Air Force, OLQ, AFBCA, B.S., Civil Engineering, 1987, University of Texas, Austin; Years of Experience: 5	

I certify that this errata sheet is correct and truthfully represents the environmental condition of property at Richards-Gebaur AFB, MO. The environmental condition of property was corrected based on available records, interviews, and sample results overlooked by the contractor preparing the EBS.

40 YAT 21


P. Mark Esch

**BRAC Environmental Coordinator** 

OL Q, AFBCA

cc: file: BEBS

**PME** 



**SUMMARY** 

This Environmental Baseline Survey (EBS) has been prepared to document the physical condition of real property at Richards-Gebaur Air Force Base (AFB), Missouri resulting from the storage, use, and disposal of hazardous substances and petroleum products and their derivatives over the installation's history, and to establish a baseline for use by the Air Force in making decisions concerning real property transactions. The preparation of an EBS is required by Department of Defense (DOD) policy before any property can be sold, leased, transferred, or acquired. Although primarily a management tool, this EBS will also be used by the Air Force in meeting its obligations under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), 42 United States Code Section 9620(h), as amended by the Community Environmental Response Facilitation Act (CERFA), Public Law 102-426.

This EBS is based on information obtained through a records search, interviews, and visual inspections. The records search included a review of all available Air Force and other agency records, including environmental restoration and compliance reports, audits, surveys, facility drawings, and inspection reports; an analysis of aerial photographs; and a review of recorded chain of title documents for the property. Interviews with employees and visual inspections of the base property and facilities were also conducted. The EBS also includes an assessment of the environmental condition of off-base properties contiguous to or relatively near the base that could pose environmental concern and/or affect the subject property. Physical inspections were conducted on off-base properties where access was obtained from the owner or operator.

Based on an analysis of the available data, property on Richards-Gebaur AFB was classified into one of seven categories:

- Category 1 Areas where no storage, release or disposal of hazardous substances or petroleum products has occurred (including no migration of these substances from adjacent areas)
- Category 2 Areas where only storage of hazardous substances or petroleum products has occurred (but no release, disposal, or migration from adjacent areas has occurred)
- Category 3 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but at concentrations that do not require a removal or remedial action

- Category 4 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, and all remedial actions necessary to protect human health and the environment have been taken
- Category 5 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, removal and/or remedial actions are under way, but all required remedial actions have not yet been taken
- Category 6 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but required response actions have not yet been implemented
- Category 7 Areas that are unevaluated or require additional evaluation.

Property in the first four categories would be eligible for deed transfer.

Property in the last three categories would not be considered for transfer until all necessary actions have been taken and the property has been reclassified into one of the first four categories. Leases would be considered on a case-by-case basis for properties within the last three categories.

#### **ON-BASE PROPERTY FINDINGS**

#### **Property Categorization Resources**

The following resources were used in property categorization. Each resource was categorized individually; findings for each resource were then reviewed to obtain the overall property category.

Category 2 through 7 properties were identified based upon the methodology presented in Chapter 2. All remaining areas were determined to be Category 1.

Areas that stored hazardous materials and/or generated hazardous waste were considered Category 2 unless a suspected or confirmed release was identified. These include dormitories and offices where it is likely that household or office products containing hazardous substances were stored.

Category 3 designations for the apron were based upon existing documentation (e.g., personnel interviews, visual site inspections, written information). Spills are known to have occurred on the apron area, but the spill reports indicate that releases were minor and all appropriate cleanup actions were taken. Contaminant levels, if present, are considered to be well below action levels.

أأف فالإنفادات أفياد

The rest of the last the state of the state

Areas where known or suspected contamination has occurred were classified as Category 4 through 7 properties based upon the current program status. In addition, new areas of potential contamination identified as a result of this EBS were classified as Category 7.

Hazardous Materials/Petroleum Products Management. Hazardous materials were stored and used at Richards-Gebaur AFB in connection with flightline, mission support, base support, and various industrial operations. The most commonly used hazardous materials included jet and motor fuels, other types of petroleum products, paints, thinners, adhesives, cleaners, lead-acid batteries, pesticides, hydraulic fluids, and halogenated and nonhalogenated solvents. Hazardous materials were stored or used at 13 locations throughout the base, of which 9 stored hazardous substances in quantities greater than 1,000 kilograms. Hazardous materials were also stored at 22 other facilities, but no data on types and quantities of materials stored was available.

Hazardous Waste/Petroleum Waste Management. Hazardous waste and waste petroleum products were stored at 25 locations throughout the base, including initial accumulation points and a central storage facility.

IRP Sites Identified to Date. Eight Installation Restoration Program (IRP) sites have been identified at Richards-Gebaur AFB and have been placed into one Operable Unit. Seven of the sites are in the Cantonment Area; the eighth site is at the Fire Training Area. Three IRP sites currently have No Further Action Planned status, and Decision Documents are under review by the U.S. Environmental Protection Agency and the Missouri Department of Natural Resources (MDNR). Three IRP sites have Preliminary Assessment/ Site Inspection status. One site has Remedial Investigation/Feasibility Study status and another is in the Remedial Design/Remedial Action phase.

Storage Tanks. Past and present locations of underground and aboveground storage tanks were identified. Storage tanks at Richards-Gebaur AFB have been used to store various petroleum products or wastes, and other miscellaneous products. There have been 36 aboveground storage tanks and 33 underground storage tanks utilized at Richards-Gebaur AFB. In addition, Richards-Gebaur AFB operated two hydrant fueling systems and one bulk fuel storage area.

Oil/Water Separators (OWSs). Past and present locations of OWSs were identified. There have been 33 OWSs utilized at Richards-Gebaur AFB.

Pesticides. Pesticides considered in this EBS include herbicides, fungicides, insecticides, and rodenticides. Pesticide control at Richards-Gebaur AFB is accomplished by a commercial pest control company. No bulk pesticides are stored or mixed, and no equipment is cleaned, on Richards-Gebaur AFB.

Medical/Biohazardous Waste. Medical/biohazardous wastes at Richards-Gebaur AFB have been generated at two facilities. The waste is disposed of off base by a licensed contractor.

Ordnance. The Small Arms Range will be cleared of any unexploded ordnance prior to base closure. Lead levels in the soil at the Small Arms Range were sampled in 1993, and found to be below regulatory action levels. Historic maps and findings from recent visual inspections indicate that ordnance disposal may have taken place at the Belton Training Complex.

Wastewater Discharges. Sanitary sewage effluent from Richards-Gebaur AFB discharges into the Little Blue Valley Sewer District. There are also three active septic tank systems with leach fields located on Richards-Gebaur AFB property.

To minimize contaminants entering the storm drainage or sanitary sewer systems, the base has a separate industrial waste sewer that serves some maintenance facilities and the flightline area. The effluent is stored in a detention reservoir and then passed through an OWS prior to being discharged into the Little Blue Valley Sewer District System.

Richards-Gebaur AFB has filed for a Discharge Permit (Forms E and F) with MDNR. In a recent study, sediment and surface water in major drainage swales and tributaries on the base were investigated for hazardous characteristics. No indications of significant contamination were found, and no remediation of sediment or surface water is required.

Radioactive and Mixed Wastes. There are no radioactive or mixed waste sites or issues at Richards-Gebaur AFB.

Solid Waste. There are no active landfills at Richards-Gebaur AFB, and no known historical landfills.

## Disclosure Resources

. + t

Disclosure resources (asbestos, polychlorinated biphenyls (PCBs), radon, and lead-based paint) were not used in property categorization.

Asbestos. A comprehensive basewide asbestos assessment study was completed in September 1987. The study included the 71 buildings on base at that time. Of the buildings surveyed, 39 were identified as having asbestos-containing material (ACM), and 32 buildings either had no suspected material found or all samples taken were negative for ACM. Facility 942 has been closed due to the condition of ACM.

William Co.

A Maintain Company of the Company of

44 114 114 11

Polychlorinated Biphenyls. All Air Force-owned transformers with 50 parts per million (ppm) or more PCBs have either been replaced with PCB-free equipment or retrofilled to bring the PCB concentration to below 50 ppm.

Radon. Based on radon samples taken by Cass and Jackson counties, the potential for radon greater than 4.0 picocuries per liter exists at Richards-Gebaur AFB. No radon surveys have been completed at Richards-Gebaur AFB because there is no family housing on base.

Lead-Based Paint. There are no residential or other high-priority facilities on base that present the risk of exposing children to lead-based paint. Facilities that were constructed prior to the implementation of the DOD ban on the use of lead-based paint in 1978 are likely to contain such paint.

#### **OFF-BASE PROPERTY FINDINGS**


Of the 16 contiguous properties surveyed, 10 were physically inspected. Based on the records search and site inspections of the properties conducted for this EBS, there are no areas on Richards-Gebaur AFB where it is known that contamination has resulted from activities on any of the off-base properties; however, areas of possible concern were noted on contiguous properties during the survey. Other than Formerly Used Defense Sites, no off-base parcels are known to have been contaminated from activities on Richards-Gebaur AFB.

#### PROPERTY CATEGORIZATION

As described previously, property on Richards-Gebaur AFB was classified into one of the seven categories based on the findings of the EBS (Figure S-1). Category 1 properties were identified in three vacant and undeveloped areas in the central, eastern, and southern portions of the Cantonment Area, as well as in the southern portion of the Belton Training Complex. Category 2 properties are present in the Cantonment Area in two small areas along the flightline, as well as in most of the central portion of the Cantonment Area. The northeastern and southern portions of the Weapons Bunker, and the access road, are also classified as Category 2 properties. Additional Category 2 properties have been identified as constituting all of the Billeting Complex and Contracting parcels. Category 3 properties consist of the apron area and one small area at the southern end of the flightline. No Category 4 properties were identified at Richards-Gebaur AFB. One Category 5 property was identified at an IRP site at the southern end of the Air Force parking apron. One Category 6 property was identified at an IRP site in the northeastern portion of the Cantonment Area.

Category 7 properties are present on much of the Cantonment Area: a large area in the northeast, along the northern portion of the flightline, in the east along 155th Street, and in three smaller areas in the central and southern

portions. Category 7 properties have also been identified as constituting all of the Air Traffic Transceiver, Fire Training Area, Small Arms Range, Non-Destructive Inspection Laboratory, Gun Storage, and Mobile Radio Transceiver parcels. In addition, Category 7 properties have been identified in the northwest and central areas of the Weapons Bunker and the northern portion of the Belton Training Complex.



Property (Category 1)

Hazardous substance stored - no release (Category 2)

Hazardous substance release, below action levels (Category 3)

Hazardous substance release,

all actions have been taken (Category 4)

all actions have been taken (Category 5)

Hazardous substance release, no actions taken (Category 6)

Areas requiring additional evaluation (Category 7)

Base Boundary

# Categorization

Figure S-1



71 × 13A

THIS PAGE INTENTIONALLY LEFT BLANK



TABLE OF CONTENTS

# TABLE OF CONTENTS

\*

				<u>Page</u>
1.0	PURPO	SE OF 1	THE ENVIRONMENTAL BASELINE SURVEY	. 1-1
	1.1		DUCTION	
	1.2	BOUND	DARIES OF THE PROPERTY AND SCOPE OF SURVEY AREA	. 1-3
2.0	SURVE	Y METH	HODOLOGY	. 2-1
	2.1	APPRO	ACH AND RATIONALE	. 2-1
		2.1.1	Description of Documents Reviewed	. 2-1
		2.1.2	Inspection of Properties Conducted	. 2-6
		2.1.3	Personnel Interviews	. 2-7
3.0	FINDIN	IGS FOR	BASE PROPERTY	. 3-1
	3.1		RY AND CURRENT USAGE	
	3.2		ONMENTAL SETTING	
	3.3		RTY CATEGORIZATION RESOURCES	
		3.3.1	Hazardous Substances	. 3-9
			3.3.1.1 Hazardous Materials/Petroleum Products Management	. 3-9
			3.3.1.2 Hazardous Waste/Petroleum Waste Management	
		3.3.2	IRP Sites Identified to Date	3-12
		3.3.3	Storage Tanks	3-15
			3.3.3.1 Aboveground Storage Tanks	3-15
			3.3.3.2 Underground Storage Tanks	3-15
			3.3.3.3 Pipelines, Hydrant Fueling, and Transfer Systems	
		3.3.4	Oil/Water Separator Systems	
		3.3.5	Pesticides	
		3.3.6	Medical/Biohazardous Waste	
		3.3.7	Ordnance	
		3.3.8	Wastewater Discharges	
		3.3.9	Radioactive and Mixed Wastes	
			Solid Waste	
	3.4		DSURE RESOURCES	
		3.4.1	Asbestos	
		3.4.2	Polychlorinated Biphenyls	
		3.4.3	Radon	
		3.4.4	Lead-Based Paint	3-20 •
4.0	FINDIN	IGS FOR	OFF-BASE PROPERTIES	. 4-1
	4.1	LAND	USES	. 4-2
	4.2	PROPE	RTY INSPECTIONS	. 4-2
5.0	CONC	LUSIONS	S	. 5-1
	5.1	PROPE	RTY MATRIX	. 5-1
	5.2		RTY ZONES	
	5.3		RCE MAP	
	5.4	DATA	GAPS	. 5-4
6.0	CERTIF	CATIO	N AND LIST OF PREPARERS	. 6-1

# TABLE OF CONTENTS (Continued)

# **APPENDICES**

~	Helelelices .
В	Sample Forms
С	Hazardous Materials Storage
D	Summary of Title Search
Ε	History of Facility Usage
۴	Hazardous Wastes Generated
G	Glossary of Terms, Acronyms, and Abbreviations

11 de 11

# LIST OF TABLES

	Page
Personnel Interviewed Hazardous Waste Accumulation Points Installation Restoration Program (IRP) Sites Aboveground Storage Tanks Underground Storage Tanks Oil/Water Separator Systems Facilities Surveyed for Asbestos Historic Locations of Transformers CERCLIS Sites RCRA Generators Emergency Response Notification System Report State Registered USTs Formerly Used Defense Sites Contiguous Property Parcel Descriptions Areas of Potential Environmental Concern Facility/Property Matrix - Richards-Gebaur AFB Property/Facility Key	3-21 3-26 3-27 3-28 3-30 3-31 3-33 . 4-5 . 4-5 . 4-6 . 4-7 . 4-9
LIST OF FIGURES	
	<u>Page</u>
Survey Areas Survey Areas Resource Layer Approach Major Land Use (1955) Major Land Use Changes (1966) 1993 Land Use Surface Hydrology Installation Restoration Program Sites Adjacent Property Map (Oversized)	. 1-6 . 2-2 . 3-2 . 3-4 . 3-5 . 3-8 3-14
	Hazardous Waste Accumulation Points Installation Restoration Program (IRP) Sites Aboveground Storage Tanks Underground Storage Tanks Oil/Water Separator Systems Facilities Surveyed for Asbestos Historic Locations of Transformers CERCLIS Sites RCRA Generators Emergency Response Notification System Report State Registered USTs Formerly Used Defense Sites Contiguous Property Parcel Descriptions Areas of Potential Environmental Concern Facility/Property Matrix - Richards-Gebaur AFB Property/Facility Key  LIST OF FIGURES  Survey Areas Resource Layer Approach Major Land Use (1955) Major Land Use Changes (1966) 1993 Land Use Surface Hydrology Installation Restoration Program Sites

THIS PAGE INTENTIONALLY LEFT BLANK



**CHAPTER 1** 

# 1.0 PURPOSE OF THE ENVIRONMENTAL BASELINE SURVEY

#### 1.1 INTRODUCTION

Purpose. This Environmental Baseline Survey (EBS) documents the physical condition of Air Force real property at Richards-Gebaur Air Force Base (AFB), Missouri resulting from the storage, use, and disposal of hazardous substances and petroleum products over the base's history. The EBS collects into a single document all available information to establish a baseline for use by the Air Force in making decisions concerning real property transactions.

Although primarily a management tool, the EBS also assists the Air Force in meeting its obligations under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), 42 United States Code (U.S.C.) Section 9620 (h), as amended by the Community Environmental Response Facilitation Act (CERFA), Public Law 102-426. An EBS is required by Department of Defense (DOD) policy before any property can be sold, leased, transferred, or acquired.

## The EBS helps the Air Force to:

- Develop sufficient information to assess the health and safety risks on the property surveyed, and determine what actions are necessary to protect human health and the environment prior to a real property transaction.
- Support decisions for Finding of Suitability to Lease/Finding of Suitability to Transfer and aid in determining lease or deed restrictions.
- Document and obtain regulator concurrence on uncontaminated property as required and defined under CERCLA Section 120(h)(4), identification of uncontaminated property.
- Support notice, when required under CERCLA Section 120(h)(1),
  of the type, quantity, and time frame of any storage, release, or
  disposal of hazardous substances or petroleum products on the
  property.
- Identify data gaps concerning environmental contamination.
- Define potential environmental liabilities associated with real property transactions.
- Aid in determining possible effects on property valuation from any contamination/concerns identified.

Content of Environmental Baseline Survey Report. The information for the EBS was obtained through a records search, visual inspections, and interviews. The records search included a title search, review of aerial photographs, and review of all available Air Force and other agency records including environmental restoration and compliance reports, records, audits, facility drawings, and inspections. Visual inspections of the base property and facilities were conducted. The EBS also includes an assessment of environmental conditions of off-base properties contiguous to or relatively near the base that could pose environmental concern and/or affect the subject property. Physical inspections were also conducted on contiguous off-base properties where access was obtained from the owner or operator. Where access was not permitted, visual inspections of off-base properties were conducted from base property or public roads.

Based on an analysis of the available data, the EBS categorizes property into one of seven categories:

- Category 1 Areas where no storage, release, or disposal of hazardous substances or petroleum products has occurred (including no migration of these substances from adjacent areas)
- Category 2 Areas where only storage of hazardous substances of petroleum products has occurred (but no release, disposal, or migration from adjacent areas has occurred)
- Category 3 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but at concentrations that do not require a removal or remedial action
- Category 4 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, and all remedial actions necessary to protect human health and the environment have been taken
- Category 5 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, removal and/or remedial actions are under way, but all required remedial actions have not yet been taken
- Category 6 Areas where storage, release, disposal, and/or migration of hazardous substances or petroleum products has occurred, but required response actions have not yet been implemented
- Category 7 Areas that are unevaluated or require additional evaluation.

Property in the first four categories would be eligible for deed transfer. Property in the last three categories would not be considered for transfer until the necessary actions have been taken and the property has been reclassified into one of the first four categories. Leases would be considered on a case-by-case basis for property within the last three categories.

Updates and Data Gaps. The EBS combines available information on the property's environmental condition into a single document. The EBS identifies data gaps in the available information, and sampling and analysis field efforts may be necessary to fill them. If possible, the Air Force will take action to fill the data gaps immediately at the time they are identified so that the EBS will be as complete and accurate as possible. Where it is not possible, the Air Force already has several programs under way to identify and characterize environmental contamination and the presence of hazardous substances that may provide the best vehicle for filling data gaps. In all cases, actions to fill data gaps will be accelerated wherever possible to support the disposal schedule. As efforts to characterize or remediate property at closing Air Force installations are completed, the EBS will be updated periodically to reflect the latest information.

Relationship to Other Documents: The comprehensive plan for the environmental restoration and closure of closing Air Force installations has been laid out by each installation in a Base Realignment and Closure (BRAC) Cleanup Plan (BCP). The plan for filling data gaps identified in the EBS will be incorporated into the BCP and updated periodically as actions are completed.

The Air Force is also preparing an Environmental Impact Statement (EIS) on the conversion and reuse process for Richards-Gebaur AFB. Although this document may contain some of the same information, it serves a different purpose. The Conversion and Reuse EIS for Richards-Gebaur AFB analyzes the impacts of disposal and reuse on the environment while the EBS documents the environmental condition of the property.

## 1.2 BOUNDARIES OF THE PROPERTY AND SCOPE OF SURVEY AREA


The EBS at Richards-Gebaur AFB was based on a review of information available for the visual and/or physical inspection of (1) property on Richards-Gebaur AFB, (2) property immediately off base (i.e., having a contiguous border with the base boundary), and (3) property within approximately 0.25 mile to 2.5 miles of the base boundary with potential environmental concerns. The results of the survey for on-base and off-base properties are discussed in Chapters 3 and 4, respectively.

Richards-Gebaur AFB, scheduled to close on September 30, 1994, is located 18 miles south of Kansas City, Missouri and 2 miles northwest of Belton, Missouri, and has property in both Cass and Jackson counties. Richards-Gebaur AFB is composed primarily of the Cantonment Area, the Belton

Training Complex, and several non-contiguous parcels. The Belton Training Complex is 4 miles south of the Cantonment Area. The other noncontiguous parcels, which are close to the Cantonment Area, are as follows: Small Arms Range, Billeting Complex, Air Traffic Transceiver, Weapons Bunker, Gun Storage, Contracting, Non-Destructive Inspection (NDI) Laboratory, Mobile Radio Transceiver, and Fire Training Area. Figure 1-1 depicts the parcels that make up Richards-Gebaur AFB.

The area that is now Richards-Gebaur AFB was used as an airport under the control of Kansas City from 1941 to 1953, when approximately 2,400 acres were conveyed to the U.S. government for establishment of an Air Force base. In August 1985, 1,360 acres of Richards-Gebaur AFB were conveyed to Kansas City to support operation of a civilian airport. Since then, the U.S. Air Force Reserve at Richards-Gebaur AFB has conducted aviation operations at Richards-Gebaur Airport under a joint use agreement with Kansas City. The scope of this EBS includes only the property currently held by Richards-Gebaur AFB.

For purposes of this document, adjacent property is defined as those properties contiguous with the existing base boundary, and/or any property that was considered within Richards-Gebaur AFB boundaries (see Figure 1-1a and b) prior to conveyance to Kansas City.



**EXPLANATION** 

Contiguous Parcel Boundary


--- Base Boundary

**Survey Areas** 





Figure 1-1a



**EXPLANATION** 

----- Contiguous Parcel Boundary

--- Base Boundary

**Survey Areas** 





*?.* .:

Figure 1-1b



CHAPTER 2

# 2.0 SURVEY METHODOLOGY

The methods used to conduct the EBS of Richards-Gebaur AFB are described in this chapter.

## 2.1 APPROACH AND RATIONALE


The EBS followed a methodical process in which the information available was analyzed and conclusions were drawn about the condition of the property. First, real property records, land use maps, facility drawings, and aerial photographs were reviewed to identify historical land and facility uses, a primary indicator of potential contamination. Areas of the base where industrial processes occurred; solid and hazardous wastes were stored, disposed of, or released; and hazardous materials were stored received the closest scrutiny. A review of recorded chain of title documents was also conducted to assess if any prior uses could reasonably have contributed to existing environmental concerns Next, CERCLA and Resource Conservation and Recovery Act (RCRA) studies and field investigations were reviewed to identify areas where the presence (or absence) of contamination had been confirmed. Then records from industrial shops, base supply, the fire department, the bioenvironmental engineer, environmental audits or surveys, and other federal and state agencies were reviewed to identify any other areas of concern. Types of surveys reviewed included asbestos-containing material (ACM), lead-based paint, and radon, where available (see Appendix A). Finally, past and present employees were interviewed and physical inspections of the property and facilities were conducted to identify any additional evidence of spills, stressed vegetation, i.e., anything that might indicate contamination.

The result is a collection of all available information into "layers" that, when laid over each other, provide a complete picture of the property's condition that enables the researchers to categorize the property into defined environmental condition categories and identify data gaps (Figure 2-1).

The major components of the analysis included a documents review (including interpretation of aerial photographs), inspections of on-base property, interviews with current and former personnel, and a chain of title review. Each of these components is described below. The approach for conducting the evaluation of off-base properties is presented in Chapter 4.

#### 2.1.1 Description of Documents Reviewed

The records search of available documentation focused primarily on records, reports, and maps maintained by the base Engineer, the Bioenvironmental



Resource Layer Approach

Figure 2-1

Engineering technician, and the 442nc Environmental Management Office. Most of the files and records pertained to activities that have occurred since 1980.

Various studies, investigations, and inspections that consider environmental conditions at the base, including regulatory compliance issues, have been conducted by the Air Force and other federal and state agencies in the past several years. The results of these studies and investigations provided the initial baseline used in developing this EBS and are referenced throughout this document. The primary types of studies or investigations include the following:

- Installation Restoration Program (IRP) studies
- Basewide environmental and infrastructure studies.
- RCRA Facility Assessments (RFAs)

٠.

- Air Force Environmental Compliance Assessment and Management Program (ECAMP) reports
- Underground storage tank (UST) investigations
- National Environmental Policy Act (NEPA) documentation
- Federal, state, and local documentation.

As part of the records search, a number of historic maps, facility drawings, and aerial photographs were reviewed and analyzed to assist in identifying past land uses and potential environmental contamination sources, and to verify other information found in the records search. Maps reviewed covered the period from 1962 to the present. The primary map resources reviewed included the Base Comprehensive Plan series (scale of 1 inch = 400 feet), the Utility Block Map series (scale of 1 inch = 50 feet), the Detailed Utilities Map ECAMP series, and design and as-built engineering drawings for specific industrial facilities (as necessary).

The types of documents and records reviewed for each environmental medium are described below. A detailed list of references used in preparing this EBS is presented in Appendix A.

Hazardous Materials/Petroleum Products Management. Activities within office areas and dormitories likely required the use of small quantities of hazardous materials, such as ammonia and other cleaning supplies. Hazardous materials usage in specific industrial facilities was determined through a review of Industrial Workplace Case Files maintained by the Bioenvironmental Engineering Services office. Specific items reviewed in

each case file included historic and current Industrial Hygiene Sampling Data forms (Air Force Form 2750), Bulk Material Sampling Data forms (Air Force Form 2751), Chronological Records of Workplace Surveillance (Air Force Form 2754), Industrial Hygiene Survey Data Sheet - General forms (Air Force Form 2758), Hazardous Materials Data forms (Air Force Form 2761), and relevant correspondence (e.g., Memoranda to the Record) contained in the files related to hazardous materials exposure. Sample forms are provided in Appendix B. Specific hazardous materials exposure incidents (e.g., spills or accidents) were noted and discussed with Bioenvironmental Engineering Services personnel.

A cumulative hazardous materials inventory was developed for each workplace based on a review of Hazardous Material Data forms listing all hazardous materials used in a particular workplace. Information on hazardous materials handling, including disposal methods, was also derived from a review of workplace case files. Information contained in these files generally covered the period from the 1980s to the present.

Hazardous Waste/Petroleum Waste Management. Hazardous waste disposal practices were defined based on a review of the Richards-Gebaur AFB Hazardous Waste Management Plan, hazardous waste log entries, IRP documents, and other documents contained in the base files. Information on hazardous waste collection and disposal procedures was obtained from interviews with base personnel. An inventory of locations where hazardous wastes were stored (e.g., initial accumulation points) was compiled based on a review of this information.

IRP Sites Identified to Date. The analysis of IRP sites consisted of a review of all Richards-Gebaur AFB IRP documents, including the Phase I, Phase II studies, Preliminary Assessments/Site Inspections (PA/SIs), Remedial Investigations (RIs), and Decision Documents. Base files related to the IRP were also reviewed and interviews were conducted with base personnel responsible for implementing IRP activities.

Storage Tanks. An inventory of existing and historic aboveground storage tanks (ASTs) and USTs and associated piping was compiled from various sources. Sources included IRP reports, UST data sheets, Real Property Accountable Records, facility drawings, Air Force Forms 2751, and base maps. Additional information was obtained through interviews with knowledgeable personnel and visual site inspections (VSIs).

Oil/Water Separators (OWSs). An inventory of existing and historic OWSs was compiled. The sources of information on OWSs are identical to those used for storage tanks, because OWSs are regulated as USTs in Missouri and must conform to all UST technical standards.

Maria de la composición della composición della

الأزالا إرخالا

. . . 4

Pesticides. For purposes of this document, pesticides include herbicides, fungicides, insecticides, and rodenticides. Information on pesticide use was obtained by contacting the private contractor responsible for pesticide management at Richards-Gebaur AFB.

Medical/Biohazardous Waste. Information on the generation and disposal of medical/biohazardous waste was obtained from the Bioenvironmental Engineering Services office, and from documents in the base files.

Ordnance. Interviews, a records search of Civil Engineering files, and VSIs have been used to determine sites on base where the disposal of ordnance may have resulted in residual soil contamination. Sites on the base where the use of firearms may have resulted in potential lead contamination were identified through a review of historic and current real property records, the Firing Range Phase II report, installation maps, and VSIs.

Wastewater Discharges. A review of the base files and various published documents was conducted to determine wastewater treatment and disposal practices on the base. Currently, all sanitary wastewater generated on Richards-Gebaur AFB is discharged to the Little Blue Valley Sewer District.

In addition to the sanitary sewer system, the base has three septic tank systems with leach fields. An inventory of historic and existing septic tank systems was compiled from a review of current and historic Sanitary Sewer System maps, the Utility Block Map series, the Real Property Accountable Records, other historic maps and facility-specific drawings, and various listings and documentation contained in the base files.

Radioactive and Mixed Wastes. Information on radioactive materials and mixed waste was obtained from the IRP documents, the Real Property Accountable Records, and the base Engineer and Bioenvironmental Engineering files.

Solid Waste. Richards-Gebaur AFB currently has no active on-base landfills. Information on current and past solid waste disposal practices was obtained from the local solid waste collection agencies.

Asbestos. Information on facilities with ACM at Richards-Gebaur AFB was obtained from the 1987 Asbestos Assessment Study. Additional ACM information was found in the Real Property Accountable Records.

Polychlorinated Biphenyls (PCBs). Information on PCB-containing equipment on the base was obtained from the base personnel at Civil Engineering, and from various documents in the base files.

Radon. Because there is no family housing at Richards-Gebaur AFB, no radon studies have been conducted. Results of radon studies conducted by the Missouri Bureau of Environmental Health were obtained.

Lead-Based Paint. Real Property Accountable records were reviewed to identify facilities constructed prior to or during 1978, which may potentially contain lead-based paint.

## 2.1.2 Inspection of Properties Conducted

Visual reconnaissance surveys (VRSs) and VSIs were performed during the EBS analysis. General VRSs were conducted over large areas of the base to identify areas with potential environmental contamination or concerns. For some areas of the base, the VRSs consisted of only a windshield survey. More focused VSIs, involving exterior and interior (walk-through) inspections, were conducted at most facilities on the base, including all industrial facilities, to identify readily apparent concerns or attributes.

The VSIs of most facilities on the base were conducted to determine or confirm the presence of environmental contamination or concerns, including unusual odors, stained soils, stressed vegetation, leachate seeps, or other indications of potential contamination (See Table 5-1). VSIs were conducted for all industrial facilities and most administrative and community (including commercial) facilities. Each facility was evaluated for unique characteristics and potential environmental concerns. The base Real Property Accountable Records (Air Force Forms 1430-1433) were reviewed to identify specific facility characteristics, such as construction materials, utility hookups, renovations, changes in facility utilization, and distinctive features (e.g., emergency electric power generators or storage tanks). More detailed inspections were conducted at those facilities that had been used for industrial purposes or that included specific features such as storage tanks, OWSs, septic tanks, or IRP sites. For many of the administrative and community facilities, only a general walk-through of each facility was conducted.

A list of facilities on base summarizing key characteristics and facility-specific environmental information is presented in Table 5-1. A copy of the form used during the VSIs is presented in Appendix B.

For those facilities that contain industrial workplaces tracked by the Bioenvironmental Engineering Services office, a summary of workplace environmental data related to hazardous material use was compiled based on a review of the industrial workplace case files. Some facilities contain multiple industrial workplaces. The summary of workplace environmental data includes a cumulative inventory list of the hazardous materials known to have been used in each facility based on available documentation (Appendix C).

#### 2.1.3 Personnel Interviews

Primary contacts made during the conduct of the EBS were with personnel from the base civil engineer, the 442nd Bioenvironmental Engineering office, Intelcom Services, and 442nd Environmental Management. Principal Civil Engineering contacts were made with Environmental and Real Estate personnel; contact was also made with the Fire Department and Operations personnel. Personnel from the Supply Squadron and Liquid Fuels maintenance were also contacted.

During the records search and VSIs, interviews were conducted with base personnel to identify potential environmental concerns related to recent and historic operations at Richards-Gebaur AFB and to verify information found in the records search. A list of personnel interviewed is provided in Table 2-1. In addition to those personnel listed in the table, many other technicians, including facility managers, were interviewed.

Table 2-1. Personnel Interviewed

Organization	Interviewed		
442nd Logistics Group			
Support Squadron	1 Civilian		
Maintenance Squadron	3 Senior Master Sergeants, 1 Technical Sergeant, 1 Master Sergeant, 1 Civilian		
442nd Medical Group  Medical Group/Environmental Health	3 Civilians		
442nd Operations Group Operation Support Squadron	2 Civilians		
442nd Support Group			
Civil Engineering Squadron	3 Civilians, 1 Captain		
Security Police Squadron	2 Civilians, 1 Master Sergeant		
Services Squadron	6 Civilians		
Communications Squadron	4 Civilians		
442nd MWR	2 Civilians		



CHAPTER 3

# 3.0 FINDINGS FOR BASE PROPERTY

This chapter of the EBS presents the findings of the records search, VSI, and personnel interviews for on-base properties. Section 3.1 provides a history of the base, while Section 3.2 gives a description of the environmental setting of the base, including utilities. Sections 3.3 and 3.4 describe resource findings and conclusions. Overall property categorization is presented in Chapter 5. Resources within Section 3.4 are disclosure issues only and are not used in property categorization.


Based on a review of existing documentation and/or the VSI, some sites were identified as potentially requiring remediation. If necessary, remediation of sites not currently undergoing restoration will be accomplished as part of the IRP or other environmental programs.

The data within each resource have been organized into tables, which are provided after Section 3.4.4. The Resource Map is provided as Figure 5-1 in Section 5.3. The data listed in the tables and shown on the resource map are based on information obtained from Richards-Gebaur AFB during the records search and VSI. Because historic data were incomplete, data gaps are shown as unknown or are footnoted at the bottom of the tables.

### 3.1 HISTORY AND CURRENT USAGE

The area now known as Richards-Gebaur AFB was initially acquired by Kansas City in 1941 as an auxiliary airport and was named Grandview Airport. In 1952, the Air Force leased Grandview Airport from Kansas City for the location of the Central Air Defense Command headquarters. In 1953 the property was formally conveyed to the U.S. government, and in 1955 the site became Grandview AFB. The base was renamed in 1957 to honor First Lieutenant John F. Richards II, who died in combat in World War I, and Lieutenant Colonel Arthur W. Gebaur, Jr., who was killed during the Korean War. Both pilots were natives of Kansas City.


Prior to 1941, the Richards-Gebaur AFB area consisted of farmland. Grandview Airport was leased to the Air Force with some development, but the Air Force built the majority of the buildings and pavement. Major land uses associated with Grandview AFB in 1955 included the airfield, which may have included only the cross-wind runways; aviation support areas, which consisted of a mobile radio transceiver, aircraft maintenance hangar, and the fire station; a maintenance and engineering area, and a billeting complex (Figure 3-1).



In the late 1950s and early 1960s, the Air Force purchased additional property adjacent to the base to lengthen the primary runway and develop family housing areas. Flightline facilities were built and a golf course was developed in 1962. Major land use changes during this time included the enlarged airfield land use; adjacent hangars and aircraft maintenance facilities; industrial land uses associated with a small weapons bunker and NDI laboratory adjacent to the airfield, and the larger storage annex south of the base; and a small arms range in the northeast portion of the base (Figure 3-2). The family housing units were added in 1959 and 1960. At about the same time, the Air Force also purchased a site in the center of an undeveloped section 4 miles south of the base in Cass County, and an associated 287-acre safety easement for weapon storage.

Richards-Gebaur AFB remained an Air Defense Command base until 1970. when the Air Force Communications Command relocated its headquarters from Scott AFB, Illinois to Richards-Gebaur AFB. In 1977, the Air Force Communications Command returned to Scott AFB, and the Military Airlift Command assumed control of the base. The area now known as the Belton Training Complex was made into a drop zone for training, retaining the safety easement. Between 1977 and 1979, the number of active duty military and civilian personnel at Richards-Gebaur AFB was drastically reduced, with the majority of the operations support functions performed by civilian contractors. In August 1985, 1,360 acres of Richards-Gebaur AFB, including the airfield, were conveyed to Kansas City, and this property was named Richards-Gebaur Airport. The Air Force retained approximately 428 acres in 11 parcels, as well as a 106-acre easement surrounding the Weapons Bunker southeast of the airfield and a 20-acre area associated with the Small Arms Range. Since that time, the U.S. Air Force Reserve has operated at the Richards-Gebaur Airport under a joint use agreement with the Kansas City Aviation Department.

Few changes have occurred on base since 1985. The 1993 land uses include aviation support areas associated with aircraft maintenance and storage hangars and the Mobile Radio Transceiver and Air Traffic Transceiver; and industrial areas, including the Small Arms Range, Weapons Bunker, Fire Training Area, and an expanded engineering and maintenance area within the Cantonment Area (Figure 3-3). In addition, there are institutional (medical) land uses associated with medical supply and training functions, and institutional (education) land uses associated with the drop zone or Belton Training Complex. Other land uses include commercial office and retail areas within the Cantonment Area, residential areas associated with ball fields, and open space along Scope Creek. The rest of the base areas are undeveloped.



35.00

The area that now comprises Richards-Gebaur AFB includes property acquired by fee purchase or Declaration of Taking between 1941 and 1960. Three parcels were excessed by the Air Force between 1974 and 1979.

A recorded chain of title search was conducted for on-base parcels to determine prior ownership or uses that could reasonably have contributed to an environmental concern. A review of the data obtained from the title search did not identify any areas of environmental concern related to past property usage. The title search included ownership of parcels from June 1933 through June 1993. These parcels are described in Appendix D.

Historical facility usage at the base was also researched. Facilities that were converted to accommodate different uses, as well as facilities that have been demolished, are listed in Appendix E.

# 3.2 ENVIRONMENTAL SETTING

Richards-Gebaur AFB is in west-central Missouri, approximately 3 miles from the Kansas state line (see Figure 1-1). The base property is divided by the Jackson and Cass County line, running east-west. The base is surrounded by Kansas City. To the northeast is the city of Grandview, and to the east and south, in Cass County, is the city of Belton.

Richards-Gebaur AFB encompasses approximately 428 acres. Air Force property consists of a Cantonment Area and ten non-contiguous parcels. Two of these parcels are located in the City of Belton, and the Belton Training Complex is located in an unincorporated area of Cass County approximately 4 miles south of the base. The remaining outlying sites are located within the City of Kansas City, near the Cantonment Area.

The topography of the area consists of rolling hills with elevations varying from 960 to 1,125 feet above mean sea level. The base is situated on the south-central portion of a broad plateau known as the Blue Ridge.

West-central Missouri exhibits a modified continental climate with rapid weather changes. Mean monthly temperatures range from 26 degrees Fahrenheit (°F) in January to 78°F in July, with an average annual temperature of 54°F. Precipitation in the area averages about 37 inches, with the majority falling in the late spring and early summer and again in the early fall. Tornados and thunderstorms are common in the spring and summer.

The utilities provided to Richards-Gebaur AFB are briefly described below.

Water Supply. The Kansas City Water and Pollution Control Department provides water to Richards-Gebaur AFB via two water mains that feed from Missouri Highway (M-)150 and Botts Road to the northern edge of the

airfield. These mains are a 12-inch and an 8-inch pipeline that both feed into a city meter pit on the south side of M-150. A 12-inch outlet from the meter pit feeds a 1,060,000-gallon and a 50,000-gallon in-ground tank. These tanks and the 12-inch main feed the water department's pump station, Facility 938.

The system distributes water through 12-inch output mains to provide the base domestic water and fire protection needs. This system supplies two additional storage tanks: a 320,000-gallon in-ground tank located near the flightline for fire protection (owned and operated by Kansas City), and an elevated 400,000-gallon steel tank at the south end of the system to provide pressure.

Wastewater. Wastewater generated on base is collected and discharged to the Little Blue Valley Sewer District Interceptor B. Interceptor B is a 12-inch pipeline that runs parallel to and west of U.S. 71 before heading west along M-150 and then turning southwest and onto the base. Sanitary sewers on base consist of 6-inch to 18-inch reinforced concrete pipes. Three active septic systems serve remote ancillary buildings.


To minimize contaminants entering the storm drainage or sanitary sewer systems, the base has a separate industrial waste sewer that serves some maintenance facilities and the flightline area. The effluent is held in a detention reservoir (Facility 943) and passed through an OWS prior to being discharged into the Little Blue Valley Sewer District system.


Drainage Patterns. The airfield and on-base storm drainage facilities consist of a combination of open channels and closed drainage systems. The closed drainage systems include pipes ranging in diameter from 18 inches to 66 inches. All base stormwater drains into Scope Creek, which flows into the Little Blue River, which flows from southwest to northeast (Figure 3-4).

**Solid** Waste. Solid waste generated on Richards-Gebaur AFB is hauled off base by a commercial hauler and deposited in the Johnson County landfill in Shawnee, Kansas. Medical wastes are collected and disposed of off base by a private contractor.

Electricity. Missouri Public Service provides electricity to Richards-Gebaur AFB through two substations: the north substation, which has a 3,750-kilovolt ampere (kVA) capacity and provides primary service to the Cantonment Area, and the 7,500-kVA south substation. Electrical power is delivered to the north substation at 34.5 kilovolts (kV), and to the south substation at 69 kV. A combination of overhead and underground lines distribute electricity to the base buildings.

Natural Gas. Gas Service, a division of Western Resources, Inc., provides natural gas to the base via two high-pressure pipelines. A 4-inch pipeline





2000 Feet

Figure 3-4

and the state of t

runs east-west along 155th Street and an 8-inch pipeline runs east-west along Markey Road. The 8-inch pipeline is a supplemental service used under low pressure conditions.

A natural gas-fired central heating plant with four boilers is operated by Kansas City and provides steam to some buildings on Richards-Gebaur AFB. Typically one boiler is operated during the winter months; a second boiler is brought on-line during unusually cold weather.

# 3.3 PROPERTY CATEGORIZATION RESOURCES

The following section describes resources used in property categorization. Items within each resource have been given a specific resource category. Findings for each resource were then reviewed to obtain the overall property category (see Table 5-1).

Category 2 through 7 properties were identified based upon the methodology presented in Chapter 2. All remaining areas were determined to be Category 1.

Areas where hazardous materials were stored and/or hazardous wastes were generated were considered Category 2 unless a suspected or confirmed release was identified. These areas include dormitories and offices where it is likely that household or office products containing hazardous substances were stored.

Category 3 designations for the apron were based upon existing documentation (e.g., personnel interviews, VSIs, written information). Spills are known to have occurred on the apron area, but the spill reports indicate that releases were minor and all appropriate cleanup actions were taken. Contaminant levels, if present, are considered to be well below action levels.

Areas where known or suspected contamination has occurred were classified as Category 4 through 7 properties based upon the current program status. In addition, new areas of potential contamination identified as a result of this EBS were classified as Category 7.

# 3.3.1 Hazardous Substances

### 3.3.1.1 Hazardous Materials Petroleum Products Management

Hazardous materials commonly used at Richards-Gebaur AFB include aviation and motor fuels, various grades of petroleum, oils, and lubricants (POL), hydraulic fluids, cleaning solvents and corrosives, paints, thinners, pesticides, and batteries. Base records were reviewed to identify quantities and types of hazardous materials stored in base facilities. Appendix C provides historical data on hazardous materials (including types and

quantities) for facilities where these substances are known to have been stored (Table C-1).

Of the 13 facilities on base for which data on storage of hazardous materials was available, 9 stored more than 1,000 kilograms (kg), or the substance's CERCLA-reportable quantity (Table C-2). Based on the usage of a facility or on information obtained during the VSIs, it was determined that hazardous materials were also stored at 22 other facilities, although complete data on types and quantities of materials stored or used at these facilities were not available. Figure 5-1 shows the locations of facilities where hazardous materials were stored. All facilities where hazardous materials were used or stored and the specific resource categories for these facilities are listed in Table 5-1.

Based upon the methodology presented in Chapter 2, no evidence of a release occurring was identified at any of the facilities; therefore, all 13 are considered Category 2. Any release potentially above action levels, resulting in a possible site inspection or remedial action, is discussed within Hazardous Waste Petroleum Waste Management or IRP Sites Identified to Date (Sections 3.3.1.2 and 3.3.2, respectively). Petroleum products are discussed in Section 3.3.3.

# 3.3.1.2 Hazardous Waste/Petroleum Waste Management

The following discussion relates to management practices and facilities used pursuant to the requirements of RCRA (40 Code of Federal Regulations [CFR] 261-265, enacted in 1978). Waste management practices in use prior to RCRA's requirements are, to the extent that they caused or contributed to environmental contamination, primarily the subject of the Air Force's IRP. Hazardous wastes generated at Richards-Gebaur AFB include solvents, POL, fuel wastes, photochemical wastes, batteries, asbestos waste, PCB spills, and wastes generated from site remediation. The state of Missouri also regulates waste oil as a hazardous waste under 10 Code of State Regulations (CSR) 25-11.010. Base records were reviewed to identify quantities and types of hazardous wastes generated or stored in base facilities. Hazardous wastes and/or petroleum wastes were stored or generated at 25 facilities on base. An historical overview of accumulation points and types of wastes stored at Richards-Gebaur AFB is provided in Table 3-1. Appendix F gives historical data on hazardous waste generated by facility. Figure 5-1 shows the locations of facilities in which hazardous wastes were generated or stored.

The base Environmental Engineer is responsible for hazardous waste management at Richards-Gebaur AFB. Richards-Gebaur AFB is a small-quantity generator (less than 1,000 kg per month) and stores hazardous waste at 21 designated accumulation points. Currently, there are 20 Initial Accumulation Points (IAPs) and one central hazardous waste storage facility

on base (Facility 973). Hazardous wastes can be stored in the IAPs in amounts up to a maximum of 55 gallons for up to 1 year from the start of accumulation. After one of these criteria is met, the hazardous waste is transferred to Facility 973, where it is held pending off-base disposal. Richards-Gebaur AFB disposes of hazardous waste in cooperation with the Defense Reutilization and Marketing Office (DRMO), located at Whiteman AFB, Missouri. DRMO arranges for a licensed contractor to remove hazardous waste off base to a treatment, storage, and disposal (TSD)-permitted treatment facility or to a TSD-permitted landfill. Hazardous waste is shipped off base in compliance with Missouri Department of Natural Resources (MDNR) and RCRA regulations; shipments and pertinent paperwork are regularly inspected by DRMO for conformity with applicable regulations. Upon base closure all accumulation points will be closed in accordance with federal, state, and local regulations. Facility 973 will be closed in accordance with RCRA guidelines.

A review of aerial photographs identified a number of areas at Richards-Gebaur AFB where a VRS should be conducted. Upon completion of the area VRSs, one site located in a wooded area directly north of the POL tank farm was recommended for further investigation to determine the presence or absence of contamination. The site is a former dump site that contains construction rubble, lumber, and general refuse deposited among the trees.

All facilities that generated or stored hazardous wastes were physically inspected in April 1993. Areas of potential environmental contamination found are described below:

- A large POL surface stain entering a site drainage ditch was noted west of Facility 704 along the fenceline.
- Several stained areas associated with equipment and oil drum storage were noted at Facility 924.
- Minor to moderate staining was noted inside Facility 918, and an area of stressed vegetation was identified just north of the facility.
- At Facility 965, three areas of potential contamination were noted: moderate petroleum stains inside the mechanical room, which continued to the building exterior; an area of stressed vegetation near the southwest corner of the building; and an area of stressed vegetation east of Facility 965.

A VSI of the Belton Training Complex discovered several areas with debris including 55-gallon drums, old car batteries, lumber, a 250-gallon AST, and tires. Additionally, records review indicated that a blasting area and a demolition pit were present at the Complex. Results of the VSI are described below.

- An area designated as the "Training and Burning Area" (C-1 Tab map, 1967) is a circular area approximately 200 feet in diameter on a slight north-facing slope. This area, which is highly eroded through the center and on the north (downhill side), is located along and drains into the stream channel in the northeast portion of the Complex. The area contained two piles of burned ammunition; each pile is approximately 3 feet in diameter and estimated to be 2 to 3 inches deep. These piles contained mostly rifle rounds.
- An area designated as a "Blasting Area" (C-1 Tab, 1967) was inspected, and no evidence of blasting was identified; the area was heavily vegetated.
- A stone cistern was discovered along an active stream bed on the Belton Training Complex/easement property line approximately 400 feet south of the access road. The cistern was estimated to be 6 feet in diameter and 3 feet deep and was likely used to provide water for cattle.

A project is in progress to determine the extent of mercury contamination in the plumbing of Facility 604 (former dental/medical office), which has been closed by the Bioenvironmental Engineering Branch due to health concerns, and the interior was not visually inspected.

Based upon the methodology presented in Chapter 2, no evidence of a release occurring was identified at 22 of the facilities where hazardous waste has been stored or generated; therefore, these facilities are considered Category 2. At the other three facilities, staining and/or stressed vegetation was noted during the VSI, and these facilities are considered Category 7. Specific resource categories for facilities where hazardous wastes were stored or generated are listed in Table 5-1. Petroleum products are discussed in Section 3.3.3.

#### 3.3.2 IRP Sites Identified to Date

The IRP was established to identify, characterize, and remediate CERCLArelated contamination on Air Force installations. The program is designed to evaluate past disposal sites, control the migration of contaminants, and control potential hazards to human health and the environment.


The IRP at Richards-Gebaur AFB was initiated in 1983. Since that time, eight sites of past contamination have been identified. The locations of the eight IRP sites are shown in Figures 3-5 and 5-1. A brief description of each site is presented in Table 3-2.

The 1983 Phase I Records Search identified nine potential disposal sites. Of these, seven were on property that was transferred from the Air Force in 1981; the U.S. Army Corps of Engineers has responsibility for remediation of these sites (see Table 4-5). The other two sites (FT-002, a former fire training area, and SS-003, an oil saturated area) are on Air Force property and are part of the continuing IRP at Richards-Gebaur AFB. The Phase I Records Search found no evidence to indicate the presence of contamination at the Belton Training Complex or migration of contamination onto off-base property.

Phase II studies in 1988 identified one additional site (SS-004, a hazardous waste drum storage area). A 1990 Site Inspection (SI) identified Site ST-005 (the POL Storage Yard) and Site SS-006 (Facility 927, a hazardous material storage area). Site ST-007 (USTs at Facility 902) was discovered in 1988 at the time of a UST removal project. Sites SS-008 (the test cell area) and SS-009 (the fire valve area) were identified during soil excavation projects in 1991 and 1992, respectively.

No Further Action Planned Decision Documents have been submitted to MDNR and the U.S. Environmental Protection Agency (U.S. EPA) for sites SS-003, SS-004, and ST-007, and the base is awaiting comments or concurrence on these three sites. A No Further Action With Deed Restriction Decision Document was filed for Site FT-002 in 1990, but it was rejected by MDNR and U.S. EPA. A 1992 RI detected no groundwater contamination, and no further action for groundwater is recommended at FT-002. Remedial action consisting of landfarming is anticipated at Site ST-005, which is in the Remedial Design stage. An interim removal action has taken place at Site SS-006. An SI at Site SS-008 has been completed and a final report is anticipated in the near future. Site SS-009 was identified in 1992 during a trenching operation to repair a water line. Contaminated soil from an unconfirmed source was identified; no further information is available.

In addition to the mandates of the IRP, prior to the transfer of any property at Richards-Gebaur AFB, the Air Force must also comply with the provisions of CERCLA Section 120(h). CERCLA Section 120(h) requires that, before property can be transferred from federal ownership, the United States must provide notice of specific hazardous waste activities on the property and include in the deed a covenant warranting that "all remedial action necessary



EYDI ANATION	

**IRP Sites** 

--- Base Boundary

	int olics
Site No.	Site Name
FT-002	North Burn Pit
SS-003	Oli Saturated Area
SS-004	Hazardous Waste Drum Storage
ST-005	POL Storage Yard
SS-006	Hazardous Material Storage Building

SS-006 Hazardous Material Storage Building 9 ST-007 Underground Storage Tanks SS-008 Test Cell Area

SS-008 Test Cell Area SS-009 Fire Valve Area

0 500 1000 2000 Feet

Installation Restoration Program Sites

Figure 3-5

tā tula kira di

Landelle Lan

to protect human health and the environment with respect to any [hazardous] substance remaining on the property has been taken before the date of such transfer." Furthermore, the covenant must also warrant that "any additional remedial action found to be necessary after the date of such transfer shall be conducted by the United States."

Eight IRP sites have been identified at Richards-Gebaur AFB. Contamination has been confirmed at six of the sites; investigations are ongoing at the other two. Interim remedial actions have been taken at four of the sites (SS-003, SS-004, SS-006, and SS-007) where contamination has been confirmed, and a remedial investigation for soils is in progress at another (FT-002). These five sites are therefore considered Category 5. At ST-005, a remedial action for confirmed contamination has been selected but not yet implemented, so that site is considered Category 6. Further investigation is planned at Sites SS-008 and SS-009, and they are considered Category 7. Specific resource categories for IRP sites are presented in Table 3-2.

# 3.3.3 Storage Tanks

The following sections describe the findings for ASTs, USTs, and OWSs based on the records search and VSI. An overview of pipelines, hydrant fueling, and transfer systems is also provided.

# 3.3.3.1 Aboveground Storage Tanks

There have been 36 ASTs used at Richards-Gebaur AFB. Table 3-3 summarizes the history of ASTs at Richards-Gebaur AFB, and Figure 5-1 shows their locations.

Based upon the methodology presented in Chapter 2, no evidence of a release occurring was identified for 32 of the ASTs; therefore, they are considered Category 2. During the VSI, staining was noted at two ASTs, but it is likely that releases were of *de minimis* quantities and affected soil was below action levels, and the ASTs are considered Category 3. No documentation of tank integrity (e.g., testing results) is available for one AST in the POL storage yard (IRP Site ST-005), and the AST at the Fire Training Area has been identified, but not confirmed, as a possible source of contamination at IRP Site FT-002. Therefore, both of these ASTs are considered Category 7.

# 3.3.3.2 Underground Storage Tanks

Table 3-4 summarizes the history and status of the 33 USTs at Richards-Gebaur AFB, and Figure 5-1 shows their locations.

Contamination has been confirmed at four USTs, which are being investigated and remediated under the IRP; these USTs are considered

Category 5 and are discussed under Section 3.3.2, IRP Sites Identified To Date. The remaining 29 USTs have not yet been closed in accordance with MDNR guidelines, and are therefore considered Category 7. Specific resource categories for USTs are presented in Table 3-4, and their locations are shown on Figure 5-1.

# 3.3.3.3 Pipelines, Hydrant Fueling, and Transfer Systems

Richards-Gebaur AFB operates a POL Storage Yard and formerly operated two hydrant fuel systems.

The POL Storage Yard consists of bulk fuel ASTs, and two fuel pumphouses and truck fueling/defueling platforms. The bulk fuel ASTs are as follows: Facility 954 is an inactive 260,000-gallon heating oil AST; Facility 955 is an active 187,000-gallon AST that holds jet propulsion fuel, grade 4 (JP-4); Facility 957 is an active 210,000-gallon JP-4 AST; and Facility 9610 consists of one inactive 10,000-gallon motor gasoline (MOGAS) AST and one inactive 10,000-gallon diesel AST. Facilities 951 and 953 are inactive fuel pumphouses. The entire POL Storage Yard is currently being investigated under the IRP as Site ST-005.

The two hydrant fuel systems consisted of steel lines extending from the POL Storage Yard to the flightline. One system transported aviation gasoline and later JP-4 fuel from a now inactive pumphouse (on property now owned by Kansas City) to Facility 941, a truck fuel stand approximately 1,200 feet away. This system began operating in 1954, and has been inactive for an unknown period of time. The second system, constructed in 1954, transported JP-4 fuel through approximately 3,400 feet of pipe from Facility 953 to Facility 902, which provided fuel to six fuel pits on the flightline. This system was deactivated in 1971 and demolished in 1988, and the fuel pits were paved over with concrete. At that time, four 50,000-gallon USTs were removed and contamination was identified. Facility 902 is being investigated under the IRP as Site ST-007. The pipelines for both hydrant systems are currently being investigated to determine if there have been any leaks or subsurface contamination and may require further investigation.

The POL Storage Yard (ST-005) and USTs at Facility 902 (ST-007) will be remediated under the IRP (see Section 3.3.2). The two hydrant lines are being investigated to determine pipe integrity and possible fuel contamination, and are considered Category 7.

# 3.3.4 Oil/Water Separator Systems

OWSs are flow-through systems designed to separate oil, fuel, and grease from water. Other contaminants potentially present in water discharged to an OWS, such as solvents, cannot be removed by this process. Water from an OWS typically discharges to an industrial or sanitary sewer. At Richards-

Gebaur AFB, 33 OWSs have been identified. Specific resource categories and histories of the OWSs are listed in Table 3-5; Figure 5-1 shows their locations. All active OWSs are being replaced with aboveground vaulted OWSs that will be regulated as ASTs. OWSs that were underground systems are regulated as USTs and will be closed in accordance with MDNR guidelines for USTs. Ten vaulted, aboveground OWSs were installed in October and November 1993 and are considered Category 2. The areas where two other aboveground OWSs were removed were inspected during the VSI and no evidence of a release was noted; therefore, these two OWSs are also considered Category 2. The remaining 21 OWSs have not yet been closed in accordance with MDNR guidelines for USTs and are therefore considered Category 7.

#### 3.3.5 Pesticides

Pesticide management at Richards-Gebaur AFB is accomplished by a private contractor under the oversight of the base contracting office and the Civil Engineering office. No bulk pesticides are stored or mixed on site, and no equipment is cleaned at Richards-Gebaur AFB. Household pests are controlled by spraying buildings with the synthetic insecticides Dursban Lo, Orthene, and Commodore. Wood-destroying insects (termites) are controlled by applying Demon in the soil surrounding each facility at depths of 12 to 14 inches. All of these pesticides are synthetic chemicals designed to be short-lived in the environment. Rodent control is also accomplished by the contractor as needed with the use of Talon G.

In the past, the base has used chlordane in wooden buildings for termite control. However, no records are available that indicate quantities used or locations of application. Base personnel have indicated that these applications were conducted in accordance with then-current standards; therefore, it is assumed that chlordane levels in the soil, if any, would be well below remedial action requirements.

Based upon the methodology presented in Chapter 2, no contamination associated with pesticides is expected.

# 3.3.6 Medical/Biohazardous Waste

Richards-Gebaur AFB operates a medical clinic (Facility 601) used for deployment training (setting up a field hospital) and for providing physicals for Reserve personnel; no in-patient services are provided. The base generates medical waste below the MDNR threshold amount of 100 kg per month, and therefore qualifies as a small-quantity generator. A permitted contractor removes medical wastes from the medical center once a month for proper disposal. The Bioenvironmental Engineer is responsible for monitoring medical wastes generated on base.

Medical and dental X-ray operations (Facility 604) produce photochemical wastes and utilize silver recovery units. The silver recovery units treat photochemical wastes prior to discharge to the local sewage system. A study to determine the extent of mercury contamination in Facility 604 is discussed in Section 3.3.1.2.

Based upon the methodology presented in Chapter 2, no evidence of a release occurring was identified at Facility 601, and it is considered Category 2. Contamination has been confirmed at Facility 604, and investigation and remedial actions are in progress, so it is considered Category 7. These facilities are listed in Table 5-1 and shown in Figure 5-1.

#### 3.3.7 Ordnance

There are no grenade or skeet ranges at Richards-Gebaur AFB. Facilities 1049 and 1050 comprise the Small Arms Range. This range will be cleared of unexploded ordnance prior to disposal. The Small Arms Range was studied in a Phase II project (Firing Range Site Phase II 1993). The report concluded that lead levels in site soils are above background levels but below levels requiring remedial action. Ordnance may have been disposed of by burning or blasting within the Belton Training Complex; rifle rounds were discovered during the VSI.

Facilities 1049 and 1050 have not been surveyed for unexploded ordnance, and are therefore considered Category 7. No investigations have been conducted at the Belton Training Complex to determine if any unexploded ordnance or residual soil contamination exists; therefore, this site is also considered Category 7.

### 3.3.8 Wastewater Discharges

Wastewater systems at Richards-Gebaur AFB consist of the sanitary sewer line, the industrial sewer line, and storm drainage.

The sanitary sewer system is connected to the Little Blue Valley Sewer District. The industrial sewer line collects effluent from the flightline and from industrial shops on base and discharges it into Facility 943, a detention reservoir. The effluent passes through an OWS (Facility 9470) and is then discharged to the sanitary sewer line leaving base. An environmental assessment of the detention reservoir is in progress. The Sanitary Sewer/Storm Water Runoff Study (Geraghty and Miller, 1991a) identified a drain at Facility 1201 as potentially draining to a leach field, and identifies interior drains in Facilities 605, 930, 948, 958, 965, and 966 that drain into the storm sewer system.

Storm water leaving the base was studied in the <u>Water Course Soil</u>
<u>Assessment, Richards-Gebaur AFB, Missouri, Phase II Final Report.</u> This

basewide report of major drainage swales indicated that no significant contamination was found in either surface water or sediments. Richards-Gebaur AFB has filed for a discharge permit (Forms E and F) with MDNR.

Active septic tanks connected to leach fields are present at Facility 1025 (an Air Traffic Transceiver), Facility 1049 (Small Arms Range control house), and Facility 1100 (Mobile Radio Transceiver).

The conclusions of the water course assessment state that no remedial measures are necessary for surface water and sediments at major drainage sites. The only discharge allowed by the Clean Water Act (33 U.S.C. Sections 1251-1387) to flow into storm sewers is that from outdoor, building roof, and general runoff drainages. Any interior building drains to storm sewers may need to be capped or routed to the sanitary sewer. The seven buildings with indoor drains (listed above) that drain to sites other than the sanitary sewer are considered Category 7.

# 3.3.9 Radioactive and Mixed Wastes

There are no known radioactive or mixed waste issues at Richards-Gebaur AFB.

#### 3.3.10 Solid Waste

There are no active landfills at Richards-Gebaur AFB, and no known historic landfills.

### 3.4 DISCLOSURE RESOURCES

Disclosure resources include asbestos, PCBs, radon, and lead-based paint. These resources were not used in property categorization. In the event that an issue arises regarding any of these resources, it will be discussed within the appropriate resource in Section 3.3.

#### 3.4.1 Asbestos

A comprehensive basewide asbestos survey was conducted in September 1987. The survey included 71 facilities. ACM was identified in 39 of these facilities; the other 32 either had no suspected ACM or samples were negative. Locations of facilities surveyed and survey results are listed in Table 3-6 and shown in Figure 5-1. The data listed in Table 3-6 represent conditions as of September 1987. Numerous renovation projects have occurred since 1987 to remove ACM. Facility 942 (former Heat Plant) is currently closed due to the condition of ACM in the building.

# 3.4.2 Polychlorinated Biphenyls

All transformers with 50 parts per million (ppm) or more PCBs have either been replaced with PCB-free equipment or retrofilled to bring the PCB concentration to below 50 ppm, and U.S. EPA, Region VII, issued a Notice of Compliance to that effect on October 21, 1993. A history of base transformers and their PCB concentrations is provided in Table 3-7. Figure 5-1 shows the locations of transformers that may have contained PCB fluids in the past. Although the status of all PCB transformers could not be determined by the records search, the Environmental Management Office reported that the base is PCB-free and all PCB transformers have been retrofilled.

#### 3.4.3 Radon

The Air Force sold or transferred all properties utilized as family housing or schools prior to implementation of the Radon Assessment and Mitigation Program; therefore the Air Force has not and does not plan to conduct any radon studies to determine the concentrations of radon in structures at Richards-Gebaur AFB. Results of a 1988 study (Missouri Department of Health, 1988) showed that more than 80 percent of samples in Cass County and more than 60 percent in Jackson County had radon levels below the U.S. EPA's recommended mitigation level of 4 picocuries per liter (pCi/l). The remainder of the samples had radon levels between 4 and 20 pCi/l, except 1 percent of the Jackson County samples, which were above 20 pCi/l.

# 3.4.4 Lead-Based Paint

The use of lead-based paints declined after 1978. A comprehensive basewide survey to determine the use of lead-based paint at Richards-Gebaur AFB has not been conducted. Facilities constructed prior to the implementation of the DOD ban on the use of lead-based paint in 1978 are likely to contain such paint. There are 95 buildings on base that were constructed prior to or during 1978. Another nine buildings have unknown construction dates. Table 5-1 lists the construction date of each facility; Figure 5-1 shows the locations of facilities, and indicates which were constructed prior to or during 1978.

فأرة فنا فاداد الدار

Table 3-1. Hazardous Waste Accumulation Points
Page 1 of 5

	<u></u>	Page 1 of 5			
Facility	Waste Stored	Amount Stored	Documented Years of Storage	Program Status	Specific Property Category
601	Developer and replenisher	8 gailons/year	1988-1989	RCRA	2
	Fixer and replenisher				
605 <sup>(a)</sup>	None	NA	NA	RCRA	2
610	Oil		<u> </u>	RCRA	2
010	Mask filters	395 gallons/year	1993-1993	n,cnA	
	Waste flammable liquid	30 pounds/year	1993-1993		ł
•	Toner	34 pounds/year	1993-1993		
619/710	Ammonia	0.5 gailon/year	1985-1985	RCRA	2
013//10	Paint	45 gallons/year	1991-1991	RCRA	-
	Paint material	626 gailons/year	1990-1991		}
	Paint thinner	61 gallons/year	1990-1991		
701(4)	None	NA	NA	RCRA	2
704		<del></del>	1987-1987	RCRA	7
704	Hydraulic fluid Hydraulic fluid	55 gallons/year	1	HCHA	′
	Transmission fluid	28 gallons/year	1989-1990		
		45 gallons/year	1987-1988		
	Transmission fluid	43 gallons/year	1989-1900		
	Used/waste engine oil	100 gallons/year	1992-1993		
	Antifreeze	341 gallons/year	1987-1988		
	Antifreeze	43 gallons/year	1989-1990		
	Gear lube	53 gallons/year	1987-1988		
	Waste oil	375 gallons/year	1991-1993		
	Paint stripper	1.5 gallons/year	1987-1988		
	Hydraulic fluid	55 gallons/year	1987-1988	1	
	Engine oil	283 gallons/year	1987-1988		
	Engine oil	216 gallons/year	1989-1991		
	Paint waste	2 gallons/year	1986-1987		
	Lube oil	315 gallons/year	1987-1987		
	Lube oil	30 gallons/year	1988-1988		•
	Lube oil	26 gallons/year	1989-1990		·
	Lube oil	50 gallons/year	1991-1991		
	Paint thinner	60 gallons/year	1989-1989		ı
	Paint thinner	50 gallons/year	1991-1991		
	Fuel filters	280 gallons/year	1989-1990		
	Oil filters	140 gallons/year	1989-1990		_

Notes: (a) Although these facilities have been identified as accumulation points, hazardous waste has never been stored there

NA = Not applicable.
RCRA = Resource Conservation and Recovery Act

Table 3-1. Hazardous Waste Accumulation Points
Page 2 of 5

Facility	Waste Stored	Amount Stored	Documented Years of Storage	Program Status	Specific Property Category
704	Motor oil	50 gallons/year	1990-1990		
(continued)	Aliphatic hydrocarbons	35 gallons/year	1990-1991		
	Lubricants	250 gallons/year	1991-1991		
711	Paint-related material	54 gallons/year	1991-1991	RCRA	2
	Used JP-4 fuel filters	190 gallons/year	1992-1992	1	
	Waste oil lubricant	48 gallons/year	1992-1992		
	Lubricants	50 gallons/year	1991-1991		
828	Petroleum PD-680	15.5 gallons/year	1985-1985	RCRA	2
	Denatured alcohol with brake fluid	5 gallons/year	1988-1988		
	JP-4 contaminated sand bags	800 gallons/year	1989-1989	,	
	JP-4 contaminated absorbent material	70 gallons/year	1989-1989		
	Absorbent Pads	55 gallons/year	1990-1990		
	Hydraulic lift fluid	550 gallons/year	1990-1990		
	JP-4 contaminated soil	879 gallons/year	1990-1990		
	Flammable liquids	100 gallons/year	1991-1991		
839	Synthetic oil	62 gallons/year	1991-1991	RCRA	2
	Synthetic oil	13.5 gallons/year	1992-1993	,	
	A/C synthetic oil	16 gailons/year	1987-1988		
	Waste synthetic oil	44 gallons/year	1992-1992		
	Penetrant	99 galions/year	1985-1985		
	Emulsifier	86 gallons/year	1985-1985		
•	HW Liquid NOSORM-E	12 gallons/year	1990-1991		
	Penetrant	50 gallons/year	1987-1987		
	Penetrant	194 gallons/year	1988-1988		
	Emulsifier	74 gallons/year	1987-1987		]
	Emulsifier	131 gallons/year	1988-1988		
	Developer	10 gallons/year	1988-1989	;	
	Developer	115 gallons/year	1992-1992	i	
	Magnaglo bath	22.5 gallons/year	1986-1986		
	Magnaglo bath	8 gallons/year	1988-1988		
	Magnaglo bath	924 galions/year	1989-1989		
	Magnaglo bath	60 gailons/year	1990-1991		
	Solvent cleaner	5 gallons/year	1990-1990		
	Emulsifier with oil	47 gallons/year	1988-1988		

RCRA = Resource Conservation and Recovery Act.

Table 3-1. Hazardous Waste Accumulation Points Page 3 of 5

		Page 3 of 5			_
Facility	Waste Stored	Amount Stored	Documented Years of Storage	Program Status	Specific Property Category
839	Oil with trichloroethane	14 gallons/year	1988-1989		
(continued)	Oil with trichloroethane	23 gallons/year	1985-1986		
•	Waste trichloroethane oil	17 gallons/year	1985-1986		
918	Sulfuric acid	20 gallons/year	1987-1988	RCRA	7
	Sulfuric acid	20 gallons/year	1989-1990		
	Sulfuric acid with lead	25 gailons/year	1986-1987		
	Nickel-cadmium batteries	40 gallons/year	· 1986-1988		
	Nickel-cadmium batteries	82 gallons/year	1989-1990	:	
	Hydraulic fluid	150 gallons/year	1985-1991		
	Hydraulic fluid	42.5 gallons/year	1992-1993		<u> </u>
	Thinner	50 gallons/year	1985-1985		Ī
	Waste hydraulic fluid	48.5 gallons/year	1991-1992	<u> </u>	1
	Synthetic engine oil	44 gallons/year	1992-1992		
927/928	Trichloroethane .	4 gallons/year	1985-1988	RCRA	2
	Carbon remover	30 gallons/year	1985-1986	1	
	Carbon remover	6 gailons/year	1988-1989		
	PD-680	50 gallons/year	1985-1986		
	Turbine oil	45 gallons/year	1986-1986		1
	Engine oil	235 gallons/year	1985-1991		
	Jet engine oil	49 gallons/year	1986-1986		
	Jet engine oil	46 gallons/year	1989-1989		
	Hydraulic fluid	47 gailons/year	1987-1988		
	Waste engine oil	92 gallons/year	1989-1989		
	Waste engine oil	45 gallons/year	1991-1992	1	
	Turco cleaner	5 gallons/year	1989-1989		}
	Used/waste turbine oil	93 gallons/year	1992-1993		]
	Waste oil with solvent	40 gallons/year	1991-1992		
	JP-4/MOGAS/water	46 gallons/year	1990-1990	L	
948/972	Waste latex paint	50 gallons/year	1992-1992	RCRA	2
	Waste oil-base paint	50 gallons/year	1992-1992		1
	Waste paint-related material	50 gallons/year	1992-1992		
	Waste sealing compound	6 pounds/year	1992-1992		

MOGAS = Motor gasoline.

RCRA = Resource Conservation and Recovery Act.

Table 3-1. Hazardous Waste Accumulation Points
Page 4 of 5

Facility	Waste Stored	Amount Stored	Documented Years of Storage	Program Status	Specific Property Category
953141	None	NA	NA	RCRA	2
958/959	Turbine oil	16.5 gallons/year	1985-1988	RCRA	2
555,555	Turbine oil	9.5 gallons/year	1989-1990	,,,,,,,	_
	Engine oil	75 galions/year	1985-1990		
	Lubricating oil	65 gallons/year	1985-1987		
	Diethylene glycol	5 gallons/year	1985-1985		•
	Transmission fluid	5 gallons/year	1986-1986	·	
	Transmission fluid	31 gallons/year	1987-1988		
	Hydraulic fluid	194 gallons/year	1987-1991		
	Monobutyl ether	5 gallons/year	1987-1988		
	Preservative oil	10 gallons/year	1988-1988		
	JP-4/MOGAS/water	10 gailons/year	1990-1990		1
	Waste oil	76 gallons/year	1991-1992		
	Motor oil	103 gallons/year	1991-1991		
	Waste engine oil	49 gallons/year	1991-1992		
	Used motor oil	50.5 gallons/year	1992-1993		
965	Stripper	261 gallons/year	1985-1985	RCRA	7
	Hydraulic fluid with methyl ethyl ketone	15 gallons/year	1985-1985		
	Toluene and methyl ethyl ketone	54 gallons/year	1985-1985		
	Thinner and methyl ethyl ketone	27 gallons/year	1985-1985		
	Epoxy remover	55 gallons/year	1985-1986		
	Polyurethane paint	151 gallons/year	1987-1987		
	Polyurethane thinner	25 gallons/year	1986-1987		
	Paint thinner	139 gallons/year	1986-1991		
	Waste paint	75 gallons/year	1991-1992		
	Waste thinner with methyl ethyl ketone	49 gallons/year	1992-1992		
966	Petroleum PD-680-11	48 gallons/year	1985-1986	RCRA	2
	Paint stripper	93 galions/year	1987-1988		
	Used paint stripper	110 gallons/year	1987-1987		
	Paint stripper	50 gallons/year	1990-1990		

Notes: The Missouri Department of Natural Resources has RCRA authority in Missouri.

r + x = x = x = x

the construction and the state of the state

<sup>(</sup>a) Although these facilities have been identified as accumulation points, hazardous waste has never been stored there.

NA = Not applicable.

RCRA = Resource Conservation and Recovery Act.

Table 3-1. Hazardous Waste Accumulation Points Page 5 of 5

Facility	Waste Stored	Amount Stored	Documented Years of Storage	Program Status	Specific Property Category
970	Tar	40 gallons, year	1990-1990	RCRA	2
	JP-4 contaminated water	45 gallons year	1990-1990		<u> </u>
973	Aliphatic hydrocarbons	15 gallons, year	1991-1991	RCRA	2
1202	Denatured alcohol with brake fluid	2 gallons/year	1990-1992	RCRA	2

Notes: The Missouri Department of Natural Resources has RCRA authority in Missouri.

RCRA = Resource Conservation and Recovery Act.

Source: U.S. Air Force, 1993b.

,		Table 3-2	Table 3-2. Installation Restoration Program (IRP) Sites	) Sites		
IRP Site	Operable Linit	Known or Suspected Material	Site Name	Program Status	Dates of Operation	Specific Property Category
FT-002	-	Waste oils, solvents, and fuels		Supplemental Remedial Investigation	1965-1988	<b>5</b>
SS-003	-	Waste petroleum, oils, and lubricants products	Oil Saturated Area	Decision Document	1955-1980	2
SS-004	-	Waste oil	Hazardous Waste Drum Storage	Decision Document	Unknown- 1985	D.
ST-005	-	Fuels	Petroleum, Oils, and Lubricants (POL) Storage Yard	Remedial Design/Remedial Action	1954-Present	9
SS-006	-	Waste oil	Hazardous Material Storage, Facility 927	Preliminary Assessment/Site Inspection; Interim Remedial Action completed in fall 1993	1957 - Present	ഥ
ST-007	-	JP-4	Leaking Underground Storage Tanks	Decision Document	1954-1971	2
SS-008	-	Petroleum, oils, and lubricants	Test Cell Area	Preliminary Assessment/Site Inspection	1956-1977	7
SS-009	-	Petroleum, oils, and lubricants	Fire Valve Area	Preliminary Assessment/Site Inspection	Unknown	7

Er tair albie na Air

Table 3-3. Aboveground Storage Tanks

		Capacity	•			Specific Property
Facility	Contents	(gallons)	Status	Years of Operation	Program Status	Category
105	Diesel	275	Active	1972-Present	Air Force Policy	2
602 interior	Diesel	90	Active	Unknown-Present	Air Force Policy	2
602 exterior	Diesel	275	Active	Unknown-Present	Air Force Policy	2
614	Diesel	90	Removed	Unknown	Air Force Policy	2
614	MOGAS	50	Removed	Unknown	Air Force Policy	2
614	MOGAS	50	Removed	Unknown	Air Force Policy	2
614	Diesel	44	Removed	Unknown	Air Force Policy	2
700	MOGAS	10,000	Active	1989-Present	Air Force Policy	2
701	Diesel	10,000	Active	1989-Present	Air Force Policy	2
710	Diesel	275	Active	Unknown-Present	Air Force Policy	2
711	Reclaimed JP-4	1,000	Active	Unknown-Present	Air Force Policy	2
841	Diesel	275	Active	1970-Present	Air Force Policy	2
901	Diesel	275	Active	1970-Present	Air Force Policy	3
918	MOGAS	20	Active	Unknown	Air Force Policy	2
921	Diesel	1,000	Removed	1956-Unknown	Air Force Policy	2
944	JP-4	2,500	Removed	1956-Unknown	Air Force Policy	2 ,
945	JP-4	500	Removed	1957-Unknown	Air Force Policy	2
945	JP-4	500	Removed	1957-Unknown	Air Force Policy	2
945	Waste PD-680, paint thinner, POL	1,000	Removed	1957-Unknown	Air Force Policy	2
945	Waste PD-680, paint thinner, POL	1,000	Removed	1957-Unknown	Air Force Policy	2
953	Diesel	44	Removed	Unknown	Air Force Policy	2
954	Heating oil	260,000	Inactive	1954-Unknown	Air Force Policy	7
955	JP-4	187,000	Active	1954-Present	Air Force Policy	2
957	JP-4	210,000	Active	1956-Present	Air Force Policy	2
958	Waste PD-680, paint thinner, POL	500	Removed	Unknown	Air Force Policy	2
963	Solvent	500	Active	Unknown-Present	Air Force Policy	2
1009	MOGAS	275	Active	Unknown-Present	Air Force Policy	2
1011	MOGAS	275	Removed	1962-Unknown	Air Force Policy	3
1025 interior	Diesel	90	Active	1972-Present	Air Force Policy	2
1025 exterior	Diesel	275	Active	1972-Present	Air Force Policy	2
1025 exterior	Diesel	560	Active	1972-Present	Air Force Policy	2
1033	Waste JP-4	5,000	Removed	1961-Unknown	Air Force Policy	7
1100	MOGAS	275	Active	Unknown-Present	Air Force Policy	2
1401	MOGAS	275	Removed	Unknown	Air Force Policy	2
9610	Diesel	10,000	Inactive	1958-Unknown	Air Force Policy	2
9610	MOGAS	10,000	Inactive	1958-Unknown	Air Force Policy	2

Notes: extenor = AST is found outside facility.

intenor = AST is found inside facility.

MOGAS = Motor gasonne.

POL = Petroleum, oils, and lubricants.

Sources: CH<sub>2</sub>M Hill, 1983.

Intelcom Support Services, 1992.

U.S. Air Force, 1993a.

Table 3-4. Underground Storage Tanks
Page 1 of 2

Facility	Contents	Capacity (gallons)	Status	Years of Operation	Program Status	Specific Property Category
105	Diesel	250	Removed	1954-1988	MDNR	7
602	Diesel	1,000	Removed	1954-1988	MDNR	7
620	Waste acid	550	Removed	1966-1988	MDNR	7
702	Gasoline	10,000	Removed	1954-1989	MDNR	7
702	Gasoline	10,000	Removed	1954-1989	MDNR	7
711	JP-4	5,000	Removed	1965-1989	MDNR	7
828	Fuel oil	1,500	Removed	1955-1981	MDNR	7
828	Fuel oil	1,650	Removed	1981-1992	MDNR	7
839	Fuel oil .	4,000	Removed	1961-1992	MDNR	7
902	JP-4	25,000	Removed	1954 <del>,</del> 1988	IRP	5
902	JP-4	25,000	Removed	1954-1988	IRP	5
902	JP-4	25,000	Removed	1954-1988	IRP	5
902	JP-4	25,000/	Removed	1954-1988	<b>IRP</b>	5
903	Diesel .	<b>320</b> 9	Unknown	1961-Unknown	MDNR	7
927	Waste solvent	500	Removed	1989-1993	MDNR	7
938	Gasoline	100	Removed	1954-1985	MDNR	7
942	Fuel oil #2	15,000 .	Removed	1955-1988	MDNR	7
942	Fuel oil #2	15,000	Removed	1955-1988	MDNR	7
947	Stoddard solvent	6,000	Removed	1958-1989	MDNR	7
948	Waste oil	500	Removed	1963-1988	MDNR	7
948	Fuel oil #2	6,000	Removed	1963-1988	MDNR	7
958	Fuel oil #2	250	Removed	1963-1988	MDNR	7
962	JP-4	4,000	Active	1984-Present	MDNR	7
962	Gasoline	4,000	Active	1984-Present	MDNR	7 .
965	Waste oil	12,000	Removed	1966-1988	MDNR	7

Note: All underground storage tanks on base are being removed in accordance with MDNR guidelines. IRP = Installation Restoration Program.

MONR = Missouri Department of Natural Resources.

Table 3-4. Underground Storage Tanks
Page 2 of 2

Facility	Contents	Capacity (gallons)	Status	Years of Operation	Program Status	Specific Property Category
1025	Fuel oil #2	550	Removed	1953-1968	MDNR	7
1025	Fuel oil #2	1,000	Removed	1968-1988	MDNR	7
1025	Diesel	275	Removed	1953-1988	MDNR	7
1100	Gasoline	250	Removed	1953-1988	MDNR	7
1100	Fuel oil #2	550	Removed	1953-1988	MDNR	7
1201	Fuel oil #2	3,000	Removed	1961-1992	MDNR	7
1202	Fuel oil #2	1,500	Removed	1959-1982	MDNR	7
1202	Fuel oil #2	1,650	Removed	1982-1992	MDNR	7

Note: All USTs on base are being removed in accordance with MDNR guidelines.

MDNR = Missouri Department of Natural Resources.

Sources: Burns and McDonnell, 1992a.

CH2M Hill, 1983.

Environmental Protection Inspection and Consulting, Inc., 1991. Environmental Risk Information and Imaging Services, 1992.

Missoun Department of Natural Resources, 1993e.

U.S. Air Force, 1992c, 1993c. U.S. Air Force SPTG-CEG, 1993.

Table 3-5. Oil/Water Separator Systems

Facility	Capacity (gallons)	Status	Years of Operation	Type of System	Program Status	Specific Property Category
702	50	Removed	1989-93	A	CWA	2
702	190	Removed	1989-93	υ	MDNR 1	7
702	550	Active	1993-Present	Α	CWA	2
702	550	Active	1993-Present	Α	' CWA	2
704	500 °	Removed	1956-89	υ	MDNR	7
704	500	Removed	1 <b>95</b> 6-75	υ	MDNR	7
704	500	Removed	1975-93	υ	MDNR	7
704	282	Removed	1989-93	U	MDNR	7
704	5 <b>50</b>	Active	1993-Present	Α	CWA	2
704	550	Active	1993-Present	Α	CWA	2
711	1000	Removed	<b>1965</b> -93	υ	MDNR	7
711	500	Removed	1965-93	υ	MDNR	7
711	282	Removed	1 <b>98</b> 9-93	U	MDNR	7
711	550	Active	1993-Present	Α	CWA	2
711	550	Active	1993-Present	Α	CWA	2
920	200	Removed	1973-93	U	MDNR	7
920	500	Removed	1973-93	U	MDNR	7
920	550	Active	, 1993-Present	Α	CWA	2
920	550	Active	1993-Present	Α	CWA	2
927	400	Closed in place	1958-89	U	MDNR	7
927	100	Closed in place	1958-89	υ	MDNR	7
940	275	Removed	1 <b>965-88</b> .	U	MDNR	7
940	1075	Removed	1965-Unknown	U	MDNR	7
944	1000	Removed	1956-88	U	MDNR	7
944	140	Removed	1956-88	υ	MDNR	7
1033	425	Closed in place	1972-89	υ	MDNR	7
1033	565	Removed	1972-89	υ	MDNR	7
9470	7800	Removed	1973-89	Α	CWA	2
9470	1000	Active	1973-Present	υ	MDNR	7
9470	1500	Removed	1973-89	υ	MDNR	7
9470	282	Removed	1989-93	U	MDNR	7
9470	550	Active	1993-Present	Α	CWA	2
9470	5 <b>5</b> 0	Active	1993-Present /	Α	CWA	2

A = Aboveground storage.

Li idi dalam d

CWA = Cleen Water Act program.

MDNR = Missouri Department of Natural Resources.

U = Underground storage.

Table 3-6. Facilities Surveyed for Asbestos Page 1 of 2

Facility (Use)	Asbestos-Containing Material (ACM) Present
000 (Steam Piping System)	All negative samples
105 (Communications Facility)	Joint insulation
243 (Dormitory)	ACM found but not described in report
245 (Swimming Pool Water Treatment)	No suspected material found
247 (Swimmers' Bath House)	Tank and pipe insulation
248 (Open Mess)	Tank, pipe, and joint insulation
250 (Dormitory)	Mechanical insulation
252 (Dormitory)	Mechanical insulation
602 (Flight Simulator Training)	Pipe and joint insulation
603 (Air Force Clinic)	Tank, pipe, and joint insulation
604 (Air Force Clinic)	Tank, pipe, and joint insulation
605 (Maintenance Shop)	Pipe and joint insulation
606 (Base Engineering Administration)	Pipe, tank, and joint insulation, transite shingles
607 (Base Engineering Administration)	All negative samples
610 (Supply/Equipment Base Warehouse)	Pipe and joint insulation
614 (Administration Office)	All negative samples
617 (Disaster Preparedness)	Joint insulation
619 (Exchange Branch)	Mechanical insulation, ceiling panels
620 (Document Storage Facility)	All negative samples
621 (Acid Storage)	No suspected material found
702 (Vehicle Fuel Station)	No suspected material found
703 (Vehicle Operations Administration)	Pipe and joint insulation
704 (Vehicle Maintenance Shop)	Pipe and joint insulation
709 (Reserve Forces Aeromedical Evacuation Training)	All negative samples
710 (Reserve Forces Operational Training)	Tank, pipe, and joint insulation
711 (Refuel Vehicles Shop)	Pipe and joint insulation
757 (Sanitary Latrine)	No suspected material found
801 (Survival Equipment Shop)	Pipe and joint insulation, transite shingles
828 (Warehouse and Shop)	Tank, pipe, and joint insulation
839 (Non-Destructive Inspection Laboratory)	Joint insulation
841 (Fixed Tactical Air Navigational Station)	All negative samples
845 (Electrical Power Station)	No suspected material found
900 (Fire Station)	Pipe and joint insulation
901 (Base Operations)	Pipe and duct insulation
903 (Electrical Power Station)	No suspected material found
904 (Base Hazardous Storage)	No suspected material found
918 (Maintenance Hangar)	Tank, pipe, and joint insulation
920 (Vehicle Service Rack)	No suspected material found

Table 3-6. Facilities Surveyed for Asbestos
Page 2 of 2

Facility (Use)	Asbestos-Containing Material (ACM) Present	
923 (Storage Shed)	No suspected material found	
924 (Maintenance/Storage)	No suspected material found	
925 (Reserve Forces Training)	Joint insulation	
926 (Headquarters/Office)	Joint insulation	
927 (Engine and Pneudraulics Shop)	Joint insulation	
930 (Electronic Counter Measures Pad Shop/Storage)	Mechanical, joint, and duct insulation, lay-in ceiling	
931 (Liquid Oxygen Storage)	No suspected material found	
936 (Non-Air Force Administration Office)	No suspected material found	
937 (Base Hazardous Storage)	No suspected material found	
940 (Aircraft General Purpose Shop)	Tank, pipe, and joint insulation	
942 (Heating Facility)	Boiler, tank, pipe and joint insulation	
946 (Base Hazardous Storage)	No suspected material found	
947 (Corrosion Control Storage)	No suspected material found .	
948 (Maintenance Dock Fuel System)	Boiler and joint insulation	
949 (Corrosion Control Storage)	No suspected material found	
951 (Maintenance Shop)	Boiler, tank, pipe, and joint insulation	
953 (Liquid Fuel Pump Station)	No suspected material found	
958 (Ground Support Shop)	Joint insulation	
962 (Ground Equipment Shop)	No suspected material found	
965 (Aircraft General Purpose Shop)	Boiler, tank, and joint insulation	
966 (Maintenance Dock)	Tank and joint insulation	
1011 (Electrical Power Station)	No suspected material found	
1025 (Air Traffic Transceivers)	Pipe and joint insulation	
1049 (Range Control House)	All negative samples	
1050 (Aboveground Magazine Storage)	No suspected material found	
1100 (Mobile Radio Transceiver)	Pipe and joint insulation	
1201 (Office)	Duct and joint insulation	
1202 (Missile Assembly and Training)	Mechanical insulation	
1203 (Aboveground Magazine Storage)	No suspected material found	
1205 (Base Hazardous Storage)	No suspected material found	
1401 (Instrument Landing System Localizer)	No suspected material found	
1800 (Instrument Landing System Marker Beacon)	No suspected material found	
1900 (Instrument Landing System Marker Beacon)	No suspected material found	

Source: Hall-Kimbrell, 1987.

Table 3-7. Historic Locations of Transformers

PCB Concentration		
Facility	(ppm)	1D Number
940	138	C149900
940	149	C149153
940	188	B746299
940	275	B746296
966	566	B730448
918	140	C382905
918	202	C382720
918	123	C382804
918	88	C382807
918	141	C382805
918	138	C382809
918	144	C382694
918	149	C382708
918	137	C382908
918	240	C382721
918	140	C382712
918	150	C382717
926	266	B751738
926	189	B750447
926	344	57J7448
926	311	57J7438
926	359	5M63714
702	331	B726756
604	72.7	C130942
604	70.3	C130879
604	72.3	C130972
605	285	B746324
605	253	B746323
931	124	T741205
931	147	E974665-63P
931	85.3	C140803
619	68.9	71K2919
610	114	B7435 <b>0</b> 0
250	130	Unknown
250	176	Unknown
250	167	Unknown

PCB = Polychionnated biphenyl.

ppm = Parts per million.

Sources: Missouri Public Service, 1988a, 1988b.


Moore Analytical, 1986.

U.S. Air Force 442 CSG/DE, 1990, 1992.

THIS PAGE INTENTIONALLY LEFT BLANK



**CHAPTER 4** 



### 4.0 FINDINGS FOR OFF-BASE PROPERTIES

CERCLA Section 120(h), as amended, requires that a physical inspection of properties adjacent to the subject real property be conducted, to the extent permitted by owners and operators of such property. As mentioned in Section 1.2, adjacent property includes those properties contiguous to the boundaries of the base, as well as those properties relatively near the base that could pose significant environmental concern or impact to the base. All reasonably obtainable federal, state, and local government records were reviewed for each contiguous property where there has been a release of any hazardous substance and/or petroleum derivative, and where activities on that property are likely to cause or contribute to a release or threatened release of any hazardous substance or petroleum product or its derivatives on the real property. The following federal and state data bases were reviewed. These data bases were queried based on the minimum search distances recommended by the American Society for Testing and Materials quidelines for conducting Phase I site assessments (American Society for Testing and Materials, 1993). Two data bases (federal National Priorities List (NPL) and federal RCRA Treatment, Storage, and Disposal facilities list) were queried beyond the minimum search distance recommended. Distances searched for each data base are provided below.

- Federal NPL 2.5 miles
- Federal Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) list - 0.5 mile
- Federal RCRA Treatment, Storage, and Disposal facilities list 2.5 miles
- Federal RCRA generators list contiguous properties
- State Environmental Contamination List 1.0 mile
- State landfill and/or solid waste disposal site lists 0.5 mile
- State leaking UST lists 0.5 mile
- State registered UST lists contiguous properties

One CERCLIS site (Table 4-1), three RCRA generator sites (Table 4-2), one Federal Emergency Response Notification System site (Table 4-3), and nine sites with state-registered USTs (Table 4-4) were identified within the Richards-Gebaur AFB search area.

In addition, eight Formerly Utilized Defense Sites (FUDS) are located on property contiguous to Richards-Gebaur AFB; these sites are listed and briefly described in Table 4-5, and shown in Figure 4-1. Potential impacts of the FUDS on Richards-Gebaur AFB property cannot be determined with available data. A records search and SI of the FUDS is currently being conducted under the management of the Kansas City District Corps of Engineers Toxic and Hazardous Waste Branch.

### 4.1 LAND USES

There are 16 contiguous properties around Richards-Gebaur AFB (see Figure 4-1). Table 4-6 lists the size and land use of each parcel, and when the parcel was visually and/or physically surveyed. The total acreage for each parcel is listed; acreage within the study area (contiguous to the base within one-quarter mile of the base boundary) is also provided.

### 4.2 PROPERTY INSPECTIONS

All contiguous off-base properties were visually inspected. Of the 16 contiguous properties surveyed, 10 were physically inspected. The off-base properties consisted of portions of the original base property that was conveyed to Kansas City in 1985 and the parcels contiguous to the Belton Training Complex. This inspection consisted of a "windshield" survey of the property. When permitted by the owner, contiguous off-base properties were physically inspected; this entailed a visit to the property, an interview with the property owner/operator (when present), and a walk-around of the property. No sampling of any kind was conducted. Unless otherwise noted, no visual signs of contamination or environmental concern were identified. A description of each parcel is provided by property identification number in Table 4-6 (see Figure 4-1 for property locations). During the property surveys, several areas on off-base property were noted where potential contamination concerns may affect base property. These areas are presented in Table 4-7 and their locations shown in Figure 4-1.

Based on the records search and VSIs of the properties conducted for this EBS, there are no areas on Richards-Gebaur AFB where it is known that contamination has resulted from activities on any of the off-base properties; however, areas of possible concern were noted on contiguous properties during the survey. No off-base properties are known to have been contaminated from activities on Richards-Gebaur AFB.

Figure 4-1. Adjacent Property Map (oversized)

THIS PAGE INTENTIONALLY LEFT BLANK

Table 4-1. CERCLIS Sites

Map ID	Facility	Address	Status
15	Richards-Gebaur AFB West Burn Pit	West of Richards-Gebaur Airport runway, near public road, on Jackson/ Cass county line, Belton, MO 64012	to Further Action, 12/18/89. Site used from 1954 to 1955 for fire training. Waste oils, solvents, and fuels were deposited in an open pit and burned.

Table 4-2. RCRA Generators

Map ID	Facility	Address	Quantity Generated	Waste Type
1	Big Iron Works, Inc.	Hangar 1010 Richards-Gebaur AFB Belton, MO 64012	More than 1,000 kilograms per month	Ignitable solid waste, corrosive solid waste, chromium
2	Prime, Inc.	Hangar 1010 Richards-Gebaur AFB Belton, MO 64012	More than 1,000 kilograms per month	Ignitable solid waste
3	BTM, Inc.	15403 Andrews Rd. Kansas City, MO 64147	Between 100 and 1,000 kilograms per month	Ignitable solid waste, cadmium, chromium, lead

Table 4-3. Emergency Response Notification System Report

Map ID	Facility	Date	Spill Location and Description
Unable to locate	Location is Richards- Gebaur AFB; responsible party is unknown	09-22-92	Main Base Road, just off flightline; fuel oil leaking from an aboveground storage tank

Table 4-4. State Registered UST's

Map ID	Facility	Address	Number of Tanks
Unable to locate	Richards-Gebaur Airport	No Street Address Kansas City, MO 64147	7
4 .	Richards-Gebaur Airport	15415 Denver Avenue, Bldg. 1301 Kansas City, MO 64147	1
5	Richards-Gebaur Airport	3500 E. 155th Street, Bldg. 820 Kansas City, MO 64147	1
6	Richards-Gebaur Airport	3514 E. 155th Street, Bldg. 803 Kansas City, MO 64147	1
7	Richards-Gebaur Airport	4500 E. 155th Street Kansas City, MO 64147	. 1
8 .	Richards-Gebaur Airport	15403 Andrews Road, Bidg. 611 Kansas City, MO 64147	5
9	Richards-Gebaur Airport	3411 E. 155th Terrace, Bldg. 829 Kansas City, MO 64147	3
10	Richards-Gebaur Airport	3401 E. 155th Terrace, Bldg. 82 Kansas City, MO 64147	2
11	Richards-Gebaur Airport	15600 Spruce Avenue, Bldg. 514 Kansas City, MO 64147	6

Richards-Gebaur AFB EBS

1	
l	
l	
l	
l	
ı	
ı	
ı	
ı	
l	
ı	
l	
ı	<b>E</b>
ļ	1993
t	5:
١	œ`
ı	ō
ŀ	ě
l	ě
1	ຼ
	×

merly Used Defense Sites	age 1 of 2
Table 4-5. For	

MAP	Site	Site Name	Location and Waste Description	Dates of Operation	Current Status
12	-	South Landfill	Near the Non-Destructive Inspection Laboratory and adjacent to Scope Creek. Site was used as a sanitary landfill until 1956. After that until 1961 some wastes, including building rubble, yard debris, and waste from some industrial shop areas, were deposited there.	1954-1961	Records Search and Site Inspection
13	8	Northeast Landfill	East of the Small Arms Range. Site was used for the disposal of miscellaneous wastes including building rubble, yard debris and wastes from some industrial shop areas. The wastes were typically burned and buried in trenches.	1961-1972	Records Search and Site Inspection
14	ო .	Contractor Rubble Burial Area	West of the golf course along Walker Road. Debris including wood, concrete, masonry and metal. Some use as a sanitary landfill has been reported here.	1954-1978	Records Search and Site Inspection
15	4	West Burn Pit	North of Jackson-Cass County line and west of the main runway. Site was used for fire training exercises for one year. Typically, waste fuels and waste oils were burned during fire training exercises.	1954-1955	Records Search and Site Inspection
16	ស	South Burn Area	Southwest of South Landfill. Site used for fire training exercises for 10 years. Typically, waste fuels and waste oils were burned during fire training exercises.	1955-1965	Records Search and Site Inspection
17	7	Radioactive Disposal Well	North of the South Landfill and east of the flightline. Low-level radioactive materials were deposited into a cased well.	1955-1970	Records Search and Site Inspection

Table 4-5. Formerly Used Defense Sites Page 2 of 2	Site Dates of Location and Waste Description Operation Current Status	Herbicide Burial Site South end of the runyay. About four cases 1971 Records Search and of herbicide, reportedly containing mercury, site Inspection in plastic pint-sized bottles were reportedly buried in a trench.	Paint Stripper Hangar Facility 1010, former Air Force fighter alert Unknown Records Search and hangar. A spill of a commercial paint Stripper contaminated the surface ditches draining this facility. Also, two metal drum sumps are located outside of two of the hangars and overflow into the surface ditches (IRP Phase II Confirmation/ Quantification Stage 2, 1988).
`	Site Number Si	<b>8</b>	11 P
-	MAP	81	24

idi alda ka Al

)

Richards-Gebaur AFB EBS

December 8, 1993

Table 4-6. Contiguous Property Percel Descriptions

		Parcel Description	Aviation Support, Airfield, Industrial, Institutional (Educational), Public	Facilities/Recreation, Vacant; Deposits of fill and debris noted north of the	base along closed crosswind runway and west of Air Traffic Transceiver.	A fuel station and storage tanks are present near Facility 901.	Military Property; Administrative office, heavy vehicle parking, equipment	storage	Other Military Property, Residential; Military Family Housing	Public Facilities/Recreation; Golf course	Other Military Property; Administrative offices	Other Military Property	Commercial, Public Facilities/Recreation, Residential, Vacant	Other Military Property; Light industrial, heavy equipment storage and	heavy equipment operational training	Public Facilities/Recreation; Church	Agricultural, Commercial; Removed USTs, small office building	Agricultural, Residential; Single-family dwelling	Agricultural, Residential; Single-family dwelling, cattle grazing	Agricultural, Residential; Single-family dwelling, cattle grazing	Agricultural, Residential; Cattle grazing	Agricultural, Residential; Single-family dwelling, cattle grazıng	Agricultural, Residential; Single-family dwelling	
ate <sup>(a)</sup>		Fnysical Inspection   F	A 90 70,01			4		<u> </u>	10/27/93	10/30/93 F		10/27/93	10/27/93	_		10/30/93	10/27/93	10/29/93	10/29/93	10/29/93				
Survey Date <sup>[4]</sup>		Visual Inspection	20,0,0	0/3-9/2/33	-	•	10/29/93		8/3-9/2/93	8/3-9/2/93	10/27/93	8/3-9/2/93	8/3-9/2/93	10/27/93		8/3-9/2/93	9/2/93	9/2/93	9/2/93	9/2/93	10/29/93	10/29/93	10/29/93	
Approximate		Within Study		055,1			σ.	)	88	15	10	2	338	, t	?	1.2	212	41	40	20	20	20	21	
	Number of	Acres within	l givei	1,330			0	)	88		01	) 6	338	2 5 5	2	1.2	212	41	40	20 20	20,2	200	2.2	, 4
Parcel	Number	(see Figure	+	-	-		r	7	~	) 5	יט יו	ກ ຜ	0 1	• 0	×	o	. C	· -	- 2	<u> </u>	<u> </u>	<u>+</u>		2

Note: (a) Dates given as month/day/year

December 8, 1993

# Table 4-7. Areas of Potential Environmental Concern Page 1 of 2

( \_\* '\* '\*

•<del>~</del>•1 •

اا 10 -			Page 1 of 2	
i   \	Map ID	Location	Condition of Off-Base Area of Concern	Specific Environmental Concern
	6	Along base boundary northwest of Petroleum, Oils, and Lubricants (POL) Storage Yard	A large rectangular area of fill material with abrupt changes of vegetation including changes in condition and/or type to areas with no vegetation. Also, dumping of construction debris has taken place, and concrete, wood, asphalt and scrap metal were noted. A hardened tar-like material was also found in this area. It measured approximately 4 feet by 3 feet by 2 feet and its source (either dumped or from the ground) could not be determined.	Changes in vegetation type can be a sign of environmental impairment as different vegetations are more or less tolerant of particular types of contaminants, and lack of vegetation may be due to soils made unsuitable by contamination. The uncontrolled dump could have potential to introduce environmental hazards. The origins and constituents of the tar-like material are unknown and may represent environment
	50	South of Facility 900 and west of Facility 801	Area consists of industrial facilities that maintain aircraft and vehicles and support other industrial operations. Two waste oil ASTs, two diesel fuel ASTs, a vehicle fuel station, five USTs, and a number of former USTs have existed here. An area of drainage leaving this area east of Facility 829 has left no vegetation. However, it could not be determined if this was due to the vigor of the drainage or potential	The industrial operations, ASTs, USTs (former and present), and vehicle refueling operations all have the potential for introducing contamination to base property by surface or subsurface migration. The drainage east of Facility 829 may be evidence of this.
•	21	East of and adjacent to the Small Arms Firing Range parcel	An active skeet range.	The skeet range may be contributing lead contamination behind the Small Arms Firing Range impact berm. The Firing Range Strophase II (August 1993) identified elevated concentrations of lead in the soils behind the Small Arms Range impact berm, facing the Skeet Range.
	AST = UST =	Aboveground storage tank. Underground storage tank.		

Richards-Gebaur AFB EBS

1- December 8, 1993

Areas of Potential Environmental Concern	Pace 2 of 2
Ā	
Table 4-7	

·.••

; • -

Map 1D	Location	Condition of Off-Base Area of Concern	Specific Environmental Concern
22	Northwest of Air Traffic Transceiver parcel, in a natural depression	Apparently active inert debris landfill, approximate dimensions 300 feet by 150 feet by 15 feet. Contents of the landfill appear to be predominately concrete, however, the exact contents are not known.	If organic material is present, the potential for migration of leachate and landfill gas is possible.
	South of Air Traffic Transceiver parcel	This area is the location of two demolished buildings (Facility 1020 and Facility 1021) and a quonset storage structure (Facility 1022). Facility 1021 appears to have been used as a maintenance/industrial shop as heavy POL stains remain on the concrete slab in a "service bay"-like pattern. An areas (15 feet by 10 feet) of subsidence south of Facility 1021's east end is present. A water capture grate runs the length of Facility 1021 along the south side and may be associated with the area of subsidence. In 1983 an unknown 2,000-gallon fuel oil storage tank is listed at Facility 1020.	Disposal practices and chemicals used at the former shop are unknown and therefore have the potential to affect base property. The unknown storage tank could be a UST, and poses a threat for release into subsurface soils. Areas of subsidence are of potential environmental concern and may represent the location of an underground utility such as a sump, UST, or OWS.

Oil/water seperator. Petroleum, oils, and lubricants. Underground storage tank. OWS = Pol = UST ==

THIS PAGE INTENTIONALLY LEFT BLANK

de ilda is d



CHAPTER 5

### 5.0 CONCLUSIONS

~ \* :

This chapter provides the summary of findings for the EBS at Richards-Gebaur AFB.

### 5.1 PROPERTY MATRIX

Table 5-1 provides a summary of all resources by facility, and Table 5-2 lists all facilities with each property. Figure 5-1 shows property boundaries and facility locations. The headings for Table 5-1 are listed below with an explanation of the information being shown:

- Facility (Use): the facility identification number or location and general use of the facility
- Property ID Number: The letters A through J have been assigned to parcels by the base. As the base was further divided based on property categories, for this report, the parcels were given number values in addition to the letters (e.g., A-1, A-2). These designations are shown on Figure 5-1.
- Year of Construction: the year the facility was constructed
- Square Footage: the area of the facility in square feet
- IRP Site: indicates any IRP sites that may affect the facility
- Hazardous Materials

H = facility has been used as a hazardous materials storage area

P = facility has been used to store pesticides Numbers 2 through 7 indicate property categorization

- Hazardous Waste
  - W = facility has been used as a hazardous waste storage area (daily collection point, satellite accumulation point, accumulation point)
  - M = medical/biohazardous waste has been generated within the facility

Numbers 2 through 7 indicate property categorization

- Storage Tanks/OWSs Type: indicates whether the tank is a UST, AST, or OWS. Number in parentheses indicates tank categorization
- Storage Tanks/OWSs Content: indicates what is stored in the tank

- Storage Tanks/OWSs Capacity (gallons): indicates the storage capacity in gallons
- ACM: indicates whether or not the facility contains asbestos

Y = ACM was identified in the asbestos survey

N = no suspected ACM was identified, or building type excludes use of ACM

U = unknown if ACM is present

- Lead-Based Paint: indicates whether the facility was constructed prior to or during 1978; blank = facility was constructed after 1978
- Type of Inspection Completed: indicates which facilities had a visual or physical inspection performed or no inspection conducted
- Overall Property Category: Indicates how the facility has been categorized.

### 5.2 PROPERTY ZONES

Figure 5-2 shows the on-base properties categorized as discussed in Section 1.1. These property zones reflect the findings of the EBS for Richards-Gebaur AFB, as discussed in Chapter 3, including identification of areas considered uncontaminated based on the requirements of CERCLA Section 120 (h).

As discussed in Section 3.3, Category 2 through 7 properties were identified based upon the methodology presented in Chapter 2. All remaining areas were determined to be Category 1.

Areas that stored hazardous materials and/or generated hazardous waste were considered Category 2 unless a suspected or confirmed release was identified. These include dormitories and offices where it is likely that household or office products containing hazardous substances were stored.

Category 3 designations for the apron were based upon existing documentation (e.g., personnel interviews, VSIs, written information). Spills are known to have occurred on the apron area, but the spill reports indicate that releases were minor and all appropriate cleanup actions were taken. Contaminant levels, if present, are considered to be well below action levels.

Areas where known or suspected contamination has occurred were classified as Category 4 through 7 properties based upon the current program status. In addition, new areas of potential contamination identified as a result of this EBS were classified as Category 7.

La datish

Category 1 properties were identified in three vacant and undeveloped areas in the central, eastern, and southern portions of the Cantonment Area, as well as in the southern portion of the Belton Training Complex. Category 2 properties are present in the Cantonment Area in two small areas along the flightline, as well as in most of the central portion of the Cantonment Area. The northeastern and southern portions of the Weapons Bunker, and the access road, are also classified as Category 2 properties. Additional Category 2 properties have been identified as constituting all of the Billeting Complex and Contracting parcels. Category 3 properties consist of the apron area and one small area at the southern end of the flightline. No Category 4 properties were identified at Richards-Gebaur AFB. One Category 5 property was identified at an IRP site at the southern end of the Air Force parking apron. One Category 6 property was identified at an IRP site in the northeastern portion of the Cantonment Area.

Category 7 properties are present on much of the Cantonment Area: a large area in the northeast, along the northern portion of the flightline, in the east along 155th Street, and in three smaller areas in the central and southern portions. Category 7 properties have also been identified as constituting all of the Air Traffic Transceiver, Fire Training Area, Small Arms Range, NDI Laboratory, Gun Storage, and Mobile Radio Transceiver parcels. In addition, Category 7 properties have been identified in the northwest and central areas of the Weapons Bunker and the northern portion of the Belton Training Complex.

### 5.3 RESOURCE MAP

, . . . .

The resource map provided (Figure 5-1) shows the findings of the EBS for Richards-Gebaur AFB based on the records search and VSI. The map identifies IRP sites, locations of storage tanks and OWSs, and locations of hazardous substance storage. The following list describes and explains some of the symbols and shading used on the map. Additional symbols are provided in the map legend.

- H = Hazardous materials used or stored within the facility
- M = Medical/biohazardous waste generated within the facility
- W = Hazardous waste generated or stored within the facility (includes accumulation points)
- A = Red = ACM within facility
   Blue = Presence of ACM within facility unknown
- Facility shaded yellow = Facility constructed prior to or during 1978.


### **5.4 DATA GAPS**

As discussed in Section 1.1, the EBS identifies data gaps that need to be resolved. The plan for resolving these data gaps will be incorporated into the BCP. Data gaps identified to date are listed below.

- A lead-based paint survey has not been conducted.
- The Belton Training Complex has not been investigated to identify potential contamination from current or past activities.

Figure 5-1. Resource Map (Oversized)

THIS PAGE INTENTIONALLY LEFT BLANK



Uncontaminated Property (Category 1)

Hazardous substance stored - no release (Category 2)

> Hazardous substance release. below action levels (Category 3)

Hazardous substance release, all actions have been taken (Category 4)

2500 Feet

Hazardous substance release, not all actions have been taken (Category 5)

Hazardous substance release, no actions taken (Category 6)

Areas requiring additional evaluation (Category 7)

Base Boundary

Property Categorization

Figure 5-2

0

THIS PAGE INTENTIONALLY LEFT BLANK

Table 5-1. Facility/Property Matrix - Richards-Gebaur AFB Page 1 of 7

;

				4	Page 1 of 7								
							5,	Storage Tanks/OWSs	'S <sub>8</sub>				
Facility (Use)	Property ID Number	Year of Construction	Square Footage	IRP Site	Hazardous Materials	Hezardous	Туре	Content	Capacity (gallons) <sup>id</sup>	ACM	Lead Based Paint	Type of Inspection Completed	Overall Property Category
6 (Power Check Pad)	151	1966	NA							z	×	None	
85 (Weather Transmitter)	(6)	1963	NA							z	×	None	2
87 (Weather Transmitter)	(9)	1963	NA .							z	×	None	2
105 (Communeations Facility)	D 12	1954	5,752				AST-A(2)	Diesel	275	>	×	Physical	'
						, , ,	UST-R(7)	Diesel	250				
243 (Dormttory)	E-1	1954	21,352							>	×	None	2
245 [Swimming Pool Water Treatment]	E 1	1961	64		Н 2					Z	×	Pliysical	2
246 (Swimming Pool)	E 1	1960	3,465							Z	×	None	2
247 (Swimmers' Bath House)	E 1	1960	1,152							٨	×	None	2
248 (Open Mess)	E-1	1954	23,934		H-2					۸ ا	×	Physical	2
250 (Dormitory)	E-1	1954	21,352							<b>\</b>	×	None	2
251 (Tennis Court)	E 1	1988	NA							z		None	2
25.2 (Dormitory)	E 1	1954	21,352							<b>&gt;</b>	×	None	2
601 (Base Medical Facility)	0.8	1991	10.500			M 2				z		Physical	2
602  Flight Simufator Training)	D 12	1956	16,444				AST-A12	Diesel	06	<b>*</b>	×	Physical	7
			-		11.2		AST A(2)	Diesel	275				
							1131 1871	Denkerf	1 0000	j	 	-     	
603 IAn Luce Chric)	0.8	1955	1 000		11 2					>	×	Phyria at	,
604 (Air Furce Clinc)	0 11	1955	4,541			Μ.7				>	×	Visual	,
605 (Base Engineering Maintenance Shop)	D 11	1953	15,886	SS 009(7)	H-2	W-2		:		>	×	Physical	7
606 (Base Engineering Administration)	D-8	1953	4,450			•				<b>\</b>	×	Physical	2
607 (Base Engineering Administration)	0.8	1955	2,001							z	×	Visual	2
608 (Base Engineering Storage Shed)	D-8	1962	640							z	×	Physical	2
609 (Base Hazardous Storage)	0.8	1962	300		H-2					z	×	Physical	2
610 (Base Warehouse Supply and Equipment)	D-8	1953	106,252		H-2	W-2	÷			>	×	Physical	2
613 (Base Engineering Storage Shop)	0.8	1962	644							z	×	Physical	2
* Air Force facilities on property owned by Kansas City	s City												•

Richards-Gebaur AFB EBS

_
G.
o)
~
Ō
_
•
8
-
_
•
=
-
=
5
•
Ö
ŏ
~
Ο.

	-	, { ,					•																		•	
	Overall Property Category	2			2	~	2	_	2	2	2	2	2	2	7	`	,			7	1				2	2
	Type of Inspection Completed	Pliveical		•	Physical	None	Physical	Physical	Physical	Physical	Physical	Physical	Physical	Physical	Physic al	Physic of	Physical		·	Physical	Physical				Physical	Physical
	Lead- Based Paint	×	:		×		×	×											Ť	×	×				×	×
	ACM	z	: ,		>		>	z	z	Z	2	2	z	2	z	z	z		7	>	>				z	>
38	Cepacity (gallons)™	90	(2) 09	44				550							10 000	10,000	10,000	10 000 190 50	550		282	200	200	500 550 550		275
Storage Tanks/OWSs	Content	Diesel	MOGAS	Diesel				Waste acid							MOGAS	Dinaol	Gasoline .	Gasoline Waste oil Waste water Waste water	Waste olf		Waste oil	Weste oil	Waste oil	Waste oil Waste water Waste oil		Dieset
S	Type	AST-R(2)	AST-R(2)	AST-R(2)				UST R(7)							AST A(2)	AST AIN	USI RCD	US I-R(7) OWS-R(7) OWS-R(7)	0WS-A(2)	Ì	0WS R(7)	0WS-R(7)	OWS R(7)	OWS R(7) OWS-A(2) OWS-A(2)		ACT A121
	Hazardous Waste						W-2	W-2								' M		_			W-7					W. 2
	Hazardous Matonals								н.2	Н-2	Н 2	Н 2	Н2	Н 2							H-2					4.3
	IAP Site																				\$5-003(5)					
	Square Footage	5,000			4,025	2,982	8,124	4,020	192	800	300	240	576	444	Š	Š	44			2,200	1 6,090		•		5,198	44 796
	Year of Construction	1973			1960	1954	1954	1961	1984	1984	1984	1984	1984	1986	1989	14119	1989			1954	1954				1975	1954
	Property ID Number	9-Q			8-Q	8 Q	9 Q	D-13	9·Q	D-8	D 8	B 0	8 C .	0 B	D 10	E 10	et a			0 10	D 10				9-0	D-8
	Facility (13s0)	614 (Administration Office)			617 (Disaster Preparedness)	618 d (Base Cold Storage)	619 (Branch Exchange)	620 (Document Storage Facility)	621 (Base Hazardous Storage)	622 (Base Hazardous Storage)	623 (Base Hazardons Storage)	624 (Base Hazardous Storage)	625 (Base Hazardous Storage)	626 (Base Supply Open Storage)	700 (Motor Vehicle Gas Storage)	701 (Person) Aurage)	702 (Vehicle Freling Station)			703 (Vehicle Operations Administration)	704 (Vehicle Maintenance Shop)				709 (Reserve Forces Aeromedical Engineering Training)	710 (Reserve Forces Operational

Table 5-1. Facility/Property Matrix - Richards-Gebaur AFB Page 3 of 7

										ĺ			
							Š	Storage Tenke/OWSs					
Facility (Use)	Property ID Number	Year of Construction	Square Footage	IRP Site	Hazardous Materials	Hazardous Wasta	Type	Content	Capacity (gallons)***	ACM	Lead Bated Paint	Type of Inspection Completed	Overall Property Category
711 (Vehicle Refueling Shop)	D-10	1968	1,920			W-2	AST-A12)	Reclaimed JP-4	1,000				-
							OWS R(7)	Waste of	282	>	×	Physical	
							OWS R(7)	Waste oil	1,000				
·	•				,		UST R(7) OWS R(7) OWS A(2) OWS A(2)	JP 4 Wasto water Wasto water Wasto oil	5,000 5003 5003 500				
750 (Recreation Facility)	D 16	1962	۸A							z	×	Visual	-
754 (Recreation Facility)	D-16	1967	NA							2	×	Visual	-
755 (Recreation Facility)	D-16	1964	NA							2	×	Visual	-
757 (Santary Latrino)	D-16	1964	238							2	×	Vistial	-
801 (Survival Equipment Shop)	-	1954	5,425							>	×	Physical	2
828 (Weapons and Release Systems Shop)	Н 1	1958	11,276		H-2	w 2	UST R(7)	Fuel all Fuel oil	1,500	>	×	Physical	,
839 (Non Destructive Inspection Laboratory)	К1	1961	6,014		н-2	W-2	UST R(7)	Fuel ort	4,000	>	×	Physical	_
841 (Fixed Tactical Air Navigational System)	(9)	1956	363				AST A(2)	Dieset	275	2	×	Physical	2
844 (Equipment Pad)	(ql	1971	360							2	×	None	2
845 (Hertiical Power Station)	ig)	Unknown	Unknown							2	×	None	2
846 (Equipment Pad)	2	1957	234							2	×	Norre	7
H48 (Sperial Tower)	ā,	1982	25							2		None	2
900 (Fire Station)	0.0	1954	12.249			W-2				<b>&gt;</b>	×	Physical	2
901 (Base Operations)	0.9	1954	8,879				AS1 A(3)	Diesel	275	<b>*</b>	×	Physical	3
902 d (Liquid Fuel Pump Station)	0.5	1954	520	ST-007(5)			UST-R(5)	JP-4	25,000 (4)			Physical	5
903 (Electric Power Statlon Building)	-	1961	233				UST-U(7)	Diasel	250	2	×	Physical	7
904 (Base Hazerd Storage)	0 1	1957	400		Н 2					2	×	Physical	7
918 (Maintenance Hangar)	D 1	1957	73,260		Н 2	W-7	AST A(2)	MOGAS	20	<b>&gt;</b>	×	Physical	١,
920 (Vehicle Service Reck)	11 0	1955	1,000	•			0WS R(7)	Weste oil	200	2	×	Physical	_
						ı	OWS R(7) OWS-A(2) OWS-A(2)	Weste oil Weste water Weste oil	500 550 550				
921 (Distal Storage)	D-11	1955	Ν				AST-R(2)	Dissel	1,000	z	×	Physical	_
										1			

AFB	
- Richards-Gebaur	
×	^
Matr	ö
Σ	4
Facility/Property	Page
e 5-1.	
Tab	

140

										ľ			
							Š	Storage Tanks/OWSs					
Facility (Uso)	Property ID Number	Year of Construction	Square	IRP Site	Hazardous Materials	Hezardous Waste	Type	Content	Capacity (gallons)	ACM	Lead Based Pant	Type of Inspection Completed	Overall Property Category
922 (Open Storage)	D-11	Unknown	Unknown							z	×	Physical	7
923 (Base Engineering Storage Shed)	D-11	1961	6,256(5)	SS-004(5)	₩.2					z	×	Physical	7
924 (Base Engineering Paving Ground f at lifty)	D-11	8561	925			W-7				z	×	Physical	7
925 (Nosorvo I orces Traumy)	0.8	1962	3,454				•		•	٨	×	Physical	2
926 (Headquarters Group)	D 8	1959	5,364							<b>*</b>	×	None	2
927 (Jet Engine Inspection and Maintenance Shop)	D-1	1959	13.278	SS-006(5)	Н-2	W-2	UST-A(7) OWS-I(7) OWS-I(7)	Waste oil Waste water Waste solvents	500 400 100	<b>&gt;</b>	×	Physical	7
928 (Base Engineering Hezardous Storegel	D-1	1989	182		Н-2	W-2				z		Physical	7
930 [Electronic Counter Measures Pad Shop/Storage]	D-1	1961	14,695		H-2					>	×	Physical	۲
931 (Liquid Oxygen Storage)	D-8	1964	2,308							z	×	Physical	2
936 (Base Hezardous Storage	D 8	1976	960		H-2					z	×	Physical	2
937 (Base Hazardous Storage)	DB	1954	640		H-2					z	×	Physical	2
938 (Water Pump Station)	D-1	Unknown	Unknown				UST R(Z)	Gasoline	100	z	×	Physicat	7
940 (Aucraft General Purpose Shop)	. D 1	1955	71,813		Н-2		OWS-R(7) OWS R(7)	Waste water Waste oil	1,075	>	×	Physical	7
941 (Truck Fill Stand)	DI	1955	NA							z	×	Physical	,
942 (Heating Facility Building)	D 1	1955	2,568				UST R(7)	Fuel oil #2	15,000 (2)	>	×	Physical	7
943 Industrial Wasto Treatment and Disposal Depotation (Inserveil)	D 1	1975	N							z	×	Physical .	,
944 d (Engine Test Cell)	D-1	1956	NA				OWS R(7) AST-R(2) OWS-R(7)	Waste fuel/oil JP-4 Waste oil	1,000	_	×	Physical	7
945 (Aircraft Wash Pad)	D:1	1952	60.003	SS-008(7)	•		AST-R(2)	JP-4	500 (2)	z	×	Physical	7
					•	,	AST-R(2)	Waste PD-680, paint thuner, POL	1,000 (2)				
946 (Base Hazardous Storage)	D-1	1960	300							z	×	Physical	7



(1)cl



# General Testing Laboratories, Inc.

## **Engineering** — Chemical Consultants





Date	July 29	_	198 <u>_</u> 8		Number	74414
Sample of .		14 .	Samples	Sample # 958-004		
Marked		Richards	Gebaur AFB # 2, 7	7-15 - Received in lab	7-15-88	
Client		EPIC,	Inc., ATTN: Conny	7 Todd	_	
TOTAL ME	TALS				-	
	Arsenic			< 0.05 ppm		
	Barium			< 0.5 ppm		•
	Cadmium			< 0.5 ppm		
	Chromium	n		< 0.5 ppm		
	Lead			1.9 ppm		
	Mercury			< 0.01 ppm		
	Selenium	n		< 0.05 ppm		
	Silver			< 0.5 ppm		
	Polychlo	orinated I	Biphenyls	< 1.00 ppm		

GENERAL TESTING LABORATORIES, INC.

Table 5-1. Facility/Property Matrix - Richards-Gebaur AFB

_	
7	
ō	
ß	
Page	
ä	

							g,	Storage Tanks/OWSs	5.8				
Facility (Use)	Property ID Number	Year of Construction	Square Footage	IRP Site	Hazardous Materials	Hazardous Waste	Туре	Content	Cepecity (cellons)	ACM	Leed- Bated	Type of Inspection Completed	Overall Property
947 (Corresion Control Utility Storage)	D.1	1958	096				UST-R(7)	Solvent-based cleaning compound	1	z	+	Visual	,
948 (Fuel Systems Mamtenance Dock)	0 1	1963	24,014		H-2	W-2	(5)81-R(7)	Waste oil	200	>	×	Physical	7
949 (Corrosion Control Utility Storage)	D 1	1963	240	   						z	×	Piveront	-
950 (Transformer Storage)	0-1	Unknown	Unknown							z	×	Physical	
951 (Base Engineering Maintenance Shop)	D-2	1954	992	ST 005(6)						>	×	Physical	9
952 (Truck Fill Stand)	0.2	1954	NA	ST-005[6]						z	×	Physic of	ء ا
953 (Liquid fuel Pump Station)	D 2	1954	518	ST 005(6)		W 2	AST R(2)	Diesel	44	z	×	Physic at	
954 (Heating Fuel Oil Storage)	ā	1954	NA	ST-005(6)			AST-1(7)	Heating oil	260,000	z	×	Physical	
955 (Jet Fuel Storage)	0.2	1954	AN	ST-005(6)			AST-A(2)	JP.4	187,000	z	×	Physical	9
957 (Jet Fuel Storage)	0.5	1956	ΝA	ST 005(6)			AST-A(2)	JP-4	210,000	z	×	Physical	9
958 (Aircraft Support Equipment Shop)	-0	1963	4,000		H-2	W 2	UST-R(7)	Fual oil #2	250	>	×	Physical	7
							AST-R(2)	Waste PD-680, paint thinner, POL	200	_			
959 (Bese Hezardous Storage)	D 1	1989	140		H-2	W-2				z		Physical	7
960 (Liquid Fuel Stand)	ī.	1955	NA							z	×	Physical	-
961 (Aircraft Wash Rack Pad)	ة	1963	40,203			7				z	×	Physical	_
962 (Aircreft Support Equipment Shop)	10	1984	1,875				UST A(7)	JP-4	4,000	z		Physical	7
7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7							UST-A(7)	Gastoline	4,000		7		
sos (Aboveground Storage Lank)	-	Unknown	Unknown				AST-A(7)	Solvent	200	z	×	Physical	7
964 (Liquid Oxygon Storage)	10	1990	1,031		Н-2					z		Physical	7
965 (Aircraft General Pupasa Ship)	=	9961	22 187		11.2	W 7	UST R(7)	Wastn oil	12 000	<b>*</b>	×	Tryan at	_
966 (Maintenance Dock)		1966	22,339		H-2	W-2				>	×	Physical	
968 (Test Stand)	÷	1982	ΑN							z		Physical	,
970 (Refueling Vehicle Parking)	9.1	1988	2,520			W-2				z		Physical	-
971 (Petroleum Operations)	D 14	1988	1,500		H-2					z		Physical	,
972 (Base Mazerdous Storege)	Ġ	1989	256			W-2				Z		Physical	7
973 (Base Hazardous Storage)		1989	1,200	SS-006(7)		W-2				z		Physical	7

1377.

							S	Storage Tanks/OWSs	Ss				
									L		Lead.	Type of	Overall
Facility	Property ID Number	Year of Construction	Square Footage	IRP Site	Hazardous Materials	Hazardous Waste	Туре	Content	Capacity (gallons) <sup>tal</sup>	ACM	Paint	Inspection Completed	Category
1009 (Instrument Landing System Localizer)	<u>i</u>	Unknown	Unknown				AST·A(2)	MOGAS	275	z	×	Physical	2
1011 (Flectical Power Station)	199	1962	128				AST-R(3)	MOGAS	275	Z	×	Physical	3
1025 (Air Traffle Transcoivers)	¥-1	1953	1,048				AST A(2)	Diesel	06	>	×	Physical,	٠ ،
		l					AST-A(2)	Diesel	275				
							AST-A(2)	Diesel	999				
	•						UST-R(7)	Fuel oil #2	550				٠
							UST-R(7)	Diesel	275				
		•			,		UST-R(7)	Fire on #2	1,000				
1027 (Support Structure Antenna)	A-1	1969	Ą							z	×	None	7
1033 (Fire Transma Facility)	- B	1973	AN	FT-002(5)		W 2	AST-RI7	Weste JP.4	6,000	z	×	Physical	7
							(7)1 SMO	Waste oil	425				
							OWS-R(7)	Waste oil	565				
1049 (Range Control House)	5	1956	2,320							z	×	Physical	7
1050 (Storage Magazine Aboveground)	2	1956	100							z	×	Physical	,
1100 (Mobile Radio Transceiver)	1.7	1953	1 048				AST-A(2)	MOGAS	275	>	×	Physical	7
							UST R(7)	Fuel oil #2	220				
							UST R(7)	Gasoline	250				
1101 (Support Structure Antenna)	F 1	1969	AN							z	×	None	,
1201 (Weapons System Maintenance	6.2	1961	1,429	,	,		UST-R(7)	Fuel oil #2	3,000	>	×	Physical	,
Management Facility)			,	,									
1202 (Missile Assembly and Training)	6.2	1961	3,852		14-2	W-2	UST R(7)	Fuel oil #2	1,500	>	×	Physical	۲
							1151 11(7)	Fuel oil #2	1 650				
1203 (Storage Magazina Aboveground)	. G 1	1961	5,644		11.2					z	×	Physic at	2
1 205 (Base Hezardous Storage)	G-1	1962	53,							z	×	Physical	2
1 206 (Spares Inert Storage)	G-2	1991	6,000							z		None	2
1 207 (Equipment Pad)	G·1	1991	7,074							z		None	2
1401 (Instrument Landing System Localizes)	(a)	1957	186				AST-R(2)	MOGAS	275	z	×	Visual	2
1600 (Reserve Forces Operational Training)	1-6	1956	1,267							z	×	Physical	7
						1						•	

Richards-Gebaur AFB EBS

3
99
6
_
œ
œ.
8.
ber 8.
mber 8.
emper
scember 8.
emper
emper

Facility (Use) Number 1601 (Reserve Forces Operational J.1 Treining)													
								Storage Tanks/OWSs	'Ss				
		Year of Construction	Square Footage	IRP Site	Hazardous Materials	Hazardous Waste	- L	Content	Capacity	Ş	Lead- Based	Type of Inspection	Overall
	1.	1956	1,267							z	×	Physical	Category 7
Duringii	  -	1960	35							z	×	Physical	1
1604 (Reserve Forces Operational J-1 Training)	<del> </del>	1966	543							z	×	Physical	7
1605 (Generator Building)	-	Unknown	Unknown							2	,		,
1800 Ilnstrument Landing System Marker Boacon)	<u> </u>	Unknown	Unknown							2 2	< ×	None	,   -
1900 (Instrument Landing System (b) Market Beacon)	2	Unknown	Unknown							z	×	None	7
9470 (OWS and Waste Storage) D 1	_	1958	۸N				OWS-A(7)	Waste oil	282	z		Physical	-
			ž				OW', A(7)	Watte od	1,000		_		, a
							OW5 18(7)	Waste oil	1,400				•
			·				OWS R(7) OWS A(2) OWS A(2)	Waste oil . Waste oil	7,800 550	_			
9610 (Fuel Storage) D.2	- 2	1958	NA	ST-005[6]			AST-1(2)	MOGAS	10,000	z	×	Physical	9
	_						AST-1(2)	Diesel	10,000				

(b) Air Force owned/operated facilities on non-Air Force property

ACM = Asbestos-containing material
AST = Aboveground storage tank
d = Aboveground storage tank
d = Edulid mass been demolished
H = Facility usage included storage of hazardous materials
I = Inactive
MoGAS = Motor gaboliazardous waste generated within the facility
MOGAS = Motor gaboliazardous waste generated within the facility
MOGAS = Motor gaboliazardous waste generated within the facility
N = Not applicable
OWS = Oil/water separator
POL = Motor gaboriazardous wastes were generated or stored
U = Underground storage tank
W = Facility where hazardous wastes were generated or stored
X = Facility was constructed prior to or during 1978
Y = Yes

Table 5-2. Property/Facility Key Page 1 of 4

Property ID Number, Property Category	Facility (Use)
A-1,7	1025 (Air Traffic Transceivers)
<u> </u>	
0.1.7	1027 (Support Structure Antenna)
B-1,7	1033 (Fireman Training Facility)
C-1,7	1049 (Range Control House)
	1050 (Storage Magazine Aboveground)
D-1.7	903 (Electric Power Station Building)
	904 (Base Hazard Storage)
	918 (Maintenance Hangar)
	927 (Jet Engine Inspection and Maintenance Shop)
	928 (Base Engineering Hazardous Storage)
	930 (Electronic Counter Measures Pad Shop/Storage)
	938 (Water Pump Station)
	940 (Aircraft General Purpose Shop)
	941 (Truck Fill Stand)
	942 (Heating Facility Building)
	943 (Industrial Waste Treatment and Disposal Detention Reservoir)
	944-d (Engine Test Cell)
	945 (Aircraft Wash Pad)
	946 (Base Hazardous Storage)
	947 (Corrosion Control Utility Storage)
	948 (Fuel Systems Maintenance Dock)
•	949 (Corrosion Control Utility Storage)
	950 (Transformer Storage)
	958 (Aircraft Support Equipment Shop)
	959 (Base Hazardous Storage)
	960 (Liquid Fuel Stand)
	961 (Aircraft Wash Rack Pad)
	962 (Aircraft Support Equipment Shop)
	963 (Aboveground Storage Tank)
	964 (Liquid Oxygen Storage)
	965 (Aircraft General Purpose Shop)
	966 (Maintenance Dock)
	968 (Test Stand)
	970 (Refueling Vehicle Parking)
	971 (Petroleum Operations)
	972 (Basa Hazardous Storage)
	973 (Base Hazardous Storage)
	9470 (OWS and Waste Storage)
D-2,6	951 (Base Engineering Maintenance Shop)
0-2,6	952 (Truck Fill Stand)
	953 (Liquid Fuel Pump Station)
	954 (Heating Fuel Oil Storage)
	955 (Jet Fuel Storage:

Table 5-2. Property/Facility Key Page 2 of 4

NV 10 5 78

Property ID Number,	Facility (Use)
Property Category	957 (Jet Fuel Storage)
D-2,6 (Continued)	9610 (Fuel Storage)
	Open land in central part of Cantonment Area
D-3,1	
D-4,3	Aircraft Apron
D-5,5	902-d (Liquid Fuel Pump Station)
D-6,1	750 (Recreation Facility)
	754 (Recreation Facility)
	755 (Recreation Facility)
	757 (Sanitary Latrine)
D-7,1	Open land north of Arnold Avenue, west of Facility 602
D-8.2	601 (Base Medical Facility)
	603 (Air Force Clinic)
	606 (Base Engineering Administration)
	607 (Base Engineering Administration)
	608 (Base Engineering Storage Shed)
	609 (Base Hazardous Storage)
	610 (Base Warehouse Supply and Equipment)
	613 (Base Engineering Storage Shop)
	614 (Administration Office)
	617 (Disaster Preparedness)
	618-d (Base Cold Storage)
	619 (Branch Exchange)
	621 (Base Hazardous Storage)
	622 (Base Hazardous Storage)
	623 (Base Hazardous Storage)
	624 (Base Hazardous Storage)
	625 (Base Hazardous Storage)
	626 (Base Supply Open Storage)
	710 (Reserve Forces Operational Training)
	900 (Fire Station)
	925 (Reserve Forces Training)
	926 (Headquarters Group)
	931 (Liquid Oxygen Storage)
<u>.</u>	936 (Base Hazardous Storage
	937 (Base Hazardous Storage)
D-9,3	901 (Base Operations)
D-9.7	709 (Reserve Forces Aeromedical Engineering Training)
D-10,7	700 (Motor Vehicle Gas Open Air Storage)
	701 (Diesel Open Air Storage)
	702 (Vehicle Fueling Station)
	703 (Vehicle Operations Administration)
	704 (Vehicle Maintenance Shop)
	711 (Refueling Vehicles Shop)
	rest transcentify terraine empty

Table 5-2. Property/Facility Key Page 3 of 4

Property ID Number,	Facility (Has)
Property Category	Facility (Use)
D-11,7	605 (Base Engineering Maintenance Shop)
	920 (Vehicle Service Rack)
	921 (Diesel Storage)
	922 (Open Storage)
	923 (Base Engineering Storage Shed)
	924 (Base Engineering Paving Ground Facility)
D-12,7	105 (Communications Facility)
	602 (Flight Simulator Training)
	604 (Air Force Clinic)
D-13,7	620 (Document Storage Facility)
E-1,2	243 (Dormitory)
	245 (Swimming Pool Water Treatment)
	246 (Swimming Pool)
	247 (Swimmers' Bath House)
	248 (Open Mess)
	250 (Dormitory)
	251 (Tennis Court)
	252 (Dormstory)
F-1,7	1100 (Mobile Radio Transceiver)
	1101 (Support Structure Antenna)
G-1,2	1203 (Storage Magazine Aboveground)
	1205 (Base Hazardous Storage)
	1207 (Equipment Pad)
G-2,2	1206 (Spares Inert Storage)
G-2,7	1201 (Weapons System Maintenance Management Facility)
	1202 (Missile Assembly and Training)
H-1,7	828 (Weapons and Release Systems Shop)
1-1,2	801 (Survival Equipment Shop)
J-1,7	1600 (Reserve Forces Operational Training)
,,	1601 (Reserve Forces Operational Training)
	1602 (Reserve Forces Operational Training)
	1604 (Reserve Forces Operational Training)
	1605 (Generator Building)
J-2,1	Open land, southern half of Belton Training Complex
K-1,7	839 (Non-Destructive Inspection Laboratory)
(a),3	6 (Power Check Pad)
(a),2	85 (Weather Transmitter)
(a),2	87 (Weather Transmitter)
(a),2	841 (Fixed Tactical Air Navigational System)
(a),2	844 (Equipment Pad)
(8),2	845 (Electrical Power Station)
	846 (Equipment Pad)
(a),2	4 to (edishusult i sa)

Note: (a) Air Force facilities on property owned by Kansas City

 $f_{I}^{A}$ 

Table 5-2. Property/Facility Key Page 4 of 4

Property ID Number, Property Category	Facility (Use)	
(a),2	848 (Special Tower)	
(a),2	1011 (Electrical Power Station)	
(a),2	1401 (Instrument Landing System Localizer)	
(a),2	1900 (Instrument Landing System Marker Beacon)	
(a),7	1009 (Instrument Landing System Localizer)	
(a),7	1800 (Instrument Landing System Marker Beacon)	

Note: (a) Air Force facilities on property owned by Kansas City

THIS PAGE INTENTIONALLY LEFT BLANK



CHAPTER 6

11

## CERTIFICATION OF THE RICHARDS-GEBAUR AIR FORCE BASE, MISSOURI ENVIRONMENTAL BASELINE SURVEY

The Environmental Baseline Survey of Richards-Gebaur Air Force Base utilized only those techniques, procedures, and processes described in this report. In our professional judgment and opinion, the facts and conditions depicted are accurate and are subject to limitations inherent in the investigative techniques used and any expressed limitations in this survey.\_\_\_\_

investigative techniques used and any expressed limitations in this survey.	
Sandra L. Cuttino, P.E.  Program Director  Air Force Base Closure - BRAC II	197 *
I certify that the property conditions and data presented in this draft report indical condition of property noted herein, and was based on a review of available record and sampling results available at the time of the survey.	ate the environmental ds, visual inspections,
P. Mark Esch BRAC Environmental Coordinator OLQ, AFBCA	6_Dec 93 Date
I have reviewed the preparer's methodology and report, and concur with the me findings to the best of my knowledge and belief.	thodology and
Marion Erwin, HQ AFCEE, Project Manager	ZDEC93
The conditions noted in this report are true to the best of my knowledge and bel	lief.
Theresa Pohlman, HQ AFBCA, Program Manager	9 Dec 93 Date
Michael Larson, HQ AFBCA, Environmental Reviewer	9 Dec 9 3

THIS PAGE INTENTIONALLY LEFT BLANK

#### LIST OF PREPARERS

- W. David Ahlborn, Project Environmental Professional, The Earth Technology Corporation B.A., 1980, Geography, California State University, San Bernardino Years of Experience: 10
- Calvin Cox, Senior Staff Geologist, The Earth Technology Corporation B.S., Geology, 1986, San Diego State University, San Diego Years of Experience: 3
- Sandra Lee Cuttino, P.E., Environmental Manager, The Earth Technology Corporation B.S., 1979, Civil Engineering, University of California, Davis Years of Experience: 14
- Marion S. Erwin, Environmental Engineer, U.S. Air Force, HQ AFCEE/ESER B.A., 1972, Biology, Cornell College, Iowa M.S., 1975, Environmental Engineering, University of Illinois, Urbana B.S., 1981, Civil Engineering, Southern Illinois University, Edwardsville Years of Experience: 10
- David Golles, Senior Staff Environmental Specialist, The Earth Technology Corporation B.A., 1988, Environmental Studies, California State University, San Bernardino Years of Experience: 4
- Peter L. Grill, Senior Staff Environmental Specialist, The Earth Technology Corporation Environmental Studies, California State University, San Bernardino Years of Experience: 5
- Maria Langmaack, Project Environmental Specialist, The Earth Technology Corporation B.A., Geography, 1987, California State University, San Bernardino Years of Experience: 6
- Thomas J. McGill; Deputy Office Director, The Earth Technology Corporation A.B.; 1971, Biology, Harvard College M.A., 1974, Ecology, University of California, Santa Barbara Ph.D., 1978, Genetics, University of California, Santa Barbara Years of Experience: 15
- Nancy Schling, Staff Environmental Specialist, The Earth Technology Corporation B.A., 1988, Geography, California State University, Long Beach Years of Experience: 4
- Larry Sievers, Senior Project Environment Professional, The Earth Technology Corporation B.S., 1988, Biology, California State University, Los Angeles Years of Experience: 6


15 1 75

Mark Walters, Senior Staff Environmental Specialist, The Earth Technology Corporation B.S., 1992, Environmental Science, University of California, Riverside Years of Experience: 4

Barbara Zeman, Senior Project Environmental Professional, The Earth Technology Corporation B.S., 1976, Electrical Engineering, Rutgers University, New Jersey M.S., 1978, Biomedical Engineering, University of Southern California, Los Angeles Years of Experience: 12



**APPENDICES** 



APPENDIX A

APPENDIX A

REFERENCES

### **REFERENCES**

- American Society for Testing and Materials, 1993 <u>Standard Practice for Environmental Site</u>

  <u>Assessments Phase I Environmental Site Assessment Process</u>
- Burns and McDonnell, 1991. <u>IRP Site Inspection SS-006 Hazardous Material Storage Area</u>
  <u>Richards-Gebaur Air Force Base, Internal Draft Report, Missouri, Kansas City, Missouri, November.</u>
- Burns and McDonnell, 1992a. Industrial Waste Line Study, Kansas City, Missouri, September.
- Burns and McDonnell, 1992b. <u>IRP Remedial Investigation Site ST-005 POL Storage Yard Richards-Gebaur Air Force Base, Missouri Final Report, Kansas City, Missouri, November.</u>
- Burns and McDonnell, 1992c. Remedial Action Site SS-003/SS-004 Oil Saturated Area and Hazardous Waste Drum Storage Area Richards-Gebaur Air Force Base, Missouri Final Closure Report, Kansas City, Missouri, May.
- Burns and McDonnell, 1992d. <u>Supplemental Remedial Investigation Report</u>, Kansas City, Missouri, April.
- Burns and McDonnell, 1992e. <u>Technical Specifications for Upgraded UST Sites</u>, Kansas City, Missouri, June.
- Burns and McDonnell, 1993a. <u>IRP Site Inspection SS-008 Test Cell Area Richards-Gebaur Air Force</u>
  <u>Base, Missouri Internal Draft Report,</u> Kansas City, Missouri, May.
- Burns and McDonnell, 1993b. <u>IRP Site Inspection Site SS-008 Test Cell Area Richards-Gebaur Air Force Base, Missouri: Work Plan, Kansas City, Missouri, January.</u>
- Burns and McDonnell, 1993c. <u>Water Course Soil Assessment Richards-Gebaur Air Force Base</u>.

  <u>Missouri Phase II Final Report</u>, Kansas City, Missouri, August.
- Burns and McDonnell Engineering, 1993a. <u>Firing Range Site Phase II Richards-Gebaur Air Force</u>
  <u>Base, Missouri Final Report, Kansas City, Missouri, August.</u>
- Burns and McDonnell Engineering, 1993b. <u>Firing Range Site Richards-Gebaur Air Force Base</u>, Kansas City, Missouri, April.
- Burns and McDonnell Engineering, 1993c. <u>IRP Remedial Action SS-006 Hazardous Material Storage</u>
  <u>Area Richards-Gebaur Air Force Base Final Work Plan</u>, Kansas City, Missouri, May.
- Burr, D., 1993. Personal communication with Dennis Burr, Bioenvironmental Engineer at Richards-Gebaur AFB, 13 April.

- Burt, K., 1993. Personal Communication with Keith Burt, Supply Manager at Richards-Gebaur Air Force Base, 14 April.
- CH<sub>2</sub>M Hill, 1983. <u>Installation Restoration Program Records Search</u>, Gainesville, Florida, March.
- Dalzal, B., 1993. Personal communication with Bob Dalzal, Environmental Engineer at Richards-Gebaur Air Force Base, 13 April.
- Dietz, C., 1993. Personal communication with Curt Dietz of MDNR RCRA Compliance, 15 April.
- EA Engineering, Science, and Technology, Inc., 1992. <u>Storm Water Report Richards-Gebaur Air</u>

  <u>Force Base Belton, Missouri, Sparks, Maryland, August.</u>
- Ecology and Environment, Inc. 1988. <u>Installation Restoration Program Phase II</u>
  <u>Confirmation/Quantification Stage 2</u>, Lancaster, New York, July.
- Environmental Protection Inspection and Consulting, Inc., 1991. Work Plan for Underground Storage Tank Closures Backfilling and Restoration, Liberty, Missouri, November.
- Environmental Risk Information and Imaging Services, 1992. Report Pertaining to Richards-Gebaur AFB, Belton, Missouri, Alexandria, Virginia, July.
- General Testing Laboratories, Inc., 1989a. <u>Geoenvironmental Exploration Building 923 Richards-Gebaur AFB, Missouri</u>, Kansas City, Missouri, November.
- General Testing Laboratories, Inc., 1989b. <u>Geoenvironmental Exploration Building 923 Richards-Gebaur AFB, Missouri</u>, Kansas City, Missouri, October.
- Geraghty and Miller, Inc, 1991a. <u>Sanitary Sewer/Storm Water Runoff Study</u>, Richards-Gebaur AFB, Missouri, December.
- Geraghty and Miller, Inc., 1991b. <u>Site Inspection ST-007 Report Leaking Underground Storage</u>
  Tank (LUST), Building 902, Overland Park, Kansas, November.
- Hall-Kimbrell, 1987. <u>Asbestos Assessment Study for Richards-Gebaur Air Force Base, Kansas City,</u>
  Missouri, Kansas City, Missouri, September.
- Hershie, A., 1993. Personal communication with Al Hershie, Real Property Officer at Richards-Gebaur Air Force Base, 16 April.
- Intelcom Support Services, 1992. <u>ISSI/CEM Support Tank Identification</u>, Kansas City, Missouri, March.
- Intelcom Support Services, 1993. Results of JP-4 Storage Tank Leak Check, Richards-Gebaur AFB, Missouri, May.

Ling of the Land of the Artistic of the Lind of the Li

- Jolly, A., 1993. Personal Communication with Andrew Lolly, Liquid Fuels Manager at Richards-Gebaur Air Force Base, 12 April.
- Leffler, Raymond (Quality Assurance Officer), 1985. Memo on Facility 953 (Liquid Fuel Pump Station), Richards-Gebaur AFB, Missouri, February
- Missouri, 1993. Code of State Regulations, Division 10-Department of Natural Resources, March.
- Missouri Department of Agriculture, 1993. Missouri Pesticide Use Act, Jefferson City, Missouri.
- Missouri Department of Health, 1988. Distribution of Indoor Radon Screening Measurements.
- Missouri Department of Natural Resources, 1985. MHWMI and RCRA Compliance Inspection Report, Independence, Missouri, June.
- Missouri Department of Natural Resources, 1992. <u>Underground Storage Tank Closure Guidance Document</u>, Jefferson City, Missouri, January.
- Missouri Department of Natural Resources, 1993a. <u>List of Registered USTs</u>, Independence, Missouri, April.
- Missouri Department of Natural Resources, 1993b. <u>Missouri Distribution of Indoor Radon Screening Measurements</u>, April.
- Missouri Public Service, 1988a. Results of Transformer Testing, Grandview, Missouri, October.
- Missouri Public Service, 1988b. PCB Content, Grandview, Missouri, May.
- Moore Analytical, 1986. Test Reports on Transformers, Sun Prairie, Wisconsin, October.
- O'Brien and Gere, 1990a. <u>Preliminary Assessment (PA) Hazardous Material Storage Site Area</u>
  <u>Richards-Gebaur Air Force Base Belton, Missouri, St Louis, Missouri, July.</u>
- O'Brien and Gere, 1990b. Remedial Investigation, St. Louis, Missouri, July.
- O'Brien and Gere, 1991. <u>Preliminary Assessment for the Hazardous Material Storage Bldg 927</u>
  (Site SS-006), St Louis, Missouri, October.
- Pilcher, T., 1993. Personal communication with Tom Pilcher, Environmental Engineer at Richards-Gebaur Air Force Base, 12 April.
- Power Systems Analysis, Inc., 1988. <u>Field Inspection Data</u>, Richards-Gebaur AFB, Missouri, January.
- Preston, 1993. Personal Communication with Capt Preston, Public Affairs Officer at Richards-Gebaur Air Force Base, 13 April

- Snider, 1993. Personal Communication with Sgt Snider of Munitions Maintenance at Richards-Gebaur Air Force Base, 14 April.
- SOS Extermination, 1993. Telephone communication with Don Franke, owner of SOS Extermination regarding pesticide usage, 14 April.
- Tetra Tech, Inc. 1982. Environmental Assessment for the Proposed Mission Change at Richards-Gebaur AFB, Missouri, Jacksonville, Florida, January.
- Thompson, J., 1993. Personal communication with J. Thompson, Project Manager at Kansas City District Corps of Engineers Toxic and Hazarcous Waste Branch, regarding status of Formerly Used Defense Sites adjacent to Richards-Gebaur AFB.
- U.S. Air Force 442 CSG/DE, 1990. <u>Transformer PCB Test Report</u>, Richards-Gebaur AFB, Missouri, September.
- U.S. Air Force 442 CSG/DE, 1992. <u>Transformer PCE Test Report</u>, Richards-Gebaur AFB, Missouri, October.
  - U.S. Air Force 442 Support Group, 1992a. <u>Hazargous Waste Management Plan</u>, Richards-Gebaur Air Force Base, Missouri, October.
  - U.S. Air Force 442 Support Group, 1992b. Operational Plan for Spill Prevention, Control and Countermeasures, Richards-Gebaur Air Force Base, Missouri, October.
  - U.S. Air Force, 1983, 1986, 1987, 1988, 1989, 1990, 1991, 1993. Spill Incident Reports, Richards-Gebaur AFB, Missouri
  - U.S. Air Force, 1990. Environmental Evaluation Recort Environmental Compliance Assessment and Management Program (ECAMP), Richards-Gebaur AFB, Missouri, August.
  - U.S. Air Force, 1992a. <u>Application for Discharge Permit</u>, Richards-Gebaur AFB, Missouri, September.
  - U.S. Air Force, 1992b. <u>Environmental Compliance Assessment and Management Program (ECAMP)</u>
    <u>Richards-Gebaur Air Force Base, Missouri FY 92</u>, Kansas City, Missouri.
  - U.S. Air Force, 1992c. Executive Summary for Upgraded UST Sites, (excerpts) June.
  - U.S. Air Force, 1993a. Real Property Inventory Change Report, Richards-Gebaur AFB, Missouri, April.
  - U.S. Air Force, 1993b. <u>Richards-Gebaur AFB Hazarzous Waste Register</u>, Richards-Gebaur AFB, Missouri, August.
  - U.S. Air Force, 1993c. UST Data Sheets, Richards-Sebaur AFB, Missouri

- U.S. Air Force AFCEE, 1993. <u>Statement of Work PA/SI Fire Valve Area and Assess Drainage Pond, Sediments</u>, Brooks AFB, Texas, May.
- U.S. Air Force Base/Liquid Fuels Management, Richards-Gebaur Air Force Base, 1993. <u>Fuels</u>
  <u>Consumption Data for Diesel, MOGAS, and JP-4, for the years 1991, 1992 and 1993</u>
  <u>through March</u>
- U.S. Air Force CES, 1987. Closing of Motor Vehicle Paint Booth Richards-Gebaur AFB, Missouri, October.
- U.S. Air Force CES, 1991. <u>AF Form 1391 Study Abandon Fuel Lines</u> Richards-Gebaur AFB, Missouri, December.
- U.S. Air Force/Liquid Fuels Management, Richards-Gebaur Air Force Base, 1993. <u>Leak Check</u>

  Computations for Tank Numbers 955 and 957, for the years 1989, 1990, 1991, and 1992.
- U.S. Air Force Reserves, 1990. <u>Decision Document North Burn Pit Area</u>, Robins Air Force Base Georgia, May.
- U.S. Air Force Reserves, 1991. <u>Decision Document Leaking Underground Storage Tank (Site ST-007) Richards-Gebaur Air Force Base, Missouri,</u> Robins Air Force Base, Georgia, December.
- U.S. Air Force Reserves, 1992a. <u>Decision Document Hazardous Waste Drum Storage (Site SS-004)</u>
  <u>Richards-Gebaur Air Force Base, Missouri,</u> Robin Air Force Base, Georgia, December.
- U.S. Air Force Reserves, 1992b. <u>Decision Document Oil Saturated Area (Site SS-003)</u>, Robins Air Force Base, Georgia, December.
- U.S. Air Force SPTG-CEG, 1993. <u>Underground Storage Tank Registration Fees</u>, Richards-Gebaur AFB, Missouri, May.
- U.S. Environmental Protection Agency, 1986. <u>Notice of Violation Pursuant to Requirements of RCRA</u>, Kansas City, Missouri, August.

THIS PAGE INTENTIONALLY LEFT BLANK



APPENDIX B

APPENDIX B
SAMPLE FORMS

### Chemical Inventory

NSM	■11 Spec	Manufacturer	Nomenclature	Quantity Used	Disposal	IEX
** 015A - 442 PU	NITIONS F	LIGHT/MUNITIONS GUN/RELEAS				
8030-00-148-9833		LOCTITE CORP	AORESIVE 271 LOCTITE	36.0 025/v	r IN PROCESS	N
8040-01-137-8418		HYSOL CHEM CORP	ADRESTVE EA9330 CPTS PTAGE	-	IN PROCESS	8
8040-01-137-8418		HYSOL CHEM CORP	ACHESIVE EA9320 19TS PTAGE	•	IN PROCESS	N
8040-00-576-2014	•	STEVEN INOUSTRIES FOR (3H)	AOHESIVE EC-1022 34	· •	IN PROCESS	ક
3439-00-255-9935		L.B. ALLEN CO, INC	ALLEN SOLDER PASTE FLUX		IN PROCESS	M
		SAF-T-LOX CHEM CORP	ANEROBIC ACHESIVE SEALANT		IN PROCESS	N
8030-00-087-8630	•	MAKOOR PRODUCTS CO	ANTISETZE COMPOUND		IN PROCESS	N
8040-00-598-5164	_	<b>80STIK (EMHART INOUSTRIES INC)</b>			IN PROCESS	9
9150-00-687-4241	-	CASTROL INC BRAY PRODUCTS INC			IN PROCESS	Ħ
6850-00-005-5305		SPEER PRODUCTS CO	CLEANING COMPOUND ACFT SURFACE	· -	IN PROCESS	N
6850-00-105-3084		CHENTRONICS INC	CLEANING COMPOUND SOLVENT		IN PROCESS	8
8030-01-041-1596		BULK CHEM DIST INC	CORROSION PREVENTIVE CHPO TY I	-	IN PROCESS	N
8930-90-546-8637		BULK CHEM. OIST. INC	CORROSION PREVENTIVE COMP TILL		IN PROCESS	8
6850-00-973-3123		CHER CONNOO. AGENCY	OGSC PD-157 CLEANS; USE		IN PROCESS	8
9150-00-F00-5368		ENERPAC, OIV APPLIED POWDER	ENERPAC HYERAULIC SIL		IN PROCESS	,
9150-01-035-5390		SULFLO	GEAR OIL 75W LUBRICANT		IN PROCESS	*
9150-00-190-0905		SULFLO INC	GREAS AUTO AND ARTILLERY		IN PROCESS	N.
9159-01-071-0749		OIXON TICONOEROGA COMPANY	GREASE ACFT ORDNANCE		IN PROCESS	N
9150-00-292-9689		ROYAL LUBREANTS CO INC	GREASE AIRCRAFT		IN PROCESS	N
9150-00-985-7317		DOW CORNING CORP	GREASE NOLY DISULFIDE	· -	IN PROCESS	N
9150-00-223-4004	5-21164	ROYAL LUBRICARTS CO INC	GREASE HOLYBOENUM DISULFIDE		IN PROCESS	ii.
9150-00-985-7246		ROYAL LUBRICANTS	GREASE, ARCFT AND INSTRUMENT		IN PROCESS	N N
9150-00-141-6770		ROYAL LUBRICANTS	GREASE, BALL AND ROLLER BEARING	_	IN PROCESS	N
5970-00-161-7422		MESTINGHOUSE ELECTR. CORP	INSULATING VARMISH REQ ENAMEL	<del>-</del>	IN PROCESS	9
	•	RANDOLF PRODUCTS CO	ISOPROPYL ALCOHOL	_	IN PROCESS	8
9150-00-458-0075			LUBE OIL GEN PURPOSE	120.0 CHS/y		Ħ
9150-00-543-7220 (	_	PROCESS RESEARCH PRODUCTS	LUBRICANT HOLYBOERUM OISULFIDE	· •	IN PROCESS	N
9150-00-948-6912		SANOSTRON PROD. COMPANY	LUBRICANT SOLIO FILM		IN PROCESS	9
9150-00-119-9291			O-RING LUSRICANT	_	IN PROCESS	ĸ
8010-00-936-8367		LHB INOUSTRIES	OLIVE ORAB #34088 SO-SURE		IN PROCESS	9
9150-01-260-2534 \			PERMA-SILK & LUBRICANT AEROSOL	120.0 CNS/y		8
8030-00-008-7205		•	PR1431-S AND ST SEALING 2 PART		IN PROCESS	9
8010-00-F00-6323 *		PMC	PWC201 ZCPRIMER		IN PROCESS	q
9150-00-145-0263		ROYAL LUBRICANTS CO.	ROYCO ZZ ACFT GREASE		IN PROCESS	¥
9150-01-104-5227			ROYCO 36 LUBRICATING OIL MPMS	=	IN PROCESS	¥
9150-00-754-2595			ROYCO 640 GREASE		IN PROCESS	¥
8040-00-117-8512			RTV-3145 AOHESIVE SEALANT		IN PROCESS	Ň
8040-00-181-8392 9	•		RTV157 SILICONE SEALANT		IN PROCESS	ų
6810-90-F00-0592 4			SAFETY-KLEEN 1:0	1800.0 GAL/yr		N
8030-00-297-667			SEALING COMPOUND EC-1300		IN PROCESS	N
6850-00-294-0860			SILICON COMPOUNO		IN PROCESS	N
6850-00-880-7615 -			SILICOME ACHESIVE PT#4		IN PROCESS	ų
9150-00-823-7860			SLYDE LUBR COMP SILICOME		IN PROCESS	4
8040-00-142-9193			SUPER GLUE	· •	IN PROCESS	3
9150-00-175-915: 4			TAPMATIC (T-F) CUTTING FLUIO#1	-	IN PROCESS	ĸ
			WHITE STENCIL INK 37875		IN PROCESS	N .
			ZZA MARSE BLACK STENCIL		IN PROCESS	5
8010-PP-WC2-01 N			ZZB PWC ZO1 Z.C. PRIMER		IN PROCESS	9
8010-PP-MC2-46 1	•		ZZC DARK BLACK PHC Z10-Z98		IN PROCESS	9
	•	•		13-		

ا المعلق من الم	। <u>-</u>	71	124
- INDUSTRIAL HY	GIENE SAMPLING DATA	OEHL USE ONLY	
iles inis space for me, nanival un	enn:)	MORKPLACE, IDENTIFIER   0 1 6	FAMUS ON STATE
	•	<u> </u>	ir 442 CAMS
DATE COLLECTED "TIDE		Munitions (G	n/Reaease)
8: 7: 0: 6: 2:	7 🍇 📆	828	Vat tRoom
MAIL   DRIGINAL 01	66 442 000/000	RichardsGeba	
(quero COPY t charges) COPY z	USAF HOSP/SCI	PBWhiteman-AFB,	
SAMPLE COLLECTED BY (Nan		NATURE	AUTOVON
FFITPITA R RENS	09756	JO tokkens	463-2144
REASON FOR		AINT F-FOLLOWUP/CLEANU	
SOURCE BEING SAMPLED	R-ROUTINE/PERIODIC SURVEY 0.0	THER (Specify)	1. 1 1 1 1 1
	E worker during clear	ning operations a	sufceation tacks
1	u Protective Equipment Engineering, Aar	ninistrative)	/
Ambient air	SAMPLE COLLE	CTION DATA	
EMPLOYEE NAME & SSAP	REIFEISS, GOLT		
OR SAMPLE LOCATION	524-13-025-3	Jame	
GEHL SAMPLE NO.			
BASE SAMPLE NO.	52870036	Sz 87003	7 RKX.70038
COLLECTING MEDIA	S534 1 a1	PDBMIO	1 CT XX 101
ANAME	Dichord How one Hand	2 Toluena	
NIOSH NO	PASSOODE	o xiSi5ialadaa	ad +  V  +  V
NAME	Mars - 12m2 Chlores	a Xilone	
ANALYSES B NIOSH NO		02821900	44 1
REQUESTED NAME			
NIOSH NO	·		
D MAME			1 2
NIOSH NO	s.	1 1 1 1 1	111111111111111111111111111111111111111
PUMP OR MONITOR NO.	Purposit DE 7.4	WACROUS	
COLLECTION TIME: OFF/ON	1500 1315	1505 / 1315	
TOTAL COLLECTION TIME	110:00	10000	
FLOW RATE: ON/OFF	. 20cc/min		
VOLUME SAMPLED	2.24	<u> </u>	
TEMPERATURE/BAROMETER	79.10/ 20.336	1 Same	
RELATIVE HUMIDITY/WIND	42.606/	- Sifne	
SUPPORTING BASE			
SAMPLES SAMPLE NO.			
COMMENTS		1	1
•		. •	İ
<del></del>	SUMMARY OF SURVEY RESUL	TS (See reverse for calculations)	
CALCULATED EXPOSURE CO	NCENTRATIONS ,	STANDARDS	
6.39 (RN	() (3840)	11.0 (TM)	(100%)

B-3

BULK MATERIAL SAMPLING DATA  Use this space for mechanical in print.  WORKPLATE OIL 6 6 FAM U 0 15 MORKPLATE OR SITE OR SITE OIL 6 6 FAM U 0 15 MORKPLATE OR SITE OR SITE BASE  Richards—Gebaur AFB, MO 442 CAMS  WORKPLATE OR SITE  Bldg . 828  DATE COLLECTED (YYUMDD)  ANIL REPORTS ORIGINAL 0 16 6 442 CSG/SGPB Richards—Gebaur AFB, MO 64030—5000  COPY 1 0 16 6 442 CSG/DE Richards—Gebaur AFB, MO 64030—5000  COPY 2 0 2 0 3 USAF HOSP/SGPB Whiteman AFB, MO 64030—5000  SAMPLE COLLECTED BY (Name Grade AFSC)  FELIPITA B. BENSON, R.N. GS—09  ALACCIDENT/INCIDENT C.COMPLAINT (F-FOLLOWUP/CLEANUP GERL PID)  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal professive equipment. Engineering, Administrative,
OR SITE   O  1 6 6 F A M U O 1 5 A BASE   ORGANIZATION   Richards—Gebaur AF3, MO 442 CAMS   WORKPL-CE OR SITE   Bldg. 828  DATE COLLECTED (YYMMDD)   BLDG NI LOCATION   ROOM/AREA   828   Y)-////////////////////////////////////
DATE COLLECTED (YYMMDD)    3   5   0   6   0   3   820   7)-7   1.1111111111111111111111111111111111
DATE COLLECTED (YYMMDD)    S
REPORTS ORIGINAL O 1 6 6 442 CSG/SGPB Richards-Gebaut AFB, MO 64030-5000  (circle if chemge) COPY 1 0 1 6 6 442 CSG/DE Richards-Gebaut AFB, MO 64030-5000  chemge) COPY 2 0 2 0 3 USAF HOSP/SGPB Whiteman AFB, MO 65305-5360  SAMPLE COLLECTED BY (Name Grade AFSC)  FELIPITA B. BENSON, R.N. GS-09  REASON FOR SUBMISSION R. A.ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP  SUBMISSION R. R. ROUTINE BACKGROUNO/PERIODIC SURVEY E.OTHER  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment.Engineering, Administrative)
REPORTS ORIGINAL O 1 6 6 442 CSG/SGPB Richards-Gebaut AFB, MO 64030-5000  (circle if CDPY 1 0 1 6 6 442 CSG/DE Richards-Gebaut AFB, MO 64030-5000  change) COPY 2 0 2 0 3 USAF HOSP/SGPB Whiteman AFB, MO 65305-5360  SAMPLE COLLECTED BY (Name Grade AFSC)  FELIPITA B. BENSON, R.N. GS-09  REASON FOR SUBMISSION  R.ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP  SUBMISSION  R.ROUTINE BACKGROUNO/PERIODIC SURVEY E.STHER  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment, Engineering, Administrative)
COPY 1 0 1 6 6 442 CSG/DE Richards—Sebaur AFB. MO 64030—5000 chenge) COPY 2 0 2 0 3 USAF HOSP/SGPB Whiteman AFB. MO 65305—5360  SAMPLE COLLECTED BY (Name Grade AFSC) SIGNATURE AUTOVON FELIPITA B. BENSON, R.N. GS—09  REASON FOR SUBMISSION R A-ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP CENT. PID  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment. Engineering, Administrative)
change)  COPY 2  O 2 0 3  USAF HOSP/SGPB Whiteman AFB, MO 65305-5360  SAMPLE COLLECTED BY (Name Grade AFSC)  FELIPITA B. BENSON, R.N. GS-09  REASON FOR SUBMISSION  R. A-ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP SUBMISSION  R. ROUTINE BACKGROUNO/PERIODIC SURVEY E-OTHER  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment, Engineering, Administrative)
SAMPLE COLLECTED BY (Name Grade AFSC)  SIGNATURE  SIGNATURE  SIGNATURE  SIGNATURE  FELIPITA B. BENSON, R.N. GS-09  REASON FOR R. A-ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP  SUBMISSION  R. ROUTINE BACKGROUNO/PERIODIC SURVEY E-OTHER  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment, Engineering, Administrative)
FELIPITA B. BENSON, R.N. GS-09  REASON FOR R.A. A.ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP GENL PID  SUBMISSION R. R. ROUTINE BACKGROUNO/PERIODIC SURVEY E.STHER  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment. Engineering, Administrative).
REASON FOR R A-ACCIDENT/INCIDENT C.COMPLAINT /F.FOLLOWUP/CLEANUP CUBMISSION R.ROUTINE BACKGROUNO/PERIODIC SURVEY C-OTHER  SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS ( Personal protective equipment. Engineering, Administrative )
SOURCE BEING SAMPLED  Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment. Engineering, Administrative)
Frayed material from around explosion proof light fixtures.  EXISTING CONTROLS (Personal protective equipment. Engineering, Administrative)
EXISTING CONTROLS ( Personal protective equipment. Engineering, Administrative ,
1/-6-1
SAMPLE COLLECTION DATA
OEHL SAMPLE NUMBER
BASE SAMPLE NUMBER G M 8 5 0 1 2 1
A CHECK FOR X MAJOR COMPONENTS 1 MAJOR COMPONENTS
Asbestos
B NIOSH NO C I 6 4 7 5 0 0 0
ANALYSES NAME
REQUESTED NIOSH NO
NAME
D NIOSH NO I I I I I I I I I I I I I I I I I I
E CHECK FOR THAZAROOUS/TOXIC WASTE HAZAROOUS/TOXIC WASTE
MATERIAL NAME LET. KITOLON
LOT NUMBER //
NSN (FSN )
SPECIFICATION (MIL or FED)
MANUFACTURER'S NAME "
DESCRIPTION OF MATERIAL  USAGE (Heared, brushed.  Sprayed, etc.)  USAGE (No in the state of the
USAGE ( Heared, brushed. Cailing lights that are
aprayed, etc.) 2xplosicin proof
SUPPORTING OEHL SAMPLE NO
BASE SAMPLE 40 C M B S O 1 2 1
SAMPLES SAMPLE TYPE
,
l
COMMENTS Employees and CE parsonnol state that dicture were inplace when Bity was opport up in 1982 and building material not recorded. This work area is occupied dally.

a 1 toky

discussed chemical usage and painting operations. Shop had necessary MSDS's however we are suppliing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surve and was within specifications. Air sampling should be conducted in the futu to determine adequacy of system.  DENNIS L. BURR BIOENVIRONMENTAL Engineering  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR BIOENVIRONMENTAL Engineering Servi	•		71	126	
920826 Contacted shop to find out why they use Lacquer paint. Will address during baseline scheduled for 3 Sept 0900.  DERMIS L. BURR Bioenvironmental Engineering Servi Bioenvironmental usage and painting operations. Shop had necessary MSDS's however we are supplifing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surve and was within specifications. Air sampling should be conducted in the future to determine adequacy of system.  DERMIS L. BURR Bioenvironmental Engineering Servi Bioenvironmental En	CASE FILE	CHRONOLOGICAL REC	ORD OF WORKPLACE SURVEILLANCE		
DERNIS L. BURK  ### Bloenvironmental Engineering Servi  ### Bloenvironmental Engineering Servi  #### Bloenvironmental Engineering Servi  ###################################		BASELINE, ANNUAL, AND SPECIAL TELECONS AND DISCREPANCY ST.	L SURVEY KEY FINDINGS AND DISCREPANCIES, ATUS CHECKS. (Sign each entry)	ANNUAL CASE FILE REVIEW:	
DENNIS L. BURR Bioenvironmental Engineering Servi  20903 Opening Conference was held w/ Mr. Bruner by Mr. Chavis and Mr. Burr. We  discussed chemical usage and painting operations. Shop had necessary MSDS's however we are supplifing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surve and was within specifications. Air sampling should be conducted in the futu  to determine adequacy of system.  DENNIS L. BURR Bloenvironmental Engineering  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR Bloenvironmental Engineering Service  921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise lab and air sampling at cleaner vat.  DENNIS L. BURR Bloenvironmental Engineering  WORKPLACE SUPERVISOR  DOUTY PHONE  OFFICE SUPERVISOR  OFFICE SUPERVISOR  WORKPLACE SUPERVISOR  POUTY PHONE  OFFICE SUPERVISOR  ORGANIZATION  REAL APB WORKPLACE MUNITIONS GUB RELEASE BLOE WOYLCCATION  ROOM/AREA	920826	Contacted shop to find o	out why they use Lacquer paint.	Will address during	
P20903 Opening Conference was held w/ Mr. Bruner by Mr. Chavis and Mr. Burr. We discussed chemical usage and painting operations. Shop had necessary MSDS's however we are supplifing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surve and was within specifications. Air sampling should be conducted in the futu to determine adequacy of system.  DENNIS L. BURR Blockwironmental Engineering  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR Blockwironmental Engineering Service System.		baseline scheduled for 3	3 Sept 0900.		
Opening Conference was held w/ Mr. Bruner by Mr. Chavis and Mr. Burr. We discussed chemical usage and painting operations. Shop had necessary MSDS's however we are supplifing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surve and was within specifications. Air sampling should be conducted in the future to determine adequacy of system.  DENNIS L. BURR BIOGRAFICATIONS 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR BIOGRAFICATION BURN BIOGRAFICATION GUN RELEASE BLOS VOLCATION FROM/AREA					
discussed chemical usage and painting operations. Shop had necessary MSDS's however we are supplifing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surved and was within specifications. Air sampling should be conducted in the future to determine adequacy of system.  DERNIS L. BURR Blockwiroumental Engineering Services of the Survey			PEGERATIONNESS	at Engineering Servic	
however we are suppliing them with 92 versions and Haz Comm. Discussed and conducted haz noise eval. The safety-kleen vat ventilation system was surved and was within specifications. Air sampling should be conducted in the future to determine adequacy of system.  DENNIS L. BURR Blockyroumental Engineering  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR Blockyroumental Engineering Server States of the States of t	920903	Opening Conference was he	eld w/ Mr. Bruner by Mr. Chavis	and Mr. Burr. We	
conducted haz noise eval. The safety-kleen vat ventilation system was surve and was within specifications. Air sampling should be conducted in the future to determine adequacy of system.    DENNIS L. BURK   Bioenvironmental Engineering		discussed chemical usage	and painting operations. Shop	had necessary MSDS's	
and was within specifications. Air sampling should be conducted in the future to determine adequacy of system.  DENNIS L. BURR Bloewyroumental Engineering  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR Bloenvironmental Engineering Server S		however we are suppliing	them with 92 versions and Haz 0	Comm. Discussed and	
DENNIS L. BURR  Bloewvironmental Engineerin  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were  reaccomplished all other forms were current and correct. The letter is  completed and distributed.  DENNIS L. BURR  Bioenvironmental Engineering Service  921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise lab.  and air sampling at cleaner vat.  DENNIS L. BURR  Bioenvironmental Engineering  WORKPLACE SUPERVISOR  MANA  WORKPLACE SUPERVISOR  WORKPLACE (DENTIFIER O) 1 6 6 F A M UNITATION  ASSE  R-G AFB  WORKPLACE  BLDG WO/LOCATION  ROOM/AREA		conducted haz noise eval	. The safety-kleen vat ventilat	ion system was surve	
DENNIS L. BURR Blocuvironmental Engineering  921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR Blocuvironmental Engineering Serv  921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise lab. and air sampling at cleaner vat.  DENNIS L. BURR Blocuvironmental Engineering  WORKPLACE SUPERVISOR  MORE Blocuvironmental Engineering  WORKPLACE SUPERVISOR  WORKPLACE SU		and was within specificat	tions. Air sampling should be o	onducted in the futur	
921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DERNIS L. BURR Bioenvironmental Engineering Server Ser		to determine adequacy of	system.	~	
921026 AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were reaccomplished all other forms were current and correct. The letter is completed and distributed.  DENNIS L. BURR BIOGRAPIACE SUPERVISOR  WORKPLACE SUPERVISOR  DUTY PHONE  DENNIS L. BURR Biochvironmental Engineering  WORKPLACE SUPERVISOR  DUTY PHONE  OFFICE SYMBOL  (Use this space for mechanical imprin:)  WORKPLACE  DENNIS L. BURR  DIOTY PHONE  OFFICE SYMBOL	,		DENNIS	L. BURR	
reaccomplished all other forms were current and correct. The letter is  completed and distributed.  DENNIS L. BURR Bioenvironmental Engineering Serv  921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise lab  and air sampling at cleaner vat.  DENNIS L. BURR Bioenvironmental Engineering  WORKPLACE SUPERVISOR  MORKPLACE SUPERVISOR  WORKPLACE SUPERVI			Bloenvi	roumental Engineering	
DENNIS L. BURR Bioenvironmental Engineering Services  921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise label and air sampling at cleaner vat.  DENNIS L. BURR Bioenvironmental Engineering  WORKPLACE SUPERVISOR  WORKPLACE SUPERVISOR  (Use this space for mechanical imprint)  WORKPLACE O 1 6 6 F A M UN O 15 MORKPLACE  IDENTIFIER O 1 6 6 F A M UN O 15 MORKPLACE  WORKPLACE  WORKPLACE  MUNITIONS GUN RELEASE  BLOG NO/LOCATION ROOM/AREA	921026	AF forms 2214, 2755, 2761, 2758, 2763, 2764, and chemical inventory were			
DENNIS L. BURR Bioenvironmental Engineering Services  921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise label and air sampling at cleaner vat.  DENNIS L. BURR Bioenvironmental Engineering  WORKPLACE SUPERVISOR  PUTY PHONE  OFFICE SYMBOL  WORKPLACE IDENTIFIER 0 1 6 6 F A M U 0 15 A A A DORGANIZATION  WORKPLACE IDENTIFIER 0 1 6 6 F A M U 0 15 A A A DORGANIZATION  WORKPLACE MUNITIONS GUN RELEASE  BLDG NO/LOCATION ROOM/AREA		reaccomplished all other	r forms were current and correct	The letter is	
921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise labeled and air sampling at cleaner vat.  DENNIS L. BURR Bioenvironmental Engineering  WORKPLACE SUPERVISOR  MANA  WORKPLACE SUPERVISOR  OFFICE SYMBOL  (Use this space for mechanical imprine)  WORKPLACE [DENTIFIER 0 1 6 6 F A M US 0 1 5 A BASE CREANIZATION 442 MS  WORKPLACE MUNITIONS GUN RELEASE  BLDG NO/LOCATION ROOM/AREA		completed and distribute	ed.	TR	
921026 Outbriefed Mr. Bruner discussed chemical listing, shop needs High noise label and air sampling at cleaner vat.  DENNIS L. BURR Bioenvironmental Engineering  WORKPLACE SUPERVISOR  OFFICE SYMBOL  (Use this space for mechanical imprine)  WORKPLACE  DUTY PHONE  OFFICE SYMBOL  ORGANIZATION  RAGAFB  WORKPLACE  MUNITIONS GUN RELEASE  BLDG YO/LOCATION  ROGM/AREA				1	
and air sampling at cleaner vat.  DENNIS L. BURR Bioenvironmental Engineering  WORKPLACE SUPERVISOR  DUTY PHONE  OFFICE SYMBOL  QUILLE IDENTIFIER 0 1 6 6 F A M U 0 1 5 A BASE  R-G AFB  WORKPLACE  MUNITIONS GUN RELEASE  BLDG NO/LOCATION  ROOM/AREA			Bicenvironmen	ical Engineering Serv	
DENNIS L. BURR  Bioenvironmental Engineering  MANA  WORKPLACE SUPERVISOR  OFFICE SYMBOL  (Use this space for mechanical imprint)  WORKPLACE  (Use this space for mechanical imprint)  WORKPLACE  (Use this space for mechanical imprint)  R-G AFB  WORKPLACE  MUNITIONS GUN RELEASE  BLDG NO/LOCATION  ROOM/AREA	921026	Outbriefed Mr. Bruner di	scussed chemical listing, shop	needs High noise label	
WORKPLACE SUPERVISOR  MANA  WORKPLACE SUPERVISOR  OFFICE SYMBOL  QU'S UN COMPLACE  IDENTIFIER 0 1 6 6 F A M U O 1 5 A  BASE  R-G AFB  WORKPLACE  MUNITIONS GUN RELEASE  BLDG NO/LOCATION  ROGM/AREA		and air sampling at clea	mer vat.	lr	
WORKPLACE SUPERVISOR  M. BRUNCA  (Use this space for mechanical imprint)  WORKPLACE  IDENTIFIER 0 1 6 6 F A M U 0 1 5 A  BASE  R-G AFB  WORKPLACE  MUNITIONS GUN RELEASE  BLDG NO/LOCATION  ROOM/AREA					
WORKPLACE SUPERVISOR  A. BRUNCA  (Use this space for mechanical imprint)  WORKPLACE IDENTIFIER 0 1 6 6 F A M U 0 1 5 A  BASE  R-G AFB  WORKPLACE MUNITIONS GUN RELEASE  BLDG 40/LOCATION  ROOM/AREA			Blockviro	mental Engineering	
WORKPLACE   WORKPLACE   O 1 6 6 F A M U O 1 5 A  BASE   GRGANIZATION    R-G AFB   442 MS    WORKPLACE   MUNITIONS GUN RELEASE    BLDG 40/LOCATION   ROOM/AREA				MANA	
WORKPLACE IDENTIFIER 0 1 6 6 F A M U O 1 5 A  BASE R-G AFB WORKPLACE MUNITIONS GUN RELEASE BLDG 40/LOCATION ROOM/AREA		<b>√</b> 0		OFFICE SYMBOL	
R-G AFB 442 MS WORKPLACE MUNITIONS GUN RELEASE BLDG NO/LOCATION ROOM/AREA			WORKPLACE		
WORKPLACE  MUNITIONS GUN RELEASE  BLDG 40/LOCATION ROOM/AREA				j	
BLDG 40/LOCATION ROOM/AREA	l		WORKPLACE		
, · · · · · · · · · · · · · · · · · · ·	1				
			1	N/A	

FORM JAN 52 2754

INDUSTRIAL HYGIENE SURVEY	DATE (YYMMDD)	WORKPLACE!	<u> </u>	
DATA SHEET - GENERAL (Use this space for mechanical imprint)	8,710,8,1,8	IDENTIFIER 0 1 6 6	F A M	U 0 1 5
(Use into apace for mechanical imprint)		Richards-Gebaur		442 CAMS
		WORKPLACE		
		Munitions (Gun/Re)	Lease)	EA
		828	1	room
	POTENTIAL HA	ZARD	<u> </u>	
<u>-</u>	Description, Operating	<u>-</u>		
		N 9150-00-168-2000 <del>-potential inhalat:</del>		
hazard.	J, 10 0			
		,		_
<del>_</del>	EVALUATIO			
( Standards/Criteri	e, Sample/Test equipm	ent and results, Discrepancies )		
Observation of operation				
held approximately arm's very large room with two				
shore intervals and appr				
are used during applicat				
<u>-</u>				
		_		
-				
	,			
	CONTROL			
( Exieting or recommen	ded; Protective equipm	ent; Engineering, or Administrative)		
Continue to use gloves a		Recommend that a fa	ace shi	eld be used
to avoid eye contact of	the spray.			
		<u></u>		
	<del>_</del>			<u> </u>
SURVEYED BY Name, Grade, APSC)	00756	REVIEWED BY ( Neme, Grade, A.F.	SC)	
FFINDITA R JENCON P V	GS-089756			

Ĺ

ţ

12 W p

AF Form 2761	HAZARD	OUS MATE	RIALS DAT	A	Page: 1	•	
	•	Organiza 442 MUNI		rkplace NITION	Off Symb MANA	Bldg No 828	•
NSN/Other 1. 343900255			nomenclat DER PASTE	ure		ification	IE N
Manufactu L.B.ALLEN	rer COMPANY INC	*	CAGE 7027		S Avail Y	MSDS in	shop
(1) ZINC	mical ingred CHLORIDE (SA AL OIL (EXPO	RA III)	ULATE	CAS Numb 7646857 8012951	25	cent .00	
Disposal:	In Process	Air %	Ground	Water %	Haz W	laste	
Remarks:							
NSN/Other 2. 597000161			nomenclati ATING ENAM		Spec N/K	ification	IE 9
Manufactu WESTINGHO	-er JSE ELECTRIC	CORP, IN	CAGE S 79500		S Avail Y	MSDS in Y	shop
(1) XYLENI (2) LEAD	JM CARBONATE	ISOMERS		CAS Numb 1330207 7439921 1317653 1309371	45 0 8	cent .00 .27 .00	
Disposal:	In Process	Air %	Ground %	Water %	Haz W	aste '	
Remarks:	٠						
NSN/Other 3. 6810002869		aterial SOPROPYL	nomenclati ALCOHOL	116		ification I-735	IE:
Manufactu RANOOLF Pi	rer RODUCTS CO		CAGE	MSO	S Avail Y	MSDS in Y	shop
	nical ingred OPYL ALCOHOL			CAS Numb 67630	_	cent .90	
Disposal:	In Process 100%	Air %	Ground %	Water %	Haz W	aste	
Remarks:							
NSN/Other		atori-1	 nomenclati			ification	—— IE:

## Visual Site Inspection Form Page 1 of 2

### RICHARDS-GEBAUR AFB ENVIRONMENTAL BASELINE SURVEY


· Date
Inspector
Facility Escort
Facility: # Name
This Facility and associated property with regards to disposal represents:
no constraints known or suspected constraints unknown constraints
Bio/Physical Setting:
Current Use:
Past Use: Same as above
Does facility generate or store Hazardous Material/Waste: Yes No
Types:
Disposal practices:
"Housekeeping" in and around building is Good Average Poor:
Effluent waste created/Destination:
Conditions not mentioned that present concerns:
Exterior Surfaces:
Interior Surfaces:
Interviews:



### Visual Site Inspection Form Page 2 of 2

### **BUILDING INSPECTION CHECKLIST**

Are there any sign	ns of the following on the property	Y Yes <u>N</u> No <u>U</u>	Unknown
A)	UST	к)	Discolored Soil
B)	AST	L)	Noxious Odors
C)	Oil Water Separator	M)	Sensitive Receptors
D)	Septic Tank	N)	Stressed Vegetation
E)	Waste Piles	0)	Fill Areas/Buried Objects
F)	Lead Paint/Pipes	P)	Drums/Drum Storage
G)	PCBs	Q)	Surface Water '
H)	Stained Sinks/Floor Drains	R)	Suspected ACM
1)	Evidence of Spills	S)	Other (Explain Below)
J)	Evidence of Improper Disposal		
Check List Descrip	otion:	Facilii -	ty Diagram
		-	
,Rc	Photo Log: oll Frame Subject	-	•
	•		



APPENDIX C

# APPENDIX C HAZARDOUS MATERIALS STORAGE

#### APPENDIX C

#### HAZARDOUS MATERIALS STORAGE

Table C-1. An inventory of hazardous materials stored in industrial workplaces based on information maintained by the Bioenvironmental Engineering Services office is presented in Table C-1. Specifically, this inventory reflects information tabulated on Air Force Form 2761, Hazardous Materials Data. The quantity and quality of data on the Hazardous Materials Data forms varies considerably over the period of available records. For some workplaces, records were available back to 1975; for others, records were only available since the mid-1980s. The most complete records are available for the last 5 years (i.e., 1987 to 1992). Since 1990, most of the data have been recorded on a computer-generated version of Air Force Form 2761.

The "Quantity Stored" entry is as it was listed on the original forms. If a quantity was not specified on the form, "unknown" has been listed in the Quantity Stored column. It should also be noted that only the amount of product usage per unit time was recorded on the Hazardous Materials Data forms; product storage per unit time was not recorded on the forms. A major assumption made for this appendix is that usage data was the only available data for storage.

The units of measure vary for different classes of products listed on the Hazardous Materials Data forms. The "Quantity Stored" for many products is given in conventional quantitative units of ounces, pounds, tons, pints, quarts, gallons, liters, and grams. Other products, however, are listed in terms of non-quantified units such as cans, boxes, rolls, tubes, kits, packs, drums, and cylinders. For these products, the conversion factors listed below were used.

1 bag	= 25 lb	1 ball = 1 lb	1 bar = 1 lb
1 barrel	= 350 lb	1  box = 100  lb	1 can = 50 lb
1 canister	= 50 lb	1 caplet = 1 lb	1 cartridge = 1 lb
1 case	= 50 lb	1 cycie = 1 lb	1 cylinder = 100 lb
1 disk	= 1 lb	1 dozen = 1 lb	1 drop = 1 lb
1 drum	= 417 lb	1 each = 1 lb	1 jar = 1 lb
1 keg	= 100 lb	1 kit = 1 lb	1 mon = 1 lb
1 pack	= 1 lb	1 package = 1 lb	1 pad = 1 lb
1 pail	= 50 lb	1 peliet = 1 lb	1  pillow = 1  lb
1 roll	= 1 lb	1 spool = 1 lb	1  stick = 1  lb
1 tablet	= 1 ib	1 tub = 1 lb	1  tube = 1  lb

For products listed using volumetric measures, such as pints, quarts, gallons, and liters, knowledge of the density or specific gravity of each product would be required to calculate the respective total weights of product usage per unit time. Given the fact that such data are not recorded on Hazardous Materials Data forms, the weight of an equivalent volume of water (1 U.S. gallon weights 8.3453 pounds or 3.7854 kilograms) was used to calculate an approximate total product weight. All weights recorded in the English system of ounces and pounds were converted to their metric equivalent.

Only the actual products used in each workplace are listed in Table C-1. In most cases, the product used (e.g., black spray paint) is a mixture of unique chemical constituents. For example, black spray paint consists of several chemical compounds, such as toluene, acetone, butyl acetate, butyl cellosolve, and isobutane. In addition, black spray paint manufactured by two different companies may contain different percentages of the same compounds (i.e., one may contain 5).



percent toluene and the other 19 percent) or an entirely different composition of chemical compounds.

Table C-2. The list of products in Table C-1 used in quantities anich are subject to reporting requirements specified under 40 CFR Part 373 is provided in Table C-2. Under Section 120(h)(1) of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), whenever any agency, department, or instrumentality of the United States enters into any contract for the sale or other transfer of real property which is owned by the United States, and on which any hazardous substance was stored for 1 year or more, known to have been released, or disposed of, the contract must include notice of the type and quantity of such hazardous substance, and the time at which such storage, release, or disposal took place, to the extent such information is available based on a complete search of agency files. Requirements for such notice are outlined in, 40 CFR Part 373.

The notice required by 40 CFR Part 373 for the storage of hazardous substances applies only when hazardous substances have been stored in quantities greater than or equal to 1,000 kilograms (or 2,205 pounds) or the CERCLA-reportable quantity for the substance as listed in 40 CFR Part 302.4, whichever is greater. Hazardous substances that are also listed under 40 CFR 261.30 as acutely hazardous wastes, and that are stored for 1 year or more are subject to the notice requirement when stored in quantities greater than or equal to 1 kilogram (2.205 pounds).

Constituents of products and their percentages are listed in Table C-2 when they were provided on Air Force Form 2761. Synonyms and Chemical Abstracts Services Registry Numbers (CASRN) for these constituents are also provided when listed in the Keller's Chemical Reg-A-Dex Chemical Cross Reference.

Table C-1. Hazardous Materials Storage, Facility 602

. . . .

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Adhesive	4 ounces/year	0.1/year	1986-1987
Adhesive	0.5 pint/year	0.2/year	1987
Adhesive	1 pint/month	0.5/month	1983
Adhesive	3 quarts/year	2.8/year	1983, 1987
Adhesive	18 ounces/year	0.5/year	1983
Adhesive	0.5 quart/week	0.5/year	1983
Adhesive	0.5 pint/year	0.2/year	1986
Adhesive	1 quart/year	0.9/year	1985, 1987
Adhesive, Anaerobic	5 cubic centimeters/ year	0.005/year	1990
Adhesive, Bostik 1125 Part A	1 kit/year	0.5/year	1990
Adhesive, Catalyst	1 quart/3 months	0.9/3 months	1983
Adhesive, Cyanoacrylate	4 ounces/year	0.1/year	1983
Adhesive, EC-1022	1 quart/year	0.9/year	1990
Adhesive, General Purpose	1 pint/year	0.5/year	1983
Adhesive, Industrial	19.5 ounces/year	0.6/year	1987
Adhesive, Industrial	1 quart/month	0.9/month	1983
Adhesive, Industrial	1 quart/year	0.9/year	1985
Adhesive, N-1030	1 quart/year	0.9/year	. 1990
Adhesive, Polychloroprene	2 ounce/4 months	0.06/4 months	1983
Adhesive, Polychloroprene	10 pints/year	4.7/year	1985
Contact Adhesive	3 quarts/year	2.8/year	1983
Corrosion Resistant	1 quart/year	0.9/year	1983
Corrosion Resistant Coating, Turcoat Liquid Accelgold	0.5 quart/year	0.5/year	1990
Corrosion Resistant Coating	1 quart/year	0.9/year	1987
Denatured Alcohol	1 quart/year	0.9/year	1983, 1985
Denatured Alcohol	1 pint/year	0.5/year	1987
Denatured Alcohol	0.5 gallon/year	1.9/year	1990
Electrical Insulating Paste Silicone Compound	1 ounce/year	0.03/year	1990
Enamel, Flat Gray Spray Paint	13 ounces/month	0.4/month	1983
Enamel, Flat White	13 ounces/week	0.4/week	1983
Enamel, Gray	1 gallon/3 years	3.8/3 years	1983
Enamel, Odorless	2 quarts/year	1.9/year	1983
Enamel, Olive Drab	13 ounces/year	0.4/year	1983
Enamel, Strata Blue	13 ounces/year	0.4/year	1983
Epoxy Patch Kit	4 ounces/2 months	0.1/2 months	1983



Table C-1. Hazardous Materials Storage, Facility 602 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Epoxy Synthetic Adhesive	1.5 ounces/2 months	0.04/2 months	1983
Foam Fast Adhesive	~ 24 ounces/year	0.7/year	1990
Graphite	Minimal		1983
Grease, Aircraft	1.75 pounds/4 years	0.8/4 years	1990
Ink, Stencil	64 ounces/year	2/year	1987
Ink, Strata Blue Parachute Marking	0.25 pint/year	0.1/year	1990
Ink, White Spraying Stencil	2 pints/year	0.9/year	1990
Lacquer	13 ounces/year	0.4/year	1,983
Lacquer	26 ounces/year	0.77/year	1983
Lacquer	26 pints/year	12.3/year	1985
Lacquer, Acrylic Silver	13 ounces/year	0.4/year	1983
Lacquer, Camouflage	13 ounces/year	0.4/year	1983, 1985
Lacquer, Gray	1 pint/year	0.5/year	1990
Lacquer, Green	13 ounces/2 years	0.4/2 years	1986
Lacquer, Spray Red	13 ounces/year	0.4/year	1983
Lacquer, White	13 ounces/2 years	0.4/2 years	1986
Lacquer, Yellow	13 ounces/2 years	0.4/2 years	1986
Leak Tec Test Compound	2 ounces/year	0.05/year	1990
Lube Oil, General Pump	1 quart/year	0.9/year	1985
Lube Oil, General Pump	1 quart/6 months	0.9/6 months	1983
Lubricating Graphite	1 ounce/year	0.03/year	1987
Lubricating Oil	1/3 ounce/year	0.009/year	1990
Methyl Ethyl Ketone	1 gallon/year	3.8/year	1985
Methyl Ethyl Ketone	1 quart/year	0.9/year	1987
Methyl Ethyl Ketone	1 gallon/2 weeks	3.8/2 weeks	1983
Methyl Ethyl Ketone	0.5 gailon/year	1.9/year	1990
Paint, Flat Black Spray .	9 ounces/week	0.3/week	1983
Paint, Green Spray	13 ounces/year	0.4/year	1983
Polychloroprene Adhesive	3 quarts/year	2.8/year	1983
Primer, Adhesive	0.5 quart/year	0.5/year	1990
Primer Coating	13 ounces/year	0.4/year	1983, 1985
Scotchgrip Plastic Adhesive	1 quart/year	0.9/year	1990
Sealing Compound, Yellow	4 ounces/year	0.1/year	1990
Silicone Compound	4 ounces/week	0.1/week	1983
Toluene	1 quart/year	0.9/year	1985
Toluene	2 quarts/year	1.9/year	1983
Toluene	1 pint/year	0.5/year	1987

Table C-1. Hazardous Materials Storage, Facility 602 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Toluene, Technical	0.125 quart/year	0.1/year	1990
Trichloroethane	0.5 pint/year	0.2/year	1983, 1985, 1987
Trichloroethane	0.125 quart/year	0.1/year	1990



Table C-1. Hazardous Materials Storage, Facility 710

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
	(Onits 1 tovided)	1081	<u> </u>
Life Support Shop			
Adhesive	12 ounces/year	0.36/year	1992-1993
Corrosion Preventative	5 ounces/year	0.15/year	1992-1993
Grease, Aircraft	1 ounce/year	0.03/year	1992-1993
Loctite Sealing Compound	20 cubic centimeters/ year	0.02/year	1992-1993
Lube Oil, General Purpose	6.2 ounces/year	0.18/year	1992-1993
Methyl Ethyl Ketone	4 ounces/year	0.1/year	1992-1993
Sealant, RTV	1.5 ounces/year	0.04/year	1992-1993
Silicone Compound	8 ounces/year	0.2/year	1993
Photo Lab/Dark Room			
Acetic Acid	10 gallons/year	37.4/year	1986
Activator	25 gallons/year	94.5/year	1986
Activator, Photographic	24 gallons/year	91/year	1992-1993
Activator, Reprotype 501	24 gallons/year	91/year	1992-1993
Ammonia	Minimal	•	1986
Cleaner/Varityper	Minimal		1986
Developer	60 gallons/year	227/year	1986
Developer	3 gailons/year	11.3/year	1986
Developer 1D2 Plus Developer Part 2	1,469 ounces/year	43.5/year	1992-1993
Film Cleaner	1 quart/year	0.9/year	1986
Fixer	8 gallons/year	30/year	1986
Fixer .	25 gallons/year	94.5/year	1986
Fixer	3 gallons/year	11.3/year	1986
Isopropyl Alcohol	4 ounces/year	0.1/year	1992-1993
Photo Flo	2 gailons/year	7.6/year	1986
Photographic Cleaner Compound	24 ounces/year	0.7/year	1992-1993
Photographic Film Cleaner	8 ounces/year	0.2/year	1992-1993
Rapid Fixer Part B	930 ounces/year	27.5/year	1992-1993
Rapid Fixer Part A	8,271 ounces/year	245/year	1992-1993
Series CHF Fixer/Hardener Part B	930 ounces/year	27.5/year	1992-1993
Series Fixer/Hardener Part A	8,271 ounces/year	244.8/year	1992-1993

La a salata de la faction de l

Table C-1. Hazardous Materials Storage, Facility 710 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Stabilizer	25 gallons/year	94.5/year	1986
Stabilizer Photo Ektamitic	24 gallons/year	91/year	1992-1993
Life Support		•	
Adhesive, Epoxy Synthetic	1 ounce/3 months	0.03/3 months	1987
Break Free	12 ounces/year	0.36/year	1987
Component 2	3 ounces/year	0.09/year	1985
Component Liner Kit	16 ounces/year	0.5/year	1987
Contact Cement	1 quart/2 weeks	0.9/2 weeks	1985, 1987
Corrosion Preventative Compound	16 ounces/year	0.5/year	1987
Epoxy Patch	6 ounces/year	0.18/year	1985, 1987
Foam Fast Adhesive	16 ounces/month	0.5/month	1987
Grease, Aircraft	1 ounce/month	0.03/month	1987
isopropyl Alcohol	1 pint/week	0.5/week	1987
Lacquer, Aerosol Black	16 ounces/2 months	0.5/2 months	1987
Lacquer, Black Paint	16 ounces/2 months	0.5/2 months	1987
Methyl Ethyl Ketone	3 quarts/year	2.8/year	1987
Primer, Light gray	16 ounces/2 months	0.5/2 months	1987
Release Agent Cap and Seal	1 pound/year	0.5/year	1985, 1987
Release Agent Mold Shell	1 quart/year	0.9/year	1985, 1987
Sealing Compound	12 ounces/year	0.36/year	1987
Silastic RTV	8 ounces/month	0.2/month	1987

Table C-1. Hazardous Materials Storage, Facility 828

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
4 Compound	16 ounces/month	0.4/month	1990
Accelerator	1 kit/month	0.5/month	1990
Adhesive	1 quart/10 years	0.9/10 years	1990
Adhesive, 2020	11 ounces/year	0.3/year	1990
Adhesive, 271 Loctite	24 ounces/year	0.7/year	1992
Adhesive, 271 Loctite	36 ounces/year	1/year	1993
Adhesive, Bostik Primer	1 quart/year	·0.9/year	1993
Adhesive, Cycling	1 ounce/2 months	0.03/2 months	1990
Adhesive, EA9330 Parts A + B	12 kits/year	5.4/year	1992-1993
Adhesive, EC-1022 3M	1 quart/year	0.9/year	1992-1993
Adhesive, RTV	2 tubes/month	0.9/month	1990
Adhesive, RTV	1 ounce/month	0.03/month	1986
Adhesive, Rubber Base	1 pint/month	0.5/month	1986
Adhesive Sealant	12 tubes/year	5.4/year	. 1993
Adhesive Sealant	6 ounces/month	0.18/month	1990
Adhesive Sealant	36 tubes/year	16.3/year	1992
Adhesive, Silicone	24 tubes/year	11/year	1993
Aircraft Corrosive Compound	1 gallon/3 years	3.8/3 years	1990
Aliphatic Isocyanate Reactant	1 gallon/year	3.8/year	1983
Aliphatic Thinner	1 gallon/year	3.8/year	1986
Allen Solder Paste Flux	3.8 ounces/year	0.1/year	1993
Allen Solder Paste Flux	12 pounds/year	5.4/year	1992
Allen Solder Paste	1 pound can/3 years	0.9/3 years	1990
Anaerobic Adhesive/Sealant	24 bottles/year		1992
Anaerobic Adhesive/Sealant	12 bottles/year		1993
Anti-Corrosive Compound	1 gallon/3 years	3.8/3 years	1990
Anti-Seize Compound	12 pounds/year	5.4/year	1986,1993
Anti-Seize Compound	5 pounds/month	2.3/month	1983
Anti-Seize Compound	1 pint/month	0.5/month	1990
Anti-Seize Compound	16 ounces/6 months	0.5/6 months	1986
Anti-Seize Compound	24 pounds/year	11/year	1983,1992
Adhesive	Unknown		1987
Byraycote 646	3 quarts/year	2.8/year	1993
Byraycote 646	12 quarts/year	11.4/year	1992
Cleaner, Aircraft	55 gallons/2 years	208/2 years	1986
Cleaning and Lubricating Compound, Electrical Contact	6 ounces/week	0.18/week	1983
Cleaning Compound	16 ounces/month	0.5/month	1986

Table C-1. Hazardous Materials Storage, Facility 828 (Continued)

S LATE

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Cleaning Compound	1 gallon/6 months	3.8/6 months	1987
Cleaning Compound	32 ounces/month	1/month	1987
Cleaning Compound, Aircraft Surface	36 cans/year	816.5/year	1993
Cleaning Compound, Aircraft Surface	78 ounces/month	2.4/month	1990
Cleaning Compound, Aircraft Surface Water Base	1 gallon/month	3.8/month	1983
Cleaning Compound, Aircraft Surface	960 ounces/year	28.4/year	1992
Cleaning Compound Solvent	72 cans/year	1,633/year	1993
Cleaning Compound Solvent	Unknown		1983
Cleaning Compound Solvent	96 ounces/month	2.8/month	1986
Cleaning Compound Solvent	1 can/day	23/day	1983
Cleaning Compound Solvent	192 ounces/year	5.7/year	1992
Compound, Lubricating	32 ounces/ month	1/month	1990
Corrosion Preventative	1 gallon/year	3.8/year	1986
Corrosion Preventative Compound	1 pint/2 months	0.5/2 months	1990
Corrosion Preventative Compound	2 gallons/month	7.6/month	1983
Corrosion Preventative Compound Type 1	. 6 cans/year	136/year	1993
Corrosion Preventative Compound Type 3	24 pints/year	11.4/year	1993
Corrosion Preventative Compound	16 ounces/month	0.5/month	1986
Corrosion Preventative Compound	384 ounces/month	12/month	1983
Corrosion Preventative Compound	2 pints/month	0.9/month	1990
Corrosion Preventative Compound	Unknown		1983
Corrosion Preventative Compound	16 ounces/month	0.5/month	1986
Corrosion Preventative Compound Type 3	72 pints/year	34/year	1992
Corrosion Preventative Compound Type 1	12 cans/year	272/year	1992

Table C-1. Hazardous Materials Storage, Facility 828 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Corrosion Removing Compound Paste	1 quart/month	0.9/month	1983
Curing Agent 2020	11 ounces/year	0.3/year	1990
Cutting Fluid	1 pint can/year	0.5/year	1990
Cutting Fluid, Tapmatic	1 pint/year '	0.5/year	1993
Cutting Fluid, Tapmatic	372 ounces/year	11/year	1992
Dark Black PWC	24 pints/year	11.4/year`	1993
Dry Film Lubricant	1 pint/6 months	0.5/6 months	1990
Edge Sealer	1.5 pints/year	0.2/year	1990
Electric Clean Lube Compound	96 ounces/month	2.8/month	1986
Enamel, Insulating	1 quart/10 years	0.9/10 years	1990
Enamel, Red	1 quart/year	0.9/year	1986
Enamel, Spray	12 ounces/year	0.36/year	1983
Enamel, Spray Paint Black	13 ounces/month	0.6/month	1983
Enamel, Olive Drab	144 pints/year	68/year	1992
Enerpac Hydraulic Oil	12 gailons/year	45.4/year	1992
Floor Finish	1 gailon/year	3.8/year	1986
Floor Finish, Non-Buffing	1 gallon/6 months	3.8/6 months	1983
Freon TF	6 pints/month	2.8/month	1990
Gear Box Lube	1 gallon/month	3.8/month	1983
Gear Lube	1 gallon/year	3.8/year	1986
Gear Lube Oil	5 gailons/year	19/year	1983
Gear Oil Lubricant 75 Weight	144 quarts/year	136/year	1992
Grease	12 cans/year	272/year	1993
Grease	1 gallon/3 months	3.8/3 months	1986
Grease	42 pounds/year	, 19/year	1992
Grease 2	8 ounces/3 months	0.2/3 months	1986
Grease, Aircraft	2.5 pounds/month	0.4/month	1983
Grease, Aircraft	1 gallon/year	3.8/year	1986
Grease, Aircraft	24 cans/year	544/year	1993
Grease, Aircraft	1 can/year	23/year	1993
Grease, Aircraft	12 quarts/year	11.4/year	1993
Grease, Aircraft	2 ounces/3 months	0.06/3 months	1986
Grease, Aircraft	4 ounces/6 months	0.12/6 months	1990
Grease, Aircraft	1 pint/year	0.5/year	1990
Grease, Aircraft	2 pounds/year	0.9/year	1986



Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Grease, Aircraft	5 pounds/6 months	2.3/6 months	1990
Grease, Aircraft	6 cans/year	136/year	1992
Grease, Aircraft	360 ounces/year	10.7/year	1992
Grease, Aircraft and Industrial	63 pounds/month	28.6/month	1983
Grease, Aircraft and Instrument	7 pounds/month	3.2/month	1986
Grease, Aircraft and Instrument	8 ounces/week	0.2/week	1983
Grease, Aircraft and Instrument	252 pounds/year	114.3/year	1992
Grease, Aircraft Ordinance	1 can/year	· 23/year	1993
Grease, Aircraft XP-190	1 gailon/6 months	3.8/6 months	1990
Grease, Artillery	1/3 gallon/year	1.1/year	1990
Grease, Auto and Artillery	6 gallons/year	22.7/year	1993
Grease, Auto and Artillery	4 pounds/year	1.8/year	1992
Grease, Auto/Artillery	7 pounds/year	3.2/year	1983
Grease, Ball and Roller Bearing	12 quarts/year	11.4/year	1993
Grease, Ball and Roller Bearing	28 ounces/month	0.83/month	1983
Grease, Ball and Roller Bearing	348 ounces/year	10.3/year	1992
Grease, Compound Plug Valve	8 ounces/month	0.2/month	1990
Grease, Dielectric	8 ounces/month	0.2/month	1986
Grease, Dielectric 2	8 ounces/3 months	0.2/3 months	1986
Grease, General Purpose	40 pounds/year	18/year	1986
Grease, Instrument	4 quarts/month	3.8/month	1990
Grease, Instrument and Aircraft	36 cans/year	816/year	1993
Grease, Moly Disulfide	12 cans/year	272/year	1993
Grease, Molybdenum	1.75 pounds/year	0.8/year	1986
Grease, Molybdenum Disulfide	1 pint/month	0.5/month	1990
Grease, Molybdenum Disulfide	840 ounces/year	25/year	1992 ·
Grease, Molybdenum Disulfide	1 gallon/year	3.8/year	1983, 19 <del>9</del> 2- 1993
Grease, Molykote M-77	2 pints/year	0.9/year	1986
Grease, Molykote M-77	1 pint/month	0.5/month	1990
Grease, Ordinance	4 pounds/month	1.8/month	1983
Grease, Plug Valve	16 ounces/month	. 0.5/month	1983
Grease, Roller Bearing	1 quart/month	0.9/month	1990
Grease, XP-190	1 ounce/month	0.03/month	1986
Hydraulic Oil	1.2 gallons/year	4.5/year	1993
Hydraulic Oil	1 gallon/3 years	3.8/3 years	1990
Hydraulic Fluid	1 quart/6 months	0.9/6 months	1986

Table C-1. Hazardous Materials Storage, Facility 828 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Ink, Stencil Black	12 pints/year	5.7/year	1993
Ink, Stencil Black	16 ounces/6 months	0.5/6 months	1990
Ink, Stencil White	16 ounces/6 months	0.5/6 months	1990
ink, Stencil White	12 pints/year	5.7/year	1993
Ink, Stencil White	372 ounces/year	11/year	1992
Insulating Varnish, Red Enamel	0.1 gailon/year	0.4/year	1993
Insulating Varnish, Red Enamel	12 gallons/year	45.4/year	1992
Isopropyl Alcohol	12 gallons/year	45.4/year	1992
Isopropyl Alcohol	1 galion/year `	3.8/year	1993
Lacquer, Acrylic	13 ounces/year	0.4/year	1983
Lacquer, Flat Black	1 pint/month	0.5/month	1990
Lacquer, Olive Drab Camouflage	1 pint/month	0.5/month	1990
Lacquer, Olive Drab	72 pints/year	34/year	1993
Lacquer, Olive Drab	1 pint/2 months	. 0.5/2 months	1990
Law Weapons Oil Arctic	1 quart/month	0.9/month	1983
Lube Oil	1 gallon/month	3.8/month	1986
Lube Oil	1 quart/month	0.9/month	1987
Lube Oil, General Purpose	1,400 ounces/year	41.4/year	1992
Lube Oil, General Purpose	120 cans/year	2,722/year	1993
Lubricant, Grease	1.75 pounds/month	0.8/month	1986
Lubricant, Molybdenum Disulfide/Silicone	1 pint/month	0.5/month	1990
Lubricant, Molybdenum Disulfide	12 pounds/year	5.4/year	1993
Lubricant, Molybdenum Disuifide	24 pounds/year	11/year	1992
Lubricant, Solid Film	48 ounces/month	1.4/month	1986
Lubricant, Solid Film	1 pint/6 months	0.5/6 months	1986
Lubricant, Solid Film	1 gallon/year	3.8/year	1983
Lubricant, Solid Film	12 quarts/year	11.4/year	1992-1993
Lubricating Oil	2 gallons/year	7.6/year	1993
Lubricating Oil	60 quarts/year	57/year	1992
Lubricating Oil	1 gallon/6 months	3.8/6 months	1983
Lubricating Oil	24 quarts/year	22.7/year	1993
Lubricating Oil	1 pint/month	0.5/month	1990
Lubricating Oil	1 pint/6 months	0.5/6 months	1990

أيساس والطلاب بالريباء أيطفاك شابات بالمردي

Table C-1. Hazardous Materials Storage, Facility 828 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Lubricating Oil	2 quarts/month	1.9/month	1990
Lubricating Oil, General Purpose	1 quart/month	0.9/month	1983
Lubricating Oil, General Purpose	128 ounces/month	3.8/month	1986
Lubricating Oil, General Purpose	2 gallons/year	7.6/year .	1990
Lubricating Oil, General Purpose	10 pints/month	4.7/month	1990
Lubricating Oil, Multi Purpose	2 gallons/year	7.6/year	1990
Lubricating Oil, Weapons	6 quarts/year	5.7/year	1992
Methyl Ethyl Ketone	1 gallon/year	3.8/year	1983
Molybdenum Disulfide	1 pound/6 months	0.5/6 months	1986
Molybdenum Disulfide Lubricating Oil	6 pounds/month	2.7/month	1983
O-Ring Lubricant	12 tubes/year	5.4/year	1993
O-Ring Lubricant	144 ounces/year	4.3/year	1992
Oil, 75 Weight	0.6 quart/year	0.6/year	1993
Oil, Arctic Weapons	1 quart/2 months	0.9/2 months	1986
Paint, Spray Gloss Black	25 ounces/month	0.7/month	1983
PD-157	36 ounces/month	1.08/month	1990
PD-157	72 cans/year	1,633/year	1993
PD-157	144 quarts/year	136/year	1992
PD-680	150 gallons/6 months	567/6 months	1986
Penetrating Oil	1 pint/6 months	0.5/6 months	1983
Perma-Silk G Lubricant Aerosol	2,304 ounces/year	68.2/year	1992
Perma-Silk G Lubricant Aerosol	120 cans/year	2,722/year	1993
Petrolatum technical	1 quart/year	0.9/year	1986
Polish, Plastic Type 1	1 pint/year	0.5/year	1986
Polyurethane Coating Aliphatic Thinner	0.5 gallon/month	1.9/month	1983
PR1431-G and GT Sealing	24 kits/year	11/year	1992
PR1431-G and Sealing	12 kits/year	5.4/year	1993
Primer, Adhesive	1 quart/10 years	0.9/10 years	1990
Primer, All Purpose	26 ounces/year	0.77/year	1983
Primer, Bostik Adhesive	12 quarts/year	11.4/year	1992
Primer, Cellulose Nitrate	5 pounds/month	2.3/month	1983
Primer, PWC201 ZC	24 pints/year	11.4/year	1992-1993
Probe	1 kit/3 months	0.5/3 months	1987
Removing Compound	1 gallon/year	3.8/year	1983
Riflebore Cleaner	1 gallon/year	3.8/year	1983

`.<

Table C-1. Hazardous Materials Storage, Facility 828 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Rigid Thread Cutting Oil	600 ounces/month	19.20/month	1983
Safety Kleen	1,800 gallons/year	6,804/year	1993
Safety Kleen 140	280 gailons/year	1,058/year	1992
Safety Kleen 140 Solvent	150 gallons/6 months	567/6 months	1990
Sealant	2 ounces/6 months	0.06/6 months	1986
Sealant Decals 4150	8 ounces/year	0.2/year	1986
Sealing Compound	8 ounces/3 months	0.2/3 months	1990
Sealing Compound	1 pint/year	0.5/year	1986
Sealing Compound	4 ounces/6 months	0.1/6 months	1986
Sealing Compound	1 kit/month	0.5/month	1987,1990
Sealing Compound GC-1300	12 ounces/year	0.36/year	1993
Sealing Compound GC-1300	24 ounces/year	0.7/year	1992
Semi Fluid Oil	1 quart/month	0.9/month	1986
Semifluid Lubricating Oil	1 gallon/month	3.8/month	1983
Silicone Adhesive	288 ounces/year	8.5/year	1992
Silicone Compound	180 ounce/year	5.3/year	1992
Silicone Compound	12 ounces/year	0.36/year	1993
Silicone Dielectric Compound	8 ounces/week	0.2/week	1983
Silicone Sealant	12 tubes/year	5.4/year	1993
Slyde Lubricating Compound Silicone	24 cans/year	544/year	1993
Slyde Lubricating Compound Silicone	2,304 ounces/year	68/year	1992
Slyde Lubricating Oil	16 ounces/3 months	0.5/3 months	1986
Solid Film Lubricant	160 ounces/month	5/month	1990
Super Bonder 430	1 bottle/month		1990
Super Glue	12 ounces/year	0.36/year	1993
Super Glue	36 ounces/year	1/year	1992
Technical Alcohol	1 gallon/year	3.8/year	1990
Zinc Chromate Primer	12 pints/year	5.7/year	1993

Table C-1. Hazardous Materials Storage, Facility 839

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Aqua Fortis, Axotic/Nitric Acid	0.2 ounce/year	.006/year	1993
Cleaner and Remover	144 ounces/year	4.3/year	1993
Cleaner/Polish	8 ounces/year	0.2/year	1985
Cleaner Remover	130 ounces/year	3.8/year	1985
Cleaner ZC-7	72 ounces/week	2.16/week	1975
Cleaning Compound, Engine Gas	5 gallons/year	19/year	1990
Cleaning Compound Solvent, Aerosol	13 ounces/year	0.4/year	1985
Corrosion Preventative Compound	2 quarts/month	1.9/month	1985
Developer	1 pint/week	0.5/week	1975
Developer	28 ounces/year	0.8/year -	1985
Developer, Aerosol	28 ounces/year	0.8/year	1985
Developer and Replenisher	12 ounces/year	0.36/year	1993
Developer and Replenisher	384 ounces/year	11.4/year	1993 ·
Developer and Replenisher	384 ounces/year	12/year	1990
Developer GI	10 gallons/year	37.8/year	1981
Developer/Replenisher Part B	12 fluid ounces/year	0.36/year	1990
Emulsifier	1 pint/week	0.5/week	1975
Emulsifier	1 gallon/month	3.8/month	1981
Emulsifier	110 gallons/year	416/year	1985
Enamel, Brown	8 ounces/year	0.2/year	1985
Enamel, Green	13 ounces/year	0.4/year	1985
Enamel, Olive Drab	13 ounces/year	0.4/year	1985
Enamel, Yellow	13 ounces/year	0.4/year	1985
Fixer and Hardener Part A	384 ounces/year	11.4/year	1990,1993
Fixer and Hardener Part B	43 ounces/year	1.3/year	1993
Fixer GI	10 gallons/year	37.8/year	1981
Fixer/Hardener	43.2 ounces/year	1.2/year	1990
Fluorescent Magnetic	8 galions/year	30/year	1985
Grease, General Purpose	8 ounces/year	0.2/year	1985
Hydrochloric Acid	0.2 ounce/year	0.006/year	1993
Hydrochloric Acid	1 ounce/5 years	0.03/5 years	1990
Hydrochloric/Muriatic Acid	0.2 ounce/year	0.006/year	1993
Kerosene	1 pint/week	0.05/week	1975
Lacquer, Acrylic Aerosol	4 ounces/year	0.01/year	1985

Table C-1. Hazardous Materials Storage, Facility 839 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Lacquer, Acrylic Clean	4 ounces/year	0.1/year	1985
Lacquer, Blue	13 ounces/year	0.4/year	1985
Lacquer, White	8 ounces/year	. 0.2/year	1985
Lacquer, White	13 ounces/year	0.4/year	1985
Lacquer, Yellow	13 ounces/year	0.4/year	1985
Lube Oil, General Purpose	16 ounces/year	0.5/year	1990,1993
Lube Oil, General Purpose	6 ounces/year	0.18/year	1985
Lubricating Oil	240 ounces/year	7.2/year	1990
Magnaflux Carrier with 14A Powder	55 gallons/year	208/year	1993
Magnaglo	0.5 gallon/month	1.9/month	1981
Magnaglo Aerosol	Unknown		1985
Magne-Tech	12 ounces/2 years	0.36/2 years	1990
Nitric Acid	1 ounce/5 years	0.03/5 years	1990
Oil, Standard Special	8 ounces/month	0.2/month	1985
Optical Lens Cleaning Compound	2 ounces/month	0.06/month	1985
Paint, Interior Flat Latex	1 gallon/2 years	3.8/2 years	1985
Penetrant	1 gallon/month	3.8/month	1981
Penetrant	18 ounces/year	0.5/year	1985
Penetrant	110 gailons/year	416/year	1985
Penetrant, Water	1 pint/week	0.5/week	1975
Penetrant ZL-22A	0.5 pint/week	0.2/week	1975
Plastic Cleaner	0.5 quart/year	0.5/year	1985
Powder with Magnaflu	100 pounds/year	45.4/year	1993
Prepared Bath AE	6 ounces/year	` 0.18/year	1993
Prepared Bath	12 ounces/month	0.36/month	1990
Primer Coating	13 ounces/year	0.4/year	1985
Remover	60 gallons/year	227/year	1993
Remover	120 gallons/year	453.6/year	1990
Remover	144 ounces/year	4.32/year	1990
Sulfur Hexafluoride Dielectric Grade Gas	25 pounds/year	11.3/year	1990,1993
Trichloroethane	3 gallons/year	11.3/year	1990,1993
Trichloroethylene	1 pint/week	0.5/week	1975
X-Ray Developer	0.1 pint/week	0.05/week	1975

Table C-1. Hazardous Materials Storage, Facility 839 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
X-Ray Fixer	0.1 pint/week	0.05/week	1975
Zyglo Cleaner	12 cans/month	272/month	1981
Zyglo Developer	1 can/month	23/month	1981
Zyglo Developer	12 ounces/year	0.36/year	1990,1993
Zyglo Developer	100 pounds/year	45.4/year	1990
Zyglo Penetrant	12 ounces/year	0.36/year	1990
Zygio Penetrant	55 gallons/year	208/year	1993
Żyglo Penetrant	110 gallons/year	416/year	1990
Zyglo Penetrate Aerosol	8 ounces/year	0.2/year	1993

Table C-1. Hazardous Materials Storage, Facility 918

	Quantity Stored	Quantity Stored	Duration of
Product	(Units Provided)	(kg)	Storage
Machine/Sheet Metal Shop			
			•
Acetone	Unknown		1985
Adhesive	1 pint/month	0.5/month	1985 ု
Adhesive	1 kit/3 months	0.5/3 months	1987
Adhesive, Epon 828	Unknown	<b>+-</b>	1985
Adhesive, Fiberglass	6 ounces/2 months	0.18/2 months	1987
Adhesive, Nitrile/Resin	1 pint/month	0.5/month	1985 ·
Adhesive, Nitrite	Unknown		1985
Adhesive, Part A	36 ounces/month	1.08/month	1987
Adhesive, Part A	1 quart/month	0.9/month	1985
Adhesive Paste, RTV	3 ounces/week	0.09/week	1985
Adhesive, RTV	6 ounces/year	0.18/year	1987
Adhesive, Scotch Weld	1 pint/month	0.5/month	1985
Adhesive Sealant	3 ounces/month	0.09/month	1985
Adhesive, Structural	1 kit/3 months	0.5/3 months	1987
Aluminum Coating Kit	6 ounces/month	0.18/month	1985
Autobody Filler	Unknown		1985
Automatic Transmission Fluid Cherry	8 ounces/year	0.2/year	1993
Brake Kleen	4 pints/year	1.9/year	1993
Brake Kleen	16 ounces/year	0.5/year	1986
Corrosion Preventative Compound	16 ounces/year	0.5/year	1985
Corrosion Preventative Compound	12 ounces/year	0.36/year	1993
Curing Agent	1 pint/3 months	0.5/3 months	1985
Curing Agent Epon	1 pint/6 months	0.5/6 months	1987
Cutting Fluid	12 pints/year	5.7/year	1993
Cutting Fluid	2 ounces/year	0.06/year	1986
Cutting Fluid	48 ounces/3 months	1.4/3 months	1985
Cutting Fluid	12 ounces/year	0.36/year	1986
Cutting Fluid	48 ounces/year	1.4/year	1985
Cutting Fluid	1 quart/year	0.9/year	1985
Cutting Fluid	48 ounces/month	1.4/month	1988
Cutting Fluid, Sulfurized	8 ounces/month	0.2/month	1988
Cutting Fluid, Tapmatic	12 pints/year	5.7/year	1993
Detergent, General Purpose	1 quart/year	0.9/year	1987

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Dye, Blue Layout	12 ounces/year	0.36/year	1993
Emulsifier Degreaser	1 pint/6 months	0.5/6 months	1985
Enamel, Floor and Deck	Unknown		1985
Epi-Seal Paste	11 ounces/month	0.3/month	1985
Epon 828	Unknown	**	1985
Epoxy Patch Kit	8 ounces/week	0.2/week	1985
Floor Polish, Umbrella High Solids	4 ounces/year	0.1/year	1986
Floor Wax	1 pint/2 months	0.5/2 months	1986
Gear Lubricant	2 ounces/year	0.06/year	1993
General Purpose Spray	48 ounces/year	1.4/year	1986
Grease, Aircraft	7 ounces/year	0.2/year	1993
Grease, Aircraft	5 ounces/year	0.15/year	1986
Hand Cleaner	14 ounces/3 months	0.4/3 months	1985
Hand Cleaner	2 ounces/month	0.06/month	1986
Hydraulic Fluid	0.5 pint/year	0.2/year	1986
Hydraulic Fluid	8 ounces/year	0.2/year	1986
isopropyl Alcohol	Unknown	••	1985
Lapping Compound All Grit Size	0.5 ounce/year	0.05/year	1993
Lay Out Dip, Blue	1 pint/6 months	0.5/6 months	1986
Layout, Blue Fluid	2 ounces/year	0.06/year	1985
Layout Dip	0.5 ounce/year	0.05/year	1985
Layout Fluid	8 ounces/year	0.2/year	1985
Lube Oil, General Purpose	Unknown	••	1993
Lube Oil, Type 2	Unknown		1993
Methyl Ethyl Ketone	1 gallon/month	3.8/month	1985, 1987
Mixing Base	3 gallons/year	11.3/year	1985
Mobil Vactra Oil 2	1 ounce/year	0.03/year	1993
Mobile 350	1 ounce/year	0.03/year	1993
Molybdenum Disulfide	0.5 ounce/year	0.05/year	1986
Motor Oil 30 Weight	2 quarts/year	1.9/year	1993
Multipurpose Spray	45 ounces/3 months	1.3/3 months	1985
Multipurpose Spray	15 ounces/year	0.4/year	1986
Never Dull	5 ounces/year	0.15/year	1993
P-Emulsin	4 ounces/year	0.11/year	1986
Paint Drier	Unknown		1985
Paint Remover and Lacquer	Unknown		1985
Penetrating Oil	8 ounces/year	0.2/year	1988




Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Primer Coating Epoxy	1 pint/3 months	0.5/3 months	1987
Rapid Tap, Cutting Fluid	16 ounces/month	0.5/month	1986
Resin	Unknown		1985
Resin/Epon 815	1 gallon/6 months	3.8/6 months	1987
Resin-Epon 815	Unknown		1985
Rigid Dark Thread Cutting Oil	1 gallon/year	3.8/year	1993
Rigid Dark Thread Cutting Oil	8 ounces/month	0.2/month	1988
Sealing Compound	1 pint/year	0.5/year	1985
Sealing Compound	6 ounces/year	0.18/year	1987
Sealing Compound	12 ounces/month	0.3/month	1987
Sealing Compound	Unknown	**	1985
Solid Film Lubricant	16 ounces/year	0.5/year	1985
Spackling Patching Compound	1 quart/year	0.9/year	1985
Spray On Layout Blue	10 ounces/year	0.3/year	1986 `
Trichloroethane	1 quart/year	0.9/year	1993
Ultron SXP-911 Water Based Coolant	55 gallons/year	208/year	1993
Vacuum Pump Lube Oil	1 ounce/month	0.03/month	1985
Weapons Oil	16 ounces/year	0.5/year	1986
Weapons Oil	12.5 ounces/year	0.37/year	1985
White Lead Basic Carbonate	2.5 pounds/year	1.1/year	1985
White Lead Basic Carbonate	0.5 ounce/year	0.02/year	1986
Zinc Chromate Putty General Purpose	Unknown		1985
Egress Shop			
Adhesive, Rubber RTV	1 pint/year	0.5/year	1993
Adhesive Sealant, RTV	1 ounce/year	0.03/year	1993
Anti-Seize Compound, Lead Free	0.2 pound/year	0.09/year	1993
Braycote 806 Grease, Instrument	1 ounce/year	0.03/year	1993
Corrosion Preventative Compound	3 ounces/year	0.09/year	1993
Corrosion Resistant Coating	1 pint/year	0.5/year	1993
Isopropyl Alcohol	1 quart/year	0.9/year	1993
Lubricant Aerosol Telomer	16 ounces/year	· 0.5/year	1993

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
O-Ring Lubricant	2 ounces/year	0.06/year	1993
PD-680	1 pint/year	0.5/year	1993
Primer Coating Parts A + B	0.5 gallon/year	1.9/year	1993
Sealing Compound 420 Anaerobic	1 cubic centimeter/year	0.001/year	· 1993
Sealing Compound Grade C Part B	1 tube/year	0.5/year	1993
Sealing Compound Parts A+B	1 tube/year	0.5/year	1993
Silicone Sealant Parts A + B	10.3 ounces/year	0.3/year	1993
Vibratite	12 ounces/year	0.36/year	1993
Docks Inspection			
Accelerator Sealing Compound	60 ounces/year	1.8/year	1993
Adhesive	2 pints/year	0.9/year	1993
Adhesive, Cyanoacrylate	5,460 grams/year	5.5/year	1986
Adhesive, Epoweld	24 kits/year	11.3/year	1993
Adhesive, Rubber	1 pint/6 months	0.5/6 months	1988
Adhesive, Rubber Base	2 pints/month	0.9/month	1984, 1986
Adhesive Sealant, RTV	6 tubes/year	2.7/year	1993
Aircraft Surface Compound	1 ounce/month	0.03/month	1988
Anaerobic Sealants	1.7 ounces/month	0.05/month	1984, 1986
Brakleen	Unknown	-	1993
Brakleen	384 ounces/month	12/month	1988
Brakleen	456 ounces/month	13.5/month	1986
Cleaning Compound	3 gallons/plane	11.3/plane	1988
Cleaning Compound Aircraft Surface	64 ounces/year	2/year	1993
Corrosion Preventative Aircraft- 50	Unknown	-	1993
Corrosion Preventative Compound	32 ounces/year	1/year	1984, 1986
Dry Lubricant Release Agent	30 ounces/month	0.89/month	1984, 1986
Enamel, Gloss Black	1 pint/month	0.5/month	1988
Epoxy Patch	20 ounces/year	0.6/year	1986
Epoxy Patch	5,460 grams/year	5.5/year	1984
Epoxy Resin Part 9309	2 kits/year	0.9/year	1993
Epoxy Resin Parts A+B	4 kits/year	1.8/year	1993

محمد المساء.

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
General Purpose Oil ,	1 gallon/month	3.8/month	1986
General Purpose Oil	Unknown		1984
Glass Cleaner	1 gallon/3 months	3.8/3 months	1988
Grease, Aerosheil 22	5 pounds/year	2.3/year	1988
Grease, Molybdenum	1 gallon/year	3.8/year	1988
Grease, Molybdenum Disulfide	Unknown		1993
Grease, Silicone Versilube 351	4 ounces/year	0.1/year	1993
Ink, Black Marking Stencil Opaque	Unknown	-	1993
Ink, Red Marking Stencil Opaque	Unknown		1993
lnk, White Marking Opaque	Unknown		1993
Lacquer, Camouflage Gray	1 pint/month		1988
Leak Detection Compound	4 ounces/month	0.1/month	1984, 1986
Leak Tec	4 ounces/year	0.1/year	1988
Lube Oil, General Purpose	12.5 ounces/year	0.37/year	1993
Lube Oil, General Purpose	Unknown	<del></del>	1993
Lubricating Oil, Aircraft Engine	28 quarts/year	26.5/year	1993
Lubricating Compound, Dimethysilic	16 ounces/year	0.5/year	1993
Lubricating Oil	4 ounces/day	0.1/day	1988
Lupri-Bond	12 ounces/month	0.36/month	1988
Marvelseal	16 ounces/month	0.5/month	1986
Methyl Ethyl Ketone	1 quart/year .	0.9/year	1993
Oil, Penetrating	1 pint/year	0.5/year	1988
Paint, Black	1 gallon/3 years	3.8/3 years	1988
Penetrating Oil	Unknown		1993
Perma-Silk G Lubricant Aerosol	16 ounces/year	0.5/year	1993
Petrolatum Technical	Unknown		1993
Plastic Polish	2 quarts/month	1.9/month	1984, 1986
Plastic Polish Liquid	1 pint/year	0.5/year	1993
Primer, Brown	1 pint/6 months	0.5/6 months	1988
Primer, Coating	1 pint/month	0.5/month	1988
Primer, RTV	Unknown		1993
Primer, Yellow	1 pint/month	0.5/month	1988
Protective Coating and Beautifier	Unknown	-	1993
PWC 218	1 can/3 months	23/3 months	1988

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Rain Repellant, Windshield	4 pints/month	1.9/month	1984, 1986
Sealing Compound Parts A + B	Unknown		1993
Silicone Adhesive Sealant	600 ounces/year	17.8/year	1984
Silicone Adhesive Sealant	15 ounces/month	0.4/month	1984
Silicone Sealant	1.5 ounces/month	0.04/month.	1988
Super Glue	Unknown	***	1993
Super Glue Adhesive	6 ounces/year	0.18/year	1993
Trichloroethane	1/2 can/month	11.3/month	1986
Two-Cycle Oil	1 pint/year	0.5/year	1993
WD-40	1 pint/year	0.5/year	1993
Electrical Battery/Environmental	•		
4 Compound Adhesive	8 ounces/year	0.2/year	1990
Acid, Boric	6 pints/year	2.8/year	1990
Acid, Sulfuric	15 gallons/year	56.7/year	1990
Adhesive	8 ounces/year	0.2/year	1993
Adhesive, C-111	8 ounces/year	0.2/year	1990
Adhesive, Epoweld	400 grams/year	4/year	1990, 1993
Adhesive, Nitrile Resin	8 ounces/year	0.2/year	1990
Adhesive, RTV	168 ounces/ year	4.8/year	1990
Adhesive, Rubber	2 ounces/year	0.6/year	1993
Adhesive, Sealant RTV	48 ounces/year	1.4/year	1993
Adhesive, Super Fast Foam	1 can/year	23/year	1993
Adhesive, Thermofit S-1009 Parts A + B	300 grams/year	0.3/year	1990
Adhesive Two Parts Thermofit	900 grams/year	0.9/year	1993
Aerosol Colors Poly PWC	4 pints/year	1.9/year	1993
Aliphatic Naphtha	1 gallon/year	3.8/year	1990
Allen Solder Paste	6 ounces/year	0.18/year	1993
Allen Solder, Paste Flux	6 ounces/year	0.18/year	1990
Battery Alkaline	Unknown		1993
Boric Acid ,	6 pints/year	2.8/year	1993
Brakleen	456 ounces/year	13.5/year	1993
Brakleen	456 ounces/year	14.4/year	1990
Cleaning and Lubricating Solvent	72 ounces/year	2/year	1993

71 156

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Cleaning Compound, Aircraft Surface	312 ounces/year	9.2/year	1993
Cleaning Compound, Aircraft Surface	312 ounces/year	9.6/year	1990
Cleaning Compound Solvent	192 ounces/year	5.7/year	1993
Cleaning Compound Solvent	192 ounces/year	6/year	1990
Corrosion Preventative Compound Type 3	12 pints/year	5.7/year	1990, 1993
Enamel; Flat Black	12 ounces/year	0.36/year	1993
Enamel, Flat Black	1 pint/year	0.5/year	1990
Enamel, Gloss Black	12 ounces:year	0.36/year	1993
Enamel, Gloss Black	1 pint/year	0.5/year	1990
Enamel, Gray	1 pint/year	0.5/year	1990
Enamel, Gray PWC	12 ounces/year	0.36/year	1993
Enamel, White	12 ounces/year	0.36/year	1993
Enamel, White	1 pint/year	0.5/year	1990
Enamel, Yellow	4 pints/year	1.9/year	1990
Gray Coating	1 kit/year	0.5/year	1990
Grease, Aircraft	5 gallons/year	19/year	1990
Grease, Aircraft	0.2 gallon/year	0.76/year	1993
Grease, General Purpose	1 pound/year	0.5/year	. 1993
Ink, Black	16 ounces/year	0.5/year	1990
ink, Black Aerosol	16 ounces/year	0.5/year	1993
Ink, White Stencil	4 pints/year	1.9/year	1993
Insulating Varnish, Red	4 ounces/year	0.1/year	1993
Lacquer	1 pint/year	0.5/year	1990
Lacquer, Acrylic Yellow	4 pints/year	1.9/year	1993
Lacquer, Aerosol	12 ounces/year	0.36/year	1993
Lacquer, Aluminum	2 pints/year	0.9/year	1990
Lacquer, Aluminum	24 ounces/year.	0.7/year	1993
Lacquer, Brown	1 pint/year	0.5/year	1990
Lacquer, Brown Aerosol	12 ounces/year	0.36/year	1993
Lacquer, Clear	1 pint/year	0.5/year	1990
Lacquer, Clear Aerosol	12 ounces/year	0.36/year	1993
Lacquer, Green	1 pint/year	0.5/year	1990
Lacquer, Green Aerosol	12 ounces/year	0.36/year	1993
Lacquer, Olive Drab	1 pint/year	0.5/year	1990
Lacquer, Olive Drab	12 ounces/year	0.36/year	1993

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

	Quantity Stored	Quantity Stored	Duration of
Product	(Units Provided)	(kg)	Storage
Leak Test Compound	48 ounces/ year	1.2/year	1990, 1993
Lube Oil, General Purpose	24 ounces/year	0.7/year	1993
Lube Oil, General Purpose Aerosol	96 ounces/year	2.8/year	1993
Lubricating Oil, Aircraft Engine	144 ounces/year	4.3/year	1993
Lubricating Oil, Aircraft Turbine Engines, Synthetic	144 ounces/year	3.6/year	1990
Lubricating Oil, General Purpose	96 ounces/year	3/year	1990
Lubricating Oil, General Purpose	24 ounces/year	0.6/year	1990
Methyl Ethyl Ketone	1 gailon/year	3.8/year	1990, 1993
Naphtha, Aliphatic	1 gallon/year	3.8/year	1993
Nitrile Resin Adhesive	8 ounces/year	0.2/year	1993
Oxygen	1 can/year	23/year	1993
Paint, Gray Aerosol	16 ounces/year	0.5/year	1993
PD-157	72 ounces/year	2.16/year	1990
Pig Repair Putty	1 can/year	23/year	1993
Primer, Z	4 pints/year	1.9/year	1993
Primer, Zinc Chromate Yellow	3 pints/year	1.4/year	1990
Primer, Zinc Chromate Yellow	36 ounces/year	1.1/year	1993
Sealing Compound Grade H	4 cans/year	91/year	1993
Silicone Adhesive	8 ounces/year	0.2/year	1993
Slyde Lubricant Compound Silicone	16 ounces/year	0.5/year	1993
Sulfuric Acid Electrolyte Grad	15 gallons/year	56.7/year	1993
Super Glue	2 ounces/year	0.06/year	1993
Torque Seal -	12 ounces/year	0.36/year	1993
Environmental Systems Pneudraulic Shop			
Adhesive, 4 Compound	8 ounces/year	0.2/year	1990
Adhesive, C-111	8 ounces/year	0.2/year	1990
Adhesive, Epoweld	400 grams/year	4/year	1990
Adhesive, Foamfast	1 can/year	23/year	1993
Adhesive, Scotch Grip Rubber	2 ounces/year	0.06/year	1993
Adhesive Sealant	24 ounces/year	0.6/year	1990
Aliphatic Naphtha	1 gailon/year	3.8/year	1990




Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Anti-Seize Compound	1 pound/year	0.5/year	1993
Battery Alkaline	Unknown	•	1993
Brake Parts Cleaner	264 cans/year	5,987/year '	1993
Brakleen	768 ounces/month	22.7/month	1986
Brakleen	228 ounces/ month	7.2/month	1990
Brakleen	264 cans/year	5,987/year	1993
Cleaning Compound Solvent	192 ounces/year	6/year	1990
Enamel, Flat Black	1 pint/year	0.5/year	1990
Enamel, Gloss Black	1 pint/year	0.5/year	1990
Enamel, Gloss White	1 pint/year	0.5/year	1990
Enamel, Gray	1 pint/year	0.5/year	1990
Enamel, Yellow	2 pints/year	0.9/year	1990
Gray Coating	1 kit/year 🕠 🗸	0.5/year	1990
Grease, Aircraft	51 pounds/3 years	23/3 years	1984, 1986
Grease, Aircraft	5 gallons/year	19/year	1990
Grease, Aircraft	0.2 pound/year	0.09/year	1993
Grease, Aircraft	2 ounces/month	0.06/month	1984, 1986
Grease, Aircraft and Instrument	1.75 pounds/year	0.8/year	1986
Grease, General Purpose	1 pound/year	0.5/year	1993
Hydraulic Film	30 pints/year	14.2/year	1990
Hydraulic Fluid .	30 gallons/year	113.4/year	1990
Hydraulic Fluid	50 gallons/year	189/year	1984, 1986
Hydraulic Fluid	13 ounces/3 months	0.4/3 months	1984, 1986
Hydraulic Fluid	5 gallons/year	19/year	1990
Hydraulic Fluid	30 pints/year	14.2/year	1993
Hydraulic Fluid	180 gallons/year	680/year	1984, 1986
Hydraulic Fluid Type 2	30 gallons/year	113.4/year	1993
lnk, Aerosol Black	19 ounces/year	0.9/year	1993
Ink, Black	16 ounces/year	0.5/year	1990
Ink, White Stencil	4 pints/year	1.9/year	1993
Insulating Varnish Red	4 ounces/year	0.1/year	1993
Lacquer, Aluminum	2 pints/year	0.9/year	1990
Lacquer	1 pint/year	0.5/year	1990
Lacquer, Brown	1 pint/year	0.5/year	1990
Lacquer, Clear	1 pint/year	0.5/year	1990
Lacquer, Green	1 pint/year	0.5/year	1990
Lacquer, Olive Drab	1 pint/year	0.5/year '	1990

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Leak Test Compound	48 ounces/year	1.2/year	1990
Lube Oil, General Purpose Aerosol	96 ounces/year	2.8/year	1993
Lube Oil, Instrument	1 quart/6 months	0.9/6 month's	1984, 1986
Lube Oil, Synthetic	15 ounces/month	0.4/month	1984, 1986
Lubri-Bond Solid Film	24 ounces/year	0.72/year	1990
Lubricating Compound, Dimethysilic	8 ounces/year	`0.2/year	1993
Lubricating Oil, Aircraft Turbine Engine	144 ounces/year	3.6/year	1990
Lubricating Oil, General Purpose	8 ounces/year	0.2/year	1993
Lubricating Oil, General Purpose	96 ounces/year	3/year	1990
Lubricating Oil, General Purpose	8 ounces/year	0.2/year	1990
Methyl Ethyl Ketone	1 gallon/year	3.8/year	1990
Methyl Ethyl Ketone	1 gallon/2 years	3.8/2 years	1986
Molybdenum Disulfide	14 ounces/2 years	0.4/2 years	1984, 1986
Nitrile/Resin	8 ounces/year	0.2/year	1990
Oxygen	1 can/year	23/year	1993
Paint Remover	1 gallon/2 years	3.8/2 years	1984, 1986
PD-680	30 gallons/month	113.4/month	1986
Pig Repair Putty	1 can/year	23/year	1993
Poly Aerosol Colors	4 pints/year	1.9/year	1993
Primer	4 pints/year	1.9/year	1993
Primer, Coating Yellow	3 pints/year	1.4/year	1990
Safety Kleen	40 gallons/year	151/year	1993
Sealing Compound	4 cans/year	91/year	1993
Silicone Compound	8 ounces/year	0.2/year	1984, 1986
Slyde Lubricating Compound	16 ounces/year	0.5/year	1993
Slyde Silicone Lubrication	16 ounces/2 years	0.5/2 years	1990
Solvent	25-30 gallons/ 6 months	94.5-113.4/6 months	1990
Super Glue	2 ounces/year	0.06/year	1993
Technical Petrolatum	1 quart/year	0.9/year	1984, 1986
Torque Seal	2 ounces/year	0.06/year	1993
Trichloroethane	8 ounces/month	0.25/month	1986
Trichloroethane Spray	144 ounces/month	4.3/month	1984, 1986



Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Trichloroethane Technical	1 quart/month	0.9/month	1984, 1986
Structural Repair Shop			
47544 B 4.28	4	1.04	1000
Adhesive 1751A Parts A + B	4 pints/year	1.9/year	1993
Adhesive EA9330 Parts A + B	4 kits/year	1.8/year	1993
Adhesive Sealant, RTV	8 tubes/year	3.6/year	1993
Epoxy Resin Part 2	100 kits/year	45.4/year	1993
General Purpose Cement Solve Glue	4 quarts/year	3.8/year	1993
Methyl Ethyl Ketone	· 4 gallons/year	15/year	1993
Microballons, Phenolic	1 pound/year	0.5/year	1993
Paint, Dark Gray	8 pints/year	3.8/year	1993
Primer, PWC	8 pints/year	3.8/year	1993
Scotch Sealer, Edge Seal	8 pints/year	3.8/year	1993
Sealant, Hi-Temp	4 kits/year	1.8/year	1993
Sealing Compound Part A	288 ounces/year	8.5/year	1993
Sealing Compound Part B	Unknown		1993
Sealing/Fastening Epocast	4 kits/year	1.8/year	1993
Thinner	4 gallons/year	15/year	1993
Fuel Systems	,		
Cleaning and Lubricating Compound	2 pints/year	0.9/year	1985-1986
JP-4	100 gallons/year	45.4/year	1985-1986
Lubricating Oil	0.5 gallon/year	1.9/year	1985-1986
Methyl Ethyl Ketone	2 gallon/year	7.6/year	1985-1986
Penetrating Oil	0.5 pint/year ,	0.2/year	1985-1986
Petrolatum	5 quarts/year	4.7/year	1985-1986
Sealant	20 tubes/week	9/week	1985-1986
Flightline Shop			
Adhesive	Unknown		1984
Adhesive, Armstrong	4 pints/year	1.9/year	1993
Adhesive, Nitrile Resin	8 ounces/year	0.2/year	1993
Adhesive, SC-840	8 ounces/year	0.2/year	1993

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Adhesive, Scotch Grip Rubber	2 ounces/year	0.06/year	1993
Adhesive Sealant, RTV	12 ounces/year	0.36/year	1993
Adhesive, Two Parts Thermofit	900 grams/year	0.9/year	1993
Aircraft Cleaning Compound	7 drums/month	1,324/month	1984
Brakleen	180 pints/year	85.1/year	1993
Cleaner Engine Wash	180 gallons/year	680.4/year	1993
Cleaning Compound	8 gallons/month	30.2/month	1984
Cleaning Compound, Aircraft Surface	180 gallons/year	680.4/year	1993
Cleaning Compound, Engine	15 gailons/year	56.7/year	1993
Cleaning Compound Solvent	120 gallons/year	453.6/year	1993
Corrosion Preventative Compound Type 3	4 cans/year	91/year	1993
Deicing Fluid	8,000 gallons/year	30,240/year	1993
Desiccant Activated	144 gallons/year	544/year	1993
Enamel, Olive Drab	18 pints/year	8.5/year	1993
Glass Cleaner	2 gallons/month	7.6/month	1984
Grease, Aeroshell	3.2 pounds/year	1.5/year	1993
Grease, Aircraft	20 pounds/year	9/year	1993
Hydraulic Fluid	16 quarts/year	15/year	1993
Hydraulic Fluid Petroleum	30 pints/year	14/year	1993
Ink, White Stencil	4 pints/year	1.9/year	1993
JP-4	Unknown	Name .	1993
Leak Test Compound	12 pints/year	5.7/year	1993
Lubricating Oil, Aircraft Engine	96 ounces/year	2.8/year	1993
Methanol	600 gallons/year	2,268/year	1993
Methanol Technical	30 gallons/month	113.4/month	1984
Methyl Ethyl Ketone	60 gallons/year	226.8/year	1993
Nitrogen	60 cylinders/year	2,722/year	1993
Oxygen, Liquid	240 gallons/year	907/year	1993
Petrolatum, Technical	7 pounds/year	3.2/year	1993
Plastic Polish Liquid	240 pints/year	113.5/year	1993
Protective Coating and Beautifying	96 pints/year	45.4/year	1993
Sealant, RTV	6 tubes/year	2.7/year	1993
Sealing Compound	4 cans/year	91/year	1993
Split Line Sealer	12 tubes/year	5.4/year	1993
Super Glue	24 ounces/year	0.7/year	1993



Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored	Duration of
		(kg)	Storage
Torque Seal	12 ounces/year	0.4/year	1993
Welding Shop			
Acetylene Tech for Welding	2 cylinders/year	91/year	1993
Acetylene Technical	1 cylinder/3 months	45.4/3 months	1984
Argon .	1 cylinder/month	45.4/month	1984
Argon Carbon Dioxide	1 cylinder/3 months	45.4/3 months	1984
Argon Lar, Liquid Only	5 cylinders/year	227/year	1993
Brazing Alloy	2 ounces/month	0.06/month	1984
Brazing Alloy, Silver	20 ounces/year	0.6/year	1993
Brazing Rod Super 185XCF	20 ounces/year	0.6/year	1993
Brought IAW Specs.	5 gailons/year	19/year	1984
Carbon Dioxide Argon Kit	4 cylinders/year	181.4/year	1993
Cast Iron Welding	1 ounce/year	0.03/year	1984
Chromatoy Flux	4 ounces/year	0.1/year	1993
Electrode Class ER 4043	Unknown		1993
Electrode	Unknown		1993
Electrode 2% Thouriated Tungsten	Unknown		1993
Electrode 312 Weld	Unknown		1993
Electrode 6011 Welding Rod	Unknown		1993
Electrode Class 12/Mis 57868	Unknown		1993
Electrode Ext Magnesium Weld	Unknown	<del></del>	1993
Electrode Pipe Craft	Unknown		1993
Electron Welding Rod 6013	Unknown ·		1993
Eutectic Brazing	8 ounces/month	0.2/month	1984
Flux Eutc Silweld 1618	20 ounces/year	0.6/year	1993
Glass Beads	100 pounds/year	45.4/year	1993
Hydrochloric Acid	0.5 ounce/year	0.02/year	1993
Hydrochloric Acid	5 ounces/year	0.15/year	1993
Lead Solder	0.7 pound/year	0.3/year	1993
Leak Test Compound	8 ounces/year	0.2/year	1993
Lube Oil Instrument	5 ounces/year	0.15/year	1993
Methyl Ethyl Ketone	1 gailon/year	3.8/year	1993
Ox-Out 536	0.5 gallon/year	1.9/year ·	1993
Oxygen Lox, Liquid Only	4 cylinders/year	181.4/year	1993
Oxygen Technical	1 cylinder/2 months	45.4/2 months	1984

Table C-1. Hazardous Materials Storage, Facility 918 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Paste Flux	2 ounces/year	0.06/year	1984
Scale and Oxide Remover	3 ounces/month	0.09/month	1984
Sil-Flux	2 ounces/year	0.06/year	1984
Soldering Paste Type 1	10 ounces/year	0.3/year	1993
Stay Safe 50 Solder	10 ounces/year	0.3/year	1993
Stay Silver White Brazing Flux	5 ounces/year	0.15/year	1993
Welco 1620 Anti-Splatter	16 ounces/year	0.5/year .	1993
Welding Rod	1 pound/year	0.5/year	1993
Welding Wire Lubricant	30 each/year	13.5/year	1993

.

Table C-1. Hazardous Materials Storage, Facility 927

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Adhesive	2 tubes/year	0.9/year	1990
Adhesive, Cyanoacrylate	2 ounce/year	0.06/year	1990
Adhesive, Parts A + B	1 kit/year	0.5/year	1990
Adhesive, Parts A + B	12 kits/year	5.4/year	1993
Adhesive, Scotch Rip 44	64 ounces/year	2/year	1983
Adhesive Sealant, RTV	24 tubes/year	11/year	1990
Adhesive Sealant, RTV	60 tubes/year	27/year	1993
Adhesive, Super Foamfast	192 ounces/year	5.6/year	1990
Adhesive, Super Foamfast	290 ounces/year	8.6/year	1993
Assembly Fluid #1	32 ounces/year	0.8/year	1990
Assembly Fluid Parts Lube	12 tubes/year	5.4/year	1993
Assembly Fuel	2 ounces/6 months	0.06/6 months	1983
B and B 3100 Cleaning Compound	55 gallons/3 months	208/3 months	1983
B and B 3100 Cleaning Compound	110 gallons/year	415.8/year	1990
Brakleen	120 pints/year	56.8/year	1993
Brakleen	38 ounces/month	1.1/month	1983
Brakleen	1,900 ounces/ year	60/year	1990
Carbon Cleaner	54 gallons/year	204/year	1983
Carbon Remover	120 gallons/year	454/year	1993
Carbon Remover Compound	55 gailons/year	208/year	1990
Cleaning Compound Engine	120 gallons/year	454/year	1993
Cleaning, Engine	50 gallons/month	189/month	1981
Cleaning Fluid	150 gallons/year	567/year	1981
Coating Compound, Thermal Silicone	1 kit/year	0.5/year	1990
Enamel, Floor Gray	1 gallon/year	3.8/year	1983
Enamel, Red	0.5 gallon/year	1.9/year	1983
Enamel, Red	1 pint/month	0.5/month	1990
Enamel, Spray Paint	1 pint/month	0.5/month	1990
Enamel, Yellow Alkyd	1 gailon/year	3.8/year	1983
Epoxy Resin Parts A + B	60 kits/year	27/year	1993
Epoxy Resin Parts A + B	1 kit/year	0.5/year	1990
Freon TF	1 pint/year	0.5/year	1993
Freon TF Cleaning Compound Solvent	16 ounces/year	0.5/year	1990
Grease, Aeroshell	5 pounds/year	2.3/year	1990

Table C-1. Hazardous Materials Storage, Facility 927 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Grease, Aeroshell Aircraft	24 pounds/year	11/year	1993
Grease, Aircraft	2 pounds/year	0.9/year	1983
Grease, Aircraft and Instrument	168 ounces/year	4.8/year	1990
Grease, Auto	1 pound/year	0.5/year	1983
Grease, Versilube G351	8 ounces/year	0.2/year	1990
Hardener, EPK 1C	4 kits/year	1.8/year	1990
Hydraulic and General Purpose	5 gallons/year	19/year	1983
Hydraulic Fluid	12 quarts/year	11.4/year	1990
Hydraulic Fluid	0.5 quart/month	0.5/month	1983
Insulation Sealant	12 kits/year	5.4/year	1993
Lacquer, Acrylic	16 ounces/year	0.5/year	1983
Lacquer, Aerosol Spray	1 pint/year	0.5/year	1990
Lacquer, Black Acrylic	32 ounces/year	1/year	1983
Lacquer, Green	16 ounces/year	0.5/year	1983
Lacquer, Silver	16 ounces/year	0.5/year	1983
Layout Dye, Blue	1 ounce/year	0.03/year	1983
Lube Oil, Aircraft	5 gallons/month	19/month	1983
Lube Oil, Synthetic	Unknown		1983
Lube Oil, Turbine	55 gallons/year	208/year	1990
Lubricant	40-50 quarts/year	38-47.3/year	1981
Lubricant, Antiseize Graphite	12 pounds/year	5.4/year	1993
Lubricant, Molykote Bonded	132 ounces/year	4/year	1993
Lubricating Oil, Aircraft Engine	120 galions/year	454/year	1993
Lubricating Oil, Turbine	50 gallons/month	189/month	1981
Methanol Technical	300 gallons/month	1,134/month	1983
Methyl Ethyl Ketone	4 gallons/year	15/year	1990
Methyl Ethyl Ketone	6 gallons/year	22.7/year	1993
Methyl Ethyl Ketone	1 gallon/month	,3.8/month	1983
Methyl Ethyl Ketone	11 gallons/month	42/month	1981
Milk of Magnesia	2 pints/month	0.9/month	1983
Molykote 321R	13 ounces/year	0.4/year	1990
Molykote 321R	13 ounces/month	0.4/month	1983
Oil, Lubricating Aircraft Turbine	45 quarts/month	43/month	1990
Paint, Flat Black	1 pint/year	0.5/year	1990
Paint, Gloss Black	1 pint/year	0.5/year	1990
Paint, Gray	2.5 gallons/year	9.5/year	1983
Paint, Gray	1 pint/year	0.5/year	1990



Table C-1. Hazardous Materials Storage, Facility 927 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
	_		
Paint, Heat Resistant Aluminum	4 ounces/week	0.1/week	. 1983
Paint, Heat Resisting Aluminum	1 quart/2 years	0.9/2 years	1990
Paint, Olive Drab	4 pints/month	1.9/month	1990
Paint, Olive Drab Spray	16 ounces/month	0.5/month	1983
Paint, Red Spray	16 ounces/year	0.5/year	1983
Paint Remover	1 gallon/month	3.8/month	1981
Penetrating Oil	12 pints/year	5.7/year	1993
Penetrating Oil	2-3 pints/year	0.9-1.4/year	1990
Penetrating Oil, Type 1	0.5 quart/month	0.5/month	1983
Plastiseal	0.5 quart/month	0.5/month	1983
PR-812 Sealing Compound	60 ounces/year	1.8/year	1990
Rapid Tap	1 ounce/6 months	0.03/6 months	1983
Resin, EPK 1C	4 kits/year	1.8/year	1990
Safety Kleen 140	490 gallons/year	1,852/year	1990
Safety Kleen 140	280 gallons/year	1,058.4/year	1993
Sealing Compound	1 gallon/year	3.8/year	1983
Sealing Compound Parts A+B	24 kits/year	11/year	1993
Silicone Compound	2 ounces/month	0.06/month	1983
Split Line Sealer	12 tubes/year	5.4/year	1993
Stoddard Solvent	50 gallons/year	189/year	1983
Super Glue.	4 ounces/year	0.1/year	1993
Thread Compound	0.5 quart/month	0.5/month	1983
Thread Compound	1 can/year	23/year	1990
Thread, Compound, Graphite	1 pound/year	0.5/year	1990
Trichloroethane	5 gallons/year	19/year	. 1983
Trichlorotrifluoroethane	1,600 ounces/year	50/year	1990
Walkway Compound, Non-Slip	1 gallon/year	3.8/year	1983
WD-40	55 gallons/year	208/year	1990
WD-40	12 gallons/year	45.4/year	1983,1993
Zinc Chromate Primer	2 pints/year	0.9/year	1990

Table C-1. Hazardous Materials Storage, Facility 930

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Avionics Weapons/Guidance			
Control Shop			
Adhesive, Air Filter	14 ounces/year	0.4/year	1987
Alcohol, Ethyl 200 Proof	1.5 gallons/year	5.7/year	1993
Alcohol, Denatured	15 ounces/year	0.4/year	1993
Aicohol, Ethyl 200 Proof	1 gallon/year	3.8/year	1993
Allen Solder Paste	0.5 ounce/year	0.02/year	1993
Cleaning and Lubricating Compound, Electrical	16 ounces/year	0.5/year	1987
Cleaning and Lubricating Contact, Electrical	288 ounces/year .	8.5/year	1993
Cleaning Compound, Optical Lens	24 ounces/year	0.7/year	1993
Cleaning Compound Solvent	13 ounces/year	0.4/year	1993
Desiccant	1 gallon/year	3.8/year	1987
Electrical Contact Cleaner	32 ounces/month	1/month	1987
Enamel, Flat Black Aerosol	0.2 pint/year	0.09/year	1993
Epoxy Resin Parts A + B	8 ounces/year	0.2/year	1993
General Purpose Cleaner	2 gallons/year	7.6/year	1987
General Purpose Detergent	1 pint/week	0.5/week	1987
Glass Cleaner	1 gallon/year	3.8/year	1987
Grease, Low Temperature Aircraft and Instrument	32 ounces/year	_ 1/year	1993
Heat Sink Silicone Compound	20 ounces/year	0.6/year	1993
Insulating Compound, Silicone 2 Parts	5 ounces/year	0.15/year	1993
Insulating Varnish, Red	2 ounces/year	0.06/year	1993
Isopropyl Alcohol	2 gallons/year	7.6/year	1987
Lacquer, Aerosol	0.5 pint/year	0.2/year	1993
Lacquer, Brown Aerosol	0.5 pint/year	0.2/year	1993
Lacquer, Gold Aerosol	0.2 pint/year	0.09/year	1993
Lubricating Oil, General Purpose	16 ounces/year	0.5/year	1993
Sealant, Loctite Grade E	5 each/year		1987
Sealant, RTV	6 ounces/year	0.18/year	1993
Sealing Compound, Aircraft Antenna	12 ounces/year	0.36/year	1993
Soldering Paste	0.45 ounce/year	0.01/year	1987
Silicone Compound	32 ounces/year	1/year	1993

Table C-1. Hazardous Materials Storage, Facility 930 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Silicone Compound	11 ounces/year	0.3/year	1987
Silicone Rubber RTV	21 pounds/year	9.5/year	1987
Silicone Sealant	10 ounces/year	0.3/year	1993
Silicone Sealant, RTV	60 ounces/year	1.8/year	1993
Solder, Tin Alloy	0.5 pound/year	0.2/year	<b>1993</b> ,
Super Glue	2 ounces/year	. 0.06/year	1993
Super Glue	3 ounces/year	0.09/year	1987
Super Glue	24 ounces/year	0.7/year	1993
Torque Seal	0.5 ounce/year	0.02/year	1993
Torque Seal	12 ounces/year	0.36/year	1993
Weapon Oil, Light	32 ounces/year	1/year	1987
Laser Shop			
Electrical Contact Cleaner	32 ounces/year	1/year	1987
General Purpose Detergent	132 ounces/year	4/year	1987
Insulating Varnish	4 ounces/year	0.1/year	1987
Plastic Polish	1 quart/year	0.9/year	1987
Silicone Compound	16 ounces/year	0.5/year	1987
Silicone, Heat Sink Compound	1 ounce/year	0.03/year	1987
Weapon Oil, Light	32 ounces/year	1/year	1987
Avionics Comm/Nav	•	•	•
Adhešive Paste, Clear RTV	12 ounces/2 months	0.36/2 months	1987
Adhesive Sealant, RTV	9 ounces/year	0.3/year	1993
Allen Solder Paste	6 ounces/year	0.18/year	1993
Brakleen	19 ounces/2 months	0.6/2 months	1987
Cleaning and Lubricating Compound	16 ounces/2 months	0.6/2 months	1987
Enamel, Gray Gloss	52 ounces/year	1.5/year	1987
Insulating Compound Silicone	1 pound/year	0.5/year	1993
Lacquer, Black	13 ounces/year	0.4/year	1987
Lubricating Oil, Watch	15 cubic centimeters/year	0.01/year	1993
Primer, RTV	1 pint/year	0.5/year	1993
Sealant Locking and Retaining Compound	50 cubic centimeters/year	0.05/year	1993

to a substantial and the state of the substantial and substantial in the substantial and subst

Table C-1. Hazardous Materials Storage, Facility 930 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Sealing Compound, Aircraft Antenna	12 ounces/year	0.36/year	1993
Silicone Compound	8 ounces/year	0.2/year	1993
Soldering Paste	2 ounces/6 years	0.06/6 years	1987

Table C-1. Hazardous Materials Storage, Facility 940

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Acrylic Brass Spray	Unknown	-	1984
Adhesive	1 quart/year	0.9/year	1987
Adhesive, Silicone	12 tubes/year	5.4/year	1993
Aliphatic Thinner	Unknown		1984
Cleaning Lube Compound, Electrical Contact	36 cans/year	817/year	1993
Component B Polyamide Converter	Unknown		1984
Detergent	Unknown	-	1984
General Purpose Detergent	72 pints/year	34/year	1993
Grease, Aircraft and Instrument	Unknown		1984
Grease, Aircraft Brayco 855	2 quarts/year	1.9/year	1993
Grease, Ball and Roller Bearing	10 pounds/year	4.5/year	1987
Grease, Ball and Roller Bearing	1 quart/year	0.9/year	1993
Grease, Ball and Roller Bearing	Unknown	•-	1984
Grease Cutter	Unknown	**	1984
Grease, General Purpose	Unknown ·		1984
Grease, General Purpose	5 pounds/year	2.3/year	1987
Grease, Molybdenum Disulfide	12 cans/year	272/year	1993
Industrial Adhesive	Unknown	•••	1984
Ink, Ideal Hardy Spray	Unknown		1984
Ink, Marking	Unknown		1984
Ink, Stencil	2 pints/month	0.9/month	1987
Lacquer	1 pint/month	0.5/month	1987
Lacquer, Acrylic	Unknown		1984
Lacquer Thinner	2 gallons/year	7.6/year	1987
Lacquer, Yellow Camouflage	Unknown	-	1984
Lube Oil, General Purpose	48 cans/year	1,089/year	1993
Lube Oil, Weapons	24 quarts/year	22.7/year	1993
Lubricant, O-Ring	12 tubes/year	5.4/year	1993
Lubricating Oil, General Purpose	Unknown		1984
Methyl Ethyl Ketone	2 galions/year	7.6/year	1987
Methyl Ethyl Ketone	Unknown		1984
Oil, VVL 800	6 pints/month	2.8/month	1987
Paint, Black Gloss Growco Spray	Unknown	••	1984
Paint, Blue Growco 5-Star	Unknown		1984
Paint, Enamel Gray	Unknown	-	1984

C-37

Table C-1. Hazardous Materials Storage, Facility 940 (Continued)

 $t \in \mathcal{V}$ 

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Paint, Grenadine Red	Unknown	••	1984
Paint, Red Growco 5-Star	Unknown	••	1984
Paint, Rough texture Black	Unknown	••	1984
Paint, Silver Growco 5-Star	Unknown	••	1984
Perma Silk Lubricating Aerosol	12 cans/year	272/year	1993
Trichlorotrifluoroethane	6 pints/year	2.8/year	1987
Zep Formula	10 pounds/month	4.5/month	1987
Zep Prod,516	36 pounds/year	16.3/year	1993

Table C-1. Hazardous Materials Storage, Facility 948

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Corrosion Control		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	0,0.090
Acrylic Lacquer	48 pints/year	22.7/year	1984
Acrylic Lacquer	12 pints/year	5.7/year	1984, 1986
Age Green Quart	24 krts/year	11/year	1993
Alcohol, Butyl	5 gallons/year	19/year	1984, 1986
Alcohol Denatured	1 gallon/month	3.8/month	1984, 1986
Alcohol, Ethyl	5 gallons/year	19/year	1984, 1986
Aliphatic Thinner	200 gallons/year	756/year	1986
Aliphatic Urethane Enamel	96 gallons/year	363/year	1984
Alkaline Cleaning Compound	500 gallons/year	1,890/year	1984, 1986
Alodine 1200	12 quarts/year	11.4/year	1993
Aiodine 1201	1 quart/year	0.9/year	1984, 1986
Aluminum Powder	4 pounds/year	1.8/year	1986
Armorcote Gray	Unknown		1984
Bituminous Plastic Asphaltic Base	5 gailons/year	19/year	1986
Black Cronar	8 gailons/year	30/year	1993
Black Waikway Compound	8 gallons/year	30/year	1993
Capcoat Poly, Black	8 kits/year	3.6/year	1993
Catalyst	12 quarts/year	11.4/year	1993
Catalyst Component	100 gallons/year	454/year	1984
Chromate Conversion Coating	1 pint/month	0.5/month	1981
Cleaning Compound	100 gallons/year	378/year	1981
Cleaning Compound	16 ounces/year	0.5/year	1984, 1986
Cleaning Compound, Engine Path	1 gailon/year	3.8/year	1986
Clear Coat	2 gallons/year	7.6/year	1986
Coating Compound	5 gallons/year	19/year	1984, 1986
Coating Epoxy Polyamide	10 pints/year	4.7/year	1986
Coating Polyurethane	12 quarts/year	11.4/year	1986
Compound Walkway	12 gallons/year	45.4/year	1986
Corrosion Preventative Compound	6 pints/year	2.8/year	1984, 1986
Corrosion Preventative Compound	1 pint/month	0.5/month	1986
Corrosion Preventative Compound	4 pints/year	1.9/year	1993
Corrosion Removing Compound	1/2 gallon/month	1.9/month	1981

Table C-1. Hazardous Materials Storage, Facility 948 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Crankcase Oil	21 ounce/year	0.62/year	1986
Dephthante and Catalyst	24 quarts/year	22.7/year	1993
Dent Filler Bondo	24 kits/year	11/year	1993
Dope and Lacquer Thinner	10 gallons/month	37.8/month	1986
Enamel, Alkyd Gloss Blue	1 quart/month	0.9/month	1986
Enamel, Black	48 pints/year	22.7/year	1984, 1986
Enamel, Clear	52 ounces/month	1.6/month	1986
Enamel, Flat Black	48 pints/year	22.7/year	1984, 1986
Enamel, Gloss	12 quarts/year	11.4/year	1984
Enamel, Gloss	1 gallon/month	3.8/month	1986
Enamel, Gloss Black	4 pints/year	1.9/year	1986
Enamel, Gloss Black	96 pints/year	45.4/year	1993
Enamel, Gray	48 pints/year	22.7/year	1984, 1986
Enamel, Green	4 gallons/year	15/year	1984, 1986
Enamel, Olive Drab	48 pints/year	22.7/year	1984, 1986
Enamel, Orange	48 pints/year	22.7/year	1984, 1986
Enamel, Orange Spray Paint	48 pints/year	22.7/year	1984, 1986
Enamel, Poly	96 gallons/year	363/year	1986
Ename!, Poly Gunship Light Green	96 gallons/year	363/year	1986
Enamel, Red	8 ounces/year	0.2/year	1984
Enamel, Red	1 gallon/month	3.8/month	1986
Enamel, Red	96 pints/year	45.4/year	1993
Ename!, White	96 pints/year	45.4/year	1993
Enamel, White	48 pints/year	22.7/year	1984, 1986
Enamel, Yellow	48 pints/year	22.7/year	1984, 1986
Epoxy, Black	48 quarts/year	45.4/year	1993
Epoxy, Blue	4 kits/year	1.8/year	1993
Epoxy, Polyamide Water Reducible	48 gallons/year	181.4/year	1993
Epoxy, Primer Yellow	2 kits/year	0.9/year	1993
Epoxy, Resin	72 quarts/year	68/year	1993
Epoxy, White	48 quarts/year	45.4/year	1993
Flat Base Curing Solution	12 kits/year	5.4/year	1993
Formula Paint Stripper 1262	12 gallons/year	45.4/year	1984
General Purpose Detergent	44 ounces/week	1.3/week	1984, 1986
Grease	1 pound/year	0.5/year	1984

Table C-1. Hazardous Materials Storage, Facility 948 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Initiator Cronar No MSDS	24 pints/year	11.4/year	1993
Ink, Black Aerosol	48 pints/year	22.7/year	1993
Lacquer, Acrylic Green	4 gallons/year	15/year	1993
Lacquer, Acrylic Yellow	2 gallons/year	7.6/year	1986
Lacquer, Aerosol White	1 pint/month	0.5/month	1986
Lacquer, Aerosol White	10 cans/year	227/year `	1986
Lacquer, Aluminum	48 pints/year	22.7/year	1993 ·
Lacquer, Black	4 pints/month	1.9/month	1986
Lacquer, Black	12 quarts/year	11.4/year	1993
Lacquer, Black	48 pints/year	22.7/year	1984, 1986
Lacquer, Blue	12 quarts/year	11.4/year	1984, 1986
Lacquer, Blue Aerosol	48 pints/year	22.7/year	1993
Lacquer, Brass	48 pints/year	22.7/year	1984, 1986
Lacquer, Camouflage	36 pints/year	17/year	1984
Lacquer, Camouflage	3 pints/month	1.4/month	1986
Lacquer Cellulose Nitrate	4 quarts/year	3.8/year	1986
Lacquer, Clear	48 pints/year	22.7/year	1984, 1986
Lacquer, Clear	4 gallons/year	15/year	1993
Lacquer, Clear Aerosol	48 pints/year	22.7/year	1993
Lacquer, Gold Aerosol	48 pints/year	22.7/year	1993
Lacquer, Gray	72 pints/year	34/year	1993
Lacquer, Green	24 quarts/year	22.7/year	1984, 1986
Lacquer, Green	4 gallons/year	15/year	1993
Lacquer, Green Aerosol	48 pints/year	22.7/year	1993
Lacquer, Olive Drab	48 pints/year	22.7/year	1993
Lacquer, Red	12 quarts/year	11.4/year	1984, 1986
Lacquer, Red	24 pints/year	11.4/year	1984, 1986
Lacquer, Silver	12 quarts/week	11.4/week	1984, 1986
Lacquer, Silver	48 pints/year	22.7/year	1984, 1986
Lacquer, Sterling	4 pounds/year	1.8/year	1984
Lacquer, White	12 quarts/year	11.4/year	1984, 1986
Lacquer, White	50 pints/year	23.7/year	1984, 1986
Latex, Green	20 gallons/year	75.6/year	1984, 1986
Lube Compound	1 pint/year	0.5/year	1986
Lube Oil	1 pint/year	0.5/year	1986
Methyl Ethyl Ketone	4 gallons/week	. 15/week	1984, 1986
Methyl Ethyl Ketone	15 gallons/month	56.7/month	1 <b>98</b> 1

Table C-1. Hazardous Materials Storage, Faculty 948 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Methyl Ethyl Ketone	72 gallons/year	272/year	1993
Naphtha	24 gallons/year	91/year	1984, 1986
Naphtha, Aliphatic	48 gallons/year	181.4/year	1993
Nitrocellulose Gloss	2 galions/year	7.6/year	1986
Paint, Aerosol	48 pints/year	22.7/year	1993
Paint, Alkyd Gloss Gray	48 pints/year	22.7/year	1984, 1986
Paint and Lacquer Remover	25 galions/year	94.5/year	1986
Paint, Blue	4 gallons/year	15/year	1993
Paint, Blue Aerosol	24 pints/year	11.4/year	1993
Paint, Brown	48 pints/year	22.7/year	1993
Paint, Camouflage Yellow	2 gallons/year	7.6/year	1984
Paint, Dark Gray	360 pints/year	170/year	1993
Paint, Flat Black Aerosol	96 pints/year	45.4/year	1993
Paint, Gray	16 pints/year	7.6/year	1993
Paint, Gray	2 gallons/year	7.6/year	1986
Paint, Gray	72 pints/year	34/year	1993
Paint, Lacquer Yellow	5 gallons/year	19/year	1986
Paint, Latex Base	4. gallons/year	15/year	1986
Paint, Latex Base Flat Interior	4 gallons/year	15/year	1986
Paint, Oil Concentrated	1 gallon/year	3.8/year	1986
Paint, Olive Drab	2 gallons/month	7.6/month	1986
Paint Remover	50 gallons/year	189/year	1984, 1986
Paint Remover	25 gallons/year	94.5/year	1984, 1986
Paint Remover	12 gallons/year	45.4/year .	1993
Paint, Remover Epoxy	4 pints/year	1.9/year	1986
Paint, Spray Green	26 ounces/month	0.8/month	1986
Paint, Strata Blue Alkyd Gloss	48 pints/year	22.7/year	1984, 1986
Paint Stripper	1 pint/month	0.5/month	1986
Paint Stripper	1 galion/year	3.8/year	1986
Paint, White	20 gallons/year	75.6/year	1986
Paint, Yellow Aerosol	48 quarts/year	45.4/year	1993
Paint, Yellow Alkyd Gloss	48 pints/year	22.7/year	1984, 1986
Paint, Yellow Spray	48 pints/year	22.7/year	1984, 1986
Paints, Lacquer Remover	25 gallons/year	94.5/year	1984
Petrolatum	3.5 pounds/year	1.6/year	1993
Pigment, Aerosol Propellant	4 pounds/year	1.8/year	1986
Pigment, Aluminum	4 pounds/year	1.8/year	1984

Table C-1. Hazardous Materials Storage, Facility 948 (Continued)

15

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Poly, Activator	10.5 gallons/year	19/year	1984
Poly, Black	100 gallons/year	378/year	1986
Poly, Black	24 quarts/year	22.7/year	1993
Poly, Blue	4 kits/year	1.8/year	1993
Poly, Blue No MSDS	12 kits/year	5.4/year	1993
Poly, Camouflage Brown	Unknown		1984
Poly, Camouflage Red	0.5 gallon/year	1.9/year	1984
Poly, Camouflage Yellow	2 gallons/year	7.6/year	1984
Poly, Clear Gloss	36 kits/year	16.3/year	1993
Poly, Clear No MSDS	8 kits/year	3.6/year	1993
Poly Coating	0.5 gallon/week	1.9/week	1984
Poly Coating, Camouflage Red	0.5 gallon/year	1.9/year	1986
Poly Coating, Gloss Gray	2 gallons/year	7.6/year	1986
Poly Coating, Gray	80 quarts/year	75.7/year	1986
Poly Coating, Olive Drab	0.5 gailon/year	1.9/year	1986
Poly Coating, Red Gloss	0.5 gailon/year	1.9/year	1986
Poly Coating, White	0.5 gallon/year	1.9/year	1986
Poly, Forest Green	96 gallons/year	363/year	1984 <sup>•</sup>
Poly, Forest Green	96 gallons/year	363/year	1986
Poly, Gloss Black	0.5 gallon/month	1.9/month	1984
Poly, Gloss Gray	2 gallons/year	7.6/year	1984
Poly, Gloss Gray	12 gallons/year	45.4/year	1984, 1986
Poly, Gray	6.5 gallons/year	11.4/year	1984
Poly, Gray	48 quarts/year	45.4/year	1993
Poly, Gray	0.5 gallon/year	1.9/year	1984
Poly, Green	100 gallons/year	378/year	1984
Poly, Gunship	96 gailons/year	363/year	1984
Poly, Olive Drab	0.5 gallon/year	1.9/year	1984
Poly, Reducer	0.5 gallon/year	1.9/year	1984
Poly, Tan	Unknown		1984
Poly, White	2 gallons/year	7.61/year	1984, 1986
Poly, White	0.5 gallon/year	1.9/year	1984
Poly, White	48 quarts/year	45.4/year	1984
Poly, White	12 quarts/year	11.4/year	1993
Poly, Yellow	12 quarts/year	11.4/year	1993
Poly, Yellow	8 gallons/year	30/year	1993
Poly, Yellow Parts A + B	6 quarts/year	5.7/year	1993

A partition of the same

distributed to the state of the

Table C-1. Hazardous Materials Storage, Facility 948 (Continued)

Product	. Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Polyamide Con	Unknown	••	1984
Polyamide Resin	100 gallons/year	378/year	1986
Polyurethane, Aliphatic	6 kits/month	2.7/month	1986
Polyurethane, Aliphatic	1 gallon/month	3.8/month	1986
Polyurethane, Aliphatic	2 kits/month	0.9/month	1986
Polyurethane, Aliphatic Green	1 kit/month	0.5/month	1986
Polyurethane, Black	5 quarts/year	4.7/year	1984
Polyurethane, Black	8 gallons/year	30/year	1984, 1986
Polyurethane, Black	24 quarts/year	22.7/year	1993
Polyurethane Coating	0.5 gallon/week	1.9/week	1986
Polyurethane Enamel, Green	24 kits/year	11/year	· 1993
Polyurethane Enamel, Red	36 kits/year	16.3/year	1993
Polyurethane Gloss, Black	0.5 gallon/month	1.9/month	1986
Polyurethane, Green	32 gallons/year	121/year	1993
Polyurethane, Green	100 gallons/year	378/year	1986
Polyurethane, Green	48 gallons/year	181.4/year	1993
Polyurethane, Green	160 gallons/year	605/year	1993
Primer, Brown	4 pints/year	1.9/year	1986
Primer, Brown	48 pints/year	22.7/year	1984, 1986, 1993
Primer, Cellulose	4 gallons/year	15/year	1984
Primer, Cellulose	12 quarts/year	11.3/year	1984
Primer Coating	72 pints/year	34/year	1984, 1986
Primer Coating	12 quarts/year	11.3/year	1986
Primer Coating	52 ounces/month	1.6/month	1986
Primer Compound 1	4 quarts/year	3.8/year	1986
Primer, Epoxy Polyamide	12 kits/month	5.4/month	1986
Primer, Gray	48 pints/year	22.7/year	1993
Primer, Light Gray	4 pints/month	1.9/month	1986
Primer, Wash	1 kit/month	0.5/month	1986
Primer, Yellow	56 ounces/month	4.8/month	1986
Reducer	12 gallons/year	45.4/year	1993
Scouring Powder	168 ounces/month	8/month	1986
SD-1 Dry Cleaning Solvent	Unknown		1984
SD-1 Dry Cleaning Solvent	5 gallons/year	19/year	1986

Table C-1. Hazardous Materials Storage, Facility 948 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Self Pressured Spray Kit	3 pints/week	1.4/week	1986
Silicone Lube	32 ounces/year	1/year	1984, 1986
Spray Tool	3 pints/week	1.4/week	1984
Stripper, Spray	72 pints/year	34/year	1993
Tetra Ethyl Glycol Di	5 gallons/year	19/year	1984
Thinner	100 gallons/year	378/year	1993
Thinner	1 gallon/year	3.8/year	1986
Thinner	48 gallons/year	181.4/year	1993
Thinner, Aliphatic	200 gallons/year	756/year	1984
Thinner, Cellulose Acetate	1 gailon/year	3.8/year	1984
Thinner, Dope and Lacquer	5 gallons/year	19/year	1986
Thinner, Lacquer Cellulose Nitrate	72 gallons/year	272/year	1993
Toluene	5 gallons/month	19/month	· 1981
Toluene	12 gallons/year	45.4/year	1984, 1986
Trichloroethane	1 quart/year	0.9/year	1984
Trichloroethane	32 ounces/year	1/year	1986
Varnish	1 gallon/year	3.8/year	1984, 1986
Walkway Compound	12 galions/year	45.4/year	1984
Walkway Compound, Dark Gray	8 gallons/year	30/year	1993
Zinc Chromate Primer	48 pints/year	22.7/year	1993
Zinc Chromate Primer Aerosol	48 pints/year	22.7/year	1984, 1986
Zinc Chromate Primer Green	48 pints/year	22.7/year	1984, 1986
Fuel Systems			
Adhesive	1/3 1/2-ounce tube/ year	0.007/year	1990
Adhesive, CS 3204	0.1 ounce/year	0.003/year	1993
Epoxy Tabs	Unknown		1993
JP-4	Unknown		1993
Leak Detection Powder	0.3 ounce/year	0.009/year	1993
Lube Oil, General Purpose	0.2 ounce/year	0.006/year	1993
Lubricating Oil, General Purpose	1/4 ounce can/year	0.007/year	1990
Methyl Ethyl Ketone	4 gallons/year	15/year	1993
Pig Putty	1.2 tubes/year	0.5/year	1993
Pro-Seal	22 ounces/year	0.6/year	1993
Sealing Compound Class A	0.2 ounce/year	0.005/year	1990

Richards-Gebaur AFB EBS

December 8, 1993



Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Sealing Compound Class B	0.5 ounce/year	0.01/year	1990
Sealing Compound	48 ounces/year	1.34/year	1993
Sealing Compound Class A	3.6 ounces/year	0.10/year	1993
Sealing Compound Class B	2.1 ounces/year	0.06/year	1993

Table C-1. Hazardous Materials Storage, Facility 958

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Acid, Boric	1 pound/year	0.45/year	1993
Adhesive	4 tubes/year	1.8/year	1990
Adhesive	8 ounces/year	0.22/year	1993
Adhesive	4 kits/year	1.8/year	1993
Adhesive	0.5 pint/year	0.22/year	1984
Adhesive, Armstrong	4 pounds/year	1.8/year	1993
Adhesive, Epoweld	1,600 grams/year		1993
Adhesive, Epoweld	4 boxes/year	180/year	1990
Adhesive, Goodrich	0.5 pint/year	0.22/year	1984
Adhesive Sealant	12 ounces/year	0.33/year	1990,1993
Aerosol, Black	13 ounces/week	0.36/week	1987
Antifreeze	4 galloris/year	14.52/year	1993
Antiseize Compound	1.5 pounds/year	0.67/year	1990
Brake fluid	4 quarts/year	3.64/year	1993
8rake Fluid, Automotive	1 gallon/year	0.91/year	1984
8rakleen	152 ounces/year	4.25/year	1993
Brakleen	152 ounces/year	4.25/year	1990
Brakleen	5 pints/year	2.25/year	1984
Cleaning Compound, Aircraft	40 gallons/year	145.2/year	1990,1993
Cleaning Compound Detergent	4 gallons/year	14.52/year	1993
Coating, Polyurethane Aliphatic	2 gailons/year	7.26/year	1984
Compound 3 Polyurethane	2 gailons/year	7.26/year	1984
Compound Insulation	2 pints/year	0.9/year	1993
Corrosion Preventative Compound	20 ounces/year	0.56/year	1984
Corrosion Preventative Compound 3	4 cans/year	90/year	1993
Dextron 2 Automatic Transmission Fluid	12 cans/year	270/year	1993
Diesel Starting Fluid	12 cans/year	270/year	1993
Diethylene Butycarbon	20 gallons/year	72.6/year	1984
Ektasolve DB Solvent	1 gallon/year	3.63/year	1990,1993
Electrical Contact Cleaner	48 ounces/year	1.34/year	1984
Enamel, Aerosol	12 pints/year	5.4/year	1993
Enamel, Alkyd Gloss Red	36 ounces/month	1/month	1984
Enamel, Alkyd Yeilow Gioss	36 ounces/year	1/year	1984
Enamel, Gloss Black	16 pints/year	7.2/year	1990,1993
Enamel, Gray	12 ounces/year	0.33/year	1984

Table C-1. Hazardous Materials Storage, Facility 958 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
	<u> </u>		1993
Enamel, Olive Drab	12 pints/year	5.4/year	
Enamel, Olive Drab Spray	72 ounces/year	2/year	1984
Enamel, Paint	1 pint/year	0.45/year	1984
Enamel, Red	48 ounces/year	1.34/year	1990
Enamel, Red	192 ounces/year	5.37/year	1993
Enamel, Silver Silicone	1 gallon/year	3.63/year	1984
Enamel, Spray Flat Black	288 ounces/year	8.06/year	1984
Enamel, Spray Red	16 ounces/week	0.45/week	1984
Enamel, White	8 pints/year	3.6/year	1993
Enamel, White	130 ounces/year	3.64/year	1984
Engine Fuel Primer	4 pints/year	1.8/year	1993
Ethyl Alcohol, Denatured	40 quarts/year	36.4/year	1993
Ethyl Alcohol, Denatured	4 quarts/year	3.64/year	1990
General Purpose Detergent	4 gallons/year	14.52/year	1993
Grease, Aircraft	20 pounds/year	19.55/year	1993
Grease, All Purpose	5 pounds/year	2.25/year	1984
Grease, Automotive and Artillery	56 ounces/year	1.56/year	1993
Grease, Bearing	30 pounds/year	13.5/year	1993
Grease, Molybdenum Disulfide	2 pounds/year	0.9/year	1984
Hydraulic Fluid	20 gallons/year	72.6/year	1993
Hydraulic Fluid	6 quarts/year	5.46/year	1990
Hydraulic Fluid	160 galions/year	580.8/year	1993
Hydraulic Fluid	40 gallons/year	145.2/year	1990
Hydraulic Fluid	40 gallons/month	145.2/month	1990
Hydraulic Fluid	28 pounds/year	12.6/year	1993
Hydraulic Fluid	16 quarts/year	14.56/year	1993
Hydraulic Fluid	100 gallons/year	363/year	1984
Hydraulic Fluid	96 quarts/year	87.36/year	1984
Hydraulic Fluid, Aircraft	40 gallons/year	145.2/year	1993
Hydraulic Fluid, Automatic Transmission	20 quarts/year	18.2/year	1990
Lacquer, Acrylic	16 ounces/month	0.44/month	1984
Lacquer, Acrylic	36 ounces/year	1/year	1984
Lacquer, Acrylic	78 ounces/year	2.18/year	1984
Lacquer, Aerosol Flat Acrylic	8 pints/year	3.6/year	1993
Lacquer, Aerosol Yellow	8 pints/year	3.6/year	1993
Lacquer, Aluminum Aerosol	12 pints/year	5.4/year	1993

Table C-1. Hazardous Materials Storage, Facility 958 (Continued)

366 35

Product  Lacquer, Brown  Lacquer, Clear Aerosol  Lacquer, Gray	(Units Provided)  1 pint/year  4 pints/year	(kg) 0.45/year	Storage 1990
Lacquer, Clear Aerosol Lacquer, Gray	4 pints/year	-	1330
Lacquer, Gray	· ·	9 0 /	1993
•		1.8/year	
	12 pint/year	5.4/year	1990
Lacquer, Green Aerosol	8 pints/year	3.6/year	1993
Lacquer, Olive Drab	8 pints/year	3.6/year	1993
Lacquer, Yellow Enamel Acrylic	12 pints/year	5.4/year	1993
Leak Test Compound	4 bottles/year		1993
Lube Oil, 30 Weight	220 gallons/year	798.6/year	1984
Lube Oil, Aircraft Engine	96 ounces/year	2.68/year	1993
Lube Oil, Aircraft Engine	12 quarts/year	10.92/year	1993
Lube Oil, Engine	220 galions/year	798.6/year	1993
Lube Oil, Engine 10 Weight	16 quarts/year	14.56/year	1993
Lube Oil, Engine	220 gallons/year	798.6/year	1990
Lube Oil, General Purpose	16 ounces/year	0.45/year	1993
Lube Oil, General Purpose	64 ounces/year	1.79/year	1993
Lube Oil, General Purpose	4 quarts/year	3.64/year	1993
Lube Oil, General Purpose	16 ounces/week	0.45/week	1987
Lube Oil, General Purpose	40 ounces/week	1.12/week	1987
Lube Oil, Steam Turbine	20 gallons/year	72.6/year	1993
Lube Solid Film Aerosol	48 ounces/year	1.34/year	1993
Lubricant, Gear	4 drums/year	750.6/year	1993
Lubricant, Solid Film	20 ounces/year	0.56/year	1984
Lubricating Compound Silicone	1 quart/year	0.91/year	1984
Lubricating Oil	64 ounces/year	1.79/year	1990
Lubricating Oil, General Purpose	16 ounces/month	0.45/month	1990
Lubricating Oil, Steam Turbine	5 gallons/3 months	18.15/3 months	1990 ´
Methyl Ethyl Ketone	3 gallons/year	10.89/year	1984
Naphtha Aliphatic	4 gallons/year	14.52/year	1993
Naphtha Aliphatic Type 2	2 gallons/year	7.26/year	1984
Oil, 15-40 Weight	48 quarts/year	43.68/year	1993
Oil, Sheil Turbo	164 ounces/year	4.59/year	1990,1993
Oil Stain	0.5 gallon/year	1.81/year	1984
Oil, Steam Turbine	5 gallons/month	18.15/month	1987
Paint, Aerosol Colors	8 pints/year	3.6/year	1993
Paint, Aluminum Heat Resisting	1 quart/year	0.91/year	1990
Paint, Aluminum Heat Resistant	1 gallon/year	3.63/year	1993
Paint, Aluminum Heat Resistant	3 quarts/year	2.73/year	1984

Landon Dillolder allegischen Lederblings Ladon L

Table C-1. Hazardous Materials Storage, Facility 958 (Continued)

1 10 140

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Paint, Black Heat Resisting Aerosol	4 pints/year	1.8/year	1993
Paint, Dark Green Aerosol	1 pint/year	0.45/year	1990
Paint, Gloss Black	1 pint/year	0.45/year	1984
Paint, Gray	12 pints/year	5.4/year	1993
Paint, Gray Aerosol	8 pints/year	3.6/year	1993
Paint, High Heat Resistant Aerosol	12 pints/year	5.4/year	1993
Paint, Latex White Testing	1 pint/year	0.45/year	1984
Paint, Olive Drab	8 pints/year	3.6/year	1990
Paint, Olive Drab	72 ounces/year	1.96/year	1987
Paint, Olive Drab	16 ounces/week	0.45/week	1984
Paint Remover	2 quarts/year	1.82/year	1984
Paint Remover	1 gallon/year	3.63/year	1984
Paint, Silver Spray	36 ounces/year	1.008/year	1984
Paint, White Aerosol	4 pints/year	1.8/year	1993
Penetrating Fluid	30 ounces/year	0.84/year	1984
Penetrating Oil	4 pints/year	1.8/year	1990
Penetrating Oil, Aerosol	48 ounces/year	1.344/year	1993
Penetrating Oil, Aerosol	60 ounces/year	1.68/year	1993
Penetrating Oil, Type 1	70 ounces/year	1.96/year	. 1984
Perma-Silk Lubricant Aerosol	64 ounces/year	1.792/year	1993
Petrolatum Technical	7 pounds/year	3.15/year	1993
Poly, Dark Green	1 pint/year	0.45/year	1993
Poly, Dark Green	24 pints/year	10.8/year	1993
Primer Coating, Aerosol Brown	16 ounces/week	0.448/week	1987
Primer, Gray	8 pints/year	3.6/year	1993
Propane	56.4 ounces/year .	1.5792/year	1990
Propane Cylinder	4 cylinders/year	180/year	1993
Protective Coating and Beautifier	4 pints/year	1.8/year	1993
Rubber Base	1 pint/year	0.45/year	1984
Safety Kleen	30 gallons/year	108.9/year	1993
Scotchlite 735	32 ounces/year	0.896/year	1993
Scotchlite Edge Sealer	32 ounces/year	0.896/year	1990
Sealing Compound	4 cans/year	90/year	1993
Sealing Compound	2 pints/year	0.9/year	1984

Oecember 8, 1993

Table C-1. Hazardous Materials Storage, Facility 958 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Silicone Sealant	8 ounces/year	0.22/year	1993
Silicone Spray Lube	64 ounces/year	1.79/year	1993
Solder, Tin Alloy	1 pound/year	0.45/year	1990,1993
Spray Kit Self Pressurized	246 ounces/year	6.88/year	1984 .
Spray Tool	16 ounces/year	0.44/year	1984
Stoddard Solvent	150 gallons/year	544.5/year	1984
Thinner	4 gallons/year	14.52/year	1990,1993
Thinner, Aliphatic Poly	6 gailons/year	21.78/year	1984
Varnish	1, galion/2 years	3.63/2 years	1984
Walkway Compound	1 gallon can/year	3.63/year	1990
Walkway Compound, Black	1 gallon/year	3.63/year	1993
Zinc Chromate Primer, Green	8 pints/year	3.6/year	1993
Zinc Chromate Primer, Green	13 ounces/month	0.36/month	1984
Zinc Chromate Primer, Yellow	13 ounces/week	0.36/week	1984

Table C-1. Hazardous Materials Storage, Facility 966

Product '	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Accelerator Sealing Compound	8 ounces/year	0.22 year	1993
Adhesive	8 ounces/4 months	0.22/4 months	1992
Adhesive, EPK	16 ounces/year	0.44/year	1993
Adhesive, Rubber Base	1 quart/year	0.91/year	1984
Adhesive Sealant, RTV	24 ounces/year	0.67/year	1993
Adhesive, Silicone	12 ounces/year	0.33/year	1993
Aerosol Room Deodorant	48 pints/year	21.6/year	1984
Battery Alkaline	Unknown		1992
Biogenic SE	1 quart/3 months	0.91/3 months	1992-1993
Chromate Primer	2 cans/month	45/month	1984
Cleaning Compound	1 pint/year	0.45/year	1984
Corrosive Preventative	1 pint/year	0.45/year	1984
Detergent	0.5 gallon/year	1.81/year	1984
Detergent	1 gallon/year	3.63/year	1984
Detergent, General Purpose	Unknown		1992
Dry Lubricating Compound	12 pints/year	5.4/year	1984
Enamel, Alkyd Gloss Yellow	Unkлown		1984
Enamel, Alkyd Strata Blue	1 can/year	23/year	1984
Enamel, Brown	48 pints/year	21.6/year	1984
Enamei, Clear	6 cans/year	135/year	1984
Enamel, Gloss Black	72 ounces/year	2.01/year	1984
Enamel, High Gloss White	6 cans/year	135/year	1984
Enamel, Red	2 pints/year	0.9/year	1993
Epoxy Patch	8 ounces/6 months	0.22/6 months	1992
Epoxy Resin	16 ounces/year	0.44/year	1993
Glass Cleaner	Unknown		1984
Glass Cleaner	10 gallons/year	36.3/year	1984
Glass Cleaner	Unknown	••	1992
Grease	5 pounds/2 months	2.25/2 months	1992
Grease, Aircraft	30 pounds/year	13.5/year	1993
Grease, Aircraft	Unknown		1984
Lacquer	Unknown		1984
Lacquer, Acrylic White	Unknown		1984
Lacquer, Aerosol Black	3 cans/year	202.5/year	1984
Lacquer, Aerosol Silver	18 cans/year	405/year	1984
Lacquer, Black	48 pints/year	21.6/year	1984
Lacquer, Black	Unknown		1984

Table C-1. Hazardous Materials Storage, Facility 966 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Lacquer, Camouflage Yellow	Unknown	-	1984
Lacquer, White	2 cans/year	45/year	1984
Lacquer, White	48 pints/year	21.6/year	1984
Lacquer, Black	2 cans/year	45/year	1984
Latex Paint, White	1 gallon/year	3.63/year	1984
Lube Compound, Dimethylsilic	8 ounces/year	0.22/year	1993
Lube Oil, General Purpose	6 ounces/year	0.16/year	1993
Lubricant	48 pints/year	21.6/year	1984
Lubricating Compound Silicone	24 pints/year	10.8/year	1984
Lubricating Compound Silicone	8 ounces/year	0.22/year	1992
Lubricating Oil	Unknown		1984
Lubricating Oil	6 ounces/6 months	0.16/6 months	1992
Lubricating Oil	48 pints/year	21.6/year	1984
Lubricating Oil, General Purpose	6 ounces/year	0.16/year	1992
Lubtork	Unknown	<b>-</b>	1992
Methyl Ethyl Ketone	3 gallons/year	10.89/year	1984
Methyl Ethyl Ketone	0.3 gallon/year	1.08/year	1993
Naphtha, Aliphatic	2 gailons/year	7.26/year	1984
Naphtha, Aliphatic	10 gallons/year	36.3/year	1984
Oil	1 quart/year	0.91/year	1984
Paint, Aerosol Red Spray	6 pints/year	2.7/year	1984
Paint, Brown Oxide Primer	48 ounces/year	1.34/year	1984
Paint, Red	6 ounces/6 months	0.16/6 months	1992
Paint, Silver Spray	Unknown	••	1984
Paint Stripping Compound	220 gallons/year	798.6/year	1984
PD-680	60 gallons/year	217.8/year	1984
Penetrating Oil, Aerosol	12 ounces/year	0.33/year	1993
Penetrating Oil Type 2	1 pint/year	0.45/year	1984
Primer Coating Yellow	18 cans/year	414/year	1984
Primer Coating Zinc Chromate	18 cans/year	414/year	1984
Primer, Gray	6 ounces/6 months	0.16/6 months	1992
Primer, Gray	6 ounces/year	0.16/year	1993
Protective Coating	24 quarts/year	21.84/year	1984
Safety Kleen	6 ounces/month	0.16/month	1992
Safety Kleen	60 galions/year	217.8/year	1993
Sealing Compound	8 tubes/2 months	3.6/2 months	1992
Silicone Compound	6 ounces/year	0.16/year	1992

Table C-1. Hazardous Materials Storage, Facility 966 (Continued)

Product	Quantity Stored (Units Provided)	Quantity Stored (kg)	Duration of Storage
Silicone, RTV	8 ounces/4 months	0.22/4 months	1992
Solvent	48 pints/year	21.6/year	1984
Spray Paints	10 cans/month	2.30/month	1984
Thinner	3 gallons/year	10.89/year	1984
Thinner, Aliphatic	Unknown		1984
Thinner, Aliphatic Polyurethane	10 gallons/year	36.3/year	1984
Thinner, Polyurethane	0.5 gallon/month	1.81/month	1984
Tórque Seal	Unknown	•	1992
Turco	Unknown		1984
Zinc Chromate Primer	2 cans/month	45/month	1984



Product	Quantity Stored	Quantity Stored (kg)	Duration of Storage
Activated Desiccant	100 pounds/year	45/year	1983
Adhesive	12 ounces/year	0.33/year	1993
Adhesive, Epoweld	2 kits/year	0.9/year	1993
Adhesive, Foam and Fabric	19.5 ounces/year	0.54/year	1983
Adhesive, General Purpose	6 ounces/year	0.16/year	1993
Adhesive, Industrial	1 quart/year	0.91/year	1983
Adhesive Parts A + B	6 ounces/year	0.16/year	1993
Adhesive, Prime Coat	12 ounces/year	0.33/year	1993
Adhesive, Rubber	0.5 pint/year	0.22/year	1986
Adhesive, Sealant, RTV	30 ounces/year	0.84/year	1993
Adhesive, Super Foamfast	48 ounces/year	1.34/year	1993
Adhesive, Thermofit	2 kits/year	0.9/year	1993
Aerosol Colors 251	2 pints/year	0.9/year	1993
Alcohol, Denatured	5 quarts/year	4.55/year	1986
Alcohol, Denatured Anhydrous	12 quarts/year	10.92/year	1993
Alcohol, Denatured Prop Solvent	12 quarts/year	10.92/year	1993
Alodine 1201	1 quart/2 years	0.91/2 years	1986
Argon Compressed Gas	10 cylinders/year	450/year	1993
Brake Cleaner	1 can/2 years	23/2 years	1983
Brake Fluid	6 gallons/year	21.78/year	1993
Brake Fluid, Automotive	1 gallon/month	3.63/month	1983
Brake Fluid, Silicone	10 gallons/year	36.3/year	1986
Brakleen	24 pints/year	10.8/year	1993
Brakleen	912 ounces/year	25.53/year	1986
Break Free	2 pints/year	0.9/year	1993
Cleaner	Unknown		1986
Cleaning Compound Detergent	2 gallons/year	7.26/year	1993
Cleaning Compound Solvent	2 pints/year	0.91/year	1993
Corrosion Preventative Compound	32 ounces/year	0.89/year	1986
Corrosion Preventative Compound	60 ounces/year	1.68/year	1993
Corrosion Preventative Compound 3	4 pints/year	1.8/year	1993
Corrosion Preventative Compound	64 ounces/year	1.79/year	1983
Cutting Fluid	14 ounces/year	0.39/year	1986
Denatured Ethyl Alcohol	1 quart/month	0.91/month	1983




Table C-1. Hazardous Materials Storage, Facility 1202 (Continued)

Product	Quantity Stored	Quantity Stored (kg)	Duration of Storage
Desiccant, Activated	2 pounds/year	0.9/year	1993
Desiccant, Activated	1 pound/year	0.45/year	1986
Diesel Fuel	10 gallons/year	36.3/year	1993
Diesel Fuel, Regular	25 galions/year	90.75/year	1986
Elmers Glue	8 ounces/year	0.22/year	1983
Enamel Acrylic, Yellow	4 pints/year	1.8/year	1993
Enamel, Alkyd Gloss	26 ounces/year	0.72/year	1986
Enamel, Black Spray Paint	1 pint/year	0.45/year	1986
Enamel, Blue	6 pints/year	2.7/year	1993
Enamel, Blue Spray	13 ounces/year	0.36/year	1983
Enamel, Gray Gloss	13 ounces/year	0.36/year	1983
Enamel, Olive Drab	18 pints/year	8.1/year	1993
Enamel, Red	10 pints/year	4.5/year	1993
Enamel, Spray	52 ounces/month	1.45/month	1983
Enamel, Spray	12.75 ounces/month	0.35/month	1983
Enamel, White	312 ounces/year	8.73/year	1986
Engine Starting Fluid	128 ounces/year	3.58/year	1986
Epoxy Resin	2 kits/year	0.9/year	1993
Filtrol Desiccant	2 pints/year	0.9/year	1993
Floor Finish Non-Buffing	10 gallons/year	36.3/year	1993
Form A Gasket	6 ounces/year	0.16/year	1993
Gasoline No-Lead Unbranded	10 gallons/year	36.3/year	1993
Grease, Aircraft and Artillery	12 pounds/year	5.4/year	1986
Grease, Aircraft and Instrument	1 pound/year	0.45/year	1986
Grease, Aircraft and Instrument	1.75 pounds/year	0.78/year	1983
Grease, Aircraft and Instrument	4 pounds/year	1.8/year	1993
Grease, Auto and Artillery	4 pounds/year	1.8/year	1993
Grease, Auto and Artillery	70 pounds/year	31.5/year	1993
Grease, Auto Lubricating	1 pound/week	0.45/week	1983
Grease, Ball and Roller Bearing	4 pounds/year	1.8/year	1993
Grease, Silicone Compound	20 ounces/year	0.56/year	1993
Hydraulic Fluid, Petroleum Base	2 gallons/year	7.26/year	1993
ink, Black Handy Spray	59,345, ounces/year	1,661.66/year	1986
Ink, Metal Marking Stencil	1 pint/year	0.45/year	1986
Ink, Red Marking	96 ounces/year	2.68/year	1986
Ink, White Handy Spray	192 ounces/year	5.37/year	1986
ink, Yellow Marking	96 ounces/year	2.68/year	1986

Table C-1. Hazardous Materials Storage, Facility 1202 (Continued)

Product	Quantity Stored	Quantity Stored (kg)	Duration of Storage
JP-4	5 gallons/year	18.15/year	1993
Lacquer, Acrylic	78 ounces/week	2.18/week	1983
Lacquer, Acrylic	2 pints/year	0.9/year	1986
Lacquer, Acrylic	0.5 gallon/year	1.81/year	1983
Lacquer, Black	2 pints/year	0.9/year	1986
Lacquer, Blue	3 pints/year	1.35/year	1993
Lacquer, Clear Acrylic	13 ounces/year	0.36/year	1986
Lacquer, Clear Aerosol	4 ounces/year	0.11/year	1993
Lacquer, Olive Drab	8,112 ounces/year	227.13/year	1986
Lacquer, Olive Drab	1 pint/year	0.45/year	1986
Lacquer, Olive Drab	18 pints/year	8.1/year	1993
Lacquer, Orange Aerosol Stencil	8 pints/year	3.6/year	1993
Lacquer, Red	1 pint/year	0.45/year	1986
Lacquer, Silver	5 quarts/year	4.55/year	1986
Lacquer, White	2 pints/year	0.9/year	1 <b>993</b> ,
Lacquer, Yellow	1,014 ounces/year	28.39/year	1986
Leak Test Compound	2 bottles/year		1993
Lube Oil	25 ounces/year	0.7/year	1983
Lube Oil	1 pound/week	0.45/week	1983
Lube Oil, Antifreeze	6 quarts/year	5.46/year	1993
Lube Oil, General Purpose	2 quarts/year	1.82/year	1993
Lubricant Fluorocarbon	32 ounces/year	0.89/year	1983
Lubricating Oil	16 ounces/year	0.44/year	1986
Lubricating Oil, Anderol	2 quarts/year	1.82/year	1993
Methyl Ethyl Ketone	5 gallons/year	18.15/year	1983
Mogas, Regular	25 gallons/year	90.75/year	1986
Molybdenum Disulfide	2 ounces/year	0.05/year	1986
Molybdenum Disulfide	12 pounds/year	5.4/year	1993
Obliterating Aerosol	1 pint/year	0.45/year	1986
Obliterating Compound	10 pints/year	4.5/year	1993
Oil, 10 Weight Special Duty	6 quarts/year	5.46/year	1993
Oil, Engine 2-Cycle Marine	80 ounces/year	2.24/year	1993
Paint, Black	12 pints/year	, 5.4/year	1993
Paint, Black	2 quarts/year	1.82/year.	1993
Paint, Black	48 pints/year	21.6/year	1993
Paint, Gray Aerosol	10 pints/year	4.5/year	1993
Paint, Orange	91 ounces/year	2.54/year	1986

Table C-1. Hazardous Materials Storage, Facility 1202 (Continued)

Product	Quantity Stored	Quantity Stored (kg)	Duration of Storage
Paint, Spray	26 ounces/month	0.72/month	1983
Paint, White	20 ounces/year	0.56/year	1986
Paint, White Stencil	18 pints/year	8.1/year	1993
Paint, Yellow Spray	13 ounces/month	0.36/month	1983
PD-680	6 gallons/year	21.78/year	1983
Perma Silk G Lubricant Aerosol	0.5 pound/year	0.22/year	1993
Primer Coating	26 ounces/month	0.72/month	1983
Primer, Gray	4 pints/month	1.8/month	1983
Safety Kleen 140	30 gallons/year	108.9/year	1993
Sealant, RTV	6 tubes/year	2.7/year	1993
Silicone Spray Lubricant, Trizol	32 ounces/year	0.89/year	1993
Super Glue	2 ounces/year	0. <b>05</b> /year	1993
Tractor Oil	1 quart/year	0.91/year	1986
Trichloroethane	1 quart/year	0.91/year	1983
Turtle Wax Car Polish	72 ounces/year	2.01/year	1993
Zep Tox 2	96 ounces/year	2.68/year	1986
Zep Tox 2	24 cans/year	552/year `	1993
Zinc Chromate Primer	104 ounces/year	2.91/year	1986
Zinc Chromate Primer	4 pints/month	1.8/month	1983

Facility	Product	Quantity Stored	Quantity Stored (kg)	Years	Constituents	8	Synonym(s)	CASRN
828	Cleaning compound sovent	72 cans/year	1,633/уевг	1993	Trichlorotrifouoroethane	76	Chlorinated fluorocarbon Freon 113 Refrigerent 113	76-13-1
				•	Carbon dioxide	m	Dry Ice	124-38-9
. 828	Cleaning compound solvent	1 can/day	23/day	1983	N	Ŋ	NE	ī
828	tube of general purpose	120 cans/vear	2,722/year	1993	Transformer oil (PCB free)	92	Į,	Z Z
,			•		Corresion inhibitor	9	N	N N
					Thermo setting acrylic	-	N	NF.
					Food grade antioxidant	0.5	NL ·	N N
					Low foaming surfactant	0.5	N	N N
0,0	157	72 cans/vear	1,633/vear	1993	NF	N	¥	N
828	PD-680	150 gallons/6 months	567/6 months	1986	Aliphatic petroleum distillates	95	NL	Į.
828	Pernal Silk G lubricant	120 cans/year	2 7 2 2 /year	1993	Molybdenum disulfide	물	NL	ž
					किन्नुसम्म किस्त स्वामुख्यास्त	ž	Z	Ī
					Antimony trioxide (sura III)	ź	Antimony tnoxide, production	1309 64 4
,					Methyl ethyl ketone	ž	2-Butanone Ethel methyl ketone Methyl acetone	78 93 3
,					Xylenes	Z	Benzene, dimethyl Dimethyl benzene	1330 20 7
					Mineral spirits	N N	NF	Ŋ
0,0	Calety Kleen	1.800 gallons/vear	6,804/vear	1993	Anti-static additive	N N	N	Ŋ
2			•		Dye	Ŋ	Ŋŗ	NF
					140 solvent	된	N	NL
		:			140	001	=	Z

Nt = Not listed

r · · :

Facility		Quentrty Stored	Quantity Stored					
Number	Product	(Units Provided)	(kg)	Years	Constituents	*	Synonymis	CASBN
828	Salety Kleen 140 solvent	150 gallons/6 months	567/6 months	1990	Anti-static addrtive	Z	N	N N
					Dye	0.003	N.	Z
					140 solvent	100	N	Z
839	Zyglo cleaner	12 cans/month	272/month	1981	N	ĭ		: <del>2</del>
839	Zyglo developer	1 can/month	23/month	1981	¥	z	N	: <del>Z</del>
918	Bruko parts cloanor	264 cans/year	5,987/ynar	1993	N	Z	Z	! <b>=</b>
918	Bruklaan	264 cms/year	5,987/yeur	1993	ž	Z	. 2	Ē Z
927	Cleaning, engine	50 gallons/month	189/month	1981	Z	! z	. Z	ž 2
927	Lubricating oil, turbine	50 gallons/month	189/month	1981	i i	ź	# <b>z</b>	ž 2
927	Methanol, technical	300 gallons/month	1,134/month	1983	Methanol	001	Methyl alcohol	67 56 1
							Monohydroxymethane Wood alcohol	
927	Lubricating oil, turbine	50 gallons/month	189/month	1981	N	¥	N	N
927	Methanol, technical	300 gallons/month	1,134/nionth	1983	Methanol	100	Methyl alcahol	67 56 1
							Monohydroxymethane Wood alcohol	
927	Salety-Kleen 140	490 gallons/year	1,852/year	1990	Anti-static additive	R	N	ž
					Dye	0.003	N	N
	:				140 solvent	100	¥	NL
927	Safety-Kleen 140	280 gallons/year	1,058.4/year	1993	140 solvent	100	N	NI.
940	Libe oil, general purpose	48 cmm/yam	1,089/yanr	1993	Translormer ort (PCB Tree)	92	. <sub>IN</sub>	z
					Corresion inhibitor	9	N	Ŋ
					Thermosetting arryla	_	Z	ž
					Food grade antioxidant	0.5	NL	Ŋ
,					Low foaming surfactant	9 0	NL	Ĭ
948	Alkabne cleaning compound	500 gallons/year	1,890/year	1984-1986	N	Ŋ	N	N
1202	Black handy spray ink	59,345/year	1,661 66/year	1986	Methylene chloride	29	Dichloromethane Methylone chloride Narkotil	75 09 2
					Aromatic hydrocarbons	15	N	N
					Ketones	8	N	z

Richards-Gebaur AFB EBS

THIS PAGE INTENTIONALLY LEFT BLANK



APPENDIX D

APPENDIX D
SUMMARY OF TITLE SEARCH

Table D-1. Summary of Title Search

	Dates of Property	
Legal Description	Transfer (*)	Type of Transfer
Portions of Section 2, T 46N, R33W		
W 1/2, W 1/2	02-28-41	Fee
	12-10-51	Fee
E 1/2, NW 1/4	09-28-46	Fee
E 1/2, SW 1/4		
W 1/2, NE 1/4		
W 1/2, SE 1/4		
Portions of Section 3, T46N, R33W		
E 1/2, NE 1/4	02-28-41	Fee
D-m' ( C- ) 44 T401 D0011	12-10-51	Fee
Portions of Section 11, T46N, R33W		
W 1/2, NW 1/4	02-22-41	Fee
E 1/2, NW 1/4	12-10-51	Fee
Portions of Sections 2, 3, 10, and 11	12-07-51	Fee
	08-25-55	Fee
Portions of Section 26, T47N, R33W	•	
W 1/2, SW 1/4	05-12-60	Fee
Portions of Section 27, T47N, R33W		
NW 1/4	05-12-60	Fee
SE 1/4		
SW 1/4		
S 1/2	11-22-55	Fee
SE 1/4, SW 1/4	12-04-56	Fee
Portions of Section 34, T47N, R33W		
E 1/2, SE 1/4	11-14-41	Fee
W 1/2, SE 1/4		
E 1/2, NW 1/4	11-14-41	Fee
E 1/2, NE 1/4	11-14-41	Fee
\$ 1/2	11-14-41	Fee
Portions of Section 35, T47N, R33W	•	
N 1/2	11-14-41	Fee
NW 1/4, SE 1/4	12-07-42	Fee
E 1/2	01-28-53	Fee
S 1/2		
Portions of Sections 34 and 35	08-25-55	Fee
Portions of Section 35	10-08-58	Fee

Note: (a) Dates given as month-day-year.

THIS PAGE INTENTIONALLY LEFT BLANK



APPENDIX E

APPENDIX E
HISTORY OF FACILITY USAGE

#### HISTORY OF FACILITY USAGE

This appendix presents a summary of facilities where past activities may have required the storage of hazardous materials or the generation of hazardous waste, and which have undergone a change in use or have been demolished.

Facility 602, constructed in 1957, was originally Headquarters Major Command and later converted to a flight simulator and office space facility. Currently, it is used as offices for the Security Police. Hazardous materials usage would most likely be associated with the maintenance of the simulators but not with the former Headquarters usage.

Facility 603 was constructed in 1957 as the Medical Food Inspection facility and now is the Bioenvironmental Engineer's office. Small quantities of hazardous materials would have been associated with the introduction of the Bioenvironmental Engineering office. Activities associated with the original use are not known.

Facility 609 was constructed in 1962 to provide storage for paint and dope and now is listed as hazardous storage.

Facility 617 was constructed in 1960 and served as a commercial transportation facility. Currently the facility is used for disaster preparedness.

Facility 618 was used for cold storage from 1954 to the 1980s. In the 1980s, the 2,982-square-foot facility was demolished. Facility 618 was located near the southeast corner of Facility 610, next to Facility 619.

Facility 619 was constructed in 1954 as Administrative Office space and has since changed use to the Exchange Branch.

Facility 620 was constructed in 1961 for Plant Reproduction and is currently used for document storage.

Facility 828 was constructed in 1955 as a warehouse and equipment shop. The facility is currently used as a weapons release shop and operations require the use of hazardous materials.

Facility 902, a JP-4 hydrant fuel pump house, was constructed in 1954 and demolished in 1988. Four 25,000-gallon USTs were removed from this site in 1988, and environmental contamination was found. Facility 902 was located along the flightline between Facilities 918 and 901.

Facility 904 was constructed in 1957 and was used for paint and dope storage and is now used for hazardous material storage.

Facility 930 was constructed in 1961 and was used as a Wing Headquarters and Communications and Electronics Shop. Currently, the facility is used for the Electronic Countermeasures pod shop and stores, and hazardous materials are used in its operations.

Facility 936 was constructed in 1976 for base engineering storage. It was later converted to a hazardous materials storage facility.

Facility 937 was constructed in 1954 and was used for paint and dope storage and is now used as hazardous material storage.



Facility 944 was a jet engine test cell and was constructed in 1956. The facility underwent a number of modifications prior to being demolished in the 1980s. An OWS, an AST, and an individual oil-fired heating plant were present at this site.

Facility 945, a concrete area on the apron, was utilized as a corrosion control facility for aircraft from 1959 until approximately 1980.

Facility 946 was constructed in 1960 and was used for paint and dope storage and is now used as hazardous material storage.

Facility 948 is a hangar constructed in 1963 and used as a maintenance dock. The facility has since been converted to a fuel systems dock


Facility 1201 was constructed in 1961 and originally designated as Security Central Control; it is now used as a Weapons Management Facility.

Facilities 1600, 1601, 1602, and 1604 are located at the Belton Training Complex. This area is leased to the U.S. Army Reserve.

Facilities 1600 and 1601 were constructed in 1956 and used as Igloo Storage facilities until the 1970s. Currently the facilities are designated as Reserve Forces Operational Training.

Facility 1602 was constructed in 1960 and was an ammunition and ordnance disposal bunker. Its current designation is Reserve Forces Operational Training.

Facility 1604 was constructed in 1966 for Segregated Storage Magazine, and was used until the 1970s. Reserve Forces Operational Training is its current designation.



APPENDIX F

# APPENDIX F HAZARDOUS WASTES GENERATED

Table F-1. Hazardous Wastes Generated Page 1 of 4

		Documented Years	
Facility	Types of Waste Generated	of Generation.	Amount Generate
601	Developer and replenisher	1988-1989	8 gallons/year
	Fixer and replenisher		
610	Oil		
	Mask filters	1993	395 gallons/year
	Waste flammable liquid	1993	30 pounds/year
	Toner	1993	34 pounds/year
619/710	Ammonia	1985	0.5 gallon/year
	Paint	1991	45 gallons/year
	Paint material	1990-1991	626 gallons/year
	Paint thinner	1991-1992	61 gallons/year
704	Hydraulic fluid	1987	55 gallons/year
	Hydraulic fluid	1989-1990	28 gallons/year
	Transmission fluid	1987-1988	45 galtons/year
	Transmission fluid	1989-1900	43 gallons/year
	Used/waste engine oil	1992-1993	100 gallons/year
	Antifreeze	1987-1988	341 gallons/year
	Antifreeze	1989-1990	43 gallons/year
	Gear lube	1987-1988	53 gallons/year
	Waste oil	1991-1993	375 gallons/year
	Paint stripper	1987-1988	1.5 gallons/year
	Hydraulic fluid	1987-1988	55 gallons/year
	Engine oil	1987-1988	283 gallons/year
	Engine oil	1989-1991	216 gallons/year
	Paint waste	1986-1987	2 gallons/year
	Lube oil	1987	315 gallons/year
	Lube oil	1988	30 gallons/year
	Lube oil	1989-1990	26 gallons/year
	Lube oil	1991	50 gallons/year
	Paint thinner	1989	60 gallons/year
	Paint thinner	1991	50 gallons/year
	Fuel filters	1989-1990	280 gallons/year
	Oil filters	1989-1990	140 gallons/year
	Motor oil	1990	50 gallons/year
	Aliphatic hydrocarbons	1990-1991	35 gallons/year
	Lubricants	1991	250 gallons/year
711	Paint-related material	1991	54 gallons/year
	Used JP-4 fuel filters	1992	190 gailtons/year

Notes: Hazardous waste is known to have been generated in other facilities also, nowever, there is no documentation available regarding specific wastes or quantities. These facilities include Facilities 605, 701, and 953.

(a) Information on years of hazardous waste generation was not available prior to 1985

Table F-1. Hazardous Wastes Generated Page 2 of 4

		of 4	
Facility	Types of Waste Generated	Documented Years of Generation <sup>(e)</sup>	Amount Generated
711 (Continued)	Waste oil lubricant	1992	48 gallons/year
	Lubricants	1991	50 gallons/year
828	Petroleum PD-680	1985	15.5 gallons/year
	Denatured alcohol w/brake fluid	1988	5 gallons/year
	JP-4 contaminated sand bags	1989	800 gallons/year
	JP-4 contaminated absorbant material	1989 -	70 gallons/year
	Absorbant Pads	1990	55 gallons/year
	Hydraulic lift fluid	1990	550 gallons/year
	JP-4 contaminated soil	1990	879 gallons/year
	Flammable liquids	1991	100 gallons/year
<b>83</b> 9	Synthetic oil	1991	62 gallons/year
	Synthetic oil	1992-1993	13.5 gallons/year
	A/C synthetic oil	1987-1988	16 gallons/year
	Waste synthetic oil	1992	44 gallons/year
	Penetrant	1985	99 gallons/year
	Emulsifier	1985	86 gallons/year
	HW Liquid NOSORM-E	1990-1991	12 gallons/year
•	Penetrant	1987	50 gallons/year
	Penetrant	1988	194 gallons/year
	Emulsifier	1987	74 gallons/year
	Emulsifier	1988	131 gallons/year
	Developer .	1988-1989	10 gallons/year
	Developer	1992	115 gallons/year
	Magnaglo bath	1986	22.5 gallons/year
	Magnaglo bath	1988	8 gallons/year
	Magnaglo bath	1989	924 gallons/year
,	Magnagio bath	1990-1991	60 gallons/year
	Solvent cleaner	1990	5 gallons/year
	Emulsifier w/oil	1988	47 gallons/year
-	Oil w/trichloroethane	1988-1989	14 gallons/year
	Oil w/trichloroethene	1985-1986	23 gallons/year
	Waste trichloroethane oil	1985-1986	17 gallons/year
<b>9</b> 18	Sulfuric acid	1987-1988	20 gallons/year
	Sulfuric acid	1989-1990	20 gallons/year
•	Lead sulfuric acid	1986-1987	25 gallons/year
	Nicad batteries	1986-1988	40 gallons/year
	Nicad batteries	1989-1990	82 gallons/year
	Hydraulic fluid	1985-1991	150 gallons/year

Table F-1 Hazardous Wastes Generated Page 3 of 4

<del></del>	Page 3		
Facility	Types of Waste Generated	Documented Years of Generation <sup>(4)</sup>	Amount Generated
918 (Continued)	Hydraulic fluid	1992-1993	42.5 gallons/year
	Thinner	1985	50 gallons/year
	Waste hydraulic fluid	1991-1992	48.5 gallons/year
	Synthetic engine oil	1992	44 gallons/year
927/928	Trichloroethane	1985-1988	4 gailons/year
	Carbon remover	1985-1986	30 gallons/year
	Carbon remover	1988-1989	6 gailons/year
	PD-680	1985-1986	50 gallons/year
	Turbine oil	1986	45 gallons/year
	Engine oil	1985-1991	235 gallons/year
	Jet engine oil	1986	49 gallons/year
	Jet engine oil	1989	46 gallons/year
	Hydraulic fluid	1987-1988	47 gallons/year
	Waste engine oii	1989	92 gallons/year
	Waste engine oil .	1991-1992	45 gallons/year
	Turco cleaner	1989	5 gallons/year
	Used/waste turbine oil	1992-1993	93 gallons/year
	Waste oil with solvent	1991-1992	40 gallons/year
	JP-4/MOGAS/water	1990	46 gallons/year
948/972	Waste latex paint	1992	50 gallons/year
	Waste oil-base paint	1992	50 gallons/year
	Waste paint-related material	1992	50 gallons/year
	Waste sealing compound	1992	6 pounds/year
958/959	Turbine oil	1985-1988	16.5 gallons/year
	Turbine oil	1989-1990	9.5 gallons/year
	Engine oil	1985-1990	75 gallons/year
	Lube oil	1985-1987	65 gallons/year
	Diethylene glycol	1985	5 gallons/year
	Transmission fluid	1986	5 gallons/year
	Transmission fluid	1987-1988	31 gallons/year
	Hydraulic fluid	1987-1991	194 gallons/year
	Monobutyl ether	1987-1988	5 gallons/year
	Preservative oil	1988	10 gallons/year
	JP-4/MOGAS/water	1990	10 gallons/year
	Waste oil	1991-1992	76 gallons/year
	Motor oil	1991	103 gallons/year
	Waste engine oil	1991-1992	49 gallons/year
	Used motor oil	1992-1993	50,5 gallons/year


MOGAS = Motor gasoline.

1

1711 P.

Table F-1. Hazardous Wastes Generated
Page 4 of 4

Facility	Types of Waste Generated	Documented Years of Generation(4)	Amount Generated
965	Stripper	1985	261 gallons/year
	Hydraulic fluid with methyl ethyl ketone	1985	15 gallons/year
	Toluene and methyl ethyl ketone	1985	54 gallons/year
	Thinner and methyl ethyl ketone	1985	27 gallons/year
	Epoxy remover	1985-1986	55 gallons/year
	Polyurethane paint	1987	151 gallons/year
	Polyurethane thinner	1986-1987	25 gallons/year
	Paint thinner	1986-1991	139 gallons/year
	Waste paint	1991-1992	75 gallons/year
	Waste thinner with methyl ethyl ketone	1992	49 gallons/year
966	Petroleum PD-680-II	1985-1986	48 gallons/year
	Paint stripper	1987-1988	93 gallons/year
	Used paint stripper	1987	110 gallons/year
	Paint stripper	1990	50 gallons/year
<b>97</b> 0	Tar	1990	40 gallons/year
	JP-4 contaminated water	1990	45 gallons/year
973	Aliphatic hydrocarbons	1991	15 gallons/year
1033	JP-4, engine oil, solvents	1969-1982	25,000 gallons/year
	JP-4	1983-1988	5,520 gallons/year
1202	Denatured alcohol with brake fluid	1990-1992	2 gallons/year
Fire Dept.	JP-4 Spill-X	1993	278 pounds/year



APPENDIX G

### APPENDIX G

GLOSSARY OF TERMS, ACRONYMS, AND ABBREVIATIONS

#### GLOSSARY OF TERMS, ACRONYMS, AND ABBREVIATIONS

Asbestos. A carcinogenic substance formerly used widely as an insulation material by the construction industry; often found in older buildings.

Friable. Easily crumbled or ground into powder.

Hazardous material. Generally, a substance or mixture of substances that has the capability of either causing or significantly contributing to an increase in mortality or an increase in serious irreversible or incapacitating reversible illness; or posing a substantial present or potential risk to human health or the environment. Use of these materials is regulated by Department of Transportation (DOT), Occupational Safety and Health Administration (OSHA), and Superfund Amendments and Reauthorization Act (SARA).

Hazardous waste. A waste, or combination of wastes, which, because of its quantity, concentration, or physical, chemical, or infectious characteristics, may either cause, or significantly contribute to, an increase in mortality or an increase in serious irreversible illness; or pose a substantial present or potential hazard to human health or the environment when improperly treated, stored, transported, disposed of, or otherwise managed. Regulated under the Resource Conservation and Recovery Act (RCRA).

Herbicide. A pesticide (q.v.), either organic or inorganic, used to destroy unwanted vegetation, especially various types of weeds, grasses, and woody plants.

Installation Restoration Program (IRP). An Air Force program to identify, characterize, and remediate environmental contamination on its installations.

Lead (Pb). A heavy metal, used in many industries, which can accumulate in the body and cause a variety of negative effects.

Mitigation. A method or action to reduce or eliminate program impacts.

National Environmental Policy Act (NEPA). Public Law 91-190, passed by Congress in 1969. The Act established a national policy designed to encourage consideration of the influences of human activities (e.g., population growth, high-density urbanization, industrial development) on the natural environment. NEPA also established the Council on Environmental Quality. NEPA procedures require that environmental information be made available to the public before decisions are made. Information contained in NEPA documents must focus on the relevant issues in order to facilitate the decision-making process.

Pesticides. Any substance, organic or inorganic, used to destroy or inhibit the action of plant or animal pests; the term thus includes insecticides, herbicides, fungicides, rodenticides, miticides, fumigants, and repellents. All pesticides are toxic to humans to a greater or lesser degree. Pesticides vary in biodegradability.

Polychlorinated biphenyls (PCBs). Any of a family of industrial compounds produced by chlorination of biphenyl. These compounds are noted chiefly as an environmental pollutant that accumulates in organisms and concentrates in the food chain with resultant pathogenic and teratogenic effects. They also decompose very slowly. Equipment containing 50 parts per million or more of PCB is regulated by the U.S. EPA.

Solvent. A substance that dissolves or can dissolve another substance.

U.S. Environmental Protection Agency (U.S. EPA). The independent federal agency, established in 1970, that regulates environmental matters and oversees the implementation of environmental laws.

#### **ACRONYMS AND ABBREVIATIONS**

ACM asbestos-containing material

AFB Air Force Base

AST aboveground storage tank

BCP BRAC Cleanup Plan

BRAC Base Realignment and Closure

CERCLA Comprehensive Environmental Response, Compensation and Liability Act
CERCLIS Comprehensive Environmental Response, Compensation and Liability

Information System

.CERFA Community Environmental Response Facilitation Act

CES Civil Engineering Squadron
CFR Code of Federal Regulations
CSR Code of State Regulations
DOD Department of Defense

DRMO Defense Reutilization and Marketing Office

EBS Environmental Baseline Survey

ECAMP Environmental Compliance Assessment and Management Program

ECL Environmental Contamination List
EIS Environmental Impact Statement

EPA see U.S. EPA
F Fahrenheit

FUDS Formerly Used Defense Sites
GSA General Services Administration

IAP initial accumulation point

IRP Installation Restoration Program
JP-4 jet propulsion fuel, grade 4

kg kilogram kV kilovolt

kVA kilovolt-ampere

MAP Management Action Plan

MDNR Missouri Department of Natural Resources

MOGAS motor gasoline

NDI Non-Destructive Inspection

NEPA National Environmental Policy Act of 1969

NPL National Priorities List

OU operable unit
OWS oil/water separator

PA/SI Preliminary Assessment/Site Inspection

PCBs polychlorinated biphenyls

pCi/l picocuries per liter

POL petroleum, oils, and lubricants

ppm parts per million

RCRA Resource Conservation and Recovery Act

RFA RCRA Facility Assessment
RI Remedial Investigation

RI/FS Remedial Investigation/Feasibility Study

SI Site Inspection

TSD treatment, storage, and disposal

U.S.C. U.S. Code

U.S. EPA U.S. Environmental Protection Agency

UST underground storage tank
VRS visual reconnaissance survey

VSI . visual site inspection

### FINAL PAGE

**ADMINISTRATIVE RECORD** 

FINAL PAGE

## FINAL PAGE

ADMINISTRATIVE RECORD

FINAL PAGE