

L1 - 7 turns around 5/16 bolt, tap at 2nd turn L2 - 26 turns of AWG 30 around 8mm form