

FROM Robert Samuel White <rsw@rswfire.com>
TO [Park Supervisor]
DATE March 16, 2025, 6:43 AM PT
SUBJECT **Golf Cart**
DOCUMENT 01JPFK4TB0V1JVBH266AK81P0T

Hi, [Park Supervisor].

I read somewhere to contact you or [Park staff] about golf cart issues, so I hope this message is welcome.

My golf cart has a few issues.

The major one is the tent structure around it - the driver side does not zip up. It cannot be sealed (the zipper is completely ripped) and with the constant rain, this means a wet environment while I'm working and potential damage to the unit.

I've tried protecting it overnight with a tarp but given the wind, this has not worked as well as I'd hoped. It is still getting very wet.

The other issue is related to the motor. It skips so the drive has never been smooth. Charles explained this to me but I can't recall the mechanics. He noted he had this unit last month and it was meant to go in for repair. I don't recall seeing any other units up there so I can understand how I ended up with it and I'm fine with the situation, I just want to note it in case you feel it requires attention.

Thanks

Sam